



**SERVICE BULLETIN  
AND  
SERVICE LETTER**

**INDEX**

**PIPER AIRCRAFT, INC.**

Published by

Piper Aircraft, Inc.  
Attn: Technical Publications  
2926 Piper Drive  
Vero Beach, Florida 32960  
U.S.A.

© 2003–2022 Piper Aircraft, Inc.



Member  
General Aviation  
Manufacturers Association

# **SERVICE PUBLICATION AVAILABILITY**

Piper terminated production of all Aerofiche (i.e., microfiche) products in 2008.

**Service Publications (i.e., service bulletins, letters, etc.) are available as described in the Customer Service Information File on the Piper website.**

The latest revision of this publication is also available as free downloads from the Piper Aircraft, Inc. website at:

<http://www.piper.com/technical-publications-documents/>

## **GENERAL**

The Service Bulletin and Service Letter Index is split by publication type (i.e., SB or SL) and then arranged by aircraft model number (i.e., PA-28, etc) with similar model series grouped together (see Table of Contents). Within these series, applicable service bulletins/letters are listed in numerical order. To locate a specific bulletin or letter, select the appropriate service publication type (i.e., SB or SL) and then locate the affected aircraft series grouping. Bulletins/letters which apply are listed therein and are identified by Subject, Model(s) Affected, and the Issue Date of the Service Bulletin/Letter. Additionally, the index may list part or kit numbers and related A.D. numbers. The Air Transport Association Code (ATA Spec. 100 / iSpec 2200) is provided to assist in maintenance record keeping and researching publications.

## **NOTES**

1. Airworthiness Directives referred to by number in the A.D. No. column and A.D. numbers listed in individual service bulletins / service letters are those which applied at the time of publication. Refer to the latest FAA Bi-weekly listing for current A.D. information. A searchable database of AD's is available on the FAA website. See the "Airworthiness Directives" link at "[www.faa.gov](http://www.faa.gov)".
2. When \*\* appears in the Part/Kit No. column, material requirements are too extensive to be listed in the index; refer to the appropriate service bulletin/letter for material identification.
3. When Part/Kit No. and/or A.D. No. column is left blank or indicates "N/A," no material and/or Airworthiness Directive is involved.
4. Airworthiness Directives may be issued without an associated service bulletin/letter; therefore, refer to Airworthiness Directive Listings issued by the FAA to determine all Airworthiness Directives applicable to an aircraft. See Note 1, above.
5. Type Certificates (TC's) for the following aircraft models are not held by Piper: AE-1, HE-1, J5A, J5A-80, J5B, J5C, L-14, PA-12, PA-12S, PA-14, PA-25, PA-60, and Stinson 108-3. See Supersession List for affected service bulletins / letters. The current TC holder(s) may be identified through the FAA (see the "Regulatory and Guidance Library" at <http://rgl.faa.gov/>).

**SERVICE BULLETIN AND SERVICE LETTER**  
**INDEX**

**TABLE OF CONTENTS**

| <b><u>SUBJECT</u></b>            | <b><u>PAGE NO.</u></b> |
|----------------------------------|------------------------|
| Service Publication Availability | iii                    |
| General                          | iv                     |
| Notes                            | iv                     |
| Supersession List                | vii                    |

**SERVICE BULLETINS**

|                                                    |      |
|----------------------------------------------------|------|
| CLASSIC AIRCRAFT: (B-2 thru PA-22)                 | SB1  |
| PA-23/PA-23-160, PA-23-235/PA-23-250, PA-E23-250   | SB9  |
| PA-24, PA-30/39                                    | SB17 |
| PA-28, PA-28R, PA-44/PA-44T                        | SB23 |
| PA-31/PA-31-300/325, PA-31-350, PA-31P, PA-31P-350 | SB41 |
| PA-31P-350,                                        | SB41 |
| PA-31T/31T1, PA-31T2/31T3, PA-42                   | SB55 |
| PA-32 Series                                       | SB65 |
| PA-34-200/200T/220T                                | SB77 |
| PA-36                                              | SB85 |
| PA-38-112                                          | SB89 |
| PA-46-310P, PA-46-350P                             |      |
| PA-46-500TP, PA-46-600TP                           |      |
| PA-46R-350T                                        | SB93 |

**SERVICE LETTERS**

|                                                    |      |
|----------------------------------------------------|------|
| CLASSIC AIRCRAFT: (B-2 thru PA-22)                 | SL1  |
| PA-23/PA-23-160, PA-23-235/PA-23-250, PA-E23-250   | SL7  |
| PA-24, PA-30/39                                    | SL15 |
| PA-28, PA-28R, PA-44/PA-44T                        | SL23 |
| PA-31/PA-31-300/325, PA-31-350, PA-31P, PA-31P-350 | SL37 |
| PA-31T/31T1/T2/T3, PA-42                           | SL47 |
| PA-32 Series                                       | SL53 |
| PA-34-200/200T/220T                                | SL61 |
| PA-36                                              | SL67 |
| PA-38-112                                          | SL69 |
| PA-46-310P, PA-46-350P                             |      |
| PA-46-500TP, PA-46-600TP                           |      |
| PA-46R-350T                                        | SL71 |

**THIS PAGE INTENTIONALLY BLANK**

# **SUPERSESSION LIST**

The following service bulletins / letters have been superseded, become obsolete, were never issued, or are no longer maintained by Piper, as indicated (see Note 5).

**NOTE:** This list is not all inclusive. Additionally, it does not include supersessions by a normal (i.e. - A, B, C, etc.) revision within the same SB/SL number.

| <u><b>Superseded /<br/>Obsolete Pub</b></u> | <u><b>New Pub<br/>or Reason</b></u> | <u><b>Superseded /<br/>Obsolete Pub</b></u> | <u><b>New Pub<br/>or Reason</b></u> | <u><b>Superseded /<br/>Obsolete Pub</b></u> | <u><b>New Pub<br/>or Reason</b></u> |
|---------------------------------------------|-------------------------------------|---------------------------------------------|-------------------------------------|---------------------------------------------|-------------------------------------|
| SB 0005                                     | Obsolete                            | SB 0101                                     | PA-12                               | SB 0670                                     | SB 1235                             |
| SB 0006                                     | Obsolete                            | SB 0102                                     | PA-12                               | SB 0687                                     | SB 1007                             |
| SB 0010                                     | Obsolete                            | SB 0105                                     | PA-12/14                            | SB 0698A                                    | SB 0811A                            |
| SB 0011                                     | Obsolete                            | SB 0106                                     | PA-12/14                            | SB 0699 (PA-34 only)                        | SB 0899                             |
| SB 0012                                     | Obsolete                            | SB 0107                                     | PA-12                               | SB 0716                                     | Not Used                            |
| SB 0013                                     | Obsolete                            | SB 0109                                     | PA-12/14                            | SB 0720                                     | PA-60                               |
| SB 0014                                     | Obsolete                            | SB 0114                                     | STINSON 108-3                       | SB 0730                                     | Not Used                            |
| SB 0015                                     | Obsolete                            | SB 0115                                     | STINSON 108-3                       | SB 0735                                     | PA-25                               |
| SB 0016                                     | Obsolete                            | SB 0137                                     | SB 0140                             | SB 0743                                     | PA-60                               |
| SB 0017                                     | Obsolete                            | SB 0141                                     | SB 0354B                            | SB 0746A                                    | PA-60                               |
| SB 0019                                     | Obsolete                            | SB 0147                                     | Obsolete                            | SB 0750                                     | PA-60                               |
| SB 0020                                     | Obsolete                            | SB 0154                                     | Obsolete                            | SB 0755                                     | PA-60                               |
| SB 0022                                     | Obsolete                            | SB 0170                                     | Obsolete                            | SB 0756                                     | PA-60                               |
| SB 0024                                     | Obsolete                            | SB 0204                                     | PA-25                               | SB 0757                                     | PA-60                               |
| SB 0025                                     | Obsolete                            | SB 0206                                     | PA-25                               | SB 0761                                     | PA-60                               |
| SB 0026                                     | Obsolete                            | SB 0215                                     | PA-25                               | SB 0770                                     | PA-60                               |
| SB 0027                                     | Obsolete                            | SB 0217                                     | PA-25                               | SB 0793                                     | SB 0809                             |
| SB 0029                                     | Obsolete                            | SB 0221                                     | PA-25                               | SB 0815                                     | PA-60                               |
| SB 0030                                     | Obsolete                            | SB 0227                                     | SB 0230A                            | SB 0818                                     | PA-60                               |
| SB 0031                                     | J5A/B/C                             | SB 0241A                                    | PA-25                               | SB 0830                                     | PA-25                               |
| SB 0032                                     | Obsolete                            | SB 0247                                     | PA-25                               | SB 0832                                     | PA-60                               |
| SB 0033                                     | Obsolete                            | SB 0298 (portions)                          | SB 0312                             | SB 0833                                     | Not Used                            |
| SB 0034                                     | J5A/B/C                             | SB 0302                                     | Obsolete                            | SB 0864                                     | SB 1008                             |
| SB 0037                                     | Obsolete                            | SB 0318A                                    | SB 0343                             | SB 0875                                     | SB 0876A                            |
| SB 0038                                     | Obsolete                            | SB 0328                                     | PA-25                               | SB 0878                                     | PA-25                               |
| SB 0039                                     | Obsolete                            | SB 0341                                     | PA-25                               | SB 0880A                                    | PA-60                               |
| SB 0041                                     | Obsolete                            | SB 0366                                     | SB 0456A                            | SB 0894                                     | SB 1087                             |
| SB 0051                                     | Obsolete                            | SB 0371                                     | SB 0456A                            | SB 0898                                     | PA-60                               |
| SB 0052                                     | Obsolete                            | SB 0372B                                    | SB 0446A                            | SB 0902                                     | PA-60                               |
| SB 0054                                     | SB 0083                             | SB 0377                                     | SB 0456A                            | SB 0903                                     | PA-60                               |
| SB 0057                                     | Obsolete                            | SB 0378                                     | SB 0456A                            | SB 0908                                     | PA-60                               |
| SB 0059                                     | Obsolete                            | SB 0388                                     | SB 0456A                            | SB 0909                                     | SB 0913A                            |
| SB 0060                                     | J5A/B/C                             | SB 0410                                     | PA-25                               | SB 0918                                     | PA-60                               |
| SB 0062                                     | Obsolete                            | SB 0413                                     | SB 1123                             | SB 0920                                     | PA-60                               |
| SB 0064                                     | Obsolete                            | SB 0414                                     | PA-25                               | SB 0942                                     | PA-60                               |
| SB 0067                                     | Obsolete                            | SB 0416                                     | SB 0446A                            | SB 0950                                     | PA-60                               |
| SB 0069                                     | Obsolete                            | SB 0426                                     | PA-25                               | SB 1011                                     | SB 1216                             |
| SB 0070                                     | Obsolete                            | SB 0430                                     | SB 0492                             | SB 1038                                     | VSP-145                             |
| SB 0087                                     | J5A/B/C                             | SB 0456A                                    | SB 1266                             | SB 1096                                     | Not Used                            |
| SB 0090                                     | PA-12                               | SB 0457                                     | SB 0479B                            | SB 1101                                     | Not Used                            |
| SB 0092                                     | PA-12                               | SB 0532                                     | PA-25                               | SB 1112                                     | Not Used                            |
| SB 0093                                     | PA-12                               | SB 0534                                     | SB 0644E                            | SB 1115                                     | Not Used                            |
| SB 0094                                     | PA-12                               | SB 0540A                                    | Cancelled                           | SB 1116                                     | Not Used                            |
| SB 0096                                     | PA-12                               | SB 0551A                                    | PA-25                               | SB 1124                                     | Not Used                            |
| SB 0097                                     | PA-12                               | SB 0581                                     | Not Used                            | SB 1129                                     | Not Used                            |
| SB 0098                                     | PA-12                               | SB 0605                                     | Obsolete                            | SB 1133                                     | Not Used                            |
| SB 0100                                     | PA-12                               | SB 636A                                     | SB 1273C                            | SB 1142                                     | Not Used                            |

# **SUPERSESSION LIST**

(continued)

| <u><b>Superseded /<br/>Obsolete Pub</b></u> | <u><b>New Pub<br/>or Reason</b></u> | <u><b>Superseded /<br/>Obsolete Pub</b></u> | <u><b>New Pub<br/>or Reason</b></u> | <u><b>Superseded /<br/>Obsolete Pub</b></u> | <u><b>New Pub<br/>or Reason</b></u> |
|---------------------------------------------|-------------------------------------|---------------------------------------------|-------------------------------------|---------------------------------------------|-------------------------------------|
| SB 1148                                     | Not Used                            | SL 0342                                     | PA-25                               | SL 0721A                                    | PA-25                               |
| SB 1149                                     | Not Used                            | SL 0343                                     | PA-25                               | SL 0724                                     | PA-25                               |
| SB 1155                                     | Not Used                            | SL 0344                                     | PA-25                               | SL 0728                                     | PA-25                               |
| SB 1163                                     | Not Used                            | SL 0351                                     | SB 0354B                            | SL 0748                                     | Obsolete                            |
| SB 1165                                     | Not Used                            | SL 0357A                                    | PA-25                               | SL 0760                                     | SB 1131                             |
| SB 1189A                                    | Not Used                            | SL 0361                                     | PA-25                               | SL 0775A                                    | Obsolete                            |
| SB 1191A                                    | Obsolete                            | SL 0371                                     | SB 0209                             | SL 0799                                     | SB 0955                             |
| SB 1203                                     | SL 1117                             | SL 0371A                                    | SB 0209                             | SL 0811                                     | SB 1248                             |
| SB 1206                                     | Not Used                            | SL 0376                                     | PA-25                               | SL 0812                                     | PA-25                               |
| SB 1215                                     | SSL 436                             | SL 0377                                     | PA-25                               | SL 0914                                     | PA-60                               |
| SB 1218A                                    | SB 1385                             | SL 0383                                     | PA-25                               | SL 0918                                     | PA-60                               |
| SB 1219                                     | SL 1125                             | SL 0385                                     | PA-25                               | SL 0919                                     | PA-60                               |
| SB 1221                                     | Not Used                            | SL 0387                                     | PA-25                               | SL 0953                                     | SB 0896                             |
| SB 1222                                     | Not Used                            | SL 0392                                     | SB 0924                             | SL 0955                                     | SB 0868                             |
| SB 1224                                     | Not Used                            | SL 0396 (portions)                          | SL 0527D                            | SL 0957                                     | PA-60                               |
| SB 1231                                     | Not Used                            | SL 0399                                     | PA-25                               | SL 0980                                     | SB 0908                             |
| SB 1239                                     | Not Used                            | SL 0403                                     | PA-25                               | SL 1030                                     | SSL 435                             |
| SB 1249                                     | SB 1252                             | SL 0428                                     | SB 0222A                            | SL 1042                                     | Not Used                            |
| SB 1263                                     | Not Used                            | SL 0452                                     | SL 0486A                            | SL 1044                                     | Not Used                            |
| SB 1265                                     | Not Used                            | SL 0455                                     | PA-25                               | SL 1050                                     | Not Used                            |
| SB 1268                                     | SB 1270                             | SL 0463A                                    | PA-25                               | SL 1061                                     | Not Used                            |
| SB 1272                                     | Not Used                            | SL 0468A                                    | PA-25                               | SL 1064                                     | Not Used                            |
| SB 1277                                     | Not Used                            | SL 0479                                     | PA-25                               | SL 1068                                     | Not Used                            |
| SB 1281                                     | SB 1285                             | SL 0488                                     | Obsolete                            | SL 1070                                     | Not Used                            |
| SB 1287A                                    | Not Used                            | SL 0489                                     | Obsolete                            | SL 1071                                     | Not Used                            |
| SB 1292                                     | Not Used                            | SL 0493                                     | Cancelled                           | SL 1073                                     | Not Used                            |
| SB 1294                                     | Not Used                            | SL 0496                                     | Obsolete                            | SL 1080                                     | Not Used                            |
| SB 1298                                     | Not Used                            | SL 0510                                     | Obsolete                            | SL 1083                                     | Not Used                            |
| SB 1310                                     | SB 1339                             | SL 0515                                     | PA-25                               | SL 1094                                     | Not Used                            |
| SB 1320                                     | SL 1229                             | SL 0521                                     | Obsolete                            | SL 1096                                     | Not Used                            |
| SB 1321                                     | Not Used                            | SL 0528                                     | Obsolete                            | SL 1098                                     | Not Used                            |
| SB 1330                                     | Not Used                            | SL 0536                                     | PA-25                               | SL 1099                                     | Not Used                            |
| SB 1335                                     | SA 46-28                            | SL 0540                                     | Obsolete                            | SL 1101                                     | Not Used                            |
| SB 1347                                     | Not Used                            | SL 0551                                     | Obsolete                            | SL 1103A                                    | Not Used                            |
| SB 1348                                     | SA 46-31                            | SL 0554                                     | Obsolete                            | SL 1109                                     | SL 1142                             |
| SB 1351                                     | Not Used                            | SL 0563                                     | PA-25                               | SL 1109A                                    | Not Used                            |
| SB 1353                                     | SA 28-05                            | SL 0570                                     | SB 0343                             | SL 1112                                     | Not Used                            |
| SB 1356                                     | SL 1297                             | SL 0572                                     | Obsolete                            | SL 1114A                                    | Not Used                            |
| SB 1373                                     | Not Used                            | SL 0583                                     | Obsolete                            | SL 1115B                                    | Not Used                            |
| SB 1374                                     | Not Used                            | SL 0586                                     | PA-25                               | SL 1119                                     | Not Used                            |
| SB 1376                                     | Not Used                            | SL 0588                                     | SB 0840 - PT1                       | SL 1133                                     | Not Used                            |
| SL 0108                                     | PA-12                               | SL 0590                                     | SB 0840 - PT2                       | SL 1136B                                    | Not Used                            |
| SL 0110                                     | PA-12                               | SL 0597                                     | SB 0965                             | SL 1139A                                    | SL 1147                             |
| SL 0113                                     | PA-12/14                            | SL 0600                                     | SB 1199                             | SL 1143                                     | Not Used                            |
| SL 0160                                     | SL 0221                             | SL 0601                                     | SB 0356                             | SL 1144                                     | Not Used                            |
| SL 0191                                     | SL 0233                             | SL 0602                                     | Obsolete                            | SL 1145                                     | Not Used                            |
| SL 0265                                     | 753-755                             | SL 0604                                     | SB 0531                             | SL 1146                                     | Not Used                            |
| SL 0282                                     | SB 0145                             | SL 0632                                     | PA-25                               | SL 1150                                     | Not Used                            |
| SL 0308                                     | SSL-141                             | SL 0640                                     | PA-25                               | SL 1151                                     | Not Used                            |
| SL 0331                                     | PA-25                               | SL 0646                                     | PA-25                               | SL 1152                                     | Not Used                            |
| SL 0332A                                    | PA-25                               | SL 0694                                     | SB 0492                             | SL 1155A                                    | Not Used                            |
| SL 0335                                     | PA-25                               | SL 0702                                     | PA-25                               | SL 1163                                     | Not Used                            |
| SL 0337                                     | PA-25                               | SL 0703                                     | Obsolete                            | SL 1166                                     | Not Used                            |



# **SUPERSESSION LIST**

(continued)

| <b><u>Superseded /<br/>Obsolete Pub</u></b> | <b><u>New Pub<br/>or Reason</u></b> | <b><u>Superseded /<br/>Obsolete Pub</u></b> | <b><u>New Pub<br/>or Reason</u></b> | <b><u>Superseded /<br/>Obsolete Pub</u></b> | <b><u>New Pub<br/>or Reason</u></b> |
|---------------------------------------------|-------------------------------------|---------------------------------------------|-------------------------------------|---------------------------------------------|-------------------------------------|
| SL 1167                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1169                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1171                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1173                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1174                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1176                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1180                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1181                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1182                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1186                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1187                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1190                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1191                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1192                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1202A                                    | SL 1247                             |                                             |                                     |                                             |                                     |
| SL 1206A                                    | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1207                                     | SL 1217                             |                                             |                                     |                                             |                                     |
| SL 1209                                     | SB 1300                             |                                             |                                     |                                             |                                     |
| SL 1215A                                    | SL 1254                             |                                             |                                     |                                             |                                     |
| SL 1223                                     | VSP 248                             |                                             |                                     |                                             |                                     |
| SL 1225                                     | SSL 482                             |                                             |                                     |                                             |                                     |
| SL 1235                                     | SB 1324                             |                                             |                                     |                                             |                                     |
| SL 1237                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1241                                     | SL 1216                             |                                             |                                     |                                             |                                     |
| SL 1242                                     | SL 1231A                            |                                             |                                     |                                             |                                     |
| SL 1243                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1248                                     | SSL 493                             |                                             |                                     |                                             |                                     |
| SL 1258                                     | SB 1349                             |                                             |                                     |                                             |                                     |
| SL 1266B                                    | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1271                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1272A                                    | SB 1369                             |                                             |                                     |                                             |                                     |
| SL 1287                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1289                                     | SB 1364                             |                                             |                                     |                                             |                                     |
| SL 1290                                     | Not Used                            |                                             |                                     |                                             |                                     |
| SL 1295                                     | SB 1366                             |                                             |                                     |                                             |                                     |
| SL 1298                                     | SSL 507                             |                                             |                                     |                                             |                                     |
| SL 1303                                     | SL 1292A                            |                                             |                                     |                                             |                                     |
| SL 1305                                     | SB 1375                             |                                             |                                     |                                             |                                     |
| SL 1306                                     | SL 1309                             |                                             |                                     |                                             |                                     |
| SL 1307                                     | SL 1293A                            |                                             |                                     |                                             |                                     |
| SL 1312                                     | SB 1383                             |                                             |                                     |                                             |                                     |
| SL 1319                                     | SB 1379                             |                                             |                                     |                                             |                                     |

THIS SPACE INTENTIONALLY BLANK

# SERVICE BULLETIN INDEX

**CLASSIC AIRCRAFT:**  
**B-2/E-2/F-2/J-2/J-3/**  
**J-4/L-21/L-18/PA-11/NE-1/**  
**PA-15/PA-16/PA-17/PA-18/**  
**PA-19/PA-20/PA-22**

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED                                                                      | DATE    | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------|-----------------|-------------|-------------|
| 1      | How to Rig Cub E2,<br>J2, J3 Airplanes                                                                                            | E2, J2 & J3                                                                             | 2/15/46 |                 |             | 2A1         |
| 2      | Special Tubing in Fuselage                                                                                                        | All Models Manufactured<br>thru December 1945                                           | 2/15/46 |                 |             | 2A2         |
| 3      | Nose Heavy Condition                                                                                                              | All Models Manufactured<br>thru December 1945                                           | 2/15/46 |                 |             | 2A3         |
| 4      | Maintenance of Fuel System                                                                                                        | All Models Manufactured<br>thru December 1945                                           | 2/15/46 |                 |             | 2A4         |
| 7      | Reinforcement of Stabilizer Yoke                                                                                                  | J2                                                                                      | 2/18/46 |                 |             | 2A5         |
| 8      | Reinforcement of Stabilizer Yoke                                                                                                  | E2 and F2                                                                               | 2/18/46 |                 |             | 2A7         |
| 9      | Tail Surface Bracing                                                                                                              | E2, F2 & J2                                                                             | 2/18/46 |                 |             | 2A9         |
| 18     | Replacement Tail Brace<br>Wire Nipples                                                                                            | J2 and J3                                                                               | 2/18/46 |                 |             | 2A11        |
| 21     | Engine Mounting Bolt Failures                                                                                                     | J3C-65 Cubs with<br>Continental A50<br>Engine Installation                              | 2/18/46 |                 |             | 2A14        |
| 23     | Removal of Bug Screen                                                                                                             | J4                                                                                      | 2/18/46 |                 |             | 2A15        |
| 28     | Electrical Wiring                                                                                                                 | J4                                                                                      | 2/18/46 |                 |             | 2A16        |
| 35     | Reinforcement of Windshield<br>Attachment                                                                                         | J3                                                                                      | 2/19/46 |                 |             | 2A20        |
| 36     | Inspection of Motor Mount                                                                                                         | J3                                                                                      | 11/4/41 |                 |             | 2A22        |
| 40     | Outlet Reinforcement on<br>12 Gallon Fuel Tanks                                                                                   | J3                                                                                      | 2/19/46 |                 |             | 2A23        |
| 42     | Elevator Bungee Installation                                                                                                      | J3S                                                                                     | 2/19/46 |                 |             | 2B1         |
| 43     | Stabilizer Link Tubes and<br>Rear Support Bearing Bracket                                                                         | J3                                                                                      | 2/19/46 |                 |             | 2B3         |
| 44     | Operation of Airplanes with<br>Enclosure Door Open                                                                                | J3                                                                                      | 2/19/46 |                 |             | 2B6         |
| 45     | Control System Interference                                                                                                       | J3                                                                                      | 2/19/46 |                 |             | 2B7         |
| 46     | Strainer Attachment Fittings                                                                                                      | J3F-50, J3L-50, J3L-55,<br>J4, J4A, J4B, J4D                                            | 2/19/46 |                 |             | 2B9         |
| 47     | Preparation for Winter<br>Operation                                                                                               | J3 Series, E2, J2, J3,<br>40 H.P. (not equipped<br>with Adequate<br>Carburetor Heater.) | 2/19/46 |                 |             | 2B11        |
| 48     | Mufflers: 1. Failure of Inner-Baffle<br>End Attachments<br>2. Inspection<br>3. Remedial Measures for<br>Preventing Engine Failure | J4A and J4F                                                                             | 2/19/46 |                 |             | 2B13        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:  
B-2/E-2/F-2/J-2/J-3/  
J-4/L-21/L-18/PA-11/NE-1/  
PA-15/PA-16/PA-17/PA-18/  
PA-19/PA-20/PA-22**

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                          | MODELS<br>AFFECTED                                                  | DATE    | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------|---------------------------------------------------------------------|---------|-----------------|-------------|-------------|
| 49     | Revised Washer for Fin<br>Brace Rod Clevis       | J3                                                                  | 2/19/46 |                 |             | 2B16        |
| 50     | Ribstitching                                     | E2, J2, J3<br>J4                                                    | 2/19/46 |                 |             | 2B17        |
| 53     | Fuel Shut-off Swivel Fitting                     | J3                                                                  | 2/20/46 |                 |             | 2B19        |
| 55     | Fuel Tank Vents                                  | J4E                                                                 | 2/20/46 |                 |             | 2B21        |
| 56     | Wing Aileron Bellcrank<br>Bracket Failures       | J4                                                                  | 2/20/46 |                 |             | 2B23        |
| 58     | Steerable Tail Wheel<br>Shock Cords              | All Models Manufactured<br>thru December 1945                       | 2/20/46 |                 |             | 2C2         |
| 61     | Aging of Protective Finish<br>on Wood Wing Spars | J3, J4,<br>L4 and L4A                                               | 2/20/46 |                 |             | 2C4         |
| 63     | Stabilizer Aluminum Yoke<br>Casting              | J3, L-4,<br>L-4A, L-4B.                                             | 2/20/46 |                 |             | 2C5         |
| 65     | Fuel Tank Repairs                                | J4E                                                                 | 2/20/46 |                 |             | 2C7         |
| 66     | Flexible Hose End<br>Fittings (3/8" Synthetic)   | J3, J4                                                              | 2/20/46 |                 |             | 2C10        |
| 68     | Stabilizer Rear Bearing Bracket                  | J3                                                                  | 2/20/46 |                 |             | 2C11        |
| 71     | Exhaust Muffler Inspection<br>and Repair         | J3, J4 Airplanes<br>Incorporating Exhaust<br>Mufflers.              | 2/20/46 |                 |             | 2C12        |
| 72     | Rudder Pedal and Floorboard<br>Attachment Lugs   | J3                                                                  | 2/20/46 |                 |             | 2C13        |
| 73     | Cockpit Enclosure Modification                   | L4                                                                  | 2/20/46 |                 |             | 2C16        |
| 74     | Rigging Procedure                                | J4                                                                  | 2/20/46 |                 |             | 2C18        |
| 75     | Carburetor Heat Control                          | J3 Airplanes with<br>Carburetor Heat Control                        | 2/20/46 |                 |             | 2C20        |
| 76     | Windshield Replacement                           | J3 Airplanes with Formed<br>Eyebrow Fairing Tubes.                  | 2/20/46 |                 |             | 2C24        |
| 77     | Seats, Safety Belts and<br>Control Cables        | E2, F2, J2, J3                                                      | 2/18/46 |                 |             | 2D4         |
| 78     | Wing Drag Wire Inspection                        | E2, F2, H2, J2                                                      | 2/18/46 |                 |             | 2D6         |
| 79     | Reinforcing of Rib Nose<br>Structure             | J4                                                                  | 2/18/46 |                 |             | 2D9         |
| 80     | Fuel Valve Control                               | J3 and J4 (Except Those<br>with Auxiliary Fuel<br>Tanks Installed.) | 2/18/46 |                 |             | 2D14        |
| 81     | Motor Mount Failure                              | All Models Manufactured<br>thru December 1945                       | 2/20/46 |                 |             | 2D17        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:  
B-2/E-2/F-2/J-2/J-3/  
J-4/L-21/L-18/PA-11/NE-1/  
PA-15/PA-16/PA-17/PA-18/  
PA-19/PA-20/PA-22

| NUMBER | SUBJECT                                                           | MODELS<br>AFFECTED                      | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------|-----------------------------------------|----------|-----------------|-------------|-------------|
| 82     | Safety Wire for Control System Turnbuckles                        | E2, J2, J3, J4                          | 2/20/46  |                 |             | 2D18        |
| 83     | Tailskid Spring Attachment Reinforcement                          | E2, J2, J3                              | 2/20/46  |                 |             | 2D20        |
| 84     | Winterization of J3C-65                                           | J3                                      | 5/9/46   |                 |             | 2E1         |
| 85     | Reworking of Bottom Cowl for Replacing Airscoop EQ5259 and EQ5370 | J3                                      | 4/25/46  |                 |             | 2E4         |
| 86     | J3 Lift Struts and Lift Strut Clevis Bolts                        | J3                                      | 10/16/46 |                 |             | 2E5         |
| 88     | Relocation of J3 Scott Brake Cylinders                            | J3                                      | 10/11/46 |                 |             | 2E10        |
| 89     | Replacement of Kem Gasoline Filter Gasket                         | J3                                      | 7/11/46  |                 |             | 2E15        |
| 91     | Inspection of Fuel Strainer Installation                          | J3                                      | 8/6/46   |                 |             | 2E17        |
| 95     | Defective Glass Fuel Strainer Bowls                               | J3                                      | 9/11/46  |                 |             | 2E23        |
| 99     | Header Tank Installation on PA-11 Airplanes                       | PA-11                                   | 7/29/47  |                 |             | 2F6         |
| 103    | Shock Strut Stop Discs                                            | J3, PA-11                               | 10/20/47 |                 |             | 2F20        |
| 104    | Fuel Line Fitting                                                 | PA-11                                   | 1/30/48  |                 |             | 2F21        |
| 108    | Model PA-11 Front and Rear Seats                                  | PA-11                                   | 10/20/48 |                 |             | 2G6         |
| 110    | Windshield Attachment                                             | PA-15                                   | 11/29/48 |                 |             | 2G11        |
| 111    | Torque Tube Connector Tube Assembly                               | J3, PA-11                               | 3/14/49  |                 |             | 2G12        |
| 112B   | Service Inspection Notes                                          | J3, J4, PA-11<br>PA-15,<br>PA-16, PA-17 | 11/19/59 |                 |             | 2G13        |
| 113    | Weight and Balance Form                                           | PA-11                                   | 5/3/49   |                 |             | 2G16        |
| 116    | Battery Box Lid                                                   | PA-20, 22                               | 3/9/51   |                 |             | 2G17        |
| 117B   | Chafing of Master Switches                                        | PA-20, 22                               | 4/14/52  |                 |             | 2G19        |
| 118    | Battery Box Lid Modification                                      | PA-16-,20,22                            | 9/21/51  |                 |             | 2G20        |
| 119    | Freezing of Nose Wheels                                           | PA-22                                   | 11/7/51  |                 |             | 2G21        |
| 120    | Replacing of Front and Rear Lift Strut Forks and Barrels          | J3, PA-11                               | 3/28/52  |                 |             | 2G24        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:  
B-2/E-2/F-2/J-2/J-3/  
J-4/L-21/L-18/PA-11/NE-1/  
PA-15/PA-16/PA-17/PA-18/  
PA-19/PA-20/PA-22**

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                  | MODELS<br>AFFECTED                                                                                      | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|----------|-----------------|-------------|-------------|
| 121    | Oil Radiator Lines                                                                                       | PA-18, PA-18A, PA-20,<br>PA-22-135 Models                                                               | 8/25/52  |                 |             | 2H3         |
| 122    | Fuel Grade Specification<br>Lycoming O-290-D2                                                            | PA-18, PA-18A, PA-18S<br>PA-20, PA-22                                                                   | 11/21/52 |                 |             | 2H4         |
| 123    | Front Spar Interference                                                                                  | PA-20, 22                                                                                               | 5/7/54   |                 |             | 2H5         |
| 124    | PA-22 Landing Gear                                                                                       | All PA-22's                                                                                             | 8/30/54  |                 | 55-07-02    | 2H6         |
| 135    | Fuel Selector Valve Pointer                                                                              | PA-20, 22                                                                                               | 3/29/55  |                 |             | 2I1         |
| 143    | Magneto Ground Wire<br>Terminal Attachment Fitting                                                       | J-Series, E-Series,<br>PA-11, PA-15, PA-16,<br>PA-17, PA-18, PA-19,<br>PA-20, PA-22                     | 10/7/55  |                 |             | 2I12        |
| 148A   | Fuel Tank Caps                                                                                           | PA-18, 18A<br>22, 23, L21 B                                                                             | 5/29/57  |                 |             | 2I17        |
| 153A   | Brake Master Cylinder Diaphragm                                                                          | PA-22                                                                                                   | 11/21/60 | 750-384         |             | 3240 2J1    |
| 157D   | Lift Strut Fork<br>Inspection And/Or<br>Replacement                                                      | J-2/J-3/NE-1/<br>L4/J4/PA-11/<br>PA-15/PA-16/PA-17/<br>PA-18/L-21A/L-21B/<br>L-18/PA-19/PA-20/<br>PA-22 | 4/22/86  | **              |             | 5701 2J5    |
| 158    | All PA-20 Name Plates                                                                                    | PA-20                                                                                                   | 9/20/57  |                 |             | 2J8         |
| 161A   | Fire Hazard                                                                                              | PA-16, 20, 22                                                                                           | 9/23/59  | **              | 57-22-01    | 2600 2J12   |
| 163A   | Fusing of Cigar Lighter Circuit                                                                          | PA-20, 22                                                                                               | 7/7/58   |                 | 58-16-01    | 3310 2J16   |
| 165    | Aileron Hinge Reinforcing Bracket                                                                        | J3, L4, L18B, PA-11,<br>PA-15, PA-16, PA-17                                                             | 5/22/58  | **              | 58-12-02    | 5750 2J22   |
| 166    | Chafing of Master Switch Wires                                                                           | PA-22                                                                                                   | 8/5/58   |                 |             | 2J24        |
| 174B   | Fabric, Fuselage,<br>Inspection and<br>Maintenance of<br>In Area of Windshield<br>Top Attachment Channel | J4, PA-15/16/17<br>PA-20<br>PA-22                                                                       | 11/30/61 |                 |             | 5300 2K15   |
| 181    | Cables, Control. 1/8" - 7 x 19<br>Flexible Stainless Steel,<br>Replacement of                            | PA-18/18A/18S<br>PA-18AS-150<br>PA-22/22S<br>PA-22S-150<br>PA-22                                        | 11/5/59  | **              | 61-16-05    | 2700 2L4    |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

**CLASSIC AIRCRAFT:**  
**B-2/E-2/F-2/J-2/J-3/**  
**J-4/L-21/L-18/PA-11/NE-1/**  
**PA-15/PA-16/PA-17/PA-18/**  
**PA-19/PA-20/PA-22**

| NUMBER | SUBJECT                                                                                                                                      | MODELS<br>AFFECTED                                                                                                                                     | DATE     | PART/KIT<br>NO. | A.D.<br>NO.            | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|------------------------|-------------|
| 182    | Foreign Registered Airplanes-<br>Inspection of Control Cables And<br>Replacement of 1/8" - 7 x 19 Flexible<br>Stainless Steel Control Cables | J3/<br>PA-11/11S/15/16/<br>16S/17/18/20/20S/<br>20-115/20-135/22/<br>22S-135/22-150/<br>22S-160,<br>L-4/L-18B/L-18C/<br>L-21A/L-21B/<br>L-21B Modified | 11/5/59  |                 |                        | 2700 2L10   |
| 183    | Tie Rods - Tail Brace<br>Streamline                                                                                                          | PA-20, PA-22,<br>PA-22-135/150/160                                                                                                                     | 11/9/59  |                 | 60-01-07               | 5340 2L12   |
| 184    | Safety Belt Attachment                                                                                                                       | PA-22-150/160                                                                                                                                          | 12/9/59  | 754-273         | 60-05-03               | 5340 2L13   |
| 198    | Clevises, Tail Brace, Replacement of                                                                                                         | PA-22-108                                                                                                                                              | 1/6/61   | 754-381         |                        | 5510 3A13   |
| 203    | Modification of Cabin Heat Box Plate                                                                                                         | PA-22-108                                                                                                                                              | 4/21/61  | **              |                        | 2140 3B1    |
| 207A   | Rudder Pedal Assembly, Inspection<br>of Weld (P/N 40892-04 And 05)                                                                           | PA-18, PA-18A                                                                                                                                          | 5/10/62  |                 | 62-02-05               | 2720 3B7    |
| 218    | Vacuum Pump Spined Coupling,<br>Replacement                                                                                                  | PA-18<br>PA-22-108                                                                                                                                     | 11/11/63 | **              |                        | 3710 3C9    |
| 250A   | Installation of Right Fuel Tank<br>Quantity Gauge Placard                                                                                    | PA-22                                                                                                                                                  | 1/29/70  | 15306-00        | 67-24-02               | 2840 3F8    |
| 264    | Aircraft Flight Manual Supplement,<br>Revision To (Para 15.0)                                                                                | PA-22S-135                                                                                                                                             | 12/22/67 |                 |                        | 3G10        |
| 305    | Inspection of Carburetor Drain Plugs                                                                                                         | PA-18-150                                                                                                                                              | 11/25/69 |                 |                        | 7310 3K12   |
| 324    | Vacuum Pump Adapter Drive<br>Assembly                                                                                                        | PA-18-150                                                                                                                                              | 9/24/70  |                 |                        | 3710 4A9    |
| 351    | Fuel Line Replacement                                                                                                                        | PA-20                                                                                                                                                  | 5/3/72   | **              | 72-21-03               | 2820 4D9    |
| 354B   | Fuel Selector Valve Lubrication                                                                                                              | PA-18/PA-20<br>PA-22                                                                                                                                   | 5/19/82  | **              | 60-10-08               | 2820 4D15   |
| 445    | Fuel Cap Inspection                                                                                                                          | PA-18                                                                                                                                                  | 1/24/75  | 454-039         |                        | 2810 5A20   |
| 485    | Rerouting of Rudder Control Cables                                                                                                           | PA-18-150                                                                                                                                              | 1/27/76  | **              |                        | 2720 5F2    |
| 522    | Fuel Tank Cap Modification, Wing                                                                                                             | PA-11, PA-16,<br>PA-18/18-150<br>PA-20, PA-22                                                                                                          | 9/28/76  |                 | 78-10-03               | 2810 5J4    |
| 528D   | Wing Lift Strut Assembly<br>Inspection/Replacement                                                                                           | J-2/J-3/NE-1/<br>L-4/J-4/PA-11/<br>PA-15/PA-16/PA-17/<br>PA-20/PA-22                                                                                   | 10/19/90 | **              | 99-26-19<br>2015-08-14 | 5701 5J21   |
| 573    | Fuel Tank Cap Modification, Wing                                                                                                             | PA-11, PA-16,<br>PA-18/18-150,<br>PA-20, PA-22                                                                                                         | 2/8/78   |                 | 78-10-03               | 2810 6E14   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:  
B-2/E-2/F-2/J-2/J-3/  
J-4/L-21/L-18/PA-11/NE-1/  
PA-15/PA-16/PA-17/PA-18/  
PA-19/PA-20/PA-22**

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED                                                                          | DATE      | PART/KIT<br>NO. | A.D.<br>NO.            | ATA<br>CODE      |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|-----------|-----------------|------------------------|------------------|
| 630A   | Collins VIR-350 And VIR-351<br>Navigation Receiver Modification                                                                   | PA-18-150                                                                                   | 2/25/80   |                 |                        | 3450 6L14        |
| 677    | Publications for Aircraft Operation                                                                                               | All Piper<br>Models                                                                         | 5/20/80   |                 |                        | PARA<br>15.0 7H4 |
| 706B   | Tail Brace Wire Support Installation                                                                                              | PA-18-150                                                                                   | 10/9/91   | **              | 81-06-08               | 5510 7L7         |
| 759    | Exhaust Muffler Inspection and<br>Modification, Piper Part Number<br>12433-00, 12433-14, 12232-00                                 | PA-18                                                                                       | 6/22/83   | 452-093         |                        | 7820 8H12        |
| 771A   | Parking Brake Application                                                                                                         | PA-20, PA-22                                                                                | 9/6/2011  | 81090-002       |                        | 1130             |
| 819    | Fuselage Door Frame<br>Tube Corrosion:<br>Repair and Protection                                                                   | J-4/PA-15/<br>PA-16/PA-17/PA-20/<br>PA-22                                                   | 2/28/86   | **              |                        | 5300 9G13        |
| 836A   | Aluminum Wire<br>Inspection                                                                                                       | E-2/J-2/J-3/NE-1/<br>L-4/J-4/PA-11/<br>PA-15/PA-16/PA-17/<br>PA-18/PA-19/PA-20/<br>PA-22    | 8/26/86   | **              |                        | 2400 9J4         |
| 855    | Use of Automobile Gasoline In<br>Piper Aircraft                                                                                   | All Piston Powered<br>Models                                                                | 1/14/87   | N/A             |                        | 2800 10A7        |
| 868    | Forward Fuel Header<br>Tank Installation                                                                                          | PA-11, PA-18                                                                                | 8/19/87   | 60763-02        |                        | 2810 10C3        |
| 910A   | Wing Lift Strut<br>Assembly Inspection                                                                                            | PA-18/18A/L-18/<br>PA-19/L-21A/L-21B                                                        | 10/10/89  | **              | 99-26-19<br>2015-08-14 | 5701 10L3        |
| 924    | Shimmy Dampener Replacement                                                                                                       | PA-22                                                                                       | 9/13/89   | 21701-06        |                        | 3250 10aB17      |
| 935    | Relocation of Aircraft<br>Serial Number Data Plate                                                                                | PA-18-150                                                                                   | 3/13/90   | 765-400         |                        | 1125 10aE5       |
| 966    | Tail Surfaces Replacement                                                                                                         | PA-18-150                                                                                   | 1/21/94   | **              |                        | 5500 10aK3       |
| 979    | Installation of Fuel Cap Cover                                                                                                    | PA-18-150                                                                                   | 1/12/95   | **              |                        | 5500 10bB6       |
| 1020   | Inspection of the Artex 110-4 ELT<br>and ELT Attachment Bracket                                                                   | PA-18-150                                                                                   | 7/10/98   | **              |                        | 2563 10b111      |
| 1026   | Distribution of Parker Hannifin<br>Airborne Service Letter 48,<br>"Inspection/Replacement of dry<br>air pump flexible couplings". | PA-18<br>PA-18-150<br>PA-22                                                                 | 11/5/98   | 753-910         |                        | 3711 10bJ20      |
| 1041   | Distribution of Airborne<br>Service Letter Number 56,<br>"Inspection and Cleaning of<br>Airborne Air Filter Elements".            | PA-18/18A/18S<br>PA-18-150<br>PA-20/20S<br>PA-22/22S                                        | 9/25/2000 | **              |                        | 3714 10cB1       |
| 1044   | Lift Strut Attachment Fitting<br>Inspection Access Provision<br>and Wing Component Corrosion<br>Inspections.                      | E-2/F-2/TG-8<br>J-2/J-3/J-4/<br>PA-11/<br>PA-15/PA-16/PA-17/<br>PA-18/PA-19/PA-20/<br>PA-22 | 7/27/2000 | 481-096         |                        | 5701 10cB19      |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT:  
B-2/E-2/F-2/J-2/J-3/  
J-4/L-21/L-18/PA-11/NE-1/  
PA-15/PA-16/PA-17/PA-18/  
PA-19/PA-20/PA-22

| NUMBER | SUBJECT                                                                                                                                      | MODELS<br>AFFECTED                                                                                                                                                                                                                                                                                                                                                                                                 | DATE       | PART/KIT<br>NO.         | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------------------|-------------|-------------|
| 1048   | Stainless Steel Control Cables                                                                                                               | PA-18-150                                                                                                                                                                                                                                                                                                                                                                                                          | 1/3/2001   | N/A                     |             | 2702 10cC9  |
| 1172A  | Lift Strut Attachment Bolt Inspection                                                                                                        | PA-16/-16S<br>PA-18/-18A/-18S<br>PA-18 "105"/-18S "105"<br>PA-18 "125"/-18S "125"<br>PA-18 "135"/-18S "135"<br>PA-18AS "135"<br>PA-18 "150"/-18A "150"<br>PA-18S "150"/-18AS "150"<br>PA-18A (Restricted)<br>PA-18A "135" (Restricted)<br>PA-18A "150"(Restricted)<br>PA-19/-19S/-20/-20S<br>PA-20/-20S "115"<br>PA-20 "135"/-20S "135"/<br>PA-22/-22-135/-22S-135<br>PA-22-150/160/-22S-150/160<br>PA-22-108 Colt | 12/11/2006 | NAS464-P6-11<br>402-830 |             | 5700 10eA5  |
| 1284B  | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-22<br>PA-22-108<br>PA-22-135<br>PA-22-150/160                                                                                                                                                                                                                                                                                                                                                                   | 4/12/2019  | N/A                     |             | 7414        |
| 1297   | Altimeter Inspection and Replacement (United Instruments SB No. 13)                                                                          | All                                                                                                                                                                                                                                                                                                                                                                                                                | 5/10/2016  | N/A                     |             | 3416        |
| 1379   | Rudder Inspection                                                                                                                            | J3C-65/L-4/NE-1/NE-2<br>J4<br>PA-11/L-18B<br>PA-15/-17<br>PA-16<br>PA-18/-19/L-18C/L-21A/L-21B<br>PA-20<br>PA-22                                                                                                                                                                                                                                                                                                   | 12/2/2022  | N/A                     |             | 5540        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

CLASSIC AIRCRAFT:  
B-2/E-2/F-2/J-2/J-3/  
J-4/L-21/L-18/PA-11/NE-1/  
PA-15/PA-16/PA-17/PA-18/  
PA-19/PA-20/PA-22

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------|--------------------|------|-----------------|-------------|-------------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.  
\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.  
\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-23/PA-23-160  
PA-23-235/PA-23-250  
PA-E23-250

| NUMBER | SUBJECT                                                             | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------|--------------------|----------|-----------------|-------------|-------------|
| 125    | Fuel System Model PA-23                                             | PA-23              | 9/29/54  |                 |             | 2H7         |
| 126    | PA-23 Power Plant                                                   | PA-23              | 10/18/54 |                 |             | 2H9         |
| 127    | PA-23 Airplane Flight Manual                                        | PA-23              | 10/15/54 |                 |             | 2H11        |
| 128    | PA-23 Landing Gears                                                 | PA-23              | 10/28/54 |                 |             | 2H12        |
| 129    | Carburetor Air Box                                                  | PA-23              | 12/28/54 |                 |             | 2H13        |
| 130    | Heater Fuel Line                                                    | PA-23              | 12/31/54 |                 |             | 2H14        |
| 131    | Addition of Rudder Extrusion<br>Chafe Strip to Wing<br>Root Fairing | PA-23              | 1/3/55   |                 |             | 2H15        |
| 132    | Fuel Valve Actuator Handle<br>Locks                                 | PA-23              | 1/5/55   |                 |             | 2H17        |
| 133    | Landing Gear Down Lock<br>Latches                                   | PA-23              | 1/18/55  |                 |             | 2H19        |
| 134    | Main Landing Gear<br>Attachment Point                               | PA-23              | 3/31/55  |                 |             | 2H22        |
| 136    | Hydraulic System - Thermal<br>Relief Valve                          | PA-23              | 4/26/55  |                 |             | 2I3         |
| 138    | Hydraulic Actuating Cylinders                                       | PA-23              | 5/9/55   |                 |             | 2I6         |
| 139    | Flexible Fuel Valve<br>Controls - right and left                    | PA-23              | 5/26/55  |                 |             | 2I7         |
| 140    | Landing Gear CO2<br>Extension System                                | PA-23              | 6/8/55   |                 |             | 2I8         |
| 142    | Wing Front Spar<br>Attachment Fitting                               | PA-23              | 10/4/55  |                 |             | 2I11        |
| 143    | Magneto Ground Wire<br>Terminal Attachment<br>Fitting               | PA-23              | 10/7/55  |                 |             | 2I12        |
| 144    | Hot Air Ducts                                                       | PA-23              | 4/11/56  |                 |             | 2I13        |
| 145    | New Anti-Retracton Device                                           | PA-23              | 12/31/56 |                 |             | 2I14        |
| 146B   | Elevator Butt Rib And Torque<br>Tube Attachment Casting Cracks      | PA-23              | 10/25/62 |                 | 63-12-02    | 5520 2I15   |
| 149    | Reinforcement of Aileron<br>Balance Weights                         | PA-23              | 12/10/56 |                 |             | 2I19        |
| 150    | Front Stabilizer Fittings -<br>right and left                       | PA-23              | 12/21/56 |                 |             | 2I21        |
| 151    | Elevator Push Pull Tube Rollers                                     | PA-23              | 2/11/57  |                 |             | 2I22        |
| 152A   | Oil Pressure Line                                                   | PA-23              | 8/29/58  | 17766-07        | 57-10-02    | 7930 2I24   |
| 155B   | Empennage Casting Cracks                                            | PA-23              | 10/28/63 |                 |             | 5500 2J2    |
| 156    | Thread Exposure on the Heim<br>Rod End Bearing                      | PA-23              | 7/2/57   |                 |             | 2J4         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                              | MODELS<br>AFFECTED           | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |      |
|--------|----------------------------------------------------------------------|------------------------------|----------|--------------------|-------------|-------------|------|
| 159    | Rudder Trim Tab Control Rod Attachment                               | PA-23                        | 10/1/57  |                    |             |             | 2J9  |
| 160    | Stabilizer Attachment Fitting                                        | PA-23                        | 10/7/57  | 17093-00           |             | 5510        | 2J11 |
| 162    | Rudder Trim Tab Adjustment Screw, Part No. 18453-00                  | PA-23                        | 2/17/58  | 18453-02           | 58-04-03    | 2720        | 2J15 |
| 169    | Placard, Operating Limitations                                       | PA-23                        | 2/4/59   | 754-224            | 59-08-03    | 1100        | 2K3  |
| 175    | Circuit Protector, Starter Solenoid                                  | PA-23                        | 6/9/59   | 754-220            | 60-03-07    | 2400        | 2K17 |
| 176    | Bellcrank Attachment, Elevator Control Tube                          | PA-23<br>PA-23-160           | 7/3/59   | **                 |             | 2730        | 2K18 |
| 185A   | Ribs, Wing Stations 95 And 110 Located Below the Main Wing Fuel Cell | PA-23<br>PA-23-160           | 9/3/63   | **                 |             | 5710        | 2L14 |
| 186    | Fuel Lines And Fuel Line Fittings, Replacement of                    | PA-23-250                    | 4/12/60  | 492-222<br>492-223 |             | 2810        | 2L16 |
| 188    | Baggage Compartment Doors, Positive Locking of                       | PA-23-250                    | 5/12/60  |                    |             | 5230        | 2L19 |
| 189    | Stabilator Tab Horn Modification                                     | PA-23-250                    | 6/22/60  | 754-329            |             | 2740        | 2L21 |
| 194    | Instrument Panel Face Plate, Replacement of                          | PA-23-160                    | 8/23/60  |                    |             | 2500        | 3A7  |
| 195A   | Baffles, Right Engine, Modification of                               | PA-23-250                    | 9/13/60  | 754-335            |             | 7230        | 3A8  |
| 196    | Rudder Tab Horn Bolt Installation                                    | PA-23-250                    | 9/9/60   | 754-344            |             | 2720        | 3A10 |
| 199A   | Stabilator Tab Horn Assembly, Inspection of                          | PA-23-250                    | 4/3/61   | 754-393            |             | 2740        | 3A15 |
| 200    | Oil Radiator Lines, Replacement of                                   | PA-23-250                    | 4/18/61  | 754-387            |             | 7920        | 3A19 |
| 213    | Rudder Trim Tab Horn, Inspection of                                  | PA-23/23-160                 | 3/5/63   |                    |             | 2720        | 3B23 |
| 214    | Carburetor Airbox Throat Vanes, Removal of                           | PA-23-235/23-250             | 4/19/63  |                    |             | 7160        | 3C1  |
| 218    | Vacuum Pump Spined Coupling, Replacement of                          | PA-23-235/23-250             | 11/11/63 | **                 |             | 3710        | 3C9  |
| 219A   | Heater, 940DB, Modification And Rewiring of                          | PA-23-250                    | 9/23/64  | **                 |             | 2140        | 3C12 |
| 225    | Vacuum Pump Mounting Gasket, Replacement of                          | PA-23-235/23-250/<br>E23-250 | 11/9/65  | 751-886            |             | 3710        | 3D12 |
| 226    | Vacuum Pump Drive Couplings, Replacement of                          | PA-23-235/23-250/<br>E23-250 | 12/20/65 | **                 |             | 3710        | 3D13 |
| 230A   | Alternate Air System Modification, Engine Induction                  | PA-23-250/<br>E23-250        | 5/6/66   | 757-021            | 66-18-03    | 7160        | 3D21 |
| 242    | Fuel System, Modification of                                         | PA-23-250/<br>E23-250        | 1/9/67   | 757-106            |             | 2800        | 3E17 |
| 243    | Starter Vibrator, Replacement of                                     | PA-23-250<br>E23-250         | 1/6/67   | 757-103            |             | 8010        | 3E18 |
| 269    | Manifold Pressure Gauge Line Filter                                  | PA-23-250                    | 2/23/68  | 760-167            |             | 7710        | 3G19 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-23/PA-23-160  
PA-23-235/PA-23-250  
PA-E23-250

| NUMBER | SUBJECT                                                                                            | MODELS<br>AFFECTED                   | DATE      | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------|--------------------------------------|-----------|----------------------|-------------|-------------|
| 273    | Tailpipe, Turbocharger, Clearance To Firewall, Inspection of                                       | PA-23-250<br>PA-E23-250              | 5/8/68    | **                   |             | 8120 3H1    |
| 280    | Artificial Horizon, R.C. Allen 3", Case Leakage of                                                 | PA-23-250                            | 7/10/68   |                      |             | 3420 3H20   |
| 290    | Fuel Flow Gauge Assemblies, Replacement of                                                         | PA-23-250 "D"                        | 5/23/69   | 760-293              |             | 7330 3J3    |
| 296    | Fuselage Aft Section Assembly, Inspection of                                                       | PA-23-250 "D"                        | 5/26/69   | 760-324              |             | 5310 3J16   |
| 300    | Hydraulic Pump Hose Assembly Inspection                                                            | PA-23-250                            | 6/3/69    | 17766-05             |             | 2910 3K3    |
| 303    | Autocontrol III And Altimatic III Series Roll Servo Modification and Roll Bridle Cable Replacement | PA-23-250<br>PA-E23-250              | 11/10/69  | 760-364              |             | 2210 3K8    |
| 306    | Alternator System Modification                                                                     | PA-23-250 "D"                        | 1/9/70    | 760-346              | 70-22-05    | 2430 3K14   |
| 319    | Exhaust System Inspection And Modification                                                         | PA-23-250                            | 4/19/71   | 33178-02<br>33178-03 | 72-14-05    | 7810 3L17   |
| 320A   | Autopilot Servo And Bridle Cable Installations, III Series, Inspection of                          | PA-23-250                            | 7/6/72    |                      |             | 2210 3L23   |
| 324    | Vacuum Pump Adapter Drive Assembly                                                                 | PA-23-250                            | 9/29/70   |                      |             | 3710 4A9    |
| 331    | Electric Trim Switch Inspection And Modifications                                                  | PA-23-250                            | 2/5/71    | 760-505              | 71-12-05    | 2730 4B3    |
| 334    | Alternate Air Hose Replacement                                                                     | PA-23-250                            | 3/17/71   | 48076-02             | 71-21-06    | 7160 4B14   |
| 335A   | Engine Controls Support Bracket Assembly Inspection                                                | PA-23<br>PA-23-160<br>PA-23-250      | 11/17/71  | 16975-00             | 71-12-01    | 7610 4B16   |
| 340    | Fuel Cell Vent/Drain Lines                                                                         | PA-23<br>PA-23-160/-235<br>PA-23-250 | 5/24/71   |                      | 88-21-07    | 2810 4C2    |
| 345    | Bungee Installation, Stabilator                                                                    | PA-23-250                            | 10/7/71   | 760-565              | 72-21-07    | 2740 4C21   |
| 349    | Master Switch Modification, Electrical System                                                      | PA-23-250                            | 4/26/72   | 760-602<br>760-606   |             | 2450 4D5    |
| 353    | Fuel Filter Assembly Outlet Port, Inspection of                                                    | PA-23-250                            | 6/1/72    | **                   |             | 7310 4D13   |
| 375    | Firewall Sealing, Lower                                                                            | PA-23-250                            | 6/20/73   | 757-758              |             | 5310 4F15   |
| 380    | Pitch Servo Bridle Cable Installation, Revised                                                     | PA-23-250                            | 7/9/73    |                      |             | 2210 4F23   |
| 385    | Wing Leading Edge Modification                                                                     | PA-23-250                            | 5/4/73    | **                   |             | 5720 4G10   |
| 389    | Bridle Cables and Bridle Cable Clamp Installation                                                  | PA-23-250                            | 8/13/73   |                      |             | 2210 4G17   |
| 401A   | Heater Fuel Valve, Inspection of                                                                   | PA-23<br>PA-23-160/-235<br>PA-23-250 | 5/16/2000 | 19460-00             | 74-22-05    | 2148 4H24   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                   | MODELS<br>AFFECTED                   | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------------|--------------------------------------|----------|--------------------|-------------|-------------|
| 404    | Flux Sensor Caution Placard<br>Installation                                               | PA-23-250                            | 11/12/73 | 33564-00           |             | 3420        |
| 408B   | Flap Outboard Hinges, Replacement                                                         | PA-23-250                            | 5/14/75  | **                 | 74-10-01    | 5750        |
| 441    | Manifold Pressure Hose<br>Clamping of                                                     | PA-23-250                            | 1/2/75   | 760-602<br>760-606 |             | 7710        |
| 451    | Throttle Control Shaft,<br>Inspection of                                                  | PA-23-250                            | 2/26/75  |                    |             | 7610        |
| 452    | Instrument Glare Shield<br>Panel Replacement                                              | PA-23-250                            | 3/3/75   | 760-932            | 75-11-05    | 2510        |
| 455    | Fuel Selector Valve Inspection                                                            | PA-23-250                            | 4/30/75  | 492-222<br>492-223 |             | 2820        |
| 461    | Encoding Altimeter Harness Rewiring                                                       | PA-23-250                            | 4/17/75  | 760-971            |             | 3410        |
| 486    | Wing Tip Navigation Light<br>Wire Insulation                                              | PA-23-250 "F"                        | 10/11/76 | 761-099            | 77-01-05    | 3340        |
| 493    | Magnetic Compass Deviation                                                                | PA-23-250                            | 3/25/76  | 761-044            | 76-11-07    | 3440        |
| 498    | Fuel Cell Vent Line Assemblies,<br>Inboard, Inspection of                                 | PA-23-250 "F"                        | 4/5/76   |                    |             | 2810        |
| 507    | Fuel System Control Cables<br>At Swivel Fittings, Inspection of                           | PA-23<br>PA-23-160/-235<br>PA-23-250 | 11/10/76 | **                 | 80-18-10    | 7320        |
| 511A   | Oxygen System Outlet<br>Refinement                                                        | PA-23-250                            | 8/24/76  | **                 |             | 3510        |
| 514    | Stabilator Tab Modification                                                               | PA-23-250 "F"                        | 9/20/76  | 761-083            |             | 2740        |
| 515    | Control Cable Ball Joint<br>Retainer Installation                                         | PA-23-250                            | 1/17/77  | **                 |             | 7610        |
| 523    | Cigar Lighter Element, 24 Volt,<br>Replacement                                            | PA-23-250 "F"                        | 10/8/76  | 55674-02           |             | 3310        |
| 527    | Electric Trim Switch Modification                                                         | PA-23-250                            | 11/5/76  | 756-047            | 77-09-10    | 2740        |
| 530    | Fuel Crossfeed Operation                                                                  | PA-23-250<br>PA-E23-250              | 12/10/76 | **                 | 77-23-09    | 2820        |
| 540    | Stabilator Tip Tube And Weight<br>Assembly Inspection And<br>Reinforcement                | PA-23-250 "F"                        | 1/4/1977 | **                 | 2021-25-11  | 2740        |
| 540B   | Stabilator Tip Tube And Weight<br>Assembly Inspection And<br>Reinforcement                | PA-23-250 "F"                        | 2/9/21   | **                 | 2021-25-11  | 5510        |
| 546    | Whelen Wing Tip Strobe Lights,<br>Reference FAA Airworthiness<br>Directive, Inspection of | PA-23-250                            | 5/18/77  | **                 | 75-05-04    | 3340        |
| 547    | Stabilator Tip Rib, Inspection of                                                         | PA-23-250 "F"                        | 3/1/77   | **                 | 2021-25-11  | 2740        |
| 550    | Engine Control Cable Inspection                                                           | PA-23-250 "F"                        | 3/29/77  | **                 |             | 7230        |
| 558    | Altimatec V and V F/D Series;<br>M-4D F/D Series: And<br>Sperry SPZ-200 F/D               | PA-23-250                            | 6/10/77  |                    |             | 2210        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-23/PA-23-160  
PA-23-235/PA-23-250  
PA-E23-250

| NUMBER | SUBJECT                                                                          | MODELS<br>AFFECTED                   | DATE     | PART/KIT<br>NO.   | A.D.<br>NO. | ATA<br>CODE      |
|--------|----------------------------------------------------------------------------------|--------------------------------------|----------|-------------------|-------------|------------------|
| 559    | Rudder Tail Light Inspection                                                     | PA-23-250                            | 8/31/77  | 472-956           |             | 3340 6C3         |
| 564    | Inspection of Emergency Gear<br>Extension Control                                | PA-23-250<br>PA-E-23-250             | 4/25/77  |                   |             | 3200 6C16        |
| 566    | Horizontal Situation Indicator, EDO<br>Aire Mitchell NSD-360,<br>Modification To | PA-23-250                            | 10/11/77 | **                |             | 3420 6D9         |
| 569    | Stabilator Tab Horn Replacement                                                  | PA-23-250                            | 8/24/77  | 761-143           | 2021-25-11  | 5510 6E2         |
| 590    | Inspection of Stabilator Tab Horn/<br>Stabilator Trim Control Rod<br>Attachment  | PA-23-250                            | 1/20/78  |                   |             | 2740 6G11        |
| 604A   | Forward Baggage Door Locking<br>System Modification                              | PA-23-250                            | 6/8/79   | **                |             | 5230 6I4         |
| 606    | Stabilator Assembly Lower<br>Surface Rivet And Rib<br>Attachment Inspection      | PA-23-250                            | 7/12/79  | **                | 79-26-01    | 2730 6I10        |
| 629    | Landing Gear Hose Assembly<br>Inspection And Replacement                         | PA-23-250                            | 11/15/78 | 17766-27          |             | 3230 6L10        |
| 630A   | Collins VIR-350 and VIR-351<br>Navigation Receiver Modification                  | PA-23-250                            | 2/25/80  |                   |             | 3450 6L14        |
| 635    | Landing Gear Selector Lever<br>Inspection And Replacement                        | PA-23<br>PA-23-235<br>PA-23-250      | 1/3/79   | 761-213           | 79-11-06    | 3200 7A23        |
| 662    | Exhaust System Inspection<br>And Modification                                    | PA-23-250                            | 11/1/79  | 763-975           |             | 7810 7E15        |
| 663    | Fuel Line/Electrical<br>Harness Inspection                                       | PA-23-250                            | 9/24/79  | **                |             | 2810 7E17        |
| 671    | Flap Control System<br>Inspection and<br>Reinforcement                           | PA-23<br>PA-23-160/-235<br>PA-23-250 | 10/20/80 | **                | 81-04-05    | 2750 7F14        |
| 672A   | Step Attachment Area Inspection/<br>Reinforcement                                | PA-23<br>PA-23-160/-235<br>PA-23-250 | 4/16/81  |                   | 80-26-04    | 5340 7F23        |
| 677    | Publications for Aircraft Operation                                              | All Piper<br>Models                  | 5/20/80  |                   |             | PARA<br>15.0 7H4 |
| 683    | Propeller Feathering, Minimum<br>Engine RPM                                      | PA-23<br>PA-23-160/-235<br>PA-23-250 | 5/16/80  | Placard<br><br>** |             | 6120 7H18        |
| 721    | Heater Fuel Regulator Valve Shroud/<br>Drain Modification                        | PA-23-250                            | 4/5/82   | 764-141           |             | 2820 8B12        |
| 771A   | Parking Brake Application                                                        | PA-23<br>PA-23-160/-235<br>PA-23-250 | 9/6/2011 | 81090-002         | 85-02-05    | 1130             |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED                   | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE         |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|-----------|-----------------|-------------|---------------------|
| 797B   | Fuel Port Restrictor Installation                                                                                                 | PA-23-250 "F"                        | 9/1/87    | 566-500         |             | 2812 9B14           |
| 798    | "TURBO" Marking Removal                                                                                                           | PA-23-250                            | 12/11/84  | N/A             |             | 1110 9B19           |
| 805A   | TRW Hartzell Propeller<br>Products Service Bulletin<br>No. 142B (O-ring Deterioration)                                            | PA-23-250                            | 3/14/86   | N/A             |             | 6110 9D15           |
| 822    | Special Inspection<br>of Hydraulic Hose,<br>Piper Part Number<br>17766-02 (465-138)                                               | PA-23<br>PA-23-160/-235<br>PA-23-250 | 4/2/86    | 17766-02        | 96-21-04    | 2912 9H3            |
| 827A   | Part I - Fuel System<br>Draining Procedure -<br>Water Contamination                                                               | PA-23<br>PA-23-160                   | 11/4/88   | N/A             | 90-23-18    | 2824 9H20           |
| 827A   | Part II - Apache<br>Dual-Fuel Drain<br>Installation                                                                               | PA-23<br>PA-23-160                   | 11/4/88   | 765-363         | 92-13-04    | 2824 9H22           |
| 836A   | Aluminum Wire<br>Inspection/Replacement                                                                                           | PA-23<br>PA-23-160/-235<br>PA-23-250 | 8/26/86   | **              |             | 2400 9J4            |
| 855    | Use of Automobile Gasoline in<br>Piper Aircraft                                                                                   | All Piston Powered<br>Models         | 1/14/87   | N/A             |             | 2800 10A7           |
| 884    | Lock Wiring of<br>V-Band Couplings                                                                                                | PA-23-250                            | 4/8/88    | **              |             | 7800 10G20<br>2100  |
| 932A   | Improved Fuel System Drainage<br>and Inspection                                                                                   | PA-23<br>PA-23-160/-235<br>PA-23-250 | 8/30/90   | **              | 90-23-18    | 2815 10aD16<br>2824 |
| 980    | Shoulder Harness Installation                                                                                                     | PA-23<br>PA-23-235<br>PA-23-250      | 1/18/95   | **              |             | 5500 10bB10         |
| 991A   | Replacement or Modification of the<br>Alternator Out Light Fuse                                                                   | PA-23-250                            | 1/29/96   | **              |             | 2437 10bD16         |
| 1022   | Inspection of Induction Air Filter and<br>Distribution of Purolator Service<br>Bulletin, SB090298.01                              | PA-23-235<br>PA-23-250               | 9/22/98   | 460-632         | 99-05-09    | 7167 10bI20         |
| 1026   | Distribution of Parker Hannifin<br>Airborne Service Letter 48,<br>"Inspection/Replacement of dry<br>air pump flexible couplings". | PA-23-250                            | 11/5/98   | 766-656         |             | 5741 10bJ20         |
| 1035A  | Distribution of Textron Lycoming<br>Service Bulletin 529B, "Reprint of<br>Crane/Lear Service Bulletin No.<br>101SB020, Rev. 3"    | PA-23-250<br>PA-E23-250              | 3/22/2007 | **              | 2003-14-03  | 7311 10bL16         |
| 1041   | Distribution of Airborne<br>Service Letter Number 56,<br>"Inspection and Cleaning of<br>Airborne Air Filter Elements".            | PA-23 Series<br>PA-23-250 Series     | 9/25/2000 | **              |             | 3714 10cB1          |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

PA-23/PA-23-160  
PA-23-235/PA-23-250  
PA-E23-250

| NUMBER | SUBJECT                                                                                                                                      | MODELS<br>AFFECTED                                                             | DATE       | PART/KIT<br>NO.               | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|------------|-------------------------------|-------------|-------------|
| 1051B  | Flap Torque Tube Replacement                                                                                                                 | PA-23<br>PA-23-160/-235<br>PA-23-250<br>PA-E23-250                             | 11/5/2002  | 104622-002                    | 81-04-05R1  | 2755        |
| 1079   | Untested Fuel Pump                                                                                                                           | PA-23-250 Series                                                               | 7/20/2001  | 62220-005                     |             | 2825        |
| 1147   | Turbocharger Clamp, Incorrect Substitution                                                                                                   | PA-23-250                                                                      | 5/14/2004  | 555-511                       |             | 7200        |
| 1160A  | Stabilator Torque Tube Assembly Inspection                                                                                                   | PA-23-235<br>PA-23-250<br>PA-E23-250                                           | 11/28/2022 | 16067-000<br>652-579          |             | 5519        |
| 1194B  | Nose Baggage Door Components, Periodic Replacement of                                                                                        | PA-23-250<br>PA-E23-250                                                        | 4/12/2012  | **                            | 2009-13-06  | 5230        |
| 1266   | Fuel Warning Placard and POH Inspection                                                                                                      | PA-23-250 "B"<br>PA-23-250 "C"<br>PA-23-250 "D"<br>PA-23-250 "E"<br>PA-E23-250 | 12/16/2014 | **                            | 2015-24-05  | 1130        |
| 1284B  | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-23-150/160                                                                  | 4/12/2019  | N/A                           |             | 7414        |
| 1286A  | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement                                                                                       | PA-23-250<br>PA-E23-250                                                        | 10/30/2015 | N/A                           |             | 7310        |
| 1295   | Nose Baggage Door Lock Inspection                                                                                                            | PA-23-250<br>PA-E23-250                                                        | 3/24/2017  | 88409-002                     | 2009-13-06  | 5230        |
| 1297   | Altimeter Inspection and Replacement (United Instruments SB No. 13)                                                                          | All                                                                            | 5/10/2016  | N/A                           |             | 3416        |
| 1299A  | Periodic Replacement of Main Landing Gear Drag Link Bolt                                                                                     | PA-23-150<br>PA-23-160<br>PA-23-235<br>PA-23-250                               | 12/18/2019 | 402-356<br>402-427<br>691-367 |             | 3210        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------|--------------------|------|-----------------|-------------|-------------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-24  
PA-30/39

| NUMBER | SUBJECT                                                                                                                                                                                                      | MODELS<br>AFFECTED                 | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |      |
|--------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------|----------|-----------------|-------------|-------------|------|
| 164    | ADF Indicator Excess Wire, Battery<br>Cable Insulation, Muffler Replacement,<br>Nose Gear Door Retraction Rod,<br>Control Wheel Replacement and<br>Reinforcement Nose Wheel Steering<br>Arm Mounting Bracket | PA-24                              | 5/16/58  |                 |             |             | 2J17 |
| 167    | Oil Cooler Line Clearance                                                                                                                                                                                    | PA-24                              | 1/6/59   | 451-855         | 59-07-05    | 7920        | 2K1  |
| 168    | Nose Gear Retraction Assist Cord                                                                                                                                                                             | PA-24                              | 1/16/59  | 754-205         | 58-25-05    | 3230        | 2K2  |
| 171    | Weight And Balance                                                                                                                                                                                           | PA-24<br>PA-24-250                 | 3/18/59  |                 |             | 800         | 2K4  |
| 172    | Control Wheel Sprocket Mounting<br>Hole, Inspection of                                                                                                                                                       | PA-24/PA-24-250<br>(w/Autocontrol) | 4/27/59  | **              | 59-12-09    | 2700        | 2K5  |
| 173    | Aileron Balance Weight<br>Attachment, Bulkhead                                                                                                                                                               | PA-24<br>PA-24-250                 | 6/23/59  | 754-233         | 59-13-02    | 2710        | 2K13 |
| 177    | Fuel Cell Filling Instructions                                                                                                                                                                               | PA-24/PA-24-250                    | 8/5/59   | 21994-00        |             | 2810        | 2K20 |
| 178    | Control Tube Guide Blocks<br>Safety Wiring of                                                                                                                                                                | PA-24<br>PA-24-250                 | 9/24/59  |                 |             | 2700        | 2K22 |
| 179    | Door Window, Refitting of                                                                                                                                                                                    | PA-24/PA-24-250                    | 11/6/59  |                 |             | 5630        | 2K24 |
| 180    | Fuel Cell Vent Tubes,<br>Modification of                                                                                                                                                                     | PA-24<br>PA-24-250                 | 11/6/59  |                 | 59-26-02    | 2810        | 2L2  |
| 187    | Safety Switches. PA-24 and 24-250<br>Landing Gear-Service Letter 314A,<br>Dated June 8, 1954                                                                                                                 | PA-24                              | 4/15/60  | 754-221         |             | 3230        | 2L18 |
| 190A   | Insulation-Cabin Heat<br>Induction System                                                                                                                                                                    | PA-24                              | 3/14/60  | 754-308         |             | 2140        | 2L23 |
| 191    | Hinge Bracket, Aileron—Part<br>No. 20211-00                                                                                                                                                                  | PA-24<br>PA-24-250                 | 6/16/60  | 20211-00        |             | 5150        | 3A1  |
| 192    | Throttle Limit Switch Bracket                                                                                                                                                                                | PA-24                              | 6/17/60  | 754-334         |             | 7610        | 3A3  |
| 193    | Fuel Cell Vent Tube,<br>Modification of                                                                                                                                                                      | PA-24                              | 6/17/60  |                 | 60-24-03    | 2810        | 3A5  |
| 197    | Master Cylinder, Brake,<br>Replacement of                                                                                                                                                                    | PA-24                              | 12/2/60  | 455-929         |             | 3240        | 3A12 |
| 201    | Vacuum Pumps, Dry, Replacement of                                                                                                                                                                            | PA-24                              | 4/13/61  | 481-681         |             | 3710        | 3A21 |
| 202    | Exhaust System, Comanche.<br>Inspection of                                                                                                                                                                   | PA-24                              | 5/22/61  | 754-396         | 61-20-02    | 7810        | 3A22 |
| 205    | Circuit Protector Wiring,<br>Inspection of                                                                                                                                                                   | PA-24                              | 8/15/61  |                 |             | 2400        | 3B3  |
| 208    | Gascolator Bowl Drain Valve                                                                                                                                                                                  | PA-24                              | 12/19/61 |                 |             | 7310        | 3B9  |
| 210    | Muffler Shrouds, Replacement of                                                                                                                                                                              | PA-24/24-250                       | 10/3/62  | 754-484         | 62-26-05    | 7810        | 3B12 |
| 211    | Main Fuel Cell Cavity Modification                                                                                                                                                                           | PA-24-250                          | 11/2/62  | 754-492         |             | 2810        | 3B17 |
| 212    | Engine-Driven Fuel Pump,<br>Installation of Vent Lines<br>(PA-24-250 W/Fuel Injection)                                                                                                                       | PA-24-250                          | 12/5/62  | 756-700         |             | 2820        | 3B20 |
| 216    | Fuel Cell Drain Modification                                                                                                                                                                                 | PA-24/24-250                       | 8/5/63   | 756-756         | 68-13-03    | 2810        | 3C4  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                   | MODELS<br>AFFECTED                           | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE       |
|--------|-------------------------------------------------------------------------------------------|----------------------------------------------|----------|--------------------|-------------|-------------------|
| 218    | Vacuum Pump Spined Coupling,<br>Replacement of                                            | PA-24/24-250<br>PA-30                        | 11/11/63 | 753-865            |             | 3710 3C9          |
| 219A   | Heater, 940DB, Modification<br>And Rewiring                                               | PA-30                                        | 9/23/64  | 756-815            |             | 2140 3C12         |
| 220    | Alternate Air Doors,<br>Replacement of                                                    | PA-30                                        | 3/3/64   | 756-794            | 64-09-05    | 7160 3C14         |
| 222A   | Airspeed Limits, Restriction To,<br>Removal of (Replacement of<br>Stabilator Torque Tube) | PA-30                                        | 8/10/64  | 756-827            | 64-28-03    | 3410 3C17         |
| 224    | Pitch Servo—Modification of—<br>Mitchell Bulletin No. A55                                 | PA-24-250<br>PA-24-260<br>PA-24-400<br>PA-30 | 4/7/65   | 756-923            | 65-11-04    | 2210 3D3          |
| 228    | Fuel Purge Valve Hose<br>Assembly, Replacement of                                         | PA-24-400                                    | 1/7/66   | 756-994            | 66-30-07    | 2810 3D15         |
| 229A   | Airspeed Limits, Restriction,<br>Removal of                                               | PA-30                                        | 6/17/66  | **                 | 66-28-06    | 3410 3D16         |
| 231A   | Fuel Tank Caps                                                                            | PA-24/24-250                                 | 10/10/66 | 25983-00           | 68-13-03    | 2810 3D23         |
| 232    | Brake Disc Assembly, Inspection of                                                        | PA-30                                        | 6/8/66   | 757-039            |             | 3240 3D24         |
| 235    | Airspeed Limit, Never-To-Exceed<br>Standardization of                                     | PA-30                                        | 9/16/66  | **                 | 66-28-06    | 3410 3E6          |
| 236    | Oxygen Cylinder                                                                           | PA-30                                        | 12/29/66 | 757-094            | 67-19-05    | 3510 3E8          |
| 238    | Fuel Purge Valve Hose Replacement                                                         | PA-24-400                                    | 12/7/66  | 757-099            |             | 3420 3E10         |
| 246    | Oxygen Cylinder Rear Retaining<br>Strap Modification of                                   | PA-30                                        | 3/21/67  | 758-109            | 67-19-05    | 3510 3E22         |
| 263    | Flight Manual Revision                                                                    | PA-30                                        | 1/15/68  | 760-168            |             | General 3G9       |
| 280    | Artificial Horizon, R.C. Allen<br>3", Case Leakage of                                     | PA-24-260<br>PA-30                           | 7/10/68  |                    |             | 3420 3H20         |
| 299    | Flight Manual Revision                                                                    | PA-30 "C"                                    | 5/29/69  | **                 |             | General 3K2       |
| 301A   | Airplane Flight Manual And<br>New Placards                                                | PA-30                                        | 11/25/69 | 760-354<br>760-355 | 69-24-04    | 1100 3K5          |
| 306    | Alternator System Modification                                                            | PA-30 "C"                                    | 1/9/70   | 760-347            | 70-22-05    | 2430 3K14         |
| 310    | Modifications, Twin Comanche<br>(Airspeed Marking, Stall Warning<br>Horn Installation)    | PA-30                                        | 5/6/70   | 760-408<br>760-373 |             | 3410 3K24<br>2700 |
| 314A   | Selector Valve, Fuel Modification                                                         | PA-30/39                                     | 9/28/70  | 760-444            |             | 2820 3L8          |
| 315    | Limit VNE Airspeed                                                                        | PA-30                                        | 7/8/70   | **                 |             | 1100 3L10         |
| 320A   | Autopilot Servo and Bridle<br>Cable Installation, III Series,<br>Inspection of            | PA-24-260<br>PA-30/39                        | 7/6/72   |                    |             | 2210 3L23         |
| 324    | Vacuum Pump Adapter Drive<br>Assembly                                                     | PA-24<br>PA-30/39                            | 9/29/70  |                    |             | 3710 4A9          |
| 331    | Electric Trim Switch<br>Inspection and Modification                                       | PA-24-260<br>PA-30/39                        | 2/5/71   | 760-505            | 71-12-05    | 2730 4B3          |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-24  
PA-30/39

| NUMBER | SUBJECT                                                                                      | MODELS<br>AFFECTED                              | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE      |
|--------|----------------------------------------------------------------------------------------------|-------------------------------------------------|----------|--------------------|-------------|------------------|
| 336    | Seat Frame Tube Replacement,<br>Vertically Adjustable                                        | PA-24-260<br>PA- 30/39                          | 3/11/71  |                    |             | 2510 4B18        |
| 343    | Hartzell Service Bulletin No. 96,<br>Amended 8/18/71 And Supplement<br>No. 1 Amended 8/18/71 | PA-30                                           | 9/9/71   | **                 |             | 6110 4C13        |
| 349    | Switch Modification, Master,<br>Electrical System                                            | PA-30/39                                        | 4/26/72  | **                 |             | 2450 4D5         |
| 354B   | Fuel Selector Valve Lubrication                                                              | PA-24-180/24-250                                | 5/19/82  | **                 | 60-10-08    | 2820 4D15        |
| 362    | VNE Speed Limit                                                                              | PA-24-250/24-260                                | 8/14/72  | **                 |             | 3410 4E19        |
| 362A   | Rudder Balance Weight Installation<br>(Does not cancel Service Bulletin<br>No 362)           | PA-24-180/24-250/<br>24-260                     | 10/6/72  | 760-705            |             | 2720 4E22        |
| 381    | Manual Revision, Pilot's<br>Operating/Airplane Flight                                        | PA-39                                           | 8/29/73  | **                 |             | General 4G1      |
| 394    | Rudder Pedal, Warning, Improper<br>Use of                                                    | PA-24-180/24-250/<br>24-260/24-400<br>PA-30/39  | 9/28/73  | 757-436            |             | 2720 4H7         |
| 411A   | Stabilator Torque Tube Bearing Block<br>Attachment Fitting Rivet Replacement                 | PA-24-180/24-250/<br>24-260/24-400<br>PA-30/39  | 4/10/74  | 760-835            | 94-13-10    | 2740 4J9         |
| 464A   | Stabilator Torque Tube Bearing<br>Block Attachment Fitting Rivets,<br>Inspection of          | All PA-24 Series<br>PA-30/39                    | 3/22/76  | 760-835            | 75-27-08    | 5530 5C16        |
| 496    | Stabilator Balance Weight<br>Tube Replacement                                                | PA-24-250/260                                   | 6/4/76   | 28035-00           | 76-19-07    | 2740 5G13        |
| 511A   | Oxygen System Outlet Refinement                                                              | PA-24-260/<br>PA-24-400<br>PA-30/39             | 9/24/76  | 761-032<br>752-583 |             | 3510 5I3         |
| 515    | Control Cable Ball Joint<br>Retainer Installation                                            | PA-24-250<br>PA-24-260/400<br>PA-30/39          | 1/17/77  | 55447-02           |             | 7610 5I10        |
| 527    | Electric Trim Switch Modification                                                            | PA-24-260<br>PA-30/39                           | 11/15/76 | 756-047            | 77-09-10    | 2740 5J18        |
| 597    | Fuel Selector Valve Replacement                                                              | PA-30/39                                        | 4/19/78  | 492-137            | 78-12-07    | 2840 6H10        |
| 677    | Publications for Aircraft Operation                                                          | All Piper<br>Models                             | 5/20/80  |                    |             | PARA 7H4<br>15.0 |
| 751    | Spar Cap Chafing Inspection                                                                  | PA-24-400<br>PA-24-180/250/260<br>PA-30/39      | 5/24/83  | **                 | 83-19-03    | 5740 8G13        |
| 771A   | Parking Brake Application                                                                    | PA-24<br>PA-24-250/260<br>PA-24-400<br>PA-30/39 | 9/6/2011 | 81090-002          | 85-02-05    | 1130             |
| 798    | "TURBO" Marking Removal                                                                      | PA-24 Series<br>PA-30/39                        | 12/11/84 | N/A                |             | 1110 9B19        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                                                  | MODELS<br>AFFECTED                                | DATE       | PART/KIT<br>NO.                          | A.D.<br>NO. | ATA<br>CODE  |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------|------------|------------------------------------------|-------------|--------------|
| 805A   | TRW Hartzell Propeller<br>Service Bulletin No. 142B<br>(O-ring Deterioration)                                                                            | PA-24-260<br>PA-30/-39                            | 3/14/86    | N/A                                      |             | 6110         |
| 836A   | Aluminum Wire<br>Inspection/Replacement                                                                                                                  | PA-24<br>PA-24-250/-260<br>PA-24-400<br>PA-30/-39 | 8/26/86    | **                                       |             | 2400         |
| 855    | Use of Automobile Gasoline In<br>Piper Aircraft                                                                                                          | All Piston Powered<br>Models                      | 1/14/87    | N/A                                      |             | 2800         |
| 861    | Heated Alternate Air Induction<br>System Installation                                                                                                    | PA-24-260                                         | 5/4/87     | 760-516                                  | 91-21-09    | 7314         |
| 884    | Lock Wiring of<br>V-Band Couplings                                                                                                                       | PA-24-260<br>PA-30/-39                            | 4/8/88     | **                                       |             | 7800<br>2100 |
| 980    | Should Harness Installation                                                                                                                              | PA-24<br>PA-24-250/-260<br>PA-24-400<br>PA-30/-39 | 1/18/95    | **                                       |             | 5500         |
| 1022   | Inspection of Induction Air Filter<br>and Distribution of Purolator Service<br>Bulletin, SB090298.01                                                     | PA-24<br>PA-24-250/-260                           | 9/22/98    | 460-632                                  | 99-05-09    | 7167         |
| 1026   | Distribution of Parker Hannifin<br>Airborne Service Letter 48,<br>"Inspection/Replacement of dry<br>air pump flexible couplings".                        | PA-24<br>PA-24-250/-260<br>PA-24-400<br>PA-30/-39 | 11/5/98    | 753-910                                  |             | 3711         |
| 1035A  | Distribution of Textron Lycoming<br>Service Bulletin 529B, "Reprint of<br>Crane/Lear Romec Service Bulletin<br>No. 101SB020, Rev. 3"                     | PA-24-260<br>PA-24-400                            | 3/22/2007  | **                                       | 2003-14-03  | 7311         |
| 1041   | Distribution of Airborne<br>Service Letter Number 56,<br>"Inspection and Cleaning of<br>Airborne Air Filter Elements".                                   | PA-24<br>PA-24-250/-260<br>PA-24-400<br>PA-30/-39 | 9/25/2000  | **                                       |             | 3714         |
| 1160A  | Stabilator Torque Tube Assembly<br>Inspection                                                                                                            | PA-24<br>PA-24-250/-260<br>PA-24-400<br>PA-30/-39 | 11/28/2022 | 652-580<br>652-581<br>652-582<br>652-583 |             | 5519         |
| 1189   | Stabilator Horn Assembly<br>Inspection                                                                                                                   | PA-24<br>PA-24-250/-260<br>PA-24-400<br>PA-30/-39 | 4/29/2010  | **                                       | 2012-17-06  | 5510         |
| 1266   | Fuel Warning Placard<br>and POH Inspection                                                                                                               | PA-24-250/260/400<br>PA-30/39                     | 12/16/2014 | **                                       | 2015-24-05  | 1130         |
| 1284B  | Lycoming SB 622A, Slick/Champion<br>Aerospace SB1-15A, Potential<br>decreased service life of Slick<br>4-cylinder magneto distributor gear<br>assemblies | PA-24                                             | 4/12/2019  | N/A                                      |             | 7414         |
| 1286A  | Lycoming SB 621A,<br>Diaphragm-Type Fuel Pump<br>Replacement                                                                                             | PA-24-250/-260<br>PA-30/39                        | 10/30/2015 | N/A                                      |             | 7310         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-24  
PA-30/39

| NUMBER | SUBJECT                                                                   | MODELS<br>AFFECTED | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------------|--------------------|-----------|-----------------|-------------|-------------|
| 1297   | Altimeter Inspection and<br>Replacement (United Instruments<br>SB No. 13) | All                | 5/10/2016 | N/A             |             | 3416        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**SB21**

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------|--------------------|------|-----------------|-------------|-------------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                                                                            | MODELS<br>AFFECTED                                                                                    | DATE      | PART/KIT<br>NO.       | A.D.<br>NO.          | ATA<br>CODE                  |      |
|--------|------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|-----------|-----------------------|----------------------|------------------------------|------|
| 209    | Propeller Bolts, Replacement of                                                                                                    | PA-28-150/160                                                                                         | 4/17/62   | 754-462V              | 62-19-03             | 6110                         | 3B11 |
| 223    | Sender Unit, Stewart-Warner<br>Fuel Quantity Gauge,<br>Modification of                                                             | PA-28-140/150/160/180/<br>235                                                                         | 2/12/65   | 756-906V              | 65-06-06             | 2840                         | 3D1  |
| 234    | Spinner Modification                                                                                                               | PA-28-150/160/180                                                                                     | 8/2/66    | 757-046V<br>757-047V  | 66-20-05             | 6110                         | 3E4  |
| 237    | Rudder Trim Installation<br>Modification                                                                                           | PA-28-140/150/160/180/<br>235                                                                         | 11/1/66   | 757-085V              |                      | 2720                         | 3E9  |
| 240    | Inspection of Aileron Balance<br>Weight, Assembly, Rudder Horn<br>Assembly And Stabilator Balance<br>Weight Assembly For Corrosion | PA-28-140/150/160/180/<br>235                                                                         | 12/13/66  |                       | 67-12-06             | 2710                         | 3E12 |
| 245    | Family Seats Center Safety<br>Attachment, Inspection of                                                                            | PA-28-140                                                                                             | 3/8/67    |                       |                      | 5340                         | 3E20 |
| 248    | Torque Links, Main Landing Gear                                                                                                    | PA-28-140/150/160/180/<br>235                                                                         | 5/12/67   | 65691-00V<br>757-123V | 70-18-05<br>67-20-04 | 3210                         | 3F2  |
| 249A   | Fuel System Improvement Kit                                                                                                        | PA-28-235                                                                                             | 3/1/68    | 757-139V              | 67-26-02             | 2800                         | 3F6  |
| 251D   | Fuel Tank Inspection                                                                                                               | PA-28-140/150/160/180<br>PA-28-201T<br>PA-28-235<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201T | 2/24/2009 | 757-572V              | 67-26-03             | 2810                         | 3F10 |
| 253    | Fuel Line Modification, Tip Tank                                                                                                   | PA-28-235                                                                                             | 7/7/67    | 757-151V<br>757-152V  | 67-26-02             | 2810                         | 3F14 |
| 261    | Aft Spar Wing Attachment<br>Bolts, Inspection of                                                                                   | PA-28-140/150/160/180/<br>235                                                                         | 11/10/67  | 760-162V              |                      | 5710                         | 3G5  |
| 274    | Retraction Fitting Replacement,<br>Main Gear                                                                                       | PA-28R-180                                                                                            | 6/3/68    | 760-208V              | 68-12-04             | 3230                         | 3H5  |
| 279    | Bridle Cable, Servo, Inspection                                                                                                    | PA-28-140/150/160/180/<br>235<br>PA-28R-180                                                           | 6/24/68   | **                    |                      | 3210<br>2210                 | 3H16 |
| 281    | Artificial Horizon, R.C. Allen<br>3", Case Leakage of                                                                              | PA-28-140/180/235<br>PA-28R-180                                                                       | 7/10/68   |                       |                      | 3420                         | 3H24 |
| 285    | Fuel Selector Control Stop Assembly                                                                                                | PA-28-235                                                                                             | 11/22/68  | 760-251V              |                      | 2820                         | 3I11 |
| 287    | Tail pipe Replacement                                                                                                              | PA-28-140/150/<br>160/180                                                                             | 1/15/69   | 63666-02V             |                      | 7810                         | 3I15 |
| 288    | Engine Breather Line Modification                                                                                                  | PA-28R-180                                                                                            | 1/16/69   |                       |                      | 7160                         | 3I17 |
| 292    | Landing Gear Modification,<br>Cherokee Arrow                                                                                       | PA-28R-180                                                                                            | 3/6/69    | 760-292V<br>67150-00V |                      | 7110<br>3230<br>3200<br>2910 | 3J6  |
| 293    | Brace, Baggage Floor                                                                                                               | PA-28-140"B"                                                                                          | 3/5/69    | 760-314V              |                      | 5230                         | 3J10 |
| 295    | Retaining Pin, Control Wheel                                                                                                       | PA-28-180/235<br>PA-28R-180/200                                                                       | 4/30/69   |                       | 69-15-01             | 2700                         | 3J14 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                            | MODELS<br>AFFECTED                              | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |      |
|--------|------------------------------------------------------------------------------------|-------------------------------------------------|----------|-----------------|-------------|-------------|------|
| 297    | Hose Replacement, Air Induction Inlet                                              | PA-28R-180/200                                  | 5/22/69  | 700-328V        | 69-12-01    | 7160        | 3J18 |
| 298    | Carburetor Heat Control Assembly (see also SB 312)                                 | PA-28-140"B"/<br>180"D"/235"C"                  | 6/2/69   | 760-320V        |             | 7310        | 3J23 |
| 305    | Drain Plugs, Carburetor, Inspection of                                             | PA-28-140/150/<br>160/180/235                   | 11/25/69 |                 |             | 7310        | 3K12 |
| 309    | Spinner/Bulkhead Inspection And Replacement                                        | PA-28R-180/200                                  | 5/8/70   | 760-410V        | 70-09-02    | 6110        | 3K20 |
| 311A   | Selector Valve, Fuel Modification                                                  | PA-28-235                                       | 9/28/70  | 760-438V        |             | 2820        | 3L3  |
| 312    | Carburetor Heat Cable Replacement                                                  | PA-28-140"B"                                    | 6/9/70   | 760-387V        |             | 7310        | 3L5  |
| 313    | Terminals, Magneto Filter                                                          | PA-28-140/150/160/180/<br>235                   | 7/1/70   | 23969-02        | 71-14-06    | 7430        | 3L6  |
| 316    | Flight Manual Weight And Balance Data Revision                                     | PA-28R-180/200                                  | 10/20/70 | **              |             | 800         | 3L12 |
| 317    | Rib, Vertical Fin, Inspection                                                      | PA-28<br>PA-28R-180/200                         | 11/18/70 | 760-451V        |             | 5530        | 3L14 |
| 322    | Vacuum Pump Adapter Drive Assembly                                                 | PA-28-140/180/235<br>PA-28R-180/200             | 9/29/70  | 760-477V        |             | 3710        | 4A3  |
| 326    | Selector Handle (2Tank) Fuel Valve, Inspection of The                              | PA-28-140/150/160/180<br>PA-28R-180/200         | 11/9/70  |                 |             | 2820        | 4A14 |
| 327    | Stabilator Balance Weight Tube Assembly Inspection                                 | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200 | 12/9/70  | **              | 70-26-04    | 2740        | 4A16 |
| 332    | Switch, Electric Trim, Inspection And Modification                                 | PA-28-180/235<br>PA-28R-180/200                 | 4/16/71  | 760-517V        | 72-17-05    | 2730        | 4B7  |
| 337    | Seat Frame Tube Replacement Vertically Adjustable                                  | PA-28-140/180/235<br>PA-28R-180/200             | 3/11/71  | **              |             | 2510        | 4B20 |
| 339    | Owner's Handbook Revision                                                          | PA-28R-180/200                                  | 6/16/71  | **              |             | 2720        | 4B24 |
| 342    | Fuel System Instructions And Modification                                          | PA-28-235                                       | 9/7/71   | 760-560V        | 77-12-01    | 2800        | 4C6  |
| 348    | Air Conditioning System. Improvement                                               | PA-28-140                                       | 1/25/72  | 760-581V        |             | 2150        | 4D4  |
| 350    | Stabilator Hinge Attaching Bolts, Inspection of                                    | PA-28-140/180/235,<br>PA-28R-200                | 3/30/72  | **              |             | 5550        | 4D7  |
| 355    | Valve, Fuel Selector, Lubrication                                                  | PA-28-140/150/160/180                           | 6/5/72   | **              |             | 2820        | 4E1  |
| 356    | Duct, Induction Air Inlet And Induction Alternate Heat, Inspection And Replacement | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200 | 9/1/72   | **              |             | 7160        | 4E7  |
| 357A   | Terminal Replacement, Alternator Output Wire                                       | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200 | 11/14/72 | 588-398V        |             | 2420        | 4E9  |
| 360    | Hose System, Modification, Air Induction                                           | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200 | 11/9/72  | **              |             | 7160        | 4E14 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                              | MODELS<br>AFFECTED                                             | DATE     | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------|----------------------------------------------------------------|----------|------------------------|-------------|-------------|
| 368    | Antenna Protector, Transponder, Installation                         | PA-28-140/180/235<br>PA-28R-200                                | 11/22/72 | 760-697V               |             | 3450 4F7    |
| 376    | Fuel Selector Control System Modification                            | PA-28-235                                                      | 4/19/73  | **                     | 77-12-01    | 2820 4F18   |
| 387    | Alternator Installation Modification                                 | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200                | 2/4/74   | 760-741V<br>760-742V   |             | 2430 4G15   |
| 393    | Seat Belt, Rear, Attachment Modification                             | PA-28-140/180/235<br>PA-28R-200                                | 12/18/73 | 760-794                | 74-09-04    | 5340 4H4    |
| 395    | Rudder Pedal, Warning, Improper Use of                               | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200                | 11/9/73  | 757-436                |             | 2720 4H9    |
| 424    | Wing Reinforcement Modification                                      | PA-28-151                                                      | 6/21/74  | 760-878V               | 74-14-04    | 5710 4K16   |
| 427    | Air Conditioning System Modification                                 | PA-28-140/180<br>PA-28R-200                                    | 8/9/74   | 760-822V               |             | 2150 4K23   |
| 434    | Seaplane Propeller Modification                                      | PA-28S-180                                                     | 11/22/74 | 79528-00               |             | 6110        |
| 435    | Aileron Centering—(I) Cable Inspection—(II) Modification             | PA-28-151                                                      | 11/4/74  | **                     | 74-24-12    | 2710 4L15   |
| 436    | Placard Inspection, Operating Limitations                            | PA-28-180                                                      | 12/10/74 | 76206-00V<br>76298-00V | 74-26-07    | 1110 4L18   |
| 444    | Fuel Valve Replacement                                               | PA-28-235                                                      | 1/15/75  | 760-895V               |             | 2820 5A19   |
| 448    | Cable Operation Inspection, Throttle and Mixture Control             | PA-28-140/151/180/235<br>PA-28R-180/200                        | 2/19/75  | **                     |             | 7320 5B4    |
| 449A   | Alternator (Chrysler) Modification And Wire End Terminal Replacement | PA-28-140/151/180/235<br>PA-28R-200                            | 5/7/75   | 558-398V               |             | 2430 5B8    |
| 450    | Quick Drain Valve Inspection Fuel Gascolator                         | PA-28-140/151/180<br>PA-28R-200                                | 2/10/75  |                        | 75-08-03    | 2820 5B12   |
| 454    | Induction Air Shroud Modification                                    | PA-28-151                                                      | 3/10/75  | 760-922V               |             | 7160 5B19   |
| 474    | Carburetor Air Box Modification                                      | PA-28-151                                                      | 6/27/75  | 760-985V               | 75-16-04    | 7160 5D21   |
| 475    | Instrument Panel Dimmer Control Assembly Modification                | PA-28-140<br>PA-28-151<br>PA-28-180<br>PA-28-235<br>PA-28R-200 | 7/10/75  |                        |             | 3310 5E1    |
| 510B   | Landing Gear, Nose, Trunnion Modification                            | PA-28R-200                                                     | 8/31/76  | 761-074V               | 76-15-08    | 3220 5I1    |
| 519A   | Fuel Selector Valve Inspection And Replacement                       | PA-28-235                                                      | 9/2/76   | 492-259<br>492-262     | 76-18-04    | 2820 5I21   |
| 531    | Engine Oil Hose Replacement                                          | PA-28-140                                                      | 1/10/77  | 63901-72V              | 76-25-06    | 7920 5L5    |
| 533    | Fuel Gauge Calibration Inspection                                    | PA-28-140/180/<br>151/181/235<br>PA-28R-200                    | 1/6/77   | **                     | 77-01-01    | 2840 5L8    |
| 536    | Carburetor Air Filter Box, Inspection of                             | PA-28-151                                                      | 1/13/77  |                        | 77-01-03    | 7310 5L15   |
| 538    | Engine Control Cable Inspection                                      | PA-28-151                                                      | 1/14/77  | 67639-06V              |             | 7610 5L20   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                 | MODELS<br>AFFECTED                                                           | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|----------|-----------------|-------------|-------------|
| 541    | Throttle Attachment Inspection                                                                                          | PA-28-140/151/<br>181/235<br>PA-28R-200                                      | 2/15/77  | **              |             | 7610 6A5    |
| 543    | Starter/Magneto Switch Inspection<br>And Replacement                                                                    | PA-28-151/181/<br>235,PA-28R-200                                             | 2/9/77   | 757-597V        |             | 7410 6A9    |
| 548    | Engine Control Rod End<br>Bearing Inspection                                                                            | PA-28-140/151/<br>161/180/181/235<br>PA-28R-200/201<br>PA-28R-201T           | 3/7/77   | **              | 77-23-03    | 7230 6A23   |
| 556    | Electric Trim Switch Modification                                                                                       | PA-28-180/235<br>PA-28R-180/200                                              | 7/25/77  |                 |             | 2730 6B20   |
| 561    | Battery Power Lead Relocation                                                                                           | PA-28R-201/201T                                                              | 4/6/77   |                 |             | 2430 6C7    |
| 563    | Landing Gear, Nose, Actuator<br>Rod End Bearing Change                                                                  | PA-28R-201/201T                                                              | 5/13/77  | 452-357V        |             | 3230 6C14   |
| 565    | Horizontal Situation Indicator<br>Modification To Edo Aire Mitchell,<br>Edo Aire Mitchell Service Bulletin<br>No. MB-13 | PA-28R-200/<br>201/201T                                                      | 6/2/77   | **              | 77-12-01    | 3420 6C20   |
| 571A   | Fuel Valve Leak Check/Fuel Cap<br>Replacement/Fuel Tank Vent<br>Check/Fuel Line Inspection                              | PA-28-235                                                                    | 10/20/77 | **              | 77-12-01    | 2810 6E5    |
| 576    | TCM-TS10360 Series Engines,<br>To Disseminate Information                                                               | PA-28R-201T                                                                  | 11/30/77 |                 |             | 7200 6E23   |
| 577    | Single Mask Oxygen System<br>Turbo Arrow III                                                                            | PA-28R-201T                                                                  | 5/1/78   | 763-808V        |             | 3500 6F1    |
| 578B   | Nose Landing Gear Down<br>Lock Replacement                                                                              | PA-28R-201/<br>201T                                                          | 9/27/78  | 67150-04V       |             | 3230 6F3    |
| 580    | Engine Cowling Air Scoop<br>Drain Hole                                                                                  | PA-28-181/235                                                                | 10/19/77 |                 | 76-25-06    | 7100 6F13   |
| 582    | Pitot and Static Sump<br>Drain Inspection                                                                               | PA-28-161/181                                                                | 12/6/77  | **              |             | 3410 6F15   |
| 611    | Hose Assembly Inspection and<br>Replacement                                                                             | PA-28R-200<br>PA-28R-201T<br>PA-44-180                                       | 11/14/78 | **              |             | 2820 6J5    |
| 612    | Fuel Gascolator Assembly<br>Inspection                                                                                  | PA-28-161<br>PA-28R-201T<br>PA-28R-201                                       | 10/25/78 |                 | 79-02-05    | 7310 6J10   |
| 623    | Diode Assembly Inspection                                                                                               | PA-28-140/151/<br>161/180/181/235<br>PA-28R-200<br>PA-28R-201<br>PA-28R-201T | 11/1/78  |                 |             | 2450 6K16   |
| 625A   | Fuel And Vapor Return Lines<br>Support                                                                                  | PA-28R-201T<br>PA-28RT-201T                                                  | 8/15/80  | 63882-73V       |             | 2810 6K22   |
| 627    | Fuel Line Inspection And<br>Modification                                                                                | PA-44-180                                                                    | 10/24/78 | 63976-34        | 79-02-02    | 2810 6L5    |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                         | MODELS<br>AFFECTED                                                                           | DATE     | PART/KIT<br>NO.     | A.D.<br>NO. | ATA<br>CODE   |      |
|--------|-----------------------------------------------------------------|----------------------------------------------------------------------------------------------|----------|---------------------|-------------|---------------|------|
| 630A   | Collins VIR-350 And VIR-351<br>Navigation Receiver Modification | PA-28-161/181<br>PA-28-236<br>PA-28R-201<br>PA-28R-201T<br>PA-44-180                         | 2/25/80  |                     |             | 3450          | 6L14 |
| 631B   | Battery Protection and Correct<br>Rear Seat Installation        | PA-28-151/161                                                                                | 10/29/81 | **                  | 81-23-05    | 2430<br>2510  | 7A1  |
| 632    | Wing Tip Strobe Light<br>Modification                           | PA-44-180                                                                                    | 12/7/78  | 481-193<br>761-237V |             | 3340          | 7A8  |
| 634    | Engine Primer Modification                                      | PA-44-180                                                                                    | 12/28/78 | 763-908V            | 79-12-11    | 7310          | 7A21 |
| 638    | Inspection of Fuel Line<br>Union Fitting                        | PA-28-161/181<br>PA-28-236<br>PA-28-201T<br>PA-28R-201/201T<br>PA-28RT-201/201T              | 4/23/79  | **                  | 79-13-03    | 2810          | 7B13 |
| 639    | Throttle Cable Installation<br>Modification                     | PA-44-180                                                                                    | 1/10/79  | **                  | 79-05-11    | 7610          | 7B17 |
| 642    | Air Filter Seal Inspection                                      | PA-28-140                                                                                    | 2/1/79   |                     |             | 7160          | 7C2  |
| 646A   | Fuel Tank Vent<br>Modification And Vent<br>Hose Replacement     | PA-28-161/181<br>PA-28-201T<br>PA-28-235<br>PA-28-236<br>PA-28R-201/201T<br>PA-28RT-201/201T | 3/5/80   | 763-934V            | 79-22-02    | 2810          | 7C17 |
| 650    | "P" Lead - Bendix<br>Magnet                                     | PA-28-236<br>PA-44-180                                                                       | 7/20/79  | 470-864V            |             | 7410          | 7D3  |
| 666    | Carburetor Air Box<br>Rivet Replacement                         | PA-44-180                                                                                    | 10/31/79 | 420-859             |             | 7310          | 7F2  |
| 667    | Part I - Carburetor<br>Air Box Modification                     | PA-28-236                                                                                    | 10/3/79  | 763-926V            |             | 7310          | 7F4  |
| 667    | Part 11 - Engine<br>Induction Air Scoop                         | PA-28-236                                                                                    | 10/3/79  | 763-953V            |             | 7160          | 7F5  |
| 677    | Publications for Aircraft Operation                             | All Piper<br>Models                                                                          | 5/20/80  |                     |             | PARA<br>1 5.0 | 7H4  |
| 678    | Nose Landing Gear Down Lock<br>Bushing Replacement              | PA-44-180                                                                                    | 3/24/80  | 764-010V            | 80-12-03    | 3230          | 7H5  |
| 679    | Throttle Linkage Modification                                   | PA-28-181                                                                                    | 3/24/80  | 764-009V            | 80-14-02    | 7610          | 7H6  |
| 681    | Boom Microphone Isolation Relay                                 | PA-28-161/181<br>PA-28-201T<br>PA-28-236<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180 | 4/24/80  | 456-703<br>180-500  | 80-14-03    | 2350          | 7H11 |
| 689A   | Aileron Push Rod<br>Functional Check                            | PA-44-180                                                                                    | 10/24/80 | **                  | 80-21-11    | 2710          | 7J7  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                        | MODELS<br>AFFECTED                                                                                              | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |      |
|--------|--------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|----------|-----------------|-------------|-------------|------|
| 691A   | Muffler Assembly<br>Inspection                                                 | PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28RT-201                                                           | 10/8/80  | **              | 80-19-01    | 7820        | 7J11 |
| 694    | Throttle Rod End<br>Assembly                                                   | PA-28R-200<br>PA-28R-201<br>PA-28RT-201                                                                         | 9/9/80   | MS-24665-132    |             | 7610        | 7J22 |
| 695    | Nose Cone Spar<br>Check / Reinforcement                                        | PA-44-180                                                                                                       | 9/10/80  | 764-080V        | 81-10-01    | 5350        | 7K1  |
| 696    | Master and Alternator                                                          | PA-44-180<br>PA-44-180T                                                                                         | 3/16/81  | 99377-60V       |             | 2450        | 7K4  |
| 699    | Rudder Torque Tube<br>Attachment Fitting and Hardware<br>Inspection            | PA-28RT-201<br>PA-28RT-201T                                                                                     | 4/1/81   | **              |             | 2720        | 7K11 |
| 702    | Aileron Reinforcement                                                          | PA-44-180                                                                                                       | 12/4/80  | 764-088V        | 81-10-04    | 5710        | 7K19 |
| 714    | Oil Cooler Hose<br>Installation Inspection                                     | PA-44-180T                                                                                                      | 6/10/81  | 35801-09V       |             | 7920        | 8A12 |
| 717    | Fuel Selector Line Inspection                                                  | PA-28-140/150/160/180<br>PA-28-151/161<br>PA-28-181<br>PA-28-236<br>PA-28R-180/200<br>PA-28R-201<br>PA-28RT-201 | 7/8/81   |                 |             | 2820        | 8A22 |
| 719    | Engine Mount Reinforcement                                                     | PA-44-180                                                                                                       | 10/15/81 | **              |             | 7120        | 8B3  |
| 724A   | Nose Landing Gear<br>Inspection, Rigging, and<br>Modification                  | PA-28R-200<br>PA-28R-201/201T<br>PA-28RT-201/201T                                                               | 4/20/82  | **              | 82-06-11    | 3220        | 8C1  |
| 725B   | Aileron Balance Weight<br>Attachment Inspection and Rework                     | PA-44-180<br>PA-44-180T                                                                                         | 11/3/97  | 764-148V        | 81-16-10    | 2715        | 8C9  |
| 738    | Nose Landing Gear Actuator<br>Rod End Inspection / Replacement                 | PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T                                         | 4/20/82  | 452-729V        |             | 3230        | 8D15 |
| 738    | Addendum 1 - Nose Landing Gear<br>Actuator Rod End Inspection /<br>Replacement | PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T                                         | 11/23/87 | 452-729         |             | 3230        | 8D15 |
| 749    | Stabilator Assist Springs<br>Inspection                                        | PA-44-180<br>PA-44-180T                                                                                         | 11/8/82  | **              |             | 2370        | 8G8  |
| 753    | Expanded Spin Recovery<br>Procedures                                           | PA-28-140                                                                                                       | 12/15/82 | 87369-44        |             | 2700        | 8G18 |
| 769    | Landing Gear Back-Up<br>Actuator Override Mechanism                            | PA-28R-180<br>PA-28R-200                                                                                        | 10/19/83 | **              |             | 2920        | 8I18 |
| 771A   | Parking Brake Application                                                      | PA-44-180/180T                                                                                                  | 9/6/2011 | 81090-002       | 85-02-05    | 1130        |      |
| 774    | Baggage Door Latch Replacement                                                 | PA-28-150/160/180<br>PA-28R-180                                                                                 | 2/22/84  | **              |             | 5230        | 8J9  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                       | MODELS<br>AFFECTED                                                                                                                                                     | DATE      | PART/KIT<br>NO.                 | A.D.<br>NO.      | ATA<br>CODE |      |
|--------|-------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------------|------------------|-------------|------|
| 775    | Electrical Bus Modification                                                   | PA-44-180/180T                                                                                                                                                         | 6/20/84   | 764-937V                        |                  | 2430        | 8J11 |
| 787C   | Main Landing Gear<br>Trunnion Housing Inspection                              | PA-44-180/180T                                                                                                                                                         | 11/7/2000 | 2599-002                        | 94-13-11         | 3211        | 8L8  |
| 789B   | Aft Inboard Wing Access Panel<br>& Aft Wing Spar Modification                 | PA-28-140<br>PA-28-150/160<br>PA-28-180<br>PA-28-235<br>PA-28R-180/200                                                                                                 | 12/3/2018 | 764-998V<br>765-106V<br><br>N/A | SAIB<br>CE-11-12 | 5711        |      |
| 798    | "TURBO" Marking Removal                                                       | PA-28-201T<br>PA-28R-201T<br>PA-28RT-201T                                                                                                                              | 12/11/84  | N/A                             |                  | 1110        | 9B19 |
| 801    | King Auto Pilot Servo<br>Bridle Clamp Installation                            | PA-28-161/181<br>PA-28-236<br>PA-28RT-201T                                                                                                                             | 12/11/84  | **                              |                  | 2200        | 9C6  |
| 804    | Battery Strap Installation                                                    | PA-28-180/181<br>PA-28-201T<br>PA-28-235<br>PA-28-236<br>PA-28R-200<br>PA-28R-201/201T<br>PA-28RT-201T                                                                 | 4/26/85   | 765-157                         |                  | 2430        | 9D12 |
| 805A   | TRW Hartzell Propeller<br>Service Bulletin No. 142B<br>(O-ring Deterioration) | PA-28-235<br>PA-28-236<br>PA-28-201T<br>PA-28R-180<br>PA-28R-200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T                                              | 3/14/86   | N/A                             |                  | 6110        | 9D15 |
| 811A   | Ammeter Replacement                                                           | PA-28-150/160<br>PA-28-180<br>PA-28-181<br>PA-28-235<br>PA-28-236<br>PA-28-201T<br>PA-28R-180<br>PA-28R-200<br>PA-28R-201/201T<br>PA-28RT-201/201T                     | 5/12/86   | **                              | 86-17-01         | 2430        | 9F4  |
| 836A   | Aluminum Wire<br>Inspection/Replacement                                       | PA-28-140<br>PA-28-150/160<br>PA-28-151/161<br>PA-28-180/181<br>PA-28-235/236<br>PA-28-201T<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T | 8/26/86   | **                              |                  | 2400        | 9J4  |
| 839    | Muffler/Stack<br>Modification                                                 | PA-28-181                                                                                                                                                              | 6/19/86   | 765-191                         |                  | 7822        | 9J14 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                | MODELS AFFECTED                                                                                                                                               | DATE      | PART/KIT NO. | A.D. NO. | ATA CODE           |
|--------|------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------|----------|--------------------|
| 840A   | Fuel Selector Valve Cover Replacement                                  | PA-28-140<br>PA-28-150/160<br>PA-28-180<br>PA-28R-180<br>PA-28R-200                                                                                           | 11/7/2013 | **           | 71-21-08 | 2822               |
| 847    | Ammeter Replacement                                                    | PA-44-180T                                                                                                                                                    | 8/28/86   | 765-302      | 86-20-11 | 2430 9K23          |
| 848    | Niagara Oil Cooler Inspection/Replacement                              | PA-28-236                                                                                                                                                     | 10/3/86   | 16599-00     |          | 7921 9L1           |
| 855    | Use of Automobile Gasoline in Piper Aircraft                           | All Piston Powered Models                                                                                                                                     | 1/14/87   | N/A          |          | 2800 10A7          |
| 856    | Stabilator Attach Fitting Corrosion Inspection                         | PA-28-140<br>PA-28-150/160<br>PA-28-151/161<br>PA-28-180<br>PA-28-181<br>PA-28-201T<br>PA-28-235<br>PA-28-236<br>PA-28R-180<br>PA-28R-200<br>PA-28R-201/201T  | 2/17/87   | **           |          | 5550 10A9          |
| 866A   | Back Up Landing Gear Extender Removal or Alternate Means of Compliance | PA-28R-180<br>PA-28R-200<br>PA-28R-201/201T<br>PA-28RT-201/201T                                                                                               | 3/4/88    | 765-303      |          | 3236 10B22         |
| 884    | Lock Wiring of V-Band Couplings                                        | PA-28-201T<br>PA-28R-201T<br>PA-28RT-201T<br>PA-44-180T                                                                                                       | 4/8/88    | **           |          | 7800 10G20<br>2100 |
| 886    | Wing Spar Inspection                                                   | PA-28-140<br>PA-28-150/160/180<br>PA-28-151/161<br>PA-28-181<br>PA-28-235<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T                            | 6/8/88    | **           |          | 5711 10H3          |
| 896    | Shoulder Harness Installation & Usage                                  | PA-28-140<br>PA-28-150/160/180<br>PA-28-151/161/181<br>PA-28-201T<br>PA-28-235/236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T | 11/28/88  | **           |          | 5340 10113         |
| 901    | Maneuvering Airspeed Placard Replacement                               | PA-28-161<br>Cadet                                                                                                                                            | 3/14/89   | 35669-143    |          | 2501 10J14         |
| 905    | Auxiliary Primer Switch Replacement                                    | PA-28-201T<br>PA-28R-201T<br>PA-28RT-201T                                                                                                                     | 4/6/89    | **           |          | 7315 10K7          |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                               | MODELS<br>AFFECTED                                                                                                                                                                                                                                                   | DATE     | PART/KIT<br>NO.     | A.D.<br>NO.      | ATA<br>CODE |
|--------|---------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|---------------------|------------------|-------------|
| 906    | Oildyne Hydraulic<br>Pump Replacement                                                 | PA-28R-201<br>PA-28RT-201T                                                                                                                                                                                                                                           | 4/10/89  | **                  |                  | 2911 10K12  |
| 916B   | Addition of Wing<br>Stall Strips                                                      | PA-28-161 Cadet<br>PA-28-161 Warrior II<br>PA-28-181 II                                                                                                                                                                                                              | 11/22/89 | **                  |                  | 1130 10aA8  |
| 933A   | Trunnion Replacement                                                                  | PA-28R-201<br>PA-28R-201T                                                                                                                                                                                                                                            | 2/20/90  | 67054-03            |                  | 3222 10aD21 |
| 937    | Engine Mount Inspection<br>and Modification                                           | PA-44-180<br>PA-44-180T                                                                                                                                                                                                                                              | 4/2/90   | 86212-024           |                  | 7120 10aE11 |
| 938    | Wire Protection                                                                       | PA-28R-201<br>PA-28R-201T                                                                                                                                                                                                                                            | 6/12/90  | 181-531<br>488-698  |                  | 3262 10aE15 |
| 940A   | Throttle Microswitch                                                                  | PA-28R-180<br>PA-28R-200<br>PA-28R-201/201T<br>PA-28RT-201/201T                                                                                                                                                                                                      | 11/28/90 | 67210-08<br>487-925 |                  | 7613 10aE21 |
| 965    | Inspection of Flap Lever<br>and Bolt                                                  | PA-28-140<br>PA-28-150/160/180<br>PA-28-151/161<br>PA-28-161 Cadet<br>PA-28-181<br>PA-28-201T<br>PA-28-235<br>PA-28-236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T                                                                   | 9/1/93   | **                  |                  | 2750 10aJ22 |
| 975    | Aging Landing Light Seal<br>Replacement and Landing<br>Light Support Modification     | PA-28-140<br>PA-28-150/160/180                                                                                                                                                                                                                                       | 11/2/94  | **                  |                  | 7160 10bA5  |
| 977    | Inspection of Wing Rear Attach<br>Fitting and Addition of Inspection<br>Access Panels | PA-28-140<br>PA-28-150/160/180<br>PA-28-151<br>PA-28-161 Warrior II & III<br>PA-28-161 Cadet<br>PA-28-181<br>PA-28-235<br>PA-28-236<br>PA-28-201T<br>PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28R-201T<br>PA-28RT-201<br>PA-28RT-201T<br>PA-44-180<br>PA-44-180T | 12/12/94 | **                  | SAIB<br>CE-11-12 | 5740 10bA12 |
| 978A   | Wing Spar Inspection                                                                  | PA-28-161 Cadet<br>PA-28-161 Warrior III<br>PA-28-181 Archer III<br>PA-28R-201<br>PA-28R-201T                                                                                                                                                                        | 8/6/99   | **                  |                  | 5711 10bB1  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                        | MODELS AFFECTED                                                                                                                                                                                                                                           | DATE      | PART/KIT NO.                 | A.D. NO.         | ATA CODE    |
|--------|------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|------------------------------|------------------|-------------|
| 990    | Pacific Scientific Seat Belt Replacement                                                       | PA-28-161<br>PA-28-181<br>PA-28R-201<br>PA-44-180                                                                                                                                                                                                         | 1/3/96    | **                           |                  | 5346 10bD12 |
| 991A   | Replacement of Modification of the Alternator Out Light Fuse                                   | PA-28-161 Cadet<br>PA-28R-201<br>PA-28R-201T                                                                                                                                                                                                              | 1/29/96   | **                           |                  | 2437 10bD16 |
| 992    | Replacement of Spinner and Additional of New Forward Spinner Bulkhead                          | PA-28-181                                                                                                                                                                                                                                                 | 3/14/96   | **                           |                  | 6110 10bD22 |
| 996    | Missing Rivet in Upper Door Frame, Forward and Aft                                             | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                                                                                                                 | 9/12/96   | **                           |                  | 5311 10bE16 |
| 1005   | Addition of Drain Holes to the Engine Induction Air Inlet Scoops                               | PA-28-181                                                                                                                                                                                                                                                 | 8/11/97   |                              |                  | 7162 10bG1  |
| 1006   | Corrosion Inspection of Main Spar Behind Fuel Tanks                                            | PA-28-140<br>PA-28-150/160/180<br>PA-28-151<br>PA-28-161 Warrior II & III<br>PA-28-161 Cadet<br>PA-28-181 Archer II & III<br>PA-28-235<br>PA-28-236<br>PA-28-201T<br>PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28R-201T<br>PA-28RT-201<br>PA-28RT-201T | 8/15/97   | **                           | SAIB<br>CE-11-12 | 530 10bG4   |
| 1016B  | Aileron Replacement                                                                            | PA-44-180<br>PA-44-180T                                                                                                                                                                                                                                   | 5/26/2016 | 86562-24/-28<br>86562-25/-29 |                  | 2715        |
| 1019   | Inspection of the Engine Oil Cooler                                                            | PA-28-181 III                                                                                                                                                                                                                                             | 6/3/98    | 85472-10                     |                  | 7925 10bI6  |
| 1020   | Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket                                   | PA-28-161 Cadet<br>PA-28-161 III<br>PA-28-181 III<br>PA-28-236<br>PA-28R-201<br>PA-44-180                                                                                                                                                                 | 7/10/98   | **                           |                  | 2563 10bI11 |
| 1022   | Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01 | PA-28-140<br>PA-28-150/160/180<br>PA-28-181 II & III<br>PA-28-235<br>PA-28-201T<br>PA-28R-201T<br>PA-28RT-201T                                                                                                                                            | 9/22/98   | 460-632                      | 99-05-09         | 7167 10bI20 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                                                                  | MODELS<br>AFFECTED                                                                                                                                                                                                                                                                                        | DATE      | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------------|-------------|-------------|
| 1023   | Inspection of Landing Gear Cylinders and Distribution of Parker Hannifin Service Bulletin SB7063                         | PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28R-201T<br>PA-28RT-201<br>PA-28RT-201T<br>PA-44-180<br>PA-44-180T                                                                                                                                                                                           | 10/8/98   | **                   |             | 2902 10bJ6  |
| 1026   | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings." | PA-28-140<br>PA-28-150/160/180<br>PA-28-151<br>PA-28-161 CADET<br>PA-28-161 WARRIOR II & III<br>PA-28-181 ARCHER II & III<br>PA-28-235<br>PA-28-236<br>PA-28-201T<br>PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28R-201 III<br>PA-28R-201T<br>PA-28RT-201 IV<br>PA-28RT-201T<br>PA-44-180<br>PA-44-180T | 11/5/98   | 753-910              |             | 3711 10bJ20 |
| 1028   | Inspection of the Aileron Control Rod Attach Fitting and the Addition of Safety Clips                                    | PA-44-180<br>PA-44-180T                                                                                                                                                                                                                                                                                   | 12/2/98   | **                   |             | 5755 10bk12 |
| 1033A  | Engine Mount Inspection and Modification                                                                                 | PA-44-180                                                                                                                                                                                                                                                                                                 | 6/12/2006 | 767-518<br>89361-016 |             | 7121 10bL10 |
| 1036   | Garmin Service Bulletin No. 9905 "GNS430 Mod 1"                                                                          | PA-28-181 III                                                                                                                                                                                                                                                                                             | 10/1/99   | **                   |             | 3426 10cA1  |
| 1037   | Inspection for Gascolator Bowl Drain Security                                                                            | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201                                                                                                                                                                                                                                                              | 10/28/99  | **                   |             | 2824 10cA5  |
| 1040   | Flight Control Wheel Collar Retainer Modification                                                                        | PA-28-161 III<br>PA-28-161 Cadet<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                                                                                                                                              | 3/20/2000 |                      |             | 2701 10cA19 |
| 1041   | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."            | PA-28-140<br>PA-28-150/-160/-180<br>PA-28S-160/-180<br>PA-28-151/-161<br>PA-28-161 Cadet<br>PA-28-181<br>PA-28-235<br>PA-28-236<br>PA-28-201T<br>PA-28R-180/-200<br>PA-28R-201/-201T<br>PA-28RT-201/-201T<br>PA-44-180/-180T                                                                              | 9/25/2000 | **                   |             | 3714 10cB1  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                   | MODELS AFFECTED                                                                                                                                                                  | DATE      | PART/KIT NO.                  | A.D. NO. | ATA CODE    |
|--------|-----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------------------------|----------|-------------|
| 1048   | Stainless Steel Control Cables                                                                            | PA-28-161 II/III<br>PA-28-161 CADET<br>PA-28-181 II/III<br>PA-28-236<br>PA-28R-201<br>PA-28R-201T<br>PA-44-180                                                                   | 1/3/2001  | N/A                           |          | 2702 10cC9  |
| 1050   | Engine Baffle Assemblies,<br>Installation of Longer Screws                                                | PA-28-161 III<br>PA-28-181 III                                                                                                                                                   | 3/7/2001  | 418-421<br>408-051<br>690-611 |          | 7236 10cC15 |
| 1057   | Low Noise Muffler Replacement                                                                             | PA-28-181 III                                                                                                                                                                    | 7/12/2001 | 766-681                       |          | 7821 10cD24 |
| 1079   | Untested Fuel Pump                                                                                        | PA-28-161 III<br>PA-28-181 III                                                                                                                                                   | 7/20/2001 | 62220-004                     |          | 2825 10cl4  |
| 1083C  | S-TEC System 55X Autopilot                                                                                | PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                                                         | 5/30/2002 | 767-316<br>767-317<br>767-320 |          | 2218 10cl19 |
| 1104   | Air Box Interference                                                                                      | PA-28-181 III                                                                                                                                                                    | 3/22/2002 | 104606-002                    |          | 7160 10dA18 |
| 1109   | Gear Warning Indication                                                                                   | PA-44-180                                                                                                                                                                        | 4/12/2002 | 472-054<br>473-028            |          | 3264 10dB14 |
| 1110   | Air Box Inspection                                                                                        | PA-44-180                                                                                                                                                                        | 5/16/2002 | 86245-034                     |          | 7160 10dB18 |
| 1117   | Rudder Trim System Bolt<br>Inspection                                                                     | PA-44-180                                                                                                                                                                        | 6/3/2002  | 402-285<br>691-306            |          | 2721 10dC16 |
| 1118   | Alternate Air Inlet Adapter<br>Inspection                                                                 | PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28RT-201                                                                                                                            | 4/19/2002 | 99047-000                     |          | 7164 10dC20 |
| 1119   | Toe Brake Installation Inspection                                                                         | PA-28R-201                                                                                                                                                                       | 8/16/2002 | 424-184<br>762-587            |          | 3241 10dD1  |
| 1122   | Wing Rib Inspections                                                                                      | PA-28-151<br>PA-28-161 WARRIOR II & III<br>PA-28-181 ARCHER II & III<br>PA-28-236<br>PA-28-201T<br>PA-28R-201<br>PA-28R-201 III<br>PA-28R-201T<br>PA-28RT-201 IV<br>PA-28RT-201T | 3/7/2003  | 35617-001<br>104721-002       |          | 5712 10dD14 |
| 1127B  | Combustion Heater Fuel Pump<br>Leakage<br>(Kelly Aerospace SIL A-110B)                                    | PA-44-180<br>PA-44-180T                                                                                                                                                          | 4/18/2005 | 767-367<br>**                 | 3-11-14  | 2800 10dE16 |
| 1131A  | Inspection of Cast Main Landing<br>Gear Strut Cylinders<br>(P/N's 65319-002, 65319-003,<br>and 65319-004) | PA-28-140<br>PA-28-150/160/180<br>PA-28-151<br>PA-28-161 II/III<br>PA-28-161 Cadet<br>PA-28-235                                                                                  | 1/18/2016 | 65489-002<br>65490-000        |          | 3210        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                                          | MODELS<br>AFFECTED                                                                | DATE       | PART/KIT<br>NO.               | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|------------|-------------------------------|-------------|-------------|
| 1134   | Servo Metered Fuel Pressure<br>Port Leakage (Lycoming SB 557;<br>Precision Airmotive SB PRS-105) | PA-28R-180<br>PA-28R-200<br>PA-28R-201 III<br>PA-28R-201<br>PA-28RT-201           | 6/10/2003  | **                            |             | 2800        |
| 1135   | GMA-340 Audio Panel Wiring                                                                       | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                         | 7/16/2003  | N/A                           |             | 2370        |
| 1136   | Auxiliary Fuel Pump Switch                                                                       | PA-28-201T<br>PA-28R-201T<br>PA-28RT-201T                                         | 9/2/2003   | 588-006<br>(99377-029)        |             | 2800        |
| 1137   | Stabilator Balance Weight<br>Tube Assembly                                                       | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201                                      | 11/6/2003  | N/A                           |             | 2749        |
| 1138   | GNS-430 / GI-106 Wiring                                                                          | PA-28-161 III                                                                     | 10/30/2003 | N/A                           |             | 3457        |
| 1139A  | Control Wheel Attachment Inspection                                                              | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                         | 4/9/2004   | **                            | 4-14-12     | 2701        |
| 1141   | Clip Nut Replacement                                                                             | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201                                      | 12/9/2003  | 477-640                       |             | 5351        |
| 1143   | Nose Cone Spar Assy Inspection                                                                   | PA-44-180<br>PA-44-180T                                                           | 7/13/2004  | **                            | 81-10-01    | 3220        |
| 1151E  | 4130N Steel Hardness Discrepancy                                                                 | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                         | 6/9/2004   | N/A                           |             | 5741        |
| 1153   | Overhead Switch Panel Assembly<br>Modification                                                   | PA-28-181 III                                                                     | 2/8/2005   | 767-382                       |             | 3340        |
| 1156A  | Nose Gear Drag Link Bolt<br>Periodic Inspection & Replacement                                    | PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T           | 11/9/21    | 402-940                       |             | 3220        |
| 1161C  | Rib Assembly Inspection and<br>Modification - Aft Wing, WS 49.25                                 | PA-28R-180<br>PA-28R-200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T | 3/6/2023   | 767-397<br>767-398            |             | 5712        |
| 1162B  | European Requirements for<br>Avidyne Entegra Equipped<br>PA-28 and PA-32 Model Aircraft          | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201                                      | 9/7/2006   | 652-589<br>767-419<br>767-422 |             | 3400        |
| 1164   | Propeller RPM Limitation and<br>Tachometer Re-Marking                                            | PA-28R-200                                                                        | 5/5/2006   | 767-510<br>62177-019          |             | 7714        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                  | MODELS<br>AFFECTED                                                                                                                                                                                                                                                                           | DATE       | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------------------|-------------|-------------|
| 1167   | Nose Gear Centering Springs                              | PA-28-161 II/III<br>PA-28-161 Cadet<br>PA-28-181 II/III                                                                                                                                                                                                                                      | 5/31/2006  | 767-514<br>767-519     |             | 3220 10dL16 |
| 1178   | Nose Gear Forging Inspection /<br>Replacement            | PA-28R-201<br>PA-44-180                                                                                                                                                                                                                                                                      | 9/24/2007  | 67050-007<br>67050-002 |             | 3222 10eB10 |
| 1179   | Main Landing Gear Cylinder<br>Assembly Inspection        | PA-28-161 III<br>PA-28-181 III                                                                                                                                                                                                                                                               | 2/1/2008   | 65490-000              |             | 3213 10eB14 |
| 1186   | Aileron Handling Placard                                 | PA-44-180<br>PA-44-180T                                                                                                                                                                                                                                                                      | 9/7/2007   | 88428-002<br>(Kit)     |             | 2710 10eD1  |
| 1187   | Voltage Suppressor Replacement                           | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                                                                                                                                                    | 2/8/2008   | 88432-002<br>(Kit)     |             | 3400 10eD4  |
| 1188   | Emergency Gear Extension Cable<br>Routing Modification   | PA-44-180<br>PA-44-180T                                                                                                                                                                                                                                                                      | 4/14/2008  | 88433-002<br>(Kit)     |             | 3200 10eD12 |
| 1197E  | Control Wheel Shaft Inspection                           | PA-28-140<br>PA-28-150/(S)-160/(S)-180<br>PA-28-151<br>PA-28-161 Warrior II & III<br>PA-28-161 Cadet<br>PA-28-181 Archer II & III<br>PA-28-235<br>PA-28-236<br>PA-28-201T<br>PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28R-201T<br>PA-28RT-201<br>PA-28RT-201T<br>PA-44-180<br>PA-44-180T | 11/2/2017  | **                     | 2010-15-10  | 2710        |
| 1198A  | Fuel Selector O-Ring                                     | PA-28-235                                                                                                                                                                                                                                                                                    | 4/20/2009  | 485-330<br>485-332     |             | 2823        |
| 1199   | Main Landing Gear Torque<br>Link Inspection              | PA-28-140<br>PA-28-150/160/180<br>PA-28-235                                                                                                                                                                                                                                                  | 2/16/2009  | 78033-000<br>63312-002 | 72-08-06    | 3213        |
| 1207   | Periodic Replacement of Nose<br>Gear Downlock Pivot Bolt | PA-44-180/180T                                                                                                                                                                                                                                                                               | 2/15/2010  | **                     |             | 3220        |
| 1209   | Nose Gear Actuator Modification                          | PA-44-180                                                                                                                                                                                                                                                                                    | 1/5/2010   | N/A                    |             | 3220        |
| 1213A  | Emergency Gear Extension Cable<br>Routing Inspection     | PA-44-180                                                                                                                                                                                                                                                                                    | 10/23/2015 | **                     |             | 3230        |
| 1220C  | Throttle Cable Seizing                                   | PA-44-180                                                                                                                                                                                                                                                                                    | 4/27/2017  | 88501                  |             | 7600        |
| 1223   | Wire Screen Replacement                                  | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                                                                                                                                                    | 11/10/10   | **                     |             | 2126        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                           | MODELS AFFECTED                                                                                                                                                                                                                                                                              | DATE       | PART/KIT NO.                    | A.D. NO.   | ATA CODE |
|--------|---------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------------------------|------------|----------|
| 1226   | Radio Support Plate Inspection                    | PA-28-161 III                                                                                                                                                                                                                                                                                | 10/28/10   | 79009-000                       |            | 3450     |
| 1227   | Rudder Trim Tab Inspection                        | PA-44-180                                                                                                                                                                                                                                                                                    | 11/2/10    | N/A                             |            | 5540     |
| 1240   | Fuel Pump Coupling Inspection                     | PA-44-180                                                                                                                                                                                                                                                                                    | 1/26/2012  | 556-406                         |            | 2820     |
| 1242A  | Rudder Pedal Assembly Inspection                  | PA-28-140<br>PA-28-150/(S)-160/(S)-180<br>PA-28-151<br>PA-28-161 Warrior II & III<br>PA-28-161 Cadet<br>PA-28-181 Archer II & III<br>PA-28-235<br>PA-28-236<br>PA-28-201T<br>PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28R-201T<br>PA-28RT-201<br>PA-28RT-201T<br>PA-44-180<br>PA-44-180T | 5/12/2020  | 99938-000<br>99938-001          |            | 2710     |
| 1244C  | Aft Wing Attach Fitting Inspection Requirements   | PA-28 Series<br>PA-28S Series<br>PA-28R Series<br>PA-28RT Series<br>PA-44 Series                                                                                                                                                                                                             | 12/3/2018  | 764-998                         |            | 5740     |
| 1245A  | Stabilator Control System Inspection              | PA-28 Series<br>PA-28S Series<br>PA-28R Series<br>PA-28RT Series<br>PA-44 Series                                                                                                                                                                                                             | 11/28/2012 | N/A                             | 2013-02-13 | 2730     |
| 1251   | Stabilator Trim Barrel Inspection                 | PA-28-140/150/160/180<br>PA-28-151/161/181<br>PA-28-161 Cadet<br>PA-28-201T/235/236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28S-160/180                                                                                                                                                   | 4/10/2013  | 63530-000                       |            | 5755     |
| 1253   | Firewall Inspection                               | PA-28-181 III                                                                                                                                                                                                                                                                                | 1/7/2013   | N/A                             |            | 7130     |
| 1259A  | Engine Control Cable Mounting Bracket Replacement | PA-44-180                                                                                                                                                                                                                                                                                    | 5/5/2017   | 106895-002                      |            | 7610     |
| 1261   | Alternator INOP Wiring Modification               | PA-44-180                                                                                                                                                                                                                                                                                    | 9/11/2013  | 88545-002                       |            | 3150     |
| 1274   | Control Wheel Bushing Inspection                  | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                                                                                                                                                    | 2/9/2015   | 68273-002                       |            | 2701     |
| 1276A  | Left Wing Root Rib Inspection                     | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                                                                                                                                                    | 4/29/2016  | 88569<br>95639-002<br>95640-000 |            | 5710     |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                                      | MODELS AFFECTED                                                                                                                                                                  | DATE       | PART/KIT NO.           | A.D. NO.   | ATA CODE |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------------------|------------|----------|
| 1278B  | Left Wing Sta. 131.60 Rib Inspection                                                                                                         | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                                        | 5/2/2019   | 35118-030              |            | 5712     |
| 1279A  | Wing Rib Inspection at Right Side WS 140.09                                                                                                  | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201                                                                                                                                     | 3/3/2016   | N/A                    | 2015-20-13 | 5712     |
| 1280A  | H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1                                                                                    | PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 III<br>PA-28R-201<br>PA-28-236<br>PA-44-180/-180T                                                                               | 4/29/2016  | 459-887                |            | 2620     |
| 1282B  | Oil Pressure Pickup Port Relocation                                                                                                          | PA-44-180                                                                                                                                                                        | 1/12/2016  | 88573-001<br>88573-002 |            | 7930     |
| 1284B  | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-28-140<br>PA-28-150/-160/-180/-235<br>PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28R-180/-200<br>PA-28R-201<br>PA-28RT-201<br>PA-44-180/-180T | 4/12/2019  | N/A                    |            | 7414     |
| 1286A  | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement                                                                                       | PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28RT-201<br>PA-44-180                                                                                                               | 10/30/2015 | N/A                    |            | 7310     |
| 1287   | Lower Wing Skin Inspection                                                                                                                   | PA-44-180/-180T                                                                                                                                                                  | 6/1/2017   | 88611-701              |            | 5730     |
| 1297   | Altimeter Inspection and Replacement (United Instruments SB No. 13)                                                                          | All                                                                                                                                                                              | 5/10/2016  | N/A                    |            | 3416     |
| 1300   | Air Box Gasket Replacement                                                                                                                   | PA-44-180                                                                                                                                                                        | 3/22/2017  | 44P710003-001          |            | 7160     |
| 1302B  | Rear Seat Inspection                                                                                                                         | PA-28-161 II-III<br>PA-28-161 Cadet<br>PA-28-181 III                                                                                                                             | 5/5/2017   | 110145-001             |            | 2520     |
| 1303A  | Diode Module Installation                                                                                                                    | PA-44-180                                                                                                                                                                        | 10/15/2018 | 681-020                |            | 3410     |
| 1304B  | Main Wing Spar Inspection                                                                                                                    | PA-28-140<br>PA-28-150/-160<br>PA-28-180<br>PA-28-235                                                                                                                            | 12/2/2021  | 765-106<br>88692       |            | 5740     |
| 1307   | Plane-Power Alternator Mounting Hardware Replacement                                                                                         | PA-28-181 III<br>PA-44-180                                                                                                                                                       | 6/28/2017  | 88617-001<br>88616-001 |            | 2410     |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                                                                                                              | MODELS<br>AFFECTED                                                                                                                                                                  | DATE       | PART/KIT<br>NO.                                                           | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------|-------------|-------------|
| 1309A  | Fuel Tank Selector Placards<br>Inspection                                                                                                                            | PA-28-140<br>PA-28-150/-160<br>PA-28-151/-161<br>PA-28-161 Cadet<br>PA-28-180<br>PA-28-181 II-III<br>PA-28-236<br>PA-28R-180/-200<br>PA-28R-201/-201T<br>PA-28RT-201/-201T          | 3/6/2018   | 581-685<br>581-686<br>581-687<br>581-890<br>581-891<br>582-693<br>582-694 | 2018-02-05  | 2822        |
| 1311   | Baggage Compartment Closeout<br>Inspection                                                                                                                           | PA-28-151/-161<br>PA-28-161 Cadet<br>PA-28-181 III                                                                                                                                  | 12/11/2017 | 65667-000                                                                 |             | 2550        |
| 1312   | Emergency Exit Inspection                                                                                                                                            | PA-44-180                                                                                                                                                                           | 6/20/2017  | N/A                                                                       |             | 5220        |
| 1313A  | Stabilator Trim Pulley Bracket<br>Inspection                                                                                                                         | PA-28-140<br>PA-28-151/-161<br>PA-28-161 Cadet<br>PA-28-180<br>PA-28-181 II-III<br>PA-28-201T<br>PA-28-235<br>PA-28-236<br>PA-28R-180/-200<br>PA-28R-201/-201T<br>PA-28RT-201/-201T | 1/17/2018  | 65636-801                                                                 |             | 2700        |
| 1316   | Plane-Power Alternator Idler Pulley<br>Bracket Improvement                                                                                                           | PA-28-181 III                                                                                                                                                                       | 11/3/2017  | 88619-001                                                                 |             | 2410        |
| 1323   | Fuel Injection Servo Vapor Return<br>Fitting Replacement<br>(Lycoming S.I. 1572,<br>Plug Replacement of Vapor Return<br>Fitting on Piper Installation of IO-360-B4A) | PA-28-181 III                                                                                                                                                                       | 9/27/2018  | **                                                                        |             | 7322        |
| 1324   | Winterization Kit Replacement<br>(Fuel Injected Engines)                                                                                                             | PA-28-181 III                                                                                                                                                                       | 3/22/2018  | 85470-005                                                                 |             | 7900        |
| 1325   | K400 Relay Wiring Inspection<br>and Mod                                                                                                                              | PA-44-180                                                                                                                                                                           | 6/19/2018  | N/A                                                                       |             | 3297        |
| 1331A  | Stabilator Idler Arm Assembly<br>Inspection                                                                                                                          | PA-28R-180/-200<br>PA-28R-201/-201T<br>PA-28RT-201/-201T                                                                                                                            | 9/27/2018  | N/A                                                                       |             | 5520        |
| 1340C  | Plane-Power Alternator Support<br>Replacement                                                                                                                        | PA-28-181 III                                                                                                                                                                       | 7/15/2022  | 106972-004                                                                |             | 2430        |
| 1342A  | Stabilator Fitting Inspection                                                                                                                                        | PA-28-140<br>PA-28-150/-160<br>PA-28-151/-161<br>PA-28-161 Cadet<br>PA-28-180<br>PA-28-181 II-III<br>PA-28-201T<br>PA-28-235<br>PA-28-236<br>PA-28R-180/-200<br>PA-28R-201/-201T    | 11/2/2021  | 62645-004                                                                 |             | 5510        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                               | MODELS<br>AFFECTED                                                                                                                                                                                                                                                 | DATE       | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------------|-------------|-------------|
| 1345A  | Main Wing Spar Inspection                                             | PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28R-201T<br>PA-28RT-201<br>PA-28RT-201T                                                                                                                                                                               | 9/17/2021  | **              | 2020-26-16  | 5711        |
| 1355B  | Tee Bar Assembly Inspection                                           | PA-28-140<br>PA-28-150/-160/-180/-235<br>PA-28S-150/-160<br>PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28-181 Pilot 100i<br>PA-28-201T<br>PA-28-236<br>PA-28R-180/-200<br>PA-28R-201/-201T<br>PA-28RT-201/-201T<br>PA-44-180/-180T | 8/18/2022  | 28F40A003       |             | 2701        |
| 1357   | Wing Rib Inspections at<br>WS 106.19 and WS 123.15.                   | PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28-201T<br>PA-28-236<br>PA-28R-201<br>PA-28R-201T<br>PA-28RT-201<br>PA-28RT-201T                                                                                                        | 10/27/2020 | N/A             |             | 5712        |
| 1362   | Aft Wing Rib Inspection at<br>Wing Stations 36.92 and 49.25           | PA-28-181 III                                                                                                                                                                                                                                                      | 11/2/2020  | N/A             |             | 5712        |
| 1363   | Rivet Dimple Inspection<br>For Tool Marks                             | PA-28-181 III<br>PA-44-180                                                                                                                                                                                                                                         | 11/13/2020 | N/A             |             | 5700/5300   |
| 1365A  | Pilot and Copilot Seat Upholstery<br>Inspection                       | PA-28-181 III<br>PA-28-181 Piper Pilot 100i<br>PA-44-180                                                                                                                                                                                                           | 7/22/2021  | 484-829         |             | 2510        |
| 1366   | Main Wing Spar Hardware<br>Inspection                                 | PA-28-140<br>PA-28-150/-160/-180/-235<br>PA-28S-150/-160<br>PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28-181 Pilot 100i<br>PA-28-201T<br>PA-28-236<br>PA-28R-180/-200<br>PA-28R-201/-201T<br>PA-28RT-201/-201T<br>PA-44-180/-180T | 5/14/21    | 96352           |             | 5711        |
| 1368   | Heater Fuel Pump Leak Inspection<br>and Replacement (Hartzell ASB 85) | PA-44-180                                                                                                                                                                                                                                                          | 7/14/21    | **              |             | 2140        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                             | MODELS<br>AFFECTED                                                                                                                                                       | DATE       | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------------------|-------------|-------------|
| 1375B  | Periodic Replacement of<br>Main Landing Gear Attachment<br>Hardware | PA-28-140<br>PA-28-150/-160/-180<br>PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28-181 Pilot 100i<br>PA-28-201T<br>PA-28-235<br>PA-28-236 | 2/27/2023  | **                     |             | 3210        |
| 1378   | Fuselage Skin Rivet Inspection                                      | PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28-181 Pilot 100i<br>PA-28-236                                                                | 8/30/2022  | **                     |             | 5330        |
| 1381   | Lower Fuselage Skin Rivet Insp.                                     | PA-44-180/180T                                                                                                                                                           | 6/9/2022   | MS20470AD4             |             | 5300        |
| 1383   | Microphone And Headphone Jack<br>Improvement                        | PA-28-181 III<br>PA-28-181 Pilot 100i                                                                                                                                    | 9/8/2022   | **                     |             | 2340        |
| 1386   | Archer Diesel Cowling Inspection                                    | PA-28-181 (DX/DTX/DLX)<br>or any other Archer<br>modified by Piper per<br>subject STC.                                                                                   | 8/22/2022  | STC SA03303AT          |             | 7110        |
| 1387   | Archer Diesel Instructions For<br>Continued Airworthiness (ICA)     | PA-28-181 (DX/DTX/DLX)<br>or any other Archer<br>modified by Piper per<br>subject STC.                                                                                   | 10/17/2022 | STC SA03303AT          |             | 0400        |
| 1388   | Archer Diesel Fuel System<br>Inspection                             | PA-28-181 (DX/DTX/DLX)<br>or any other Archer<br>modified by Piper per<br>subject STC.                                                                                   | 9/14/2022  | STC SA03303AT          |             | 2820        |
| 1389   | Fuselage Skin and Wing Rib Inspection                               | PA-28RT-201<br>PA-28RT-201T<br>PA-44-180<br>PA-44-180T                                                                                                                   | 1/18/2023  | 86486-006<br>67681-806 |             | 5300 / 5710 |
| 1391A  | GFC 500 Autopilot Pitch Trim                                        | PA-28-181 Pilot 100i                                                                                                                                                     | 1/9/2023   | 88730-701              |             | 2216        |
| 1393   | Engine Control Cables Inspection                                    | PA-28-181 III<br>PA-28-181 Pilot 100i<br>PA-44-180                                                                                                                       | 12/22/2022 | 455-350<br>653-946     |             | 7600        |
| 1393   | Lower Cockpit Channel Inspection                                    | PA-44-180                                                                                                                                                                | 4/27/2023  | 189-625                |             | 5300        |
| 1399   | Wing Rib Modification                                               | PA-28-151/-161<br>PA-28-201/-201T<br>PA-28RT-201/-201T                                                                                                                   | 3/16/2023  | 35615-001<br>35615-003 |             | 5700        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-28  
PA-28R  
PA-44/PA-44T

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------|--------------------|------|-----------------|-------------|-------------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                                                                                                                                                                                             | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE                                          |      |
|--------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|----------|--------------------|-------------|------------------------------------------------------|------|
| 254    | Oil Cooler Hoses, Engine Replacement & Rerouting of                                                                                                                                                                                 | PA-31              | 8/17/67  | 757-167            | 67-25-06    | 7920                                                 | 3F16 |
| 255    | Emergency Exit Window Mechanism, Modification of                                                                                                                                                                                    | PA-31              | 8/9/67   | 757-159            |             | 5220                                                 | 3F17 |
| 256    | Pneumatic Pump Hose, Replacement                                                                                                                                                                                                    | PA-31              | 8/25/67  | 757-175            |             | 3710                                                 | 3F18 |
| 257    | Modifications, Piper Navajo (Five Sections)                                                                                                                                                                                         | PA-31              | 10/10/67 | **                 |             | 7720<br>3210<br>6110<br>7920<br>2810<br>2910<br>3200 | 3F19 |
| 258    | Alternate Air Box Assembly                                                                                                                                                                                                          | PA-31              | 11/1/67  | 757-189            |             | 7160                                                 | 3F24 |
| 262    | Terminals, Solenoid, Insulation of                                                                                                                                                                                                  | PA-31              | 12/19/67 | 757-185            |             | 3310                                                 | 3G8  |
| 265    | Louvered Access Plates, Wing Fillet                                                                                                                                                                                                 | PA-31              | 2/5/68   | **                 |             | 5710                                                 | 3G11 |
| 266    | Fasteners, Engine Cowling                                                                                                                                                                                                           | PA-31              | 2/23/68  | 760-190<br>757-179 |             | 7110                                                 | 3G13 |
| 267A   | Flight Manual Revision                                                                                                                                                                                                              | PA-31              | 5/28/68  | **                 |             | General                                              | 3G15 |
| 268    | Valve Assembly, Manifold And Check                                                                                                                                                                                                  | PA-31              | 2/28/68  | 760-174            |             | 7710                                                 | 3G18 |
| 270    | Deicer Boot Installation, Elevator Tip                                                                                                                                                                                              | PA-31              | 2/23/68  | 757-200            |             | 3010                                                 | 3G20 |
| 271    | Filter, Inline, Pneumatic System                                                                                                                                                                                                    | PA-31              | 3/1/68   | 460-866            |             | 3710                                                 | 3G21 |
| 272A   | Terminal Screws, Electrical, Security of - Voltage Regulator Selector Switch And Master Switch                                                                                                                                      | PA-31              | 5/6/68   | **                 |             | 2430                                                 | 3G22 |
| 276    | Channel Clearance, Aileron Cable/Floorboard Support                                                                                                                                                                                 | PA-31              | 5/23/68  | **                 |             | 2710                                                 | 3H11 |
| 277    | Level, Fuel Selector, Cable Attachment Assembly                                                                                                                                                                                     | PA-31-300          | 7/10/68  | 760-214            | 77-26-02    | 2820                                                 | 3H13 |
| 278    | Control Panel (Fuel) Area, Rerouting And Securing of Wire In The, And Clearance of The Cross Feed Line                                                                                                                              | PA-31-300          | 5/27/68  | 760-216            | 68-13-01    | 2800                                                 | 3H15 |
| 280    | Artificial Horizon, R.C. Allen 3", Case Leakage of                                                                                                                                                                                  | PA-31-300          | 7/10/68  |                    |             | 3420                                                 | 3H2  |
| 283    | Warning System, Landing Gear, Modification To The                                                                                                                                                                                   | PA-31-300          | 10/4/68  | 760-250            |             | 3260                                                 | 3I5  |
| 284    | Torque Tube Assembly, Elevator, Inspection of - Section I; Replacement of The Steel Elevator Torque Tube Assembly, Part Numbers 40070-00 or 40070-04 With Aluminum Elevator Torque Tube Assembly, Part Number 40070-05 - Section II | PA-31/300          | 9/27/68  | 40070-05           |             | 2740                                                 | 3I6  |
| 286    | Hinge Attaching Rivets, Door, Main Landing Gear (In Board)                                                                                                                                                                          | PA-31/300          | 10/29/68 | 420-236            |             | 3210                                                 | 3I13 |
| 289    | Friction, Elevator Control System                                                                                                                                                                                                   | PA-31/300          | 2/17/69  |                    | 69-06-04    | 2730                                                 | 3I19 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                           | MODELS<br>AFFECTED         | DATE     | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |      |
|--------|-------------------------------------------------------------------------------------------------------------------|----------------------------|----------|----------------------|-------------|-------------|------|
| 294    | Stall Strips                                                                                                      | PA-31/300                  | 5/16/69  | 760-321<br>760-322   | 69 11 05    | 5720        | 3J12 |
| 304    | Stall Strip Inspection                                                                                            | PA-31/300                  | 11/17/69 | **                   |             | 5720        | 3K9  |
| 306    | Alternator System Modification                                                                                    | PA-31/300                  | 1/9/70   | 760-349<br>760-358   | 70-22-05    | 2430        | 3K14 |
| 307    | Electrical System Modification,<br>Wing Flap                                                                      | PA-31/300                  | 3/23/70  | 760-381              |             | 2750        | 3K16 |
| 308A   | Seats, Aft Facing                                                                                                 | PA-31/300                  | 5/4/70   | **                   |             | 2570        | 3K17 |
| 320A   | Autopilot Servo And Bridle Cable<br>Installations, III Series, Inspection of                                      | PA-31/300<br>PA-31P        | 7/6/72   |                      |             | 2210        | 3L23 |
| 323    | Spar Assemblies, Rudder And<br>Elevator, Modification of The                                                      | PA-31/300                  | 9/21/70  | **                   | 70-26-06    | 5520        | 4A6  |
| 325    | Battery Drain Relocation                                                                                          | PA-31/300                  | 11/23/70 | 760-436              | 71-01-04    | 2430        | 4A12 |
| 330    | Selector Mechanism Modification<br>Landing Gear 11A                                                               | PA-31                      | 1/20/71  | 760-510              |             | 3200        | 4B1  |
| 331    | Switch, Electric, Trim Inspection<br>And Modification                                                             | PA-31/300<br>PA-31P        | 2/5/71   | 760-505              | 71-12-05    | 2730        | 4B3  |
| 333    | Safety Strap, Cabin Entrance Door,<br>Inspection And Replacement                                                  | PA-31                      | 2/18/71  | **                   |             | 5210        | 4B10 |
| 338    | Rivet Installation, Longitudinal<br>Bulkhead                                                                      | PA-31P                     | 4/21/71  | **                   |             | 5300        | 4B22 |
| 344    | Emergency Gear Extension Operation<br>Information, Revised                                                        | PA-31<br>PA-31P            | 10/12/71 | 760-570              |             | 3200        | 4C19 |
| 346    | Flight Manual, Airplane, Mandatory<br>Revision                                                                    | PA-31                      | 3/23/72  | **                   |             | 2430        | 4C22 |
| 347    | Weldon Service Bulletin WPSB-2<br>(Electric Fuel Pumps)                                                           | PA-31                      | 11/17/71 | 760-573<br>760-574   |             | 2820        | 4C24 |
| 361    | Elevator Hinge Bracket<br>Reinforcement, Inspection                                                               | PA-31                      | 8/17/72  | 43757-17<br>43757-18 |             | 5550        | 4E16 |
| 363    | Cowl Shield Installation                                                                                          | PA-31/300/310<br>PA-31-350 | 2/19/73  | 760-689              |             | 7110        | 4E24 |
| 365    | Torquemeter Oil Pump, Replacement<br>of (Reference Avco Lycoming Service<br>Bulletin No. 350 Dated July 21, 1972) | PA-31P                     | 8/29/72  | LW12637              |             | 7920        | 4F3  |
| 379A   | Rudder Control Cable Routing,<br>Inspection of                                                                    | PA-31-350                  | 10/25/74 | 41953-03<br>41953-04 | 75-06-04    | 2720        | 4F20 |
| 383    | Fuel Selector Valve Control<br>Handle, Modification of                                                            | PA-31-350<br>PA-31P        | 4/25/73  | 760-755              |             | 2820        | 4G4  |
| 384    | Propeller Blade Shank, Inspection<br>of (Hartzell Service Bulletin No.<br>94A Dated March 1, 1973)                | PA-31/300/310              | 4/25/73  | **                   |             | 6110        | 4G5  |
| 386    | Moisture Shield Installation,<br>Circuit Probe                                                                    | PA-31-310<br>PA-31-350     | 9/11/73  | 760-772              |             | 2450        | 4G13 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                                                                                    | MODELS<br>AFFECTED                   | DATE     | PART/KIT<br>NO.     | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------------------------|--------------------------------------|----------|---------------------|-------------|-------------|
| 389    | Bridle Cable And Bridle Cable<br>Clamp Installation                                                                        | PA-31-310<br>PA-31-350<br>PA-31P     | 8/13/73  |                     |             | 2210 4G17   |
| 391    | Loading Instructions, Cargo                                                                                                | PA-31-310                            | 6/6/74   | **                  |             | 5230 4G23   |
| 392    | Automatic Flight Control System<br>(V Series) Precautionary Operating<br>Placard And System Modification                   | PA-31-310<br>PA-31-350<br>PA-31P     | 7/11/73  | 760-793             |             | 2210 4H2    |
| 394    | Rudder Pedal, Warning,<br>Improper Use of                                                                                  | PA-31/300/310<br>PA-31-350<br>PA-31P | 9/28/73  | 757-436             |             | 2720 4H7    |
| 398    | Copilot Gyro Operation -<br>Altimatec V Series Automatic<br>Flight Control System                                          | PA-31-310<br>PA-31-350<br>PA-31P     | 9/13/73  | **                  |             | 2210 4H15   |
| 399    | High Altitude Operation. Ignition<br>System For (Avco Lycoming<br>Service Instruction No. 1291,<br>Dated November 2. 1973) | PA-31-350                            | 10/29/73 | **                  |             | 7420 4H16   |
| 400    | Alternator Pulley And Belt<br>Replacement                                                                                  | PA-31-310<br>PA-31-350               | 2/6/74   | 760-805             |             | 2430 4H21   |
| 405    | Fuel Crossfeed Control Mod                                                                                                 | PA-31-350                            | 10/31/73 | 760-814             |             | 2820 4I13   |
| 407    | Ball Joint Assemblies Control<br>Attachment, Inspection of                                                                 | PA-31/300<br>PA-31-350<br>PA-31-P    | 11/14/73 | 469-142             |             | 5340 4I22   |
| 409    | Elevator Control Tube, Inspection of                                                                                       | PA-31P                               | 6/7/74   | 40847-04            | 75-09-10    | 2730 4J4    |
| 415    | MAA Plate Replacement And<br>Tailpipe Gasket Installation                                                                  | PA-31-310                            | 1/21/74  | 462-062             |             | 7810 4J19   |
| 417    | Heater (Manual) Fuel Shut-off<br>Valve, Removal of                                                                         | PA-31-300                            | 8/26/74  |                     | 74-26-04    | 2140 4J22   |
| 419    | Elevator Control Tube Attachment,<br>Inspection of                                                                         | PA-31-310<br>PA-31-350<br>PA-31P     | 2/20/74  |                     |             | 2730 4K2    |
| 420    | Windshield, Heated, Inspection of                                                                                          | PA-31P                               | 8/7/74   | 760-882             |             | 3040 4K4    |
| 421    | Fuel Selector Valve Replacement                                                                                            | PA-31P                               | 3/18/74  | 492-239             |             | 2820 4K9    |
| 422    | Fuel Selector Valve Control<br>Handle, Inspection of                                                                       | PA-31-350                            | 3/11/74  |                     |             | 2820 4K11   |
| 423    | Deicer (Propeller Electric)<br>Solenoid Replacement                                                                        | PA-31P                               | 3/13/74  | 487-167             |             | 6110 4K13   |
| 431    | Placard, Electric Razor Outlet                                                                                             | PA-31-350                            | 8/5/74   | SK-23601<br>SK-2361 |             | 3320 4L8    |
| 432    | Fuselage Bulkhead, Modification<br>To The                                                                                  | PA-31-310<br>PA-31-350               | 9/6/74   | 760-295             |             | 5310 4L9    |
| 433    | Elevator Control Tube<br>Inspection of                                                                                     | PA-31/300/310<br>PA-31-350           | 12/17/74 | **                  | 75-09-10    | 2730 4L11   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                | MODELS<br>AFFECTED                                | DATE      | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE       |
|--------|--------------------------------------------------------------------------------------------------------|---------------------------------------------------|-----------|------------------------|-------------|-------------------|
| 442    | Circuit Breaker Rewiring,<br>Emergency Fuel Pump                                                       | PA-31/300/310<br>PA-31-350                        | 1/22/75   | 760-905                |             | 2820 5A15         |
| 443    | Fuel Cell Fitting (Main)<br>Inspection of                                                              | PA-31/300                                         | 4/4/75    | 760-929<br>40518-00/01 |             | 2810 5A16         |
| 446A   | Cable Replacement, Rudder/Nose<br>Gear Steering                                                        | PA-31P                                            | 7/8/75    | 760-923                | 75-16-02    | 2720<br>3250 5A23 |
| 458    | Propeller Air Charge Loss, Aircraft<br>Operating Advisory                                              | PA-31P                                            | 4/11/75   | **                     | 75-22-14    | 6100 5C3          |
| 460A   | Battery Drain And Vent Relocation                                                                      | PA-31-350                                         | 1/23/76   | 761-029<br>760-941     | 76-04-10    | 2430 5C8          |
| 461    | Encoding Altimeter Harness Rewiring                                                                    | PA-31-310<br>PA-31-350<br>PA-31P                  | 4/17/75   | **                     |             | 3410 5C10         |
| 462A   | Tailpipe Support Bracket Installation                                                                  | PA-31P                                            | 11/3/75   | 760-974                | 76-06-09    | 7810 5C12         |
| 470    | Propeller Feather Assist Spring<br>Assembly Installation                                               | PA-31P                                            | 10/27/75  |                        |             | 6110 5D6          |
| 473    | Alternator Switch Bus Bar<br>Link Installation                                                         | PA-31P                                            | 3/24/76   | 49167-03               | 76-11-06    | 2450 5D19         |
| 478A   | Airspeed Limitation Placard,<br>Installation of                                                        | PA-31P                                            | 8/20/76   | 761-075                | 76-11-01    | 3410 5E7          |
| 479B   | Alternate Air Door Magnetic Catch<br>Assembly Modification/Replacement;<br>Engine Induction Air System | PA-31-325<br>PA-31-350                            | 3/23/76   | 761-037<br>761-038     | 80-13-06    | 7160 5E9          |
| 480    | Emergency Fuel Pump Circuit<br>Breaker Placards, Inspection of                                         | PA-31-310/325<br>PA-31-350                        | 10/10/75  | **                     |             | 2820 5E11         |
| 487    | Control Shaft Collar<br>Attachment Modification                                                        | PA-31-300/310<br>PA-31-325<br>PA-31-350<br>PA-31P | 11/7/75   | 401-264<br>407-584     | 76-04-11    | 2710 5F7          |
| 488    | Landing Gear Selector Cable<br>Forward Attachment Pin,<br>Modification of                              | PA-31-310/325<br>PA-31-350<br>PA-31P              | 10/24/75  | **                     | 96-24-13    | 3200 5F10         |
| 492A   | Exhaust System Modification<br>TIG0-541 -E1A                                                           | PA-31P                                            | 5/29/2012 | **                     | 76-06-09    | 7800              |
| 494B   | Flap Control System, Inspection of                                                                     | PA-31-300/325<br>PA-31-350<br>PA-31P              | 7/17/79   | **                     | 82-27-13    | 2750 5G6          |
| 497    | Throttle And Propeller Pitch<br>Control Attachment Modification                                        | PA-31P                                            | 3/29/76   | 761-031                |             | 7610<br>6120 5G16 |
| 500    | Elevator Balance Weight<br>Modification                                                                | PA-31-325<br>PA-31-350                            | 4/23/76   | 761-040<br>761-041     | 76-15-07    | 2730 5G23         |
| 507    | Fuel System Control Cables At<br>Swivel Fittings, Inspection of                                        | PA-31/300/325<br>PA-31P                           | 11/10/76  | **                     | 80-18-10    | 7320 5H15         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                                                                                       | MODELS<br>AFFECTED                   | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|----------|--------------------|-------------|-------------|
| 509    | Engine Mount Assembly<br>Attachment Nuts, Replacement of                                                                      | PA-31-310/325<br>PA-31-350           | 6/25/76  | 404-890            |             | 7120 5H22   |
| 511A   | Oxygen System Outlet Refinement                                                                                               | PA-31/300/325<br>PA-31-350<br>PA-31P | 9/24/76  | 761-032<br>752-583 |             | 3510 5I3    |
| 512    | Seat Track Modification                                                                                                       | PA-31/325                            | 10/21/76 | 761-086            |             | 5340 5I5    |
| 515    | Control Cable Ball Joint<br>Retainer Installation                                                                             | PA-31/300/325<br>PA-31/350           | 1/17/77  | 55447-02           |             | 7610 5I10   |
| 521    | Stabilizer Stringer Attachment,<br>Inspection of                                                                              | PA-31/325<br>PA-31/350               | 9/20/76  | 522-881            | 77-01-06    | 5530 5J1    |
| 523    | Cigar Lighter Element Replacement,<br>24 Volt                                                                                 | PA-31/325<br>PA-31-350<br>PA-31P     | 10/8/76  | 55674-02           |             | 3310 5J7    |
| 525    | Seat Latch Mechanism Modification,<br>Pilot/Copilot                                                                           | PA-31/300<br>PA-31-350<br>PA-31P     | 11/15/76 | 55842-02           |             | 5340 5J12   |
| 526A   | Microphone And Phone Jack<br>Relay Modification, Pilot/Copilot                                                                | PA-31/300/325<br>PA-31-350<br>PA-31P | 7/25/77  | 48757-02           | 77-08-02    | 2350 5J15   |
| 527    | Electric Trim Switch Modification                                                                                             | PA-31/300<br>PA-31-350<br>PA-31P     | 11/5/76  | 756-047            | 77-09-10    | 2740 5J18   |
| 529    | Aircraft Data (MAA) Plate<br>Inspection And Replacement                                                                       | PA-31                                | 11/5/76  | 53750-02           | 77-03-03    | 5330 5K3    |
| 535    | Radio Power Relay Cover Spacer<br>Bushings, Replacement of                                                                    | PA-31/325<br>PA-31-350               | 12/15/76 |                    | 77-07-03    | 2450 5L13   |
| 544    | Airspeed Placard Installation                                                                                                 | PA-31-325                            | 3/8/77   | 761-125            | 77-10-09    | 3410 6A11   |
| 546    | Whelen Wing Tip Strobe Lights,<br>Reference FAA Airworthiness<br>Directive, Inspection of                                     | PA-31/325<br>PA-31-350<br>PA-31P     | 5/18/77  | **                 |             | 3340 6A16   |
| 549    | Elevator Bungee Link Modification                                                                                             | PA-31/325<br>PA-31-350               | 2/16/77  |                    | 78-01-02    | 2730 6B2    |
| 550    | Engine Control Cable Inspection                                                                                               | PA-31/325<br>PA-31-350               | 3/29/77  | **                 |             | 7230 6B4    |
| 554    | Spar Reinforcement, Front,<br>Right Wing                                                                                      | PA-31/325<br>PA-31-350               | 3/7/77   |                    | 77-14-14    | 5710 6B15   |
| 558    | Servo Bridle Cable Clamp Bolt<br>Torque Revision; Altimatic V And<br>V F/D Series; M-4D F/D Series;<br>And Sperry SPZ-200 F/D | PA-31/325<br>PA-31-350<br>PA-31P     | 6/10/77  |                    |             | 2210 6C1    |
| 560    | Flap Condition. Asymmetric,<br>Recommended Operating Procedure                                                                | PA-31/300/325<br>PA-31-350<br>PA-31P | 4/4/77   | **                 |             | 2750 6C5    |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                | MODELS<br>AFFECTED                                                    | DATE     | PART/KIT<br>NO.      | A.D.<br>NO.              | ATA<br>CODE      |
|--------|----------------------------------------------------------------------------------------|-----------------------------------------------------------------------|----------|----------------------|--------------------------|------------------|
| 566    | Horizontal Situation Indicator,<br>Modification To Edo-Aire Mitchell<br>NSD-360        | PA-31/325<br>PA-31-350                                                | 10/11/77 | **                   |                          | 3420 6D9         |
| 567    | Flap Solenoid Repositioning                                                            | PA-31/300/325<br>PA-31-350                                            | 6/7/77   |                      | 77-19-06                 | 2750 6D20        |
| 574    | Fuel Crossfeed Control Shaft Security                                                  | PA-31-350                                                             | 7/13/77  | **                   |                          | 2820 6E17        |
| 575    | Inspection of Horizontal, Stabilizer<br>And Vertical Fin Stringer<br>Attachment Rivets | PA-31/325<br>PA-31-350                                                | 8/3/77   | 522-881              | 77-24-01                 | 5510 6E19        |
| 591    | Inspection of Goodyear BTC-39<br>Fuel Cells                                            | PA-31/300<br>PA-31-350<br>PA-31P                                      | 3/22/78  | **                   |                          | 2810 6G13        |
| 592    | Inspection of Fuel Selector<br>Lever Assembly Installation                             | PA-31/325                                                             | 2/16/78  |                      | 78-08-10                 | 2820 6G24        |
| 595    | Elevator Outboard Hinge Bracket<br>Rivets Replacement                                  | PA-31/325<br>PA-31-350                                                | 6/5/78   | 762-575              |                          | 5550 6H4         |
| 604A   | Forward Baggage Door Locking<br>System Modification                                    | PA-31/300/325<br>PA-31-350<br>PA-31P                                  | 6/8/79   | **                   |                          | 5230 6I4         |
| 621    | Elevator Cable Inspection And<br>Cable Guard Installation                              | PA-31-350                                                             | 10/13/78 | 71045-02<br>189-545  | 78-26-11                 | 2730 6K10        |
| 626C   | Elevator Down Spring<br>Inspection/Replacement                                         | PA-31/300<br>PA-31-325<br>PA-31-350                                   | 2/28/97  | **                   | 98-08-18<br>79-01-04     | 2730 6L1         |
| 629    | Landing Gear Hose Assembly<br>Inspection And Replacement                               | PA-31-325<br>PA-31-350                                                | 11/15/78 | 17766-27             |                          | 3230 6L10        |
| 630A   | Collins VIR-350 And VIR-351<br>Navigation Receiver Modification                        | PA-31<br>PA-31-325<br>PA-31-350<br>PA-31P                             | 2/25/80  |                      |                          | 3450 6L14        |
| 636A   | Superseded by SB 1273 and Atlanta ACO AMOC letter dated Jun 10, 2015                   |                                                                       |          |                      | 96-12-12                 |                  |
| 641    | Heater Fuel Drain Hose<br>Modification                                                 | PA-31/300/325<br>PA-31-350                                            | 4/5/79   | **                   |                          | 2140 7B22        |
| 643A   | Oil And Manifold Pressure<br>Tubes Inspection                                          | PA-31<br>PA-31-325<br>PA-31-350                                       | 12/8/80  | 41907-00<br>41913-00 |                          | 7930 7C4<br>7710 |
| 644E   | Turbo-Charger Exhaust Coupling<br>Inspection/Replacement                               | PA-31/31-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 5/9/2012 | **                   | 2014-23-03<br>2013-10-04 | 8123             |
| 645A   | Crossfeed Valve Inspection                                                             | PA-31/31-325<br>PA-31-350                                             | 7/2/79   | **                   |                          | 2820 7C14        |
| 647A   | Outboard Flap Track Inspection<br>Inspection And Reinforcement                         | PA-31<br>PA-31-325<br>PA-31-350<br>PA-31P                             | 11/24/80 | 763-986              | 80-14-06<br>81-23-06     | 2750 7C19        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                           | MODELS<br>AFFECTED                               | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE  |      |
|--------|-------------------------------------------------------------------|--------------------------------------------------|----------|-----------------|-------------|--------------|------|
| 648A   | Part I - Scott Fuel Selector<br>Valve Inspection                  | PA-31<br>PA-31-300<br>PA-31-350<br>PA-31P        | 4/27/87  | 760-504         | 80-18-10    | 7324         | 7C21 |
| 648A   | Part II - Fuel Selector<br>Valve Control Cable Inspection         | PA-31<br>PA-31-300/325<br>PA-31P                 | 4/27/87  | **              |             | 7324         | 7C23 |
| 648A   | Part III - Fuel Selector<br>Valve Control Cable Replacement       | PA-31<br>PA-31-300/325<br>PA-31P                 | 4/27/87  | **              |             | 7324         | 7C24 |
| 649    | Elevator Control Stop Inspection                                  | PA-31/31-300<br>PA-31-325<br>PA-31-350           | 3/29/79  |                 | 79-12-02    | 2730         | 7D1  |
| 651    | Control Shaft Roll Pin<br>Inspection                              | PA-31/31-300<br>PA-31-325<br>PA-31-350<br>PA-31P | 5/11/79  | 480-732         | 79-14-02    | 2710         | 7D6  |
| 653    | Modification of Weight and<br>Balance Plotters                    | PA-31<br>PA-31-325<br>PA-31-350                  | 12/3/79  | Placard**       |             | 800          | 7D11 |
| 654    | Cigar Lighter Installation<br>Modification                        | PA-31<br>PA-31-325<br>PA-31-350                  | 6/23/80  | **              |             | 3310         | 7D13 |
| 658    | Elevator Inspection<br>And Reinforcement                          | PA-31P                                           | 7/31/79  | 763-943         | 80-02-15    | 2730         | 7E5  |
| 659    | Rudder And Aileron Trim<br>Tab Attachment Inspection              | PA-31P                                           | 7/19/79  | 406-829         |             | 2710<br>2720 | 7E7  |
| 664    | Elevator Torque Tube<br>Attachment Inspection                     | PA-31<br>PA-325<br>PA-31-350                     | 12/14/79 | **              |             | 2730         | 7E20 |
| 677    | Publications for Aircraft Operation                               | All Piper<br>Models                              | 5/20/80  |                 |             | PARA         | 7H4  |
| 682    | Main Landing Gear<br>Inboard Door Hinge<br>Inspection/Replacement | PA-31<br>PA-31-325<br>PA-31-350<br>PA-31P        | 7/24/80  | **              | 80-26-05    | 3210         | 7H15 |
| 684    | PA-31-350 Chieftain/Takeoff Flaps                                 | PA-31-350                                        | 4/14/80  | **              | 80-08-05    | 2750         | 7I16 |
| 685    | Elevator Bellcrank<br>Assembly Inspection                         | PA-31<br>PA-31-325<br>PA-31-350                  | 9/23/80  | **              |             | 2730         | 7I18 |
| 688    | Placards Installation Check                                       | PA-31<br>PA-31-325<br>PA-31-350                  | 7/1/80   | Placard**       | 80-17-06    | 1130         | 7I24 |
| 690    | Elevator Balance Weight<br>Inspection                             | PA-31<br>PA-31-325<br>PA-31-350                  | 7/7/80   | **              | 80-17-02    | 2730         | 7J9  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                              | MODELS<br>AFFECTED                                                        | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |      |
|--------|------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|----------|-----------------|-------------|-------------|------|
| 693    | Engine Baffle Seats Inspection/<br>Modification                                                      | PA-31/31-300<br>PA-31-350                                                 | 7/28/80  | **              | 80-20-04    | 7230        | 7J16 |
| 697    | PA-31, PA-31-325 Takeoff Flaps                                                                       | PA-31<br>PA-31-325                                                        | 8/11/80  | **              | 80-21-07    | 2750        | 7K7  |
| 700A   | Nose Wheel Inspection/<br>Replacement                                                                | PA-31<br>PA-31-325<br>PA-31-350<br>PA-31P                                 | 10/12/81 | 551-791         | 97-07-03    | 3240        | 7K14 |
| 704    | Cabin Fan Fuse Installation                                                                          | PA-31<br>PA-31-325<br>PA-31-350                                           | 6/7/82   | **              |             | N/A<br>2120 | 7L1  |
| 705    | Main Landing Gear Door<br>Actuator Fitting                                                           | PA-31P                                                                    | 6/30/81  |                 |             | 3250        | 7L5  |
| 707    | PA-31-350 Chieftain<br>Takeoff Flaps                                                                 | PA-31-350                                                                 | 2/4/81   | 764-101         |             | 2750        | 7L11 |
| 708    | PA-31 and PA-31-325<br>Takeoff Flaps<br>(Refer to SB 697)                                            | PA-31<br>PA-31-325                                                        | 4/7/81   | 764-101         |             | 2750        | 7L16 |
| 737    | Elevator Outboard Hinge<br>Installation Inspection                                                   | PA-31P                                                                    | 4/23/82  | 764-381         |             | 5550        | 8B12 |
| 739    | Restriction of Flap Travel and<br>Inspection of Wing Flap Flexible<br>Drive Shaft                    | PA-31<br>PA-31-325<br>PA-31-350<br>PA-31P                                 | 3/1/82   | **              | 82-27-13    | 2750        | 8D19 |
| 752    | Cigar Lighter Circuit<br>Modification                                                                | PA-31P                                                                    | 10/18/82 | 454-656         |             | 3310        | 8G16 |
| 771A   | Parking Brake Application                                                                            | PA-31P                                                                    | 9/6/2011 | 81090-002       | 85-02-05    | 1130        |      |
| 779B   | Part I - Landing Gear<br>Upper Bearing Retaining<br>Pin Replacement And<br>Strut Assembly Inspection | PA-31/31-300<br>PA-31-325<br>PA-31-350<br>T-1020<br>PA-31P                | 10/12/87 | **              | 85-08-05    | 3200        | 8K1  |
| 797B   | Fuel Port Restrictor<br>Installation                                                                 | PA-31, 31-310<br>PA-31-325<br>PA-31-350<br>T-1020<br>PA-31P-350<br>PA-31P | 9/1/87   | **              | 87-21-01    | 2812        | 9B14 |
| 798    | "TURBO" Marking Removal                                                                              | PA-31, 31-310<br>PA-31-325<br>PA-31-350<br>PA-31P                         | 12/11/84 | N/A             |             | 1110        | 9B19 |
| 802    | Aft Bulkhead (Fuselage Station<br>332 0) Inspection                                                  | PA-31P                                                                    | 12/12/84 | 764-983         | 85-05-01    | 5310        | 9C10 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                                             | MODELS<br>AFFECTED                                                                 | DATE    | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE        |
|--------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|---------|-----------------|-------------|--------------------|
| 805A   | TRW Hartzell Propeller<br>Service Bulletin No 142B<br>(O-ring Deterioration)        | PA-31<br>PA-31-325<br>PA-31-350<br>T-1020<br>PA-31P-350<br>PA-31P                  | 3/14/86 | N/A             |             | 6110 9D15          |
| 822    | Special Inspection<br>of Hydraulic Hose,<br>Piper Part Number<br>17766-02 (465-138) | PA-31-300<br>PA-31-310<br>PA-31-325<br>PA-31-350<br>T-1020<br>PA-31P-350<br>PA-31P | 4/2/86  | 17766-02        | 96-21-04    | 2912 9H3           |
| 825    | Crossover Fuel<br>Line Inspection                                                   | PA-31-300<br>PA-31-310                                                             | 4/8/86  |                 |             | 2823 9H14          |
| 826A   | Elevator Hinge<br>Inspection/Replacement                                            | PA-31P                                                                             | 9/22/86 | 45253 03        |             | 5550 9H17          |
| 829    | Oil Separator<br>Assembly Replacement                                               | PA-31P-350                                                                         | 4/18/86 | 2564-02         |             | 7250 9I9           |
| 836A   | Aluminum Wire<br>Inspection/Replacement                                             | PA-31-300<br>PA-31-310<br>PA-31-325<br>PA-31-350<br>PA-31P                         | 8/26/86 | **              |             | 2400 9J4           |
| 845A   | Main Landing Gear<br>Forward Side Brace<br>Inspection/Replacement                   | PA-31/PA-310/325<br>PA-31-350<br>T1020<br>PA-31P<br>PA-31P-350                     | 10/9/87 |                 | 88-05-05    | 3218 9K16          |
| 855    | Use of Automobile Gasoline in<br>Piper Aircraft                                     | All Piston Powered<br>Models                                                       | 1/14/87 | N/A             |             | 2800 10A7          |
| 859    | Nose Gear Shuttle Valve<br>Bracket Installation                                     | T-1020                                                                             | 3/30/87 | 765-315         |             | 3225 10A18         |
| 860    | Main Landing Gear Downlock<br>Cable Anti-Rotation Stop<br>Replacement               | PA-31-300<br>PA-31-310<br>PA-31-325<br>PA-31-350<br>T-1020<br>PA-31P               | 4/14/87 | **              |             | 3210 10A20         |
| 884    | Lock Wiring of<br>V-Band Couplings                                                  | PA-31<br>PA-31-325<br>PA-31-350<br>T-1020<br>PA-31P<br>PA-31P-350                  | 4/8/88  | **              |             | 7800 10G20<br>2100 |
| 897B   | Elevator Butt Rib Refinement                                                        | PA-31P                                                                             | 7/15/97 | **              |             | 5520 10I21         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                     | MODELS<br>AFFECTED                                                                 | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|----------|-----------------|-------------|-------------|
| 907    | Windshield Heat<br>Fuse Installation                                                                                        | PA-31-300<br>PA-31-310<br>PA-31-325<br>PA-31-350<br>T-1020                         | 4/11/89  | **              |             | 3047 10K15  |
| 923    | Main Landing Gear Actuator<br>Reinforcement Bracket<br>Replacement                                                          | PA-31-300<br>PA-31-310<br>PA-31-325<br>PA-31-350<br>T-1020<br>PA-31P<br>PA-31P-350 | 8/16/89  | 73786-02        | 96-21-11    | 5740 10aB13 |
| 926A   | Hartzell Service Bulletin No. 165E,<br>Inspection for Cracks in Certain<br>Three Blade "Y" Shank Aluminum<br>Propeller Hubs | PA-31<br>PA-31-325<br>PA-31-350<br>PA-31P-350                                      | 3/7/94   | **              | 94-17-13    | 6113 10aC1  |
| 927    | Hartzell Service Bulletin No. 164,<br>Inspection for Cracks in Certain<br>Two Blade "Y" Shank Aluminum<br>Propeller Hubs    | PA-31-300                                                                          | 12/4/89  | **              | 2001-23-08  | 6113 10aC18 |
| 967    | Aileron Hinge Inspection and<br>Replacement                                                                                 | PA-31P                                                                             | 1/24/94  | **              | 96-21-03    | 5750 10aK15 |
| 974    | Aileron Hinge Inspection and<br>Replacement                                                                                 | PA-31<br>PA-31-300<br>PA-31-325<br>PA-31-350<br>PA-31P-350                         | 10/19/94 | **              | 96-21-03    | 5750 10bA1  |
| 991A   | Replacement or Modification of the<br>Alternator Out Light Fuse                                                             | PA-31<br>PA-31-300<br>PA-31-325<br>PA-31-350<br>PA-31-350 T 1020<br>PA-31P         | 1/29/96  | **              |             | 2437 10bD16 |
| 998A   | Elevator Spar Inspection                                                                                                    | PA-31<br>PA-31-300<br>PA-31-325<br>PA-31-350<br>PA-31-350 T 1020<br>PA-31P-350     | 8/4/97   | **              | 99-12-05    | 2730 10bDF1 |
| 1002   | Elevator Down Spring Inspection<br>/Replacement                                                                             | PA-31P                                                                             | 6/5/97   | **              | 98-08-18    | 2739 10bF17 |
| 1003   | Wing Spar Splice Plate Replacement                                                                                          | PA-31<br>PA-31-300<br>PA-31-325<br>PA-31-350<br>PA-31-350 T 1020                   | 6/16/97  | **              | 98-09-25    | 5711 10bF20 |
| 1004   | Inspection of the E303 Electrical<br>Connector and Heater Blower<br>Power Wire                                              | PA-31-350<br>PA-31-350 T 1020                                                      | 6/6/97   | **              |             | 2451 10bF22 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                                                                                              | MODELS<br>AFFECTED                                                                       | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|-----------|-----------------|-------------|-------------|
| 1007   | Horizontal Stabilizer Spar and<br>Outboard Hinge Inspection and<br>Modification                                                      | PA-31<br>PA-31-300<br>PA-31-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P-350           | 9/30/97   | 766-646         | 99-06-01    | 5511 10bG13 |
| 1008   | Elevator Butt Rib Refinement                                                                                                         | PA-31<br>PA-31-300<br>PA-31-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P-350           | 9/30/97   | 766-642         |             | 5521 10bG15 |
| 1026   | Distribution of Parker Hannifin<br>Airborne Service Letter 48,<br>"Inspection/Replacement of dry<br>air pump flexible couplings".    | PA-31-300<br>PA-31-325<br>PA-31-350<br>PA-31-350 T-1020                                  | 11/5/98   | 753-910         |             | 3711 10bJ20 |
| 1035A  | Distribution of Textron Lycoming<br>Service Bulletin 529B, "Reprint of<br>Crane/Lear Romec Service Bulletin<br>No. 101SB020, Rev. 3" | PA-31<br>PA-31-300<br>PA-31-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 3/22/2007 | **              | 2003-14-03  | 7311 10bL16 |
| 1041   | Distribution of Airborne<br>Service Letter Number 56,<br>"Inspection and Cleaning of<br>Airborne Air Filter Elements."               | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350         | 9/25/2000 | **              |             | 3714 10cB1  |
| 1045   | Forward Wing Spar Attach<br>Bracket Inspection                                                                                       | PA-31<br>PA-31-300                                                                       | 9/18/2000 | **              |             | 5741 10cB23 |
| 1105A  | Rudder Torque Tube Assembly<br>Inspection                                                                                            | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350         | 9/22/2003 | 767-349         |             | 2725 10dA22 |
| 1125   | Elevator Trim Wheel Replacement                                                                                                      | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350         | 4/15/2003 | 43751-000       |             | 2733 10dE11 |
| 1134   | Servo Metered Fuel Pressure<br>Port Leakage (Lycoming SB 557;<br>Precision Airmotive SB PRS-105)                                     | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350         | 6/10/2003 | **              |             | 2800 10dG5  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                           | MODELS<br>AFFECTED                                                               | DATE       | PART/KIT<br>NO.                                | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|------------|------------------------------------------------|-------------|-------------|
| 1174   | Lock Assembly Inspection /<br>Modification<br>(Cabin Door, Baggage Doors,<br>Nacelle Locker Door) | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 2/15/2007  | 473-146<br>88406-002                           |             | 5200 10eA13 |
| 1194B  | Nose Baggage Door Components,<br>Periodic Replacement of                                          | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 4/12/2012  | **                                             | 2009-13-06  | 5230        |
| 1233B  | Periodic Replacement of<br>Main Landing Gear Rod Ends                                             | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 6/24/2014  | 762-554<br>758-440                             |             | 3210        |
| 1246   | Emergency Exit Window<br>Inspection                                                               | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020                         | 10/29/2012 | 41307-000<br>41307-003<br>53181-000<br>453-694 |             | 5220        |
| 1257A  | Fuel Hose Inspection                                                                              | PA-31-350<br>PA-31-350 T-1020                                                    | 8/4/2015   | 39995-034<br>LW-18302                          |             | 7310        |
| 1260A  | Front Spar Attachment Bulkhead<br>Inspection                                                      | PA-31-350<br>PA-31-350 T-1020                                                    | 5/12/2020  | 88614-701<br>44758-000<br>44758-001            |             | 5312        |
| 1266   | Fuel Warning Placard<br>and POH Inspection                                                        | PA-31<br>PA-31-300<br>PA-31P                                                     | 12/16/2014 | **                                             | 2015-24-05  | 1130        |
| 1273C  | Bulkhead Modification at FS 317.75                                                                | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020                         | 11/9/2022  | 764-028                                        | 2016-05-01  | 5300        |
| 1286A  | Lycoming SB 621A,<br>Diaphragm-Type Fuel Pump<br>Replacement                                      | PA-31-300                                                                        | 10/30/2015 | N/A                                            |             | 7310        |
| 1289A  | Bulkhead Inspection,<br>Fuselage Station 332.00                                                   | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020                         | 10/26/2016 | 88578-001                                      |             | 5312        |
| 1295   | Nose Baggage Door Lock Inspection                                                                 | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 3/24/2017  | 88409-002                                      | 2009-13-06  | 5230        |
| 1297   | Altimeter Inspection and<br>Replacement (United Instruments<br>SB No. 13)                         | All                                                                              | 5/10/2016  | N/A                                            |             | 3416        |
| 1301   | Wiring Inspection                                                                                 | PA-31P-350                                                                       | 1/6/2017   | N/A                                            |             | 2497        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

PA-31T/31T1  
PA-31T2/31T3  
PA-42

| NUMBER | SUBJECT                                                                                       | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE                              |
|--------|-----------------------------------------------------------------------------------------------|--------------------|----------|--------------------|-------------|------------------------------------------|
| 440    | Refinement Modifications, Cheyenne                                                            | PA-31T             | 12/17/74 | **                 |             | 2750 5A9<br>6110<br>3420<br>2150<br>6140 |
| 446A   | Cable Replacement, Rudder/Nose<br>Gear Steering                                               | PA-31T             | 7/8/75   | 760-923            | 75-16-02    | 2720 5A23<br>3250                        |
| 453A   | Scoop Modification, Engine Air Inlet                                                          | PA-31T             | 4/7/75   | 760-942            |             | 7160 5B18                                |
| 456A   | Warning Placard Replacement                                                                   | PA-31T             | 5/28/75  | **                 |             | 2840 5B24                                |
| 459    | Servo Cable Clamp Replacement,<br>Aileron And Rudder, M-4D<br>Automatic Flight Control System | PA-31T             | 4/22/75  | 33078-03           |             | 2210 5C6                                 |
| 465    | Fuel Vent Line, Inspection of                                                                 | PA-31T             | 5/21/75  |                    |             | 2810 5C20                                |
| 466    | Air Conditioning System Modification                                                          | PA-31T             | 6/2/75   | 760-979            |             | 2150 5C22                                |
| 468    | Elevator Trim Tab Attachment<br>Hinges And Screw Assembly,<br>Inspection of                   | PA-31T             | 5/9/75   | **                 |             | 5550 5D2                                 |
| 476    | Elevator Trim Control Cable<br>Turnbuckles, Inspection of                                     | PA-31T             | 10/9/75  | 454-867            |             | 2730 5E4                                 |
| 477A   | Elevator Control Tube And Trim<br>Tab System Modification                                     | PA-31T             | 11/3/75  | 760-989            | 76-03-01    | 2730 5E6                                 |
| 481A   | Elevator Assembly Inspection And<br>Elevator Butt Rib Replacement                             | PA-31T             | 11/3/75  | **                 | 76-03-01    | 5520 5E14                                |
| 484    | Starter Generator System Modification                                                         | PA-31T             | 12/5/75  | 761-019            |             | 8010 5E24                                |
| 487    | Control Shaft Collar Attachment<br>Modification                                               | PA-31T             | 11/7/75  | 401-264<br>407-584 | 76-04-11    | 2710 5F7                                 |
| 488    | Landing Gear Selector Cable Forward<br>Attachment Pin, Modification of                        | PA-31T             | 10/24/75 | **                 | 96-24-13    | 3200 5F10                                |
| 494B   | Flap Control System, Inspection of                                                            | PA-31T             | 7/17/79  | **                 | 82-27-13    | 2750 5G6                                 |
| 504    | Elevator Hinge System Modification                                                            | PA-31T             | 6/1/76   | 761-056            | 76-18-06    | 5550 5H8                                 |
| 511A   | Oxygen System Outlet Refinement                                                               | PA-31T             | 9/24/76  | 761-032<br>752-583 |             | 3510 5I3                                 |
| 515    | Control Cable Ball Joint<br>Retainer Installation                                             | PA-31T             | 1/17/77  | 55447-02           |             | 7610 5I10                                |
| 517    | Engine Oil Temperature Gauge<br>Placard Installation                                          | PA-31T             | 10/5/76  | 757-487            |             | 7930 5I17                                |
| 523    | Cigar Lighter Element Replacement,<br>24 Volt                                                 | PA-31T             | 10/8/76  | 55674-02           |             | 3310 5J7                                 |
| 525    | Seat Latch Mechanism<br>Modification, Pilot/Copilot                                           | PA-31T             | 11/15/76 | 55842-02           |             | 5340 5J12                                |
| 526A   | Microphone And Phone Jack Relay<br>Modification, Pilot/Copilot                                | PA-31T             | 11/30/76 | 48757-02           | 77-08-02    | 2350 5J15                                |
| 546    | Whelen Wing Tip Lights,<br>Reference FAA Airworthiness<br>Directive, Inspection of            | PA-31T             | 5/18/77  | **                 |             | 3340 6A16                                |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                       | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------------------------------------------------|--------------------|----------|--------------------|-------------|-------------|
| 558    | Servo Bridle Cable Clamp Bolt<br>Torque Revision; Altimatic V And<br>V F/D Series; M-4D F/D Series;<br>And Sperry SPZ-200 F/D | PA-31T             | 6/10/77  |                    |             | 2210 6C1    |
| 560    | Flap Condition, Asymmetric,<br>Recommended Operating Procedure                                                                | PA-31T             | 4/4/77   | **                 |             | 2750 6C5    |
| 562    | Annunciator Panel Oil Temperature<br>Indicator System Modification                                                            | PA-31T             | 10/4/77  | **                 |             | 3310 6C10   |
| 568    | Nose Wheel Replacement<br>(High Flotation Tire Option)                                                                        | PA-31T             | 4/26/77  | 45520-07           |             | 3240 6E1    |
| 570A   | Inspection of Main Landing Gear<br>Actuating Cylinder Rod End<br>Bearing Assy.                                                | PA-31T             | 8/30/78  | 762-554            | 78-02-01    | 3230 6E3    |
| 572    | Pilot's Operating Manual/Pilot's<br>Operating Handbook Revision                                                               | PA-31T             | 6/9/77   | **                 |             | 800 6E12    |
| 585    | Air Control Cable Stand-off<br>Installation                                                                                   | PA-31T             | 3/9/78   | 763-821            |             | 2130 6F22   |
| 588    | Pilot's Operating Manual (POM) /<br>Pilot's Operating Handbook (POH)<br>Revision, Flap Selector Operation                     | PA-31T             | 11/24/78 | **                 |             | 2750 6G7    |
| 589B   | Inspection of Turn And Bank<br>Suction System Check Value/<br>Vacuum System Modification                                      | PA-31T             | 9/25/79  | **                 |             | 3420 6G8    |
| 591    | Inspection of Goodyear BTC-39<br>Fuel Cells                                                                                   | PA-31T             | 3/22/78  | **                 |             | 2810 6G13   |
| 594A   | Modification of Left And Right<br>Circuit Protector Mounting<br>Board Installation                                            | PA-31T/31T1        | 7/7/78   | 763-873            |             | 3910 6H2    |
| 598A   | Inspection of Main Landing<br>Gear Brake Discs (Cleveland)                                                                    | PA-31T             | 6/13/78  | 754-618<br>754-626 |             | 3240 6H12   |
| 599A   | Replacement of Cleveland High<br>Flotation Nose Wheel Assembly                                                                | PA-31T<br>PA-31T1  | 10/4/78  | 551-782            |             | 3240 6H14   |
| 604A   | Forward Baggage Door Locking<br>System Modification                                                                           | PA-31T             | 6/8/79   | **                 |             | 5230 6I4    |
| 629    | Landing Gear Hose Assembly<br>Inspection And Replacement                                                                      | PA-31T<br>PA-31T1  | 11/15/78 | 17766-27           |             | 3230 6L10   |
| 630A   | Collins VIR-305 And VIR-351<br>Navigation Receiver Modification                                                               | PA-31T<br>PA-31T1  | 2/25/80  |                    |             | 3410 6L14   |
| 640    | Electroluminescent<br>Panel Inverter Replacement<br>And/Or Relocation                                                         | PA-31T<br>PA-31T1  | 6/22/79  | 763-929<br>763-944 | 79-19-09    | 3910 7B20   |
| 647A   | Outboard Flap Track<br>Inspection and Modification                                                                            | PA-31T<br>PA-31T1  | 11/24/80 | 763-986            | 81-23-06    | 2750 7C19   |
| 651    | Control Shaft Roll Pin<br>Inspection                                                                                          | PA-31T<br>PA-31T1  | 5/11/79  | 480-732            | 79-14-02    | 2710 7D6    |
| 658    | Elevator Inspection<br>And Reinforcement                                                                                      | PA-31T<br>PA-31T1  | 7/31/79  | 763-943            | 80-02-15    | 2730 7E5    |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-31T/31T1  
PA-31T2/31T3  
PA-42

| NUMBER | SUBJECT                                                           | MODELS<br>AFFECTED           | DATE     | PART/KIT<br>NO.     | A.D.<br>NO.        | ATA<br>CODE      |
|--------|-------------------------------------------------------------------|------------------------------|----------|---------------------|--------------------|------------------|
| 659    | Rudder And Aileron Trim<br>Tab Attachment Inspection              | PA-31T<br>PA-31T1            | 7/19/79  | 406-829             |                    | 2710 7E7<br>2720 |
| 660    | Gyro Inverter Power<br>Selector Switch Guard<br>Installation      | PA-31T1                      | 9/26/79  | 29321-02            |                    | 3940 7E9         |
| 665A   | Throttle Control Ball Joint<br>Connector and Rod End              | PA-31T<br>PA-31T1            | 5/30/80  | **                  |                    | 7320 7E23        |
| 674    | Rudder Trim Mechanism Modification<br>And Trim Tab Rigging        | PA-31T<br>PA-31T1            | 1/23/80  | **                  |                    | 2720 7G13        |
| 677    | Publications for Aircraft Operation                               | All Piper<br>Models          | 5/20/80  |                     |                    | PARA 7H4<br>15.0 |
| 680    | Ground Clearance Switch<br>Fuse Installation                      | PA-31T<br>PA-31T1            | 4/23/80  | **                  |                    | 3450 7H7         |
| 682    | Main Landing Gear<br>Inboard Door Hinge<br>Inspection/Replacement | PA-31T<br>PA-31T1            | 7/24/80  | **                  | -25-01<br>80-26-05 | 3210 7H15        |
| 692    | Oxygen Mask<br>Replacement                                        | PA-31T                       | 8/6/80   | 474-108             |                    | 3510 7J14        |
| 704    | Cabin Fan Fuse Installation                                       | PA-31T2<br>PA- 42            | 6/7/82   | **                  |                    | 2120 7L1         |
| 705    | Main Landing Gear Door<br>Actuator Fitting                        | PA-31T<br>PA-31T1            | 6/30/81  |                     |                    | 3250 7L5         |
| 715A   | Elevator Control Tube Inspection                                  | PA-31T<br>PA-31T1<br>PA-31T2 | 4/25/83  | **                  |                    | 2730 8A15        |
| 722    | Avionics Cooling Fan Inspection/<br>Replacement                   | PA-31T<br>PA-31T1            | 4/16/82  | 764-375             |                    | 2300 8B14        |
| 726    | Razor Inverter Wiring Inspection                                  | PA-42                        | 7/21/81  |                     |                    | 3320 8C11        |
| 727    | Powerplant Firewall Inspection                                    | PA-42                        | 7/21/81  | 411-583<br>404-559  |                    | 5410 8C13        |
| 728    | Hydraulic Pump Replacement                                        | PA-42                        | 9/17/82  | **                  |                    | 2910 8C15        |
| 731    | Heater Air Distribution Box Thermal<br>Switch Installation        | PA-31T<br>PA-31T1            | 3/17/82  | 764-227<br>764-228  |                    | 2140 8C21        |
| 733    | Emergency Exit Window Installation                                | PA-31T<br>PA-31T1<br>PA-31T2 | 1/25/82  | 189-743             | 82-11-04           | 5630 8D3         |
| 734    | Fuel Scavenge Pump Check<br>Valves Relocation                     | PA-31T<br>PA-31T1<br>PA-31T2 | 12/11/81 |                     |                    | 2820 8D6         |
| 736    | Nacelle Fuel Tank Check<br>Valve Installation                     | PA-42                        | 12/17/82 | 492-233<br>57761-06 |                    | 2820 8D10        |
| 740    | Ice Vane and Control Circuit<br>Breaker Replacement               | PA-42                        | 4/15/83  | 454-722             |                    | 3020 8E18        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                              | MODELS<br>AFFECTED                      | DATE      | PART/KIT<br>NO.    | A.D.<br>NO.     | ATA<br>CODE |
|--------|------------------------------------------------------------------------------------------------------|-----------------------------------------|-----------|--------------------|-----------------|-------------|
| 741    | Part I - Wing Flap Travel Restriction<br>and Inspection of Wing Flap<br>Flexible Drive Shaft         | PA-31T                                  | 3/1/82    | **                 |                 | 2750        |
| 741    | Part II - Wing Flap Operating<br>Procedures                                                          | PA-31T<br>PA-31T1                       | 3/1/82    | **                 |                 | 2750        |
| 742    | Engine Oil Hose and Fitting<br>Replacement                                                           | PA-42                                   | 10/12/82  | 764-407            |                 | 7920        |
| 754    | Air Conditioning Condenser<br>Fan Impeller Replacement                                               | PA-31T<br>PA-31T1                       | 2/14/83   | 460-102<br>506-501 |                 | 2100        |
| 764    | Pilot's Side Window<br>Inspection                                                                    | PA-42                                   | 7/27/83   | **                 |                 | 5610        |
| 765    | Rivet Installation/Replacement,<br>Tail Fin Fuselage                                                 | PA-42                                   | 7/11/83   | **                 |                 | 5530        |
| 766A   | Main Landing Gear<br>Slotted Up Lock Hook<br>Brackets Replacement                                    | PA-31T2<br>PA-31T3                      | 8/15/2017 | 40616              |                 | 3210        |
| 767    | Cleveland 40-106 Main Landing<br>Gear Wheels Replacement                                             | PA-31T<br>PA-31T1                       | 10/25/83  | 551-775            |                 | 3240        |
| 768A   | Main Landing Gear Pivot<br>Shaft Assy Bolts<br>Inspection/Replacement                                | PA-42<br>PA-42-720<br>PA-42-1000        | 5/24/85   | **                 |                 | 3210        |
| 773A   | Bulkhead (Fuselage Station<br>332.0) Inspection                                                      | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3 | 5/3/84    | **                 | 96-10-13        | 5310        |
| 776A   | Part I - Fuel Quantity Placards<br>Replacement                                                       | PA-31T/T1<br>PA-31T2                    | 2/16/88   | **                 |                 | 1100        |
| 776A   | Part II-Weight And Balance<br>Plotter Replacement                                                    | PA-31T/T1<br>PA-31T2                    | 2/16/88   | **                 |                 | 1100        |
| 777    | Fuel Quantity Placards                                                                               | PA-42                                   | 3/19/84   | **                 |                 | 1100        |
| 778    | Aileron Trim Tab Control Tube<br>& Rudder Cable Retainer Hardware<br>Inspection                      | PA-42                                   | 4/24/84   | **                 |                 | 2700        |
| 779B   | Part I - Landing Gear<br>Upper Bearing Retaining Pin<br>Replacement And Strut<br>Assembly Inspection | PA-31T/T1<br>PA-31T2/T3<br>PA-42        | 10/12/87  | **                 | 85-08-05<br>N/A | 3200        |
| 779B   | Part II - Landing Gear<br>Upper Bearing And Strut<br>Assembly Inspection                             | PA-42                                   | 10/12/87  | **                 |                 | 3200        |
| 785    | Inline Fuel Filter Mod -<br>Janitrol                                                                 | PA-42<br>PA-42-720                      | 7/19/84   | **                 |                 | 7312        |
| 788    | Avionics (Copilot) Bus Lead<br>Hardware Replacement                                                  | PA-42<br>PA-42-720                      | 7/19/84   | **                 |                 | 2457        |
| 795A   | Electrical Connector<br>Improvement                                                                  | PA-31T/T1<br>PA-31T2                    | 4/29/85   | **                 |                 | 2430        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-31T/31T1  
PA-31T2/31T3  
PA-42

| NUMBER | SUBJECT                                                                             | MODELS<br>AFFECTED                            | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------|-----------------------------------------------|-----------|-----------------|-------------|-------------|
| 806    | Revision of Airspeed<br>Markings Due To Position<br>Error Change                    | PA-42-720                                     | 7/1/85    | 765-181         |             | 3412 9E1    |
| 807    | Flow Strip Position<br>Inspection                                                   | PA-42<br>PA-42-720                            | 6/19/85   | N/A             |             | 5721 9E4    |
| 812    | Rudder Stop Inspection<br>And Replacement                                           | PA-42-1000                                    | 11/4/85   | 75695-05        |             | 2720 9F11   |
| 814    | Generator Control Unit<br>Sleeve Installation                                       | PA-42-1000                                    | 3/14/86   | 765-190         |             | 2430 9F18   |
| 816C   | Ignition Select<br>Mode During<br>Approach and Landing                              | PA-42-1000                                    | 3/28/89   | 765-306         | 86-21-10    | 7428 9G1    |
| 817D   | Main Landing Gear<br>Forward Side Brace<br>Inspection/Replacement                   | PA-42-1000                                    | 1/15/2015 | **              |             | 3218        |
| 821A   | Special Inspection of<br>Fuel Quantity Probes                                       | PA-31T/PA-31T1<br>PA-31T2/PA-31T3             | 5/14/86   | **              |             | 2842 9G23   |
| 822    | Special Inspection<br>of Hydraulic Hose,<br>Piper Part Number<br>17766-02 (465-138) | PA-31T/T1/T2<br>PA-31T3<br>PA-42<br>PA-42-720 | 4/2/86    | 17766-02        | 96-21-04    | 2912 9H3    |
| 823    | Engine Control<br>Cables Modification                                               | PA-42-1000                                    | 3/19/86   | 765-195         |             | 7324 9H6    |
| 826A   | Elevator Hinge<br>Inspection/Replacement                                            | PA-31T/31T1<br>PA-31T2/31T3                   | 9/22/86   | 45253-03        |             | 5550 9H17   |
| 831    | Ice Deflector<br>Vane Modification                                                  | PA-31T1<br>PA-31T3                            | 4/18/86   | 765-156         |             | 7250 9I16   |
| 835    | Wing - Nose Rib,<br>Station 0.50, Modification<br>And Wire Harness<br>Inspection    | PA-42-1000                                    | 5/15/86   | 765-305         |             | 5712 9J1    |
| 836A   | Aluminum Wire<br>Inspection/Replacement                                             | PA-31T/T1                                     | 8/26/86   | **              |             | 2400 9J4    |
| 838    | Fuel Vent System<br>Installation-Wing<br>Panel Modification                         | PA-42-1000                                    | 6/23/86   | 765-192         |             | 2814 9J11   |
| 841A   | Main Landing Gear,<br>Forward Side Brace<br>Inspection/Replacement                  | PA-31T3<br>PA-42<br>PA-42-720/720R            | 10/8/87   | **              |             | 3218 9J19   |
| 842    | Rudder Trailing<br>Edge Rework                                                      | PA-42-1000                                    | 6/23/86   | 765-200         |             | 5523 9K1    |
| 843    | Part I - Garrett Service Bulletin<br>No TPE331-72-7029                              | PA-42-1000                                    | 3/27/87   | **              |             | 7201 9K4    |
| 843    | Part II - Starter/Generator Bracket<br>Retrofit Installation                        | PA-42-1000                                    | 3/27/87   | **              |             | 7201 9K4    |
| 844    | Stick Pusher Relay<br>Box Modification                                              | PA-42-1000                                    | 7/28/86   | 765-307         |             | 2201 9K12   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                  | MODELS<br>AFFECTED                             | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |       |
|--------|----------------------------------------------------------------------------------------------------------|------------------------------------------------|----------|--------------------|-------------|-------------|-------|
| 845A   | Main Landing Gear<br>Forward Side Brace<br>Inspection/Replacement                                        | PA-31T/31T1<br>PA-31T2                         | 10/9/87  | **                 | 96-10-14    | 3218        | 9K16  |
| 846A   | Wing Tip Tank Vent<br>Line Assembly Inspection<br>(Piper Part Number 75389-02)                           | PA-42-1000                                     | 9/19/86  | **                 | 86-18-10    | 2813        | 9K21  |
| 849    | Improved Brake Piston/Insulator<br>And Pressurized Brake<br>Reservoir Installation                       | PA-42-1000                                     | 10/8/86  | **                 |             | 3243        | 9L5   |
| 850    | Part I - Garrett Service<br>Bulletin No. TPE331-75-7001                                                  | PA-42-1000                                     | 10/8/86  | **                 |             | 7120        | 9L7   |
| 850    | Part II - Left Engine<br>Mount Inspection                                                                | PA-42-1000                                     | 10/8/86  | **                 |             | 7120        | 9L7   |
| 857    | Tailcone Drain Holes, Fuselage<br>Station 332.00                                                         | PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000 | 3/10/87  | N/A                |             | 5305        | 10A12 |
| 859    | Nose Gear Shuttle Valve<br>Bracket Installation                                                          | PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000 | 3/30/87  | 765-315            |             | 3225        | 10A18 |
| 860    | Main Landing Gear Downlock<br>Cable Anti-Rotation<br>Stop Replacement                                    | PA-31T/31T1/31T2<br>PA-31T3<br>PA-42           | 4/14/87  | **                 |             | 3210        | 10A20 |
| 867    | Fuel Quantity Sensor Replacement                                                                         | PA-42-1000                                     | 6/24/87  | 765-335            |             | 2840        | 10C1  |
| 869    | Fire Extinguisher<br>Annunciator Circuit<br>Modification                                                 | PA-42<br>PA-42-720<br>PA-42-1000               | 9/9/87   | **                 |             | 2600        | 10C5  |
| 870    | Lear Siegler Power<br>Equipment Corporation<br>(LSPEC) Service<br>Information Letter<br>No. 23090-004-01 | PA-42-1000                                     | 9/25/87  | **                 |             | 2400        | 10C7  |
| 873    | Part I - Engine Mount<br>Inspection And Barrel<br>Nut Replacement                                        | PA-42-1000                                     | 12/22/87 | **                 |             | 7100        | 10D13 |
| 873    | Part II - Engine Inlet<br>Inspection And Modification                                                    | PA-42-1000                                     | 12/22/87 | **                 |             | 7100        | 10D14 |
| 874    | Nacelle Rework                                                                                           | PA-42-1000                                     | 2/8/88   | 765-320<br>765-334 |             | 5410        | 10E4  |
| 877    | Control Column Chain<br>Inspection                                                                       | PA-42-720<br>PA-42-720R<br>PA-42-1000          | 1/6/88   | 472-684            |             | 2702        | 10F19 |
| 881B   | TPE 331-14 Engine<br>Idle Gear Bearing<br>Replacement                                                    | PA-42-1000                                     | 2/19/88  | **                 |             | 7261        | 10G10 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-31T/31T1  
PA-31T2/31T3  
PA-42

| NUMBER | SUBJECT                                                                           | MODELS<br>AFFECTED                                                            | DATE     | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE        |
|--------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------|----------|----------------------|-------------|--------------------|
| 882    | Outboard Flap Transmission<br>Clearance Inspection/<br>Modification               | PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000                                | 3/8/88   | 89140-02<br>89141-02 |             | 2758 10G14         |
| 884    | Lock Wiring of<br>V-Band Couplings                                                | PA-31T/31T1<br>PA-31T2/31T3<br>PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000 | 4/8/88   | **                   |             | 7800 10G20<br>2100 |
| 885    | Main Landing Gear Actuator<br>Attach Bolt                                         | PA-42-1000                                                                    | 5/4/88   | **                   |             | 3213 10H1          |
| 887    | Elevator Skin/Stringer<br>Inspection/Modification                                 | PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000                                | 6/29/88  | **                   |             | 2730 10H10         |
| 888    | Rudder Pedal Torque<br>Tube Attach Bracket<br>Modification                        | PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000                                | 7/12/88  | **                   |             | 2721 10H13         |
| 889    | Main Landing Gear<br>Uplock Hook Bracket<br>Inspection and Roller<br>Modification | PA-31T1                                                                       | 7/1/88   | 41413-79             |             | 3230 10H17         |
| 897B   | Elevator Butt Rib Refinement                                                      | PA-31T/31T1<br>PA-31T2                                                        | 7/15/97  | **                   |             | 5520 10I21         |
| 911    | Tip Tank Tailcone<br>Attachment Improvement                                       | PA-42-1000                                                                    | 5/30/89  | 765-379              |             | 5722 10L9          |
| 912    | Rework of Plug -<br>Main Landing Gear<br>Oleo Tube                                | PA-42-1000                                                                    | 6/9/89   | **                   |             | 3212 10L11         |
| 914    | Bleed Air Hose<br>Replacement                                                     | PA-42<br>PA-42-720<br>PA-42-720R                                              | 7/12/89  | **                   |             | 2181 10aA1         |
| 922    | Main Landing Gear<br>Actuator Attach Bracket<br>Replacement                       | PA-42<br>PA-42-720<br>PA-42-720R                                              | 8/16/89  | 765-372              |             | 5740 10aB11        |
| 923    | Main Landing Gear<br>Actuator Reinforcement<br>Bracket Replacement                | PA-31T<br>PA-31T1/31T2<br>PA-31T3                                             | 8/16/89  | 73786-02             | 96-21-11    | 5740 10aB13        |
| 925    | Addition of Check Valve To<br>Motive Flow Supply Line                             | PA-42<br>PA-42-720<br>PA-42-720R                                              | 11/13/89 | **                   |             | 2823 10aB20        |
| 929A   | Main Landing Gear Upper Strut<br>Housing Inspection                               | PA-42-1000                                                                    | 8/9/94   | 75215-04             |             | 3211 10aD3         |
| 931    | Elevator Trim Wheel Shaft Roll<br>Pin Safety Wire Installation                    | PA-42-720<br>PA-42-720R<br>PA-42-1000                                         | 1/9/90   | **                   |             | 2733 10aD13        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                       | MODELS<br>AFFECTED                                                                        | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------|-----------------|-------------|-------------|
| 945    | Cheyenne Rudder Torque Tube Assembly                                                                          | PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000                                            | 10/19/90  | **              |             | 5541 10aG8  |
| 954    | Instrument Static Line Installation                                                                           | PA-31T/31T1<br>PA-31T2//31T3                                                              | 3/3/92    | **              |             | 3410 10aH20 |
| 957    | Engine Fuel Pump Overboard Drain Line Installation                                                            | PA-42<br>PA-42-720<br>PA-42-720R                                                          | 2/24/92   | 766-257         |             | 2820 10aI9  |
| 967    | Aileron Hinge Inspection and Replacement                                                                      | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000            | 1/24/94   | **              | 96-21-03    | 5750 10aK15 |
| 969A   | Upper Main Gear Housing Inspection and Replacement                                                            | PA-42<br>PA-42-720<br>PA-42-720R                                                          | 5/19/2022 | 57680-09        |             | 3211        |
| 972    | Emergency Exit Window Inspection and Replacement                                                              | PA-42-1000                                                                                | 9/21/94   | **              |             | 5620 10aL10 |
| 974    | Aileron Hinge Inspection and Replacement                                                                      | PA-31T3                                                                                   | 10/19/94  | **              | 96-21-03    | 5750 10bA1  |
| 984    | Inspection and Replacement of Outer Side Windows                                                              | PA-42<br>PA-42-720<br>PA-42-720R                                                          | 7/14/95   | **              |             | 5750 10bC10 |
| 1032   | Elevator Spar Refinement                                                                                      | PA-31T<br>PA-31T1<br>PA-31T2                                                              | 7/15/99   | 766-655         |             | 2730 10bL6  |
| 1041   | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements." | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000 | 9/25/2000 | **              |             | 3714 10cB1  |
| 1047   | Elevator Spar Refinement                                                                                      | PA-31T3 (T1040)                                                                           | 12/4/2000 | 766-655         |             | 2730 10cC6  |
| 1048   | Stainless Steel Control Cables                                                                                | PA-42<br>PA-42-720<br>PA-42-1000                                                          | 1/3/2001  | N/A             |             | 2702 10cC9  |
| 1105A  | Rudder Torque Tube Assembly Inspection                                                                        | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3                                                   | 9/22/2003 | 767-349         |             | 2725 10dA22 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

PA-31T/31T1  
PA-31T2/31T3  
PA-42

| NUMBER | SUBJECT                                                                                           | MODELS<br>AFFECTED                                                                        | DATE      | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------|----------------------|-------------|-------------|
| 1125   | Elevator Trim Wheel Replacement                                                                   | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000 | 4/15/2003 | 43751-000            |             | 2733 10dE11 |
| 1128   | Engine Fuel Valve Inspection<br>(Honeywell OIL OI331-19)                                          | PA-42-1000                                                                                | 2/21/2003 | N/A                  |             | 2800 10dE24 |
| 1174   | Lock Assembly Inspection /<br>Modification<br>(Cabin Door, Baggage Doors,<br>Nacelle Locker Door) | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000 | 2/15/2007 | 473-146<br>88406-002 |             | 5200 10eA13 |
| 1194B  | Nose Baggage Door Components,<br>Periodic Replacement of                                          | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720<br>PA-42-1000               | 4/12/2012 | **                   | 2009-13-06  | 5230        |
| 1233B  | Periodic Replacement of<br>Main Landing Gear Rod Ends                                             | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720<br>PA-42-1000               | 6/24/2014 | 762-554<br>758-440   |             | 3210        |
| 1235   | Data Plate Inspection                                                                             | PA-31T<br>PA-31T1                                                                         | 11/3/2011 | N/A                  |             | 1120        |
| 1248   | Engine Oil Cooler Inlet Hose<br>Inspection                                                        | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3                                                   | 9/5/2012  | 565-484<br>565-936   |             | 7900        |
| 1295   | Nose Baggage Door Lock Inspection                                                                 | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720<br>PA-42-1000               | 3/24/2017 | 88409-002            | 2009-13-06  | 5230        |
| 1297   | Altimeter Inspection and<br>Replacement (United Instruments<br>SB No. 13)                         | All                                                                                       | 5/10/2016 | N/A                  |             | 3416        |
| 1301   | Wiring Inspection                                                                                 | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3                                                   | 1/6/2017  | N/A                  |             | 2497        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-31T/31T1  
PA-31T2/31T3  
PA-42

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE | GRID |
|--------|---------|--------------------|------|-----------------|-------------|-------------|------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.  
\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.  
\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-32 SERIES

| NUMBER | SUBJECT                                                                            | MODELS<br>AFFECTED                                                | DATE      | PART/KIT<br>NO.      | A.D.<br>NO.          | ATA<br>CODE | GRID |
|--------|------------------------------------------------------------------------------------|-------------------------------------------------------------------|-----------|----------------------|----------------------|-------------|------|
| 233    | Brake Disc Assembly, Inspection of                                                 | PA-32-260                                                         | 6/8/66    | 757-039V             |                      | 3240        | 3E2  |
| 237    | Rudder Trim Installation Modification                                              | PA-32-260                                                         | 11/1/66   | 757-085V             |                      | 2720        | 3E9  |
| 239    | Windshield Collars, Inner And<br>Outer, Replacement of                             | PA-32-260                                                         | 12/12/66  | 757-095              |                      | 5610        | 3E11 |
| 240    | Balance Weight Assembly Aileron<br>And Stabilator, Inspection of, For<br>Corrosion | PA-32-260                                                         | 12/13/66  |                      | 67-12-06             | 2710        | 3E12 |
| 244    | Heater Duct Tunnel Modification<br>Cabin                                           | PA-32-260/300                                                     | 2/2/67    | 757-110V             |                      | 2140        | 3E19 |
| 248    | Torque Links, Main Landing Gear                                                    | PA-32-260/300                                                     | 5/12/67   | **                   | 67-20-04<br>70-18-05 | 3210        | 3F2  |
| 249A   | Fuel System Improvement Kit                                                        | PA-32-260/300                                                     | 3/1/68    | 757-139V             | 67-26-02             | 2800        | 3F6  |
| 251D   | Fuel Tank Inspection                                                               | PA-32-260/300<br>PA-32-301/301T<br>PA-32R-300<br>PA-32RT-300/300T | 2/24/2009 | 757-572V             | 67-26-03             | 2810        | 3F10 |
| 252    | Mixture Control Cable, Inspection of                                               | PA-32-300                                                         | 5/15/67   | 65451-05V            |                      | 7320        | 3F12 |
| 253    | Fuel Line Modification, Tip Tank                                                   | PA-32-260/300                                                     | 7/7/67    | 757-151V<br>757-152V | 67-26-02             | 2810        | 3F14 |
| 259    | Storm Window Placard, PA-32-260<br>Cherokee                                        | PA-32-260                                                         | 11/7/67   | 757-314V             |                      | 5610        | 3G2  |
| 260    | Duct, Engine Air Inlet, Replacement<br>of The                                      | PA-32-300                                                         | 11/8/67   | 760-159V             | 67-30-06             | 7160        | 3G4  |
| 261    | Aft Spar Wing Attachment<br>Bolts, Inspection of                                   | PA-32-260/300                                                     | 11/10/67  | 760-162V             |                      | 5710        | 3G5  |
| 275    | Electrical System, Modification<br>of The                                          | PA-32-260/300                                                     | 6/19/68   | **                   |                      | 2400        | 3H8  |
| 279    | Bridle Cable, Servo. Inspection<br>of And Modification To                          | PA-32                                                             | 6/24/68   | **                   |                      | 2210        | 3H16 |
| 281    | Artificial Horizon, R.C. Allen 3",<br>Case Leakage of                              | PA-32-260/300                                                     | 7/10/68   | **                   |                      | 3420        | 3H24 |
| 282    | Mixture Control Cable, Replacement                                                 | PA-32-300                                                         | 8/12/68   | 760-235V             |                      | 7320        | 3I4  |
| 285    | Stop Assembly, Fuel Selector Control                                               | PA-32-260                                                         | 11/22/68  | 760-251V             |                      | 2820        | 3I11 |
| 291    | Flight Manual Revision                                                             | PA-32S-300<br>PA-32-260/300                                       | 3/28/69   | 760-313V             |                      | 3250        | 3J5  |
| 295    | Pin, Retaining, Control Wheel                                                      | PA-32-260 "B"<br>PA-32-300 "B"                                    | 4/30/69   | **                   | 69-15-01             | 2700        | 3J14 |
| 305    | Carburetor Drain Plugs Inspection                                                  | PA-32-260                                                         | 11/25/69  |                      |                      | 7310        | 3K12 |
| 311A   | Selector Valve, Fuel, Modification                                                 | PA-32-260/300<br>PA-32S-300                                       | 4/28/70   | 760-438V             |                      | 2820        | 3L3  |
| 317    | Rib Inspection, Vertical Fin                                                       | PA-32-260/300                                                     | 11/18/70  | 760-451V             |                      | 5530        | 3L14 |
| 321A   | Throttle Knob Roll Pin Retaining Ring                                              | PA-32-260/300                                                     | 11/2/70   | 756-044V             |                      | 7610        | 4A1  |
| 322    | Vacuum Pump Adapter Drive<br>Assembly                                              | PA-32-260/300                                                     | 9/29/70   | 760-477V             |                      | 3710        | 4A3  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                  | MODELS<br>AFFECTED          | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |      |
|--------|------------------------------------------------------------------------------------------|-----------------------------|----------|-----------------|-------------|-------------|------|
| 327    | Stabilator Balance Weight Tube<br>Assembly Inspection                                    | PA-32-260/300<br>PA-32S-300 | 12/9/70  | **              | 70-26-04    | 2740        | 4A16 |
| 329A   | Belt Attachment Modification,<br>Seat                                                    | PA-32-260/300<br>PA-32S-300 | 3/25/71  | 760-515V        | 71-09-05    | 5340        | 4A23 |
| 332    | Switch, Electric Trim, Inspection<br>And Modification                                    | PA-32-260/300               | 4/16/71  | 760-517V        | 72-17-15    | 2730        | 4B7  |
| 337    | Seat Frame Tube Replacement,<br>Vertically Adjustable                                    | PA-32-260/300               | 3/11/71  | **              |             | 2510        | 4B20 |
| 342    | Fuel System Instructions And<br>Modification                                             | PA-32-260/300<br>PA-32S-300 | 9/7/71   | 760-560V        | 77-12-01    | 2800        | 4C6  |
| 350    | Stabilator Hinge Attaching Bolts,<br>Inspection of                                       | PA-32-260/300               | 3/30/72  | **              |             | 5550        | 4D7  |
| 356    | Duct, Induction Air Inlet And<br>Induction Alternate Heat, Inspection<br>And Replacement | PA-32-260/300<br>PA-32S-300 | 9/1/72   | **              |             | 7160        | 4E7  |
| 357A   | Terminal Replacement, Alternator<br>Output Wire                                          | PA-32-260/300               | 11/14/72 | 588-398V        |             | 2420        | 4E9  |
| 360    | Hose System Modification,<br>Air Induction                                               | PA-32-260/300<br>PA-32S-300 | 11/9/72  | **              |             | 7160        | 4E14 |
| 368    | Antenna Protector, Transponder,<br>Installation                                          | PA-32-260/300               | 11/22/72 | 760-697V        |             | 3450        | 4F7  |
| 376    | Fuel Selector Control System<br>Modification                                             | PA-32-260/300<br>PA-32S-300 | 4/19/73  | **              | 77-12-01    | 2820        | 4F18 |
| 387    | Alternator Installation Modification                                                     | PA-32-260/300               | 2/4/74   | 760-742V        |             | 2430        | 4G15 |
| 395    | Rudder Pedal, Warning Improper<br>Use of                                                 | PA-32-260/300               | 11/9/73  | 757-436V        |             | 2720        | 4H9  |
| 403    | Stall Warning Light Relocation                                                           | PA-32-260/300               | 1/29/74  | 760-808V        | 74-09-02    | 2780        | 4I9  |
| 412    | Glove Compartment Modification                                                           | PA-32-260/300               | 4/9/74   | 581-025         |             | 2510        | 4J12 |
| 427    | Air Conditioning System Modification                                                     | PA-32-300                   | 8/9/74   | 760-822V        |             | 2150        | 4K23 |
| 428    | Steering System Modification                                                             | PA-32-260/300               | 7/30/74  | 760-885V        | 74-18-13    | 3250        | 4L1  |
| 444    | Fuel Valve Replacement                                                                   | PA-32-260/300               | 1/15/75  | 760-895V        |             | 2820        | 5A19 |
| 448    | Cable Operation Inspection, Throttle<br>And Mixture Control                              | PA-32-260/300               | 2/19/75  | **              |             | 7320        | 5B4  |
| 449A   | Alternator (Chrysler) Modification And<br>Wire End Terminal Replacement                  | PA-32-260/300               | 5/7/75   | 558-398V        |             | 2430        | 5B8  |
| 463    | Door Forward Baggage, Inspection<br>And Modification                                     | PA-32-260/300               | 4/17/75  | 760-972V        | 75-10-03    | 5230        | 5C14 |
| 469A   | Oil Cooler Assembly Inspection                                                           | PA-32-300                   | 9/5/75   | **              |             | 7920        | 5D4  |
| 475    | Instrument Panel Dimmer Control<br>Assembly Modifications                                | PA-32-260/300               | 7/10/75  |                 |             | 3310        | 5E1  |
| 503A   | Fuel Tank Line Assembly, Inboard,<br>Inspection of                                       | PA-32R-300                  | 10/11/77 | **              | 76-11-09    | 2810        | 5H5  |
| 510B   | Landing Gear, Nose, Trunnion<br>Modification                                             | PA-32R-300                  | 8/31/76  | 761-074V        | 76-15-08    | 3220        | 5I1  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT                                                                                                                  | MODELS<br>AFFECTED                   | DATE     | PART/KIT<br>NO.      | A.D.<br>NO.          | ATA<br>CODE  |      |
|--------|--------------------------------------------------------------------------------------------------------------------------|--------------------------------------|----------|----------------------|----------------------|--------------|------|
| 519A   | Fuel Selector Valve Inspection<br>And Replacement                                                                        | PA-32-260/300<br>PA-32R-300          | 9/2/76   | **                   | 76-18-04             | 2820         | 5I21 |
| 520    | Muffler Shroud Inspection                                                                                                | PA-32-300<br>PA-32R-300              | 10/18/76 | **                   |                      | 7810         | 5I23 |
| 524    | Induction Air Box Bolt Replacement                                                                                       | PA-32-300<br>PA-32R-300              | 2/2/77   | **                   |                      | 7160         | 5J9  |
| 533    | Fuel Gauge Calibration<br>Inspection                                                                                     | PA-32-260/300                        | 1/6/77   | **                   | 77-01-01             | 2840         | 5L8  |
| 537    | Throttle Linkage Bolt Replacement                                                                                        | PA-32-300<br>PA-32R-300              | 1/12/77  | **                   | 80-14-02             | 7610         | 5L17 |
| 538    | Engine Control Cable Inspection                                                                                          | PA-32-260/300<br>PA-32R-300          | 1/14/77  | **                   |                      | 7610         | 5L20 |
| 541    | Throttle Attachment Inspection                                                                                           | PA-32-260                            | 2/15/77  | **                   |                      | 7610         | 6A5  |
| 543    | Starter/Magneto Switch Inspection<br>And Replacement                                                                     | PA-32-260/300<br>PA-32R-300          | 2/9/77   | 757-597V             |                      | 7410         | 6A9  |
| 548    | Engine Control Rod End Bearing<br>Inspection                                                                             | PA-32-260/300<br>PA-32R-300          | 3/7/77   | **                   | 77-23-03             | 7230         | 6A23 |
| 556    | Electric Trim Switch<br>Modification                                                                                     | PA-32-260/300                        | 7/25/77  | 756-047              |                      | 2730         | 6B20 |
| 557    | Fuel Line Modification                                                                                                   | PA-32-260                            | 5/19/77  | 63882-17V            |                      | 2810         | 6B23 |
| 563    | Landing Gear, Nose, Actuator<br>Rod End Bearing Change                                                                   | PA-32R-300                           | 5/13/77  | 452-357V             |                      | 3230         | 6C14 |
| 565    | Horizontal Situation Indicator,<br>Modification To Edo Aire Mitchell;<br>Edo Aire Mitchell Service Bulletin<br>No. MB-13 | PA-32-260/300<br>PA-32R-300          | 6/2/77   | **                   |                      | 3420         | 6C20 |
| 571A   | Fuel Valve Leak Check/Fuel Cap<br>Replacement/Fuel Tank Vent Check/<br>Fuel Line Inspection                              | PA-32-260<br>PA-32-300<br>PA-32S-300 | 10/20/77 | **                   | 77-12-01             | 2810         | 6E5  |
| 580    | Engine Cowling Scoop Drain Hole                                                                                          | PA-32-260                            | 10/19/77 |                      |                      | 7100         | 6F13 |
| 586B   | Engine Oil Coolers (Left and Right),<br>Inspection                                                                       | PA-32R-300<br>PA-32RT-300            | 7/24/78  | 763-859V             | 78-01-03<br>78-16-08 | 7920         |      |
| 593    | Nose Landing Gear Lock Hook<br>Replacement                                                                               | PA-32R-300                           | 6/9/78   |                      |                      | 3230         | 6H1  |
| 616    | Hydraulic Pressure Switch Inspection<br>And Nose Gear Actuator Rod End<br>Bearing Replacement                            | PA-32RT-300<br>PA-32RT-300T          | 5/1/79   |                      |                      | 2930<br>3230 | 6J19 |
| 619    | Control Column Stop Modification                                                                                         | PA-32RT-300<br>PA-32RT-300T          | 9/22/78  | 763-895V             | 78-22-07             | 2710         | 6K4  |
| 622    | Pitch Trim Re-Wiring On<br>Aircraft Equipped With<br>Altimatic IIIC                                                      | PA-32-260/300<br>PA-32R-300          | 9/28/78  | 35669-60<br>35669-61 |                      | 2210         | 6K14 |
| 624    | Loading Limitation Placard And<br>Manual Change                                                                          | PA-32-260/300<br>PA-32S-300          | 5/24/79  | 763-911V             |                      | 800          | 6K19 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                  | MODELS AFFECTED                                                                                                             | DATE     | PART/KIT NO.         | A.D. NO. | ATA CODE     |      |
|--------|--------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|----------|----------------------|----------|--------------|------|
| 630A   | Collins VIR-350 And VIR-351 Navigation Receiver Modification             | PA-32-260/300<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T                                                                  | 2/25/80  |                      |          | 3450         | 6L14 |
| 646A   | Fuel Tank Vent Modification And Vent Hose Replacement                    | PA-32-260/300<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T                                                                  | 3/5/80   | **                   | 80-14-01 | 2810         | 7C17 |
| 652    | Fuel Flow Indicator Line- Replacement                                    | PA-32RT-300T                                                                                                                | 6/15/79  | 67700-348            | 79-13-04 | 7330         | 7D9  |
| 655    | Firewall Reinforcement                                                   | PA-32RT-300T                                                                                                                | 8/27/79  | 763-935V             |          | 5410         | 7D15 |
| 656    | Window Curtain Rod Support Area Inspection                               | PA-32-260/300<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T                                                                  | 9/13/79  | **                   |          | 5520         | 7D17 |
| 657A   | Turbo-Charger Exhaust Coupling And Tailpipe Flange Inspection            | PA-32RT-300T                                                                                                                | 8/14/79  | 556-108              |          | 7810         | 7E1  |
| 669    | Altimatec IIIC Autopilot Trim Servo Cable Alignment Modification         | PA-32-300<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T                                                                      | 1/14/80  | **                   |          | 2210         | 7F10 |
| 675    | Throttle Operation Pre-And Post-Flight Check                             | PA-32RT-300T<br>PA-32R-301T                                                                                                 | 2/19/80  | 67639-013V           |          | 7610         | 7G21 |
| 677    | Publications for Aircraft Operation                                      | All Piper Models                                                                                                            | 5/20/80  |                      |          | PARA 15.0    | 7H4  |
| 681    | Boom Microphone Isolation Relay                                          | PA-32-260<br>PA-32-300<br>PA-32-301<br>PA-32-301T<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301<br>PA-32R-301T | 4/24/80  | 456-703              | 80-14-03 | 2350         | 7H11 |
| 701    | Rudder/Aileron Interconnect Bracket Interference                         | PA-32-301<br>PA-32-301T                                                                                                     | 12/4/80  | 68525-08V<br>419-948 |          | 2720<br>2710 | 7K16 |
| 703    | Aileron Balance Weight Attachment Inspection and Rework                  | PA-32-301<br>PA-32-301T<br>PA-32R-301<br>PA-32R-301T                                                                        | 3/4/81   | 764-091V             |          | 2710         | 7K20 |
| 738    | Nose Landing Gear Actuator Rod End Replacement                           | PA-32R-300<br>PA-32R-301 SP                                                                                                 | 4/20/82  | 452-729V             |          | 3230         | 8D14 |
|        |                                                                          | PA-32R-301T SP<br>PA-32RT-300<br>PA-32RT-300T                                                                               | 4/20/82  | 452-729V             |          | 3230         | 8D15 |
| 738    | Addendum 1 - Nose Landing Gear Actuator Rod End Inspection / Replacement | PA-32R-300<br>PA-32R-301 SP<br>PA-32R-301T SP<br>PA-32RT-300<br>PA-32RT-300T                                                | 11/23/87 | 452-729              |          | 3230         | 8D15 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT                                                                 | MODELS<br>AFFECTED                                                                            | DATE      | PART/KIT<br>NO.       | A.D.<br>NO.      | ATA<br>CODE        |
|--------|-------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|-----------|-----------------------|------------------|--------------------|
| 747    | Nose Landing Gear Actuator Attach Bolt Replacement                      | PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301<br>PA-32R-301T                        | 9/17/82   | 86700-46V<br>402-869V |                  | 3230 8G3           |
| 772    | Fuel Selector Inspection/Replacement                                    | PA-32R-300<br>PA-32-301<br>PA-32-301T<br>PA-32R-301<br>PA-32R-301T                            | 4/6/84    | 69735-05V             |                  | 2820 8J3           |
| 789B   | Aft Inboard Wing Access Panel & Aft Wing Spar Modification              | PA-32-260<br>PA-32-300                                                                        | 12/3/2018 | 764-998V<br>765-106V  | SAIB<br>CE-11-12 | 5711               |
| 798    | "TURBO" Marking Removal                                                 | PA-32RT-300T                                                                                  | 12/11/84  | N/A                   |                  | 1110 9B19          |
| 801    | King Auto Pilot Servo Bridle Clamp Installation                         | PA-32-301/301T<br>PA-32R-301/301T                                                             | 12/11/84  | **                    |                  | 2200 9C6           |
| 804    | Battery Strap Installation                                              | PA-32-301T                                                                                    | 4/26/85   | 765-157               |                  | 2430 9D12          |
| 805A   | TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration) | PA-32-260<br>PA-32-300<br>PA-32-301/301T<br>PA-32R-300<br>PA-32RT-300/300T<br>PA-32R-301/301T | 3/14/86   | N/A                   |                  | 6110 9D15          |
| 811A   | Ammeter Replacement                                                     | PA-32-260<br>PA-32-300<br>PA-32R-300<br>PA-32RT-300/300T<br>PA-32-301/301T<br>PA-32R-301/301T | 5/12/86   | **                    | 86-17-01         | 2430 9F4           |
| 836A   | Aluminum Wire Inspection/Replacement                                    | PA-32-301T                                                                                    | 8/26/86   | **                    |                  | 2400 9J4           |
| 855    | Use of Automobile Gasoline in Piper Aircraft                            | All Piston Powered Models                                                                     | 1/14/87   | N/A                   |                  | 2800 10A7          |
| 856    | Stabilator Attach Fitting Corrosion Inspection                          | PA-32-260<br>PA-32-300<br>PA-32-301/301T<br>PA-32R-300<br>PA-32R-301/301T                     | 2/17/87   | **                    |                  | 5550 10A9          |
| 866A   | Part I - Back Up Landing Gear Extender Removal                          | PA-32R-300<br>PA-32RT-300/300T<br>PA-32R-301/301T                                             | 3/4/88    | 765-199               |                  | 3236 10B22         |
| 866A   | Part II - Alternate means of Compliance                                 | PA-32R-300<br>PA-32RT-300/300T<br>PA-32R-301/301T                                             | 3/4/88    | N/A                   |                  | 3236 10B22         |
| 884    | Lock Wiring of V-Band Couplings                                         | PA-32-301T<br>PA-32R-301T<br>PA-32RT-300T                                                     | 4/8/88    | **                    |                  | 7800 10G20<br>2100 |
| 886    | Wing Spar Inspection                                                    | PA-32-260/300                                                                                 | 6/8/88    | **                    |                  | 5711 10H3          |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                     | MODELS<br>AFFECTED                                                                                                          | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|----------|--------------------|-------------|-------------|
| 896    | Shoulder Harness<br>Installation & Usage                                                                                    | PA-32-260/300<br>PA-32-301/301T<br>PA-32R-300<br>PA-32RT-300/300T<br>PA-32R-301/301T                                        | 11/28/88 | **                 |             | 5340 10I13  |
| 904    | Textron Lycoming<br>Service Bulletin<br>No. 484                                                                             | PA-32-301T<br>PA-32RT-300T<br>PA-32R-301T                                                                                   | 3/20/89  | **                 |             | 7821 10K1   |
| 906    | Oildyne Hydraulic<br>Pump Replacement                                                                                       | PA-32R-301<br>PA-32R-301T                                                                                                   | 4/10/89  | **                 |             | 2911 10K12  |
| 926A   | Hartzell Service Bulletin No. 165E,<br>Inspection for Cracks in Certain<br>Three Blade "Y" Shank Aluminum<br>Propeller Hubs | PA-32-301T<br>PA-32R-301T                                                                                                   | 3/7/94   | **                 | 94-17-13    | 6113 10aC1  |
| 927    | Hartzell Service Bulletin No. 164,<br>Inspection for Cracks in Certain<br>Two Blade "Y" Shank Aluminum<br>Propeller Hubs    | PA-32-300<br>PA-32S-300<br>PA-32R-300<br>PA-32RT-300/300T<br>PA-32-301/301T<br>PA-32R-301/301T                              | 12/4/89  | **                 | 2001-23-08  | 6113 10aC18 |
| 933A   | Trunnion Replacement                                                                                                        | PA-32R-301                                                                                                                  | 2/20/90  | 67054-03           |             | 3222 10aD21 |
| 938    | Wire Protection                                                                                                             | PA-32R-301<br>PA-32R-301T                                                                                                   | 6/12/90  | 189-531<br>488-698 |             | 3262 10aE15 |
| 946    | Forward Left Fuselage Frame<br>Inspection and Replacement                                                                   | PA-32R-300<br>PA-32RT-300<br><br>PA-32RT-300T<br>PA-32R-301<br>PA-32R-301T                                                  | 3/4/91   | 766-244            |             | 5311 10aG11 |
| 952    | Textron Lycoming Service Bulletin<br>No. 499 "Installation of One-Piece<br>Exhaust Pipe"                                    | PA-32RT-300T<br>PA-32-301T<br>PA-32R-301T                                                                                   | 5/9/91   | **                 |             | 7821 10aH11 |
| 955    | Engine Mount and Nose Landing<br>Gear Attachment                                                                            | PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301<br>PA-32R-301T                                                      | 3/3/92   | 766-252<br>766-253 | 93-05-10    | 7120 10aH23 |
| 965    | Inspection of Flap Lever and Bolt                                                                                           | PA-32-260<br>PA-32-300<br>PA-32-301<br>PA-32-301T<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301<br>PA-32R-301T | 9/1/93   | **                 |             | 2750 10aJ22 |
| 968    | Exhaust System Hardware and<br>Gasket Replacement                                                                           | PA-32R-301                                                                                                                  | 3/11/94  | **                 |             | 7810 10aK21 |
| 970    | Defrost System Modification                                                                                                 | PA-32R-301                                                                                                                  | 4/18/94  | **                 |             | 7810 10aL2  |
| 971    | Exhaust System Inspection<br>and Replacement                                                                                | PA-32R-301                                                                                                                  | 9/2/94   | **                 |             | 7810 10aL5  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT                                                                         | MODELS AFFECTED                                                                                                                                                         | DATE     | PART/KIT NO.           | A.D. NO.         | ATA CODE    |
|--------|---------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------------|------------------|-------------|
| 973    | Engine Lower Cowling Modification                                               | PA-32R-301                                                                                                                                                              | 9/30/94  | **                     |                  | 7810 10aL19 |
| 977    | Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels | PA-32-260<br>PA-32-300<br>PA-32-301<br>PA-32-301T<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301<br>PA-32R-301T                                             | 12/12/94 | **                     | SAIB<br>CE-11-12 | 5740 10bA12 |
| 986    | Inspection for Proper Orientation of Battery Vent Tube Assembly                 | PA-32R-301 II HP                                                                                                                                                        | 9/6/95   |                        |                  | 2430 10bC22 |
| 990    | Pacific Scientific Seat Belt Replacement                                        | PA-32R-301 II HP                                                                                                                                                        | 1/3/96   | **                     |                  | 5346 10bD12 |
| 993    | KLN-90B GPS Wiring Modification                                                 | PA-32R-301                                                                                                                                                              | 3/18/96  | **                     |                  | 3441 10bE4  |
| 996    | Missing Rivet in Upper Door Frame, Forward and Aft                              | PA-32R-301 II HP                                                                                                                                                        | 9/17/96  | **                     |                  | 5311 10bE16 |
| 1005   | Addition of Drain Holes to the Engine Induction Air Inlet Scoops                | PA-32R-301 II HP                                                                                                                                                        | 8/11/97  |                        |                  | 7162 10BG4  |
| 1006   | Corrosion Inspection of Main Spar Behind Fuel Tanks                             | PA-32-260<br>PA-32-300<br>PA-32-301<br>PA-32-301T<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T<br>PA-32R-301T II TC | 8/15/97  | **                     | SAIB<br>CE-11-12 | 530 10bG4   |
| 1009   | Replacement of the Engine Induction Air Inlet Elbow at the Fuel Injector Servo  | PA-32R-301 II HP                                                                                                                                                        | 10/6/97  | **                     |                  | 7161 10bG18 |
| 1015A  | Replacement of the Ammeter Shunt Wire Fuse Assemblies                           | PA-32R-301 II HP                                                                                                                                                        | 6/11/98  | 101166-10<br>101166-11 |                  | 2434 10bH14 |
| 1018A  | Product Improvement, Winterization Plate Kit(Revised)                           | PA-32R-301T II TC                                                                                                                                                       | 6/7/99   | 766-653                |                  | 7921 10bI2  |
| 1020   | Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket                    | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                   | 7/10/98  | 758-696                |                  | 2563 10bI11 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                    | MODELS<br>AFFECTED                                                                                                                                           | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE     |
|--------|----------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|-------------|-----------------|
| 1022   | Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01                             | PA-32-260<br>PA-32-300<br>PA-32-301<br>PA-32R-300<br>PA-32RT-300<br>PA-32R-301 SP<br>PA-32R-301 II HP                                                        | 9/22/98   | 460-632         | 99-05-09    | 7167 10bI20     |
| 1023   | Inspection of Landing Gear Cylinders and Distribution of Parker Hannifin Service Bulletin SB7063                           | PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC                                        | 10/8/98   | **              |             | 2902 10bJ6      |
| 1024   | Replacement of Control System Spacers and Inspection of Aileron Cables                                                     | PA-32R-301 II HP<br>PA-32R-301 II TC                                                                                                                         | 10/1/98   | **              |             | 2712 10bJ12     |
| 1025   | Replacement of the Alternate Air Door                                                                                      | PA-32R-301T II TC                                                                                                                                            | 10/21/98  | **              |             | 7164 10bJ16     |
| 1026   | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".   | PA-32-260<br>PA-32-300<br>PA-32-301<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC | 11/5/98   | 753-910         |             | 3711 10bJ20     |
| 1028   | Inspection of the Aileron Control Rod Attach Fitting and the Addition of Safety Clips                                      | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                        | 12/2/98   | **              |             | 5755 10bK12     |
| 1030A  | Distribution of Textron Lycoming Service Bulletin 538A, "Air Inlet tube Replacement" and Drain Improvement                 | PA-32R-301T II TC                                                                                                                                            | 9/10/99   | **              |             | 7168 10bK21     |
| 1031   | Horizon Engine Instruments Repair or Replacement                                                                           | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                        | 7/14/99   | **              |             | 7710/7720 10bL3 |
| 1035A  | Distribution of Textron Lycoming Service Bulletin 529B, "Repair of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 3" | PA-32-301T<br>PA-32R-301T SP<br>PA-32R-301T II TC<br>PA-32RT-300T                                                                                            | 3/22/2007 | **              | 2003-14-03  | 7311 10bL16     |
| 1036   | Garmin Service Bulletin No. 9905 'GNS430 Mod. 1"                                                                           | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                        | 10/1/99   |                 |             | 3426 10cA1      |
| 1039   | Manifold Pressure Gauge (MAP) Wiring Modification                                                                          | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                        | 2/14/2000 |                 |             | 7715 10cA15     |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT                                                                                                                | MODELS<br>AFFECTED                                                                                                                                                                  | DATE      | PART/KIT<br>NO.                      | A.D.<br>NO. | ATA<br>CODE |
|--------|------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------------------------------|-------------|-------------|
| 1041   | Distribution of Airborne<br>Service Letter Number 56,<br>"Inspection and Cleaning of<br>Airborne Air Filter Elements." | PA-32-260<br>PA-32-300/-32S-300<br>PA-32-301<br>PA-32-301T<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-300<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC | 9/25/2000 | **                                   |             | 3714 10cB1  |
| 1048   | Stainless Steel Control Cables                                                                                         | PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                              | 1/3/2001  | N/A                                  |             | 2702 10cC9  |
| 1049   | Engine Baffle Brace Installation                                                                                       | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                               | 4/9/2001  | 766-684                              |             | 7236 10cC13 |
| 1081A  | Horizon Aerospace Analog<br>Instrument Pointer Calibration                                                             | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                               | 12/9/2002 | N/A                                  |             | 7700 10cl12 |
| 1083C  | S-TEC System 55X Autopilot                                                                                             | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                               | 5/30/2002 | 767-318                              |             | 2218 10cl19 |
| 1092B  | Engine Mount Inspection                                                                                                | PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                              | 4/28/2003 | 38729-021<br>38729-022<br>104642-002 |             | 7121 10cK22 |
| 1131A  | Inspection of Cast Main Landing<br>Gear Strut Cylinders<br>(P/N's 65319-002, 65319-003,<br>and 65319-004)              | PA-32-260                                                                                                                                                                           | 1/18/2016 | 65489-002<br>65490-000               |             | 3210        |
| 1134   | Servo Metered Fuel Pressure<br>Port Leakage (Lycoming SB 557;<br>Precision Airmotive SB PRS-105)                       | PA-32-300<br>PA-32-301<br>PA-32-301T<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC                       | 6/10/2003 | **                                   |             | 2800 10dG5  |
| 1135   | GMA-340 Audio Panel Wiring                                                                                             | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                               | 7/16/2003 | N/A                                  |             | 2370 10dG13 |
| 1137   | Stabilator Balance Weight<br>Tube Assembly                                                                             | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                               | 11/6/2003 | N/A                                  |             | 2749 10dG20 |
| 1139A  | Control Wheel Attachment Inspection                                                                                    | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                | 4/9/2004  | **                                   | 4-14-12     | 2701 10dH4  |
| 1141   | Clip Nut Replacement                                                                                                   | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                               | 12/9/2003 | 477-640                              |             | 5351 10dH15 |
| 1145A  | Autopilot Installation and Testing                                                                                     | PA-32-301FT<br>PA-32-301XTC                                                                                                                                                         | 2/17/2004 | 600-520<br>692-411                   |             | 2210 10dI4  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                 | MODELS<br>AFFECTED                                                                                                                                                                                                      | DATE      | PART/KIT<br>NO.               | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------------------------|-------------|-------------|
| 1151E  | 4130N Steel Hardness Discrepancy                                                        | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                                    | 6/9/2004  | **                            |             | 5741 10dJ4  |
| 1161C  | Rib Assembly Inspection and<br>Modification - Aft Wing, WS 49.25                        | PA-32R-300<br>PA-32RT-300/300T<br>PA-32R-301 SP<br>PA-32R-301T Turbo SP<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                        | 3/6/2023  | 767-397<br>767-398            |             | 5712 10dK19 |
| 1162B  | European Requirements for<br>Avidyne Integra Equipped<br>PA-28 and PA-32 Model Aircraft | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                                    | 9/7/2006  | 652-591<br>767-418<br>767-422 |             | 3400 10dL1  |
| 1169A  | Tailcone Pressure Duct Support<br>Strap                                                 | PA-32-301FT<br>PA-32-301XTC                                                                                                                                                                                             | 1/17/2007 | 767-547                       |             | 2100 10dL22 |
| 1171   | Stormscope Erroneous Strike<br>Indication                                               | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                                    | 9/20/2006 | 767-548                       |             | 3400 10eA3  |
| 1178   | Nose Gear Forging Inspection /<br>Replacement                                           | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                                                                   | 9/24/2007 | 67050-002                     |             | 3222 10eB10 |
| 1179   | Main Landing Gear Cylinder<br>Assembly Inspection                                       | PA-32-301FT<br>PA-32-301XTC                                                                                                                                                                                             | 2/1/2008  | 65490-000                     |             | 3213 10eB14 |
| 1180A  | V-Band Exhaust Coupling<br>Inspection                                                   | PA-32R-301T II TC                                                                                                                                                                                                       | 3/14/2007 | **                            |             | 7200 10eB18 |
| 1187   | Voltage Suppressor Replacement                                                          | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                                    | 2/8/2008  | 88432-002<br>(Kit)            |             | 3400 10eD4  |
| 1197E  | Control Wheel Shaft Inspection                                                          | PA-32-260<br>PA-32-300<br>PA-32-301<br>PA-32-301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC<br>PA-32S-300 | 11/2/2017 | **                            | 2010-15-10  | 2710        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT                                            | MODELS<br>AFFECTED                                                                                                                                                                                           | DATE       | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------------------|-------------|-------------|
| 1198A  | Fuel Selector O-Ring                               | PA-32-260<br>PA-32-300<br>PA-32-301<br>PA-32-301FT<br>PA-32-301T<br>PA-32-301XTC<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC    | 4/20/2009  | 485-330<br>485-332     |             | 2823        |
| 1199   | Main Landing Gear Torque<br>Link Inspection        | PA-32-260<br>PA-32-300                                                                                                                                                                                       | 2/16/2009  | 78033-000<br>63312-002 | 72-08-06    | 3213        |
| 1216B  | Aileron Rib Inspection                             | PA-32-301<br>PA-32-301FT<br>PA-32-301T<br>PA-32-301XTC<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC                                                                           | 9/5/2012   | 38650-007<br>38650-008 |             | 5755        |
| 1242A  | Rudder Pedal Assembly Inspection                   | PA-32-260<br>PA-32(S)-300<br>PA-32-301<br>PA-32-301FT<br>PA-32-301T<br>PA-32-301XTC<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC | 5/12/2020  | 99938-000<br>99938-001 |             | 2710        |
| 1244C  | Aft Wing Attach Fitting Inspection<br>Requirements | PA-32 Series<br>PA-32R Series<br>PA-32RT Series<br>PA-32S Series                                                                                                                                             | 12/3/2018  | 764-998                |             | 5740        |
| 1245A  | Stabilator Control System Inspection               | PA-32 Series<br>PA-32R Series<br>PA-32RT Series<br>PA-32S Series                                                                                                                                             | 11/28/2012 | N/A                    | 2013-02-03  | 2730        |
| 1247B  | Garmin SafeTaxi® Limitation                        | PA-32-301FT<br>PA-32R-301T II TC                                                                                                                                                                             | 3/13/2019  | N/A                    |             | 3420        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                   | MODELS<br>AFFECTED                                                                                                                                                            | DATE       | PART/KIT<br>NO.  | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------------|-------------|-------------|
| 1251   | Stabilator Trim Barrel Inspection                                         | PA-32-260/300<br>PA-32-301/301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-300<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC<br>PA-32S-300        | 4/10/2013  | 63530-000        |             | 5755        |
| 1280A  | H3R Fire Extinguisher Replacement,<br>H3R Aviation SB 2015-1              | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                          | 4/29/2016  | 459-887          |             | 2620        |
| 1286A  | Lycoming SB 621A,<br>Diaphragm-Type Fuel Pump<br>Replacement              | PA-32-300<br>PA-32-301<br>PA-32-301FT<br>PA-32R-300<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32RT-300                                                                       | 10/30/2015 | N/A              |             | 7310        |
| 1297   | Altimeter Inspection and<br>Replacement (United Instruments<br>SB No. 13) | All                                                                                                                                                                           | 5/10/2016  | N/A              |             | 3416        |
| 1304B  | Main Wing Spar Inspection                                                 | PA-32-260<br>PA-32-300                                                                                                                                                        | 12/2/2021  | 765-106<br>88692 |             | 5740        |
| 1342A  | Stabilator Fitting Inspection                                             | PA-32-260/300<br>PA-32-301/301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-300<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC                      | 11/2/2021  | 62645-004        |             | 5510        |
| 1355B  | Tee Bar Assembly Inspection                                               | PA-32-260/300<br>PA-32-301/301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-300<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC<br>PA-32RT-300/-300T | 8/18/2022  | 28F40A003        |             | 2701        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-32 Series

| NUMBER | SUBJECT                                                             | MODELS<br>AFFECTED                                                                                                                                                                          | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|-------------|-------------|
| 1366   | Main Wing Spar Hardware<br>Inspection                               | PA-32-260/300<br>PA-32-301/301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-300<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC<br>PA-32RT-300/-300T<br>PA-32S-300 | 5/14/21   | 96352           |             | 5711        |
| 1375B  | Periodic Replacement of<br>Main Landing Gear Attachment<br>Hardware | PA-32-260/300<br>PA-32-301/301T<br>PA-32-301FT<br>PA-32-301XTC                                                                                                                              | 2/27/2023 | **              |             | 3210        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**SB77**

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------|--------------------|------|-----------------|-------------|-------------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.  
\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.  
\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT                                                          | MODELS<br>AFFECTED | DATE      | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|------------------------------------------------------------------|--------------------|-----------|------------------------|-------------|-------------|
| 251D   | Fuel Tank Inspection                                             | PA-34-200          | 2/24/2009 | 757-572V               |             | 2810 3F10   |
| 350    | Stabilator Hinge Attaching Bolts<br>Inspection of                | PA-34-200          | 3/30/72   | **                     |             | 5550 4D7    |
| 352    | Pitot Static System Lines<br>Replacement                         | PA-34-200          | 6/13/72   | 760-614V<br>760-615V   |             | 3030 4D12   |
| 357A   | Terminal Replacement, Alternator<br>Output Wire                  | PA-34-200          | 11/14/72  | 588-398V               |             | 2420 4E9    |
| 358    | Induction Air Box Valve Inspection                               | PA-34-200          | 7/31/72   | 96776-00V              | 72-17-01    | 7160 4E11   |
| 359    | Pitot Static System Instrument<br>Lines Modification             | PA-34-200          | 10/10/72  | 760-679V               |             | 3410 4E13   |
| 364A   | Circuit Breaker Replacement, Fuel<br>Pump, Electric              | PA-34-200          | 11/16/72  | 454-707                |             | 2820 4F1    |
| 367    | Stabilator Tip Balance Weight<br>Inspection                      | PA-34-200          | 8/25/72   | **                     | 72-18-06    | 2740 4F5    |
| 368    | Antenna Protector, Transponder<br>Installation                   | PA-34-200          | 11/22/72  | 760-697V               |             | 3450 4F7    |
| 369    | Wing Assembly, Aft, Inspection and<br>Modification of            | PA-34-200          | 9/8/72    | 760-696V               | 73-11-02    | 5110 4F8    |
| 370    | Fuel Injector Servo Mounting Nut<br>Inspection                   | PA-34-200          | 9/12/72   |                        |             | 7310 4F10   |
| 373A   | Exhaust System Inspection                                        | PA-34-200          | 6/12/73   | **                     | 73-14-02    | 7810 4F12   |
| 374    | Induction Air Box Replacement                                    | PA-34-200          | 2/2/73    | 760-722V               | 72-17-01    | 7160 4F14   |
| 382    | Fuel Tank Vent Systems, Inspection                               | PA-34-200          | 8/22/73   |                        |             | 2810 4G2    |
| 390A   | Trim Tab, Rudder Servo, Inspection                               | PA-34-200          | 5/30/73   | **                     | 73-13-01    | 2210 4G20   |
| 395    | Rudder Pedal, Warning, Improper<br>Use of                        | PA-34-200          | 11/9/73   | 757-436                |             | 2720 4H9    |
| 406    | Oleo Struts, Main Landing Gear,<br>Inspection and Maintenance of | PA-34-200          | 11/16/73  | **                     | 73-11-02    | 3210 4I15   |
| 412    | Glove Compartment Modification                                   | PA-34-200          | 4/9/74    | 581-025                |             | 2510 4J12   |
| 429    | Fuel Line Chafing—Engine<br>Nacelles, Prevention of              | PA-34-200          | 8/12/74   | 760-877V<br>760-886V   | 74-17-08    | 2810 4L3    |
| 437A   | Spar Straps, Inspection of Seneca                                | PA-34-200          | 10/16/75  |                        |             | 5710 5A1    |
| 438    | Fuel Quantity, Revised Usable                                    | PA-34-200/200T     | 8/6/75    | **                     | 75-20-03    | 2840 5A6    |
| 447    | Baggage Door Inspection and<br>Modification to the Forward       | PA-34-200/200T     | 2/7/75    |                        |             | 5230 5B1    |
| 475    | Instrument Panel Dimmer Control<br>Assembly Modification         | PA-34-200/200T     | 7/10/75   |                        |             | 3310 5E1    |
| 483    | Turbocharger Oil Hose<br>Modification, Seneca II                 | PA-34-200T         | 11/12/75  | 761-023V               | 75-25-03    | 8010 5E23   |
| 491    | Pneumatic Deicer Tubing Inspection                               | PA-34-200T         | 2/19/76   | 761-018V               |             | 3700 5F16   |
| 502A   | Heated Lift Detector Inspection                                  | PA-34-200T         | 7/1/76    | 69669-156V<br>472-890V |             | 3260        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                        | MODELS<br>AFFECTED      | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE       |
|--------|----------------------------------------------------------------------------------------------------------------|-------------------------|----------|--------------------|-------------|-------------------|
| 542    | Induction Air Box Filter Locator Change                                                                        | PA-34-200T              | 2/25/77  | 761-130V           |             | 7160 6A7          |
| 545    | Fuselage Rivets, Inspection and Installation                                                                   | PA-34-200/200T          | 2/23/77  | 522-898            |             | 5330 6A13         |
| 548    | Engine Control Rod End Bearing Inspection                                                                      | PA-34-200/200T          | 3/7/77   | 452-557            | 77-23-03    | 7230 6A23         |
| 553    | Avionics Bus Bar Inspection and Modification                                                                   | PA-34-200/200T          | 4/15/77  | 761-133V           |             | 2450 6B13         |
| 555    | Rudder Cable Guard Inspection, Seneca II                                                                       | PA-34-200T              | 3/9/77   | 62701-72V          |             | 2720 6B17         |
| 565    | Horizontal Situation Indicator Modification to Edo Aire Mitchell; Edo Aire Mitchell Service Bulletin No. MB-13 | PA-34-200T              | 6/2/77   | **                 |             | 3420 6C20         |
| 576    | TCM TS10360 Series Engines To Disseminate Information                                                          | PA-34-200T              | 11/30/77 |                    |             | 7200 6E23         |
| 579    | Inspection of Vertical Fin and Stabilator Attachment Fittings                                                  | PA-34-200/200T          | 11/14/77 | **                 | 80-09-04    | 5550 6F5          |
| 584    | Engine Instruments and Fuel Flow Line Inspection and Modification                                              | PA-34-200T              | 12/13/77 | **                 |             | 7330 6F20<br>7700 |
| 596A   | Fuel Line Inspection and Modification                                                                          | PA-34-200T              | 9/22/78  | **                 | 78-21-03    | 2810 6H6          |
| 601    | Inspection of Battery Box Vent                                                                                 | PA-34-200T              | 8/11/78  |                    | 78-21-03    | 2430 6H20         |
| 602    | Inspection of the Main Wing Spar Attaching Nuts                                                                | PA-34-200T              | 7/3/78   | 404-532V           |             | 5750 6I1          |
| 611    | Hose Assembly Inspection and Replacement                                                                       | PA-34-200T              | 11/14/78 | **                 |             | 2820 6J5          |
| 630A   | Collins VIR-350 and VIR-351 Navigation Receiver Modification                                                   | PA-34-200T              | 2/25/80  |                    |             | 3450 6L14         |
| 633B   | Forward Baggage Door Inspection and Modification                                                               | PA-34-200<br>PA-34-200T | 10/3/80  | 36521-02V          | 88-04-05    | 5230 7A10         |
| 656    | Window Curtain Rod Support Area Inspection                                                                     | PA-34-200T              | 9/13/79  | **                 |             | 5520 7D17         |
| 668    | Avionics Master Relay Wiring Inspection                                                                        | PA-34-200T              | 11/12/79 |                    |             | 2450 7F6          |
| 669    | Altimatec IIIC Autopilot Trim Servo Cable Alignment Modification                                               | PA-34-200T              | 1/14/80  | **                 |             | 2210 7F10         |
| 677    | Publications for Aircraft Operation                                                                            | All Piper Models        | 5/20/80  |                    |             | PARA 15 0 7H4     |
| 681    | Boom Microphone Isolation Relay                                                                                | PA-34-200T              | 4/24/80  | 456-703<br>180-500 | 80-14-03    | 2350 7H11         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT                                                                                          | MODELS<br>AFFECTED                                         | DATE      | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE  |       |
|--------|--------------------------------------------------------------------------------------------------|------------------------------------------------------------|-----------|------------------------|-------------|--------------|-------|
| 711    | Missing Rivets, Left Hand<br>Fuselage Station 108                                                | PA-34-220T                                                 | 3/27/81   | **                     |             | 5330         | 8A3   |
| 712A   | Fuel Selector Valve<br>Inspection and Cable<br>Clevis Replacement                                | PA-34-220T                                                 | 4/20/81   | 491-960V<br>764-121V   |             | 2820         | 8A7   |
| 718A   | Seneca III Surface Deicer<br>System                                                              | PA-34-220T                                                 | 10/29/81  | 764-222V               |             | 3000         | 8B1   |
| 732    | Landing Gear Selector Switch<br>Shield                                                           | PA-34-220T                                                 | 11/11/81  | 87431-02V<br>488-702V  | 82-04-08    | 3200         | 8C23  |
| 758    | Radio Master Relay Replacement                                                                   | PA-34-220T                                                 | 2/14/83   |                        |             | 2450         | 8H10  |
| 762    | Exhaust System Heat Exchanger<br>Inspection                                                      | PA-34-200                                                  | 5/26/83   | 78463-10V<br>78463-18V | 83-14-05    | 7810         | 8H21  |
| 787C   | Main Landing Gear<br>Trunnion Housing                                                            | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T IV | 11/7/2000 | 2599-002               | 94-13-11    | 3211         | 8L8   |
| 798    | "TURBO" Marking Removal                                                                          | PA-34-200T                                                 | 12/11/84  | N/A                    |             | 1110         | 9B19  |
| 801    | King A/P Servo Bridle Clamp<br>Installation                                                      | PA-34-220T                                                 | 12/11/84  | **                     |             | 2200         | 9C6   |
| 805A   | TRW Hartzell Propeller<br>Service Bulletin No 142B<br>(O-ring Deterioration)                     | PA-34-200<br>PA-34-200T<br>PA-34-220T                      | 3/14/86   | N/A                    |             | 6110         | 9D15  |
| 811A   | Ammeter<br>Replacement                                                                           | PA-34-200T                                                 | 5/12/86   | **                     | 86-17-01    | 2430         | 9F4   |
| 836A   | Aluminum Wire<br>Inspection/Replacement                                                          | PA-34-200<br>PA-34-200T<br>PA-34-220T                      | 8/26/86   | **                     |             | 2400         | 9J4   |
| 855    | Use of Automobile Gasoline in<br>Piper Aircraft                                                  | All Piston Powered<br>Models                               | 1/14/87   | N/A                    |             | 2800         | 10A7  |
| 856    | Stabilator Attach Fitting<br>Corrosion Inspection                                                | PA-34-200<br>PA-34-200T<br>PA-34-220T                      | 2/17/87   | **                     |             | 5550         | 10A9  |
| 872    | Forward Baggage Compartment<br>Door Latch Spring<br>Installation And Door<br>Assembly Inspection | PA-34-200<br>PA-34-200T<br>PA-34-220T                      | 11/9/87   | 765-330                | 88-04-05    | 5230         | 10D5  |
| 884    | Lock Wiring of<br>V Band Couplings                                                               | PA-34-200T<br>PA-34-220T                                   | 4/8/88    | **                     |             | 7800<br>2100 | 10G20 |
| 893    | Nose Gear Centering<br>Attach Belt                                                               | PA-34-200<br>PA-34-200T                                    | 10/11/88  | 400-910                | 92-13-05    | 3220         | 10I3  |
| 896    | Shoulder Harness<br>Installation & Usage                                                         | PA-34-200<br>PA-34-200T<br>PA-34-220T                      | 11/28/88  | **                     |             | 5340         | 10I13 |
| 899    | Rudder Torque Tube<br>Fitting Replacement                                                        | PA-34-200<br>PA-34-200T<br>PA-34-220T                      | 2/10/89   | **                     | 92-08-04    | 2720         | 10J8  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                               | MODELS<br>AFFECTED                                      | DATE     | PART/KIT<br>NO.    | A.D.<br>NO.      | ATA<br>CODE |
|--------|---------------------------------------------------------------------------------------|---------------------------------------------------------|----------|--------------------|------------------|-------------|
| 905    | Auxiliary Primer<br>Switch Replacement                                                | PA-34-200T<br>PA-34-220T                                | 4/6/89   | **                 |                  | 7315 10K7   |
| 906    | Oildyne Hydraulic<br>Pump Replacement                                                 | PA-34-200T<br>PA-34-220T                                | 4/10/89  | **                 |                  | 2911 10K12  |
| 938    | Wire Protection                                                                       | PA-34-220T                                              | 6/12/90  | 189-531<br>488-698 |                  | 3262 10aE1  |
| 956    | Main Landing Gear Trunnion<br>Attach Fittings                                         | PA-34-200<br>PA-34-200T<br>PA-34-220T                   | 3/3/92   | **                 |                  | 3211 10aH10 |
| 965    | Inspection of Flap Lever and Bolt                                                     | PA-34-200<br>PA-34-200T<br>PA-34-220T                   | 9/1/93   | **                 | 96-10-03         | 2750 10aJ3  |
| 976    | Inspection for and Replacement<br>of Components with Suspect<br>"O" Rings             | PA-34-220T                                              | 12/9/94  | **                 |                  | 2911 10bA10 |
| 977    | Inspection of Wing Rear Attach<br>Fitting and Addition of Inspection<br>Access Panels | PA-34-200<br>PA-34-200T<br>PA-34-220T                   | 12/12/94 | **                 | SAIB<br>CE-11-12 | 5740 10bA12 |
| 983    | Station 49.5<br>Frame Inspection                                                      | PA-34-220T                                              | 5/25/95  | **                 |                  | 5310 10bC4  |
| 987    | Prop Deice Timer<br>Wiring Inspection                                                 | PA-34-220T III<br>PA-34-220T IV                         | 9/11/95  | **                 |                  | 3000 10bD1  |
| 988    | Pneumatic Deice Switch<br>Relocation                                                  | PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV | 11/9/95  | 558-790<br>179-771 |                  | 3013 10bD4  |
| 989    | Inspection for Stabilator Trim<br>Screw Assembly Attachment Hardware                  | PA-34-220T IV                                           | 12/20/95 | **                 |                  | 2791 10bD8  |
| 990    | Pacific Scientific Seat Belt<br>Replacement                                           | PA-34-220T IV                                           | 1/3/96   | **                 |                  | 5346 10bD12 |
| 993    | KLN-90B GPS Wiring Modification                                                       | PA-34-220T IV                                           | 3/18/96  | **                 |                  | 3441 10bE4  |
| 996    | Missing Rivet in Upper Door Frame,<br>Forward and Aft                                 | PA-34-220T (IV)                                         | 9/12/96  | **                 |                  | 5311 10bE16 |
| 1005   | Addition of Drain Holes to the Engine<br>Induction Air Inlet Scoops                   | PA-34-220T (V)                                          | 8/11/97  |                    |                  | 7162 10bG1  |
| 1010   | Replacement of Fuel Selector Levers                                                   | PA-34-220T V                                            | 11/3/97  | 766-645            |                  | 2822 10bG21 |
| 1013   | Replacement of Crankcase Breather<br>System                                           | PA-34-220T V                                            | 2/5/98   | **                 |                  | 7925 10bH6  |
| 1014   | Replacement of Battery Power Fuse                                                     | PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V   | 3/2/98   | 461-681            |                  | 2436 10bH11 |
| 1017   | Alternator Regulator Wiring Diagram                                                   | PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V   | 4/10/98  | **                 |                  | 2436 10bH21 |
| 1020   | Inspection of the Artex 110-4 ELT<br>and ELT Attachment Bracket                       | PA-34-220T IV<br>PA-34-220T V                           | 7/10/98  | **                 |                  | 2563 10bI11 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT                                                                                                                  | MODELS<br>AFFECTED                                                                                 | DATE       | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE        |
|--------|--------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|------------|------------------------|-------------|--------------------|
| 1022   | Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01                           | PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V              | 9/22/98    | 460-632                | 99-05-09    | 7167 10bI20        |
| 1023   | Inspection of Landing Gear Cylinder and Distribution of Parker Hannifin Service Bulletin SB7063                          | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 10/8/98    | **                     |             | 2902 10bJ6         |
| 1026   | Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings". | PA-34-200<br>PA-34-200T<br>PA-34-220T III(28V)<br>PA-34-220T IV                                    | 11/5/98    | 753-910                |             | 3711 10bJ20        |
| 1031   | Horizon Engine Instruments Repair or Replacement                                                                         | PA-34-220T V                                                                                       | 7/14/99    | **                     |             | 7710 10bL3<br>7720 |
| 1039   | Manifold Pressure Gauge (MAP) Wiring Modification                                                                        | PA-34-220T V                                                                                       | 2/14/2000  |                        |             | 7715 10cA15        |
| 1041   | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."            | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 9/25/2000  | **                     |             | 3714 10cB1         |
| 1042   | Heated Deice Panel Inspection                                                                                            | PA-34-220T V                                                                                       | 6/9/2000   | 31637-003              |             | 3041 10cB10        |
| 1043   | Deice Control Valve Replacement                                                                                          | PA-34-220T V                                                                                       | 7/13/2000  | **                     |             | 3014 10cB15        |
| 1048   | Stainless Steel Control Cables                                                                                           | PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V                            | 1/3/2001   | N/A                    |             | 2702 10cC9         |
| 1081A  | Horizon Aerospace Analog Instrument Pointer Calibration                                                                  | PA-34-220T V                                                                                       | 12/9/2002  | N/A                    |             | 7700 10cI12        |
| 1083C  | S-TEC System 55X Autopilot                                                                                               | PA-34-220T V                                                                                       | 5/30/2002  | 767-319                |             | 2218 10cI19        |
| 1097A  | Pneumatic Deicer Deflate Valve Assembly Replacement                                                                      | PA-34-220T V                                                                                       | 2/25/2002  | 592-676                |             | 3010 10cL16        |
| 1100A  | Stabilator Trim Link Assembly                                                                                            | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 10/31/2001 | 96003-000              |             | 5511 10cL12        |
| 1113   | Nose Gear Down Lock Pin Inspection                                                                                       | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 6/5/2002   | 95829-000<br>95830-000 |             | 3235 10dC3         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                          | MODELS<br>AFFECTED                                                                                 | DATE       | PART/KIT<br>NO.                                                  | A.D.<br>NO.              | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|------------|------------------------------------------------------------------|--------------------------|-------------|
| 1123D  | Nose Gear Inspection<br>and Product Improvements                                                 | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 1/26/2022  | 767-357<br>767-358<br>767-359<br>767-368<br>693-215<br>95394-005 | 2005-13-16<br>2022-09-13 | 3220        |
| 1127B  | Combustion Heater Fuel Pump<br>Leakage<br>(Kelly Aerospace SIL A-110b)                           | PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V              | 4/18/2005  | 767-367<br>**                                                    | 3-11-14                  | 2800 10dE16 |
| 1130   | Vertical Fin Contour / Rivet Check                                                               | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 11/11/2003 | 767-369                                                          |                          | 5300 10dF8  |
| 1134   | Servo Metered Fuel Pressure<br>Port Leakage (Lycoming SB 557;<br>Precision Airmotive SB PRS-105) | PA-34-200                                                                                          | 6/10/2003  | **                                                               |                          | 2800 10dG5  |
| 1135   | GMA-340 Audio Panel Wiring                                                                       | PA-34-220T V                                                                                       | 7/16/2003  | N/A                                                              |                          | 2370 10dG13 |
| 1136   | Auxiliary Fuel Pump Switch                                                                       | PA-34-200T                                                                                         | 9/2/2003   | 588-006<br>(99377-029)                                           |                          | 2800 10dG17 |
| 1137   | Stabilator Balance Weight<br>Tube Assembly                                                       | PA-34-220T V                                                                                       | 11/6/2003  | N/A                                                              |                          | 2749 10dG20 |
| 1139A  | Control Wheel Attachment Inspection                                                              | PA-34-220T V                                                                                       | 4/9/2004   | **                                                               | 4-14-12                  | 2701 10dH4  |
| 1141   | Clip Nut Replacement                                                                             | PA-34-220T V                                                                                       | 12/9/2003  | 477-640                                                          |                          | 5351 10dH15 |
| 1146   | Vertical Fin Aft Spar Reinforcing<br>Angle Low Edge Distance Inspection                          | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 11/5/2004  | **                                                               |                          | 5300 10dI10 |
| 1151E  | 4130N Steel Hardness Discrepancy                                                                 | PA-34-220T V                                                                                       | 6/9/2004   | N/A                                                              |                          | 5741 10dJ4  |
| 1157A  | Pressurized Magnetos & Tachometer<br>Sensor Assemblies; Field Upgrade                            | PA-34-220T V                                                                                       | 6/20/2005  | **                                                               |                          | 7414 10dK1  |
| 1161C  | Rib Assembly Inspection and<br>Modification - Aft Wing, WS 49.25                                 | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 3/6/2023   | 767-397<br>767-398                                               |                          | 5712 10dK19 |
| 1184   | Inspection of Engine Mount<br>for Evidence of Contact<br>with Oil Line Fitting                   | PA-34-220T V                                                                                       | 6/15/2007  | 37105-000                                                        |                          | 7120 10eC12 |
| 1187   | Voltage Suppressor Replacement                                                                   | PA-34-220T V                                                                                       | 2/8/2008   | 88432-002<br>(Kit)                                               |                          | 3400 10eD4  |
| 1284   | Aspen Avionics EFD1000 Update<br>to Software Version 2.10.2                                      | PA-34-220T                                                                                         | 2/7/2023   | n/A                                                              |                          | 3420        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT                                                                                                                                      | MODELS<br>AFFECTED                                                                                 | DATE       | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|------------|------------------------|-------------|-------------|
| 1197E  | Control Wheel Shaft Inspection                                                                                                               | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 11/2/2017  | **                     | 2010-15-10  | 2710        |
| 1223   | Wire Screen Replacement                                                                                                                      | PA-34-220T V                                                                                       | 11/10/2010 | **                     |             | 2126        |
| 1225   | Inaudible Traffic Information System (TIS) or Traffic Advisory System (TAS) Aural Alerts                                                     | PA-34-220T V                                                                                       | 7/26/2011  | N/A                    |             | 3440        |
| 1241   | Wastegate Clearance Inspection                                                                                                               | PA-34-220T V                                                                                       | 5/10/2012  | **                     |             | 7120        |
| 1242A  | Rudder Pedal Assembly Inspection                                                                                                             | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 5/12/2020  | 99938-000<br>99938-001 |             | 2710        |
| 1244C  | Aft Wing Attach Fitting Inspection Requirements                                                                                              | PA-34 Series                                                                                       | 12/3/2018  | 764-998                |             | 5740        |
| 1245A  | Stabilator Control System Inspection                                                                                                         | PA-34 Series                                                                                       | 11/28/2012 | N/A                    | 2013-02-03  | 2730        |
| 1247B  | Garmin SafeTaxi® Limitation                                                                                                                  | PA-34-220T V                                                                                       | 3/13/2019  | N/A                    |             | 3420        |
| 1252   | Garmin G600 Systems Software Upgrade to Version 0942.40                                                                                      | PA-34-220T V                                                                                       | 10/2/2013  | N/A                    |             | 3420        |
| 1254   | Stabilator Drain Hole Inspection                                                                                                             | PA-34-220T V                                                                                       | 1/14/2013  | N/A                    |             | 5755        |
| 1270A  | Re-enablement of GDL 69, GSR 56, and/or GTS 825 for EASA Importation                                                                         | PA-34-220T V                                                                                       | 6/4/2014   | N/A                    |             | 3420        |
| 1274   | Control Wheel Bushing Inspection                                                                                                             | PA-34-220T V                                                                                       | 2/9/2015   | 68273-002              |             | 2701        |
| 1280A  | H3R Fire Extinguisher Replacement, H3R Aviation SB 2015-1                                                                                    | PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V              | 4/29/2016  | 459-887                |             | 2620        |
| 1284B  | Lycoming SB 622A, Slick/Champion Aerospace SB1-15A, Potential decreased service life of Slick 4-cylinder magneto distributor gear assemblies | PA-34-200                                                                                          | 4/12/2019  | N/A                    |             | 7414        |
| 1285   | Propeller Deice Timer Inspection                                                                                                             | PA-34-220T IV<br>PA-34-220T V                                                                      | 8/14/2015  | N/A                    |             | 3060        |
| 1286A  | Lycoming SB 621A, Diaphragm-Type Fuel Pump Replacement                                                                                       | PA-34-200                                                                                          | 10/30/2015 | N/A                    |             | 7310        |
| 1297   | Altimeter Inspection and Replacement (United Instruments SB No. 13)                                                                          | All                                                                                                | 5/10/2016  | N/A                    |             | 3416        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                               | MODELS<br>AFFECTED                                                                                 | DATE       | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|------------|-----------------|-------------|-------------|
| 1303A  | Diode Module Installation                                             | PA-34-220T V                                                                                       | 10/15/2018 | 681-020         |             | 3410        |
| 1337   | Emergency Power Supply<br>Modification                                | PA-34-220T V                                                                                       | 2/15/2019  | 107279-002      | 2020-24-09  | 2497        |
| 1355B  | Tee Bar Assembly Inspection                                           | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 8/18/2022  | 28F40A003       |             | 2701        |
| 1366   | Main Wing Spar Hardware<br>Inspection                                 | PA-34-200<br>PA-34-200T<br>PA-34-220T III<br>PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V | 5/14/2021  | 96352           |             | 5711        |
| 1368   | Heater Fuel Pump Leak Inspection<br>and Replacement (Hartzell ASB 85) | PA-34-220T III (28V)<br>PA-34-220T IV<br>PA-34-220T V                                              | 7/14/2021  | **              |             | 2140        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                     | MODELS<br>AFFECTED         | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE                       |
|--------|---------------------------------------------------------------------------------------------|----------------------------|----------|--------------------|-------------|-----------------------------------|
| 396    | Propeller Stop, Low Pitch                                                                   | PA-36-285                  | 1/29/74  |                    |             | 6110 4H11                         |
| 397    | Fuel Quantity Placards, Revised                                                             | PA-36-285                  | 5/2/74   | **                 | 74-13-07    | 2840 4H12                         |
| 402    | Starter Shaft Inspection<br>Tiara (Continental Aircraft Engine<br>Service Bulletin #M73-20) | PA-36-285                  | 10/5/73  | **                 |             | 8010 4I4                          |
| 418    | Lift Detector Relocation And<br>Modification                                                | PA-36-285                  | 8/13/74  | 760-843V           | 74-21-02    | 2700 4K1                          |
| 425    | Wing Spar Center Section Bolts,<br>Replacement of                                           | PA-36-285                  | 6/14/74  | 760-871V           | 74-14-06    | 5750 4K18                         |
| 439    | Flap Control System, Modification<br>of The                                                 | PA-36-285                  | 12/27/74 | 760-903V           | 75-01-02    | 2750 5A8                          |
| 467    | Spray Pump Windmill Assembly<br>Modification                                                | PA-36-285                  | 10/29/75 | **                 |             | 910 5C24                          |
| 471A   | Wing Attachment Fittings, Forward<br>And Aft, Inspection And<br>Modification                | PA-36-285                  | 7/16/76  | **                 | 77-02-06    | 5750 5D15                         |
| 472    | Main Spar Center Section Carry<br>Through Assembly Modification of                          | PA-36-285                  | 6/6/75   | 760-978            |             | 5310 5D18                         |
| 482    | Control Stick Torque Tube<br>Inspection of                                                  | PA-36-285                  | 10/22/75 | **                 |             | 7610 5E21                         |
| 489    | Muffler Clamp Installation                                                                  | PA-36-285                  | 3/12/76  | 761-017            |             | 7810 5F13                         |
| 490    | Safety Harness Installation<br>Modification                                                 | PA-36-285                  | 6/30/76  | 761-022<br>761-057 |             | 5340 5F14                         |
| 495B   | Rudder Control Horn Attachment<br>Bolts, Inspection of                                      | PA-36-285/300<br>PA-36-375 | 7/13/81  | **                 | 76-05-07    | 2720 5G11                         |
| 499    | Induction Air Filter Cover Assembly                                                         | PA-36-285                  | 3/18/76  |                    |             | 7160 5G20                         |
| 501    | Wing Main Spar Lower Bolt<br>Replacement                                                    | PA-36-285                  | 4/27/76  | 761-058            | 76-25-02    | 5750 5H1                          |
| 505    | Precautionary Operating Placard<br>Installation                                             | PA-36-285                  | 4/29/76  | 98000-62           |             | 1130 5H10                         |
| 506    | Tail Structure Modification                                                                 | PA-36-285                  | 8/23/76  | 761-034<br>761-067 | 77-04-02    | 3270 5H12                         |
| 508    | Fuel Tank Vents, Inspection of                                                              | PA-36-285                  | 6/15/76  |                    |             | 2810 5H19                         |
| 513    | Engine Air Induction System<br>Modification                                                 | PA-36-285                  | 7/15/76  | 761-053            |             | 7160 5I6                          |
| 516    | Control Rod End Bearing                                                                     | PA-36-285                  | 1/20/77  | 761-095            |             | 7200<br>2140<br>2730<br>2710 5I13 |
| 518    | Rudder Spar Hinge Inspection                                                                | PA-36-285                  | 2/22/77  | 98125-04           | 77-21-03    | 5550 5I19                         |
| 539    | Fuel Quantity Gauge Inspection                                                              | PA-36-285                  | 1/27/77  | 76784-02           |             | 2840 5L23                         |
| 546    | Whelen Wing Tip Strobe Lights<br>Reference FAA Airworthiness Directive,<br>Inspection of    | PA-36-285/300              | 5/18/77  | **                 |             | 3340 6A16                         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                                    | MODELS AFFECTED                     | DATE      | PART/KIT NO. | A.D. NO.   | ATA CODE  |
|--------|----------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-----------|--------------|------------|-----------|
| 552A   | Wing Spar Carry Through Assembly Inspection                                                                                | PA-36-285<br>PA-36-300              | 8/3/2018  | **           | 2021-11-16 | 5700      |
| 583    | Voltage Regulator/Over Voltage Relay Rewiring                                                                              | PA-36-300                           | 10/31/77  | **           |            | 2430      |
| 587    | Exhaust Stack Modification                                                                                                 | PA-36-300                           | 2/6/78    | **           |            | 7810      |
| 608A   | Inspection/Replacement of Elevator And Aileron System Control Rod End Bearings                                             | PA-36-285/300<br>PA-36-375          | 9/29/78   | **           | 78-26-05   | 2710      |
| 615    | Inspection of Engine Mount And Modification If Required                                                                    | PA-36-285                           | 9/21/78   | 763-887      | 79-12-09   | 7120      |
| 630A   | Collins VIR-350 And VIR-351 Navigation Receiver Modification                                                               | PA-36-300<br>PA-36-375              | 2/25/80   |              |            | 3450      |
| 677    | Publications for Aircraft Operation                                                                                        | All Piper Models                    | 5/20/80   |              |            | PARA 15.0 |
| 713    | Fuel Cell Inspection                                                                                                       | PA-36-285/300                       | 5/11/81   | 97989-00     |            | 2810      |
|        | and Servicing                                                                                                              | PA-36-375                           |           | 97989-01     |            |           |
| 729    | Rudder Cable and Seat Belt Attachment Shackle Inspection                                                                   | PA-36-285/300<br>PA-36-375          | 9/22/81   | 486-566      |            | 2720      |
| 744    | Wing Spar and Wing Spar Carry-Through Assembly and Components Replacement                                                  | PA-36-285/300<br>PA-36-375          | 5/12/82   | **           |            | 5710      |
| 771A   | Parking Brake Application                                                                                                  | PA-36-285/300/375                   | 9/6/2011  | 81090-002    | 85-02-05   | 1130      |
| 797B   | Fuel Port Restrictor Installation                                                                                          | PA-36-285/300<br>PA-36-375          | 9/1/87    | 566-502      |            | 2812      |
| 805A   | TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration)                                                    | PA-36-285/300<br>PA-36-375          | 3/14/86   | N/A          |            | 6110      |
| 828    | Fuselage Tubing Crack Inspection                                                                                           | PA-36-300<br>PA-36-375              | 4/7/86    | **           | 92-15-15   | 5345      |
| 836A   | Aluminum Wire Inspection/Replacement                                                                                       | PA-36-285/300<br>PA-36-375          | 8/26/86   | **           |            | 2400      |
| 855    | Use of Automobile Gasoline In Piper Aircraft                                                                               | All Piston Powered Models           | 1/14/87   | N/A          |            | 2800      |
| 926A   | Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs         | PA-36-285<br>PA-36-300<br>PA-36-375 | 3/7/94    | **           |            | 6113      |
| 1035A  | Distribution of Textron Lycoming Service Bulletin 529A, "Repair of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 2" | PA-36-375                           | 3/22/2007 | **           |            | 7311      |
| 1041   | Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."              | PA-36-285<br>PA-36-300<br>PA-36-375 | 9/25/2000 | **           |            | 3714      |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-36

| NUMBER | SUBJECT                                                                   | MODELS<br>AFFECTED | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------------|--------------------|-----------|-----------------|-------------|-------------|
| 1286   | Lycoming SB 621A,<br>Diaphragm-Type Fuel Pump<br>Replacement              | PA-36-285/300      | 9/22/2015 | N/A             |             | 7310        |
| 1297   | Altimeter Inspection and<br>Replacement (United Instruments<br>SB No. 13) | All                | 5/10/2016 | N/A             |             | 3416        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**SB89**

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------|--------------------|------|-----------------|-------------|-------------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE BULLETIN INDEX

PA-38-112

| NUMBER | SUBJECT                                                                                                            | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE  |      |
|--------|--------------------------------------------------------------------------------------------------------------------|--------------------|----------|--------------------|-------------|--------------|------|
| 600A   | Aft Fuselage/Tail Cone Area<br>Rivet Replacement                                                                   | PA-38-112          | 4/28/78  |                    |             | 5350         | 6H16 |
| 603    | Fuel Gauges And Instrument<br>Cluster Grounding Harness<br>Installation                                            | PA-38-112          | 7/25/78  | **                 | 79-17-05    | 2840<br>3310 | 6I2  |
| 607A   | Part I - Inspect And Attain Clearance<br>Between The Rudder Leading Edge<br>And The Vertical Fin Trailing<br>Edge  | PA-38-112          | 6/2/78   |                    |             |              | 6I13 |
| 607A   | Part II - Install Straps To Maintain<br>Clearance Between Rudder Leading<br>Edge And Vertical Fin Trailing<br>Edge | PA-38-112          | 6/2/78   |                    |             | 2730         | 6I14 |
| 607A   | Part III - Inspect And Attain Clearance<br>Between Elevator Leading Edge<br>And Stabilizer Trailing Edge           | PA-38-112          | 6/2/78   | 763-872            |             | 2720         | 6I15 |
| 609A   | Pilot And Copilot Control Wheel<br>Replacement Modification                                                        | PA-38-112          | 7/31/78  | **                 |             | 2700         | 6I23 |
| 610    | Gascolator Fuel Line Installation<br>Inspection                                                                    | PA-38-112          | 7/18/78  | 462-049            |             | 7310         | 6J2  |
| 613A   | Installation of Bearing Retention<br>Plates On Bottom Rudder Hinge<br>Bracket Assembly                             | PA-38-112          | 1/11/80  | 763-881            | 79-03-02    | 5550         | 6J12 |
| 614    | Inspection of Throttle And<br>Mixture Control Placards For<br>Proper Placement                                     | PA-38-112          | 8/11/78  | **                 |             | 7610<br>7320 | 6J14 |
| 617B   | Engine Mount Inspection/<br>Replacement                                                                            | PA-38-112          | 1/30/81  | **                 | 81-23-07    | 7120         | 6J22 |
| 618    | Inspection of Left And Right<br>Wing Rear Spar Attach Fittings                                                     | PA-38-112          | 9/5/78   | **                 |             | 5110         | 6K1  |
| 620    | Tomahawk Magneto Replacement                                                                                       | PA-38-112          | 10/26/78 | **                 |             | 7410         | 6K6  |
| 628A   | Inspection of Vertical Fin<br>Forward Spar Attachment Plate                                                        | PA-38-112          | 11/8/78  | 77553-05           |             | 5530         | 6L7  |
| 630A   | Collins VIR-350 And VIR-351<br>Navigation Receiver Modification                                                    | PA-38-112          | 2/25/80  |                    |             | 3450         | 6L14 |
| 637    | Part I - Inspection of Upper<br>Forward Vertical Fin Spar<br>Attach Fitting                                        | PA-38-112          | 12/29/78 | 77615-07           | 79-08-02    | 5510         | 7B5  |
| 637    | Part II - Inspection of Vertical<br>Fin/Fuselage And Horizontal<br>Tail/Vertical Fin Spar Attach<br>Fitting Bolt   | PA-38-112          | 12/29/78 |                    | 79-08-02    | 5510         | 7B7  |
| 661    | Control Column<br>Installation Modification                                                                        | PA-38-112          | 8/22/79  |                    | 85-11-06    | 2700         | 7E12 |
| 673B   | Replacement of Main Landing<br>Gear Attachment Clamp, Bolts,<br>And Barrel Nuts                                    | PA-38-112          | 10/2/86  | 765-171<br>765-172 | 90-19-03    | 3210         | 7G11 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

**SB91**

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                        | MODELS<br>AFFECTED           | DATE     | PART/KIT<br>NO. | A.D.<br>NO.          | ATA<br>CODE  |       |
|--------|--------------------------------------------------------------------------------|------------------------------|----------|-----------------|----------------------|--------------|-------|
| 676    | Nose Gear Strut Modification                                                   | PA-38-112                    | 6/5/80   | 764-007         |                      | 3220         | 7H1   |
| 677    | Publications for Aircraft Operation                                            | All Piper<br>Models          | 5/20/80  |                 |                      | PARA<br>15.0 | 7H4   |
| 686    | Upper Rudder Hinge Bracket<br>Replacement                                      | PA-38-112                    | 5/23/80  | **              | 98-03-16<br>80-22-13 | 5550         | 7I20  |
| 709    | Aileron Torque Tube Bearing<br>Inspection                                      | PA-38-112                    | 7/13/81  | **              |                      | 2710         | 7L21  |
| 710    | Vertical Fin Forward Spar<br>Attachment Plate Replacement<br>Life Limits       | PA-38-112                    | 10/10/82 | **              | 82-27-08             | 5530         | 8A1   |
| 723    | Aileron Balance Weight Rib<br>Inspection/Reinforcement                         | PA-38-112                    | 8/19/81  | **              | 82-02-01             | 2710         | 8B18  |
| 745    | Part I - Forward Fin Spar Inspection<br>Piper Part No. 77601-03                | PA-38-112                    | 10/10/82 | 764-427         | 82-27-08             | 5510         | 8F19  |
| 745    | Part II-Fuselage Bulkhead Assembly<br>Inspection, Piper Part No. 77553-02      | PA-38-112                    | 10/10/82 | 77553-06        | 82-27-08             | 5310         | 8F20  |
| 745    | Part III - Fin Spar Attachment<br>Plate Replacement Piper Part<br>No. 77553-05 | PA-38-112                    | 10/10/82 | 77553-05        | 82-27-08             | 5510         | 8F20  |
| 745    | Part IV-Aft Vertical Fin<br>Spar Inspection, Piper Part<br>No. 77601-02        | PA-38-112                    | 10/10/82 | **              | 82-27-08             | 5510         | 8F21  |
| 748    | Radio Support Installation                                                     | PA-38-112                    | 8/4/82   | 477-673         |                      | 2320         | 8G6   |
| 760    | Throttle Cable Inspection<br>Replacement of Jam Nut                            | PA-38-112                    | 4/16/84  | 2458-02         |                      | 7610         | 8H15  |
| 763A   | Upper Forward and Aft<br>Vertical Fin Spar Inspection<br>and Reinforcement     | PA-38-112                    | 7/25/83  | 764-965         | 83-19-01             | 5530         | 8I1   |
| 800    | Elevator Control Travel<br>Modification                                        | PA-38-112                    | 11/19/84 | 76193-02        | 85-11-06             | 2730         | 9C4   |
| 813    | Throttle Cable Installation<br>Inspection                                      | PA-38-112                    | 1/3/86   | 77907-002       |                      | 7612         | 9F14  |
| 834    | Rear Spar Frame<br>Stiffener Installation<br>(Fuselage Station 99.29)          | PA-38-112                    | 4/22/86  | 765-177         |                      | 5310         | 9I23  |
| 836A   | Aluminum Wire<br>Inspection/Replacement                                        | PA-38-112                    | 8/26/86  | **              |                      | 2400         | 9J4   |
| 851    | Carburetor Air Box Valve<br>Assembly Inspection/Modification                   | PA-38-112                    | 10/9/86  | **              |                      | 7163         | 9L16  |
| 855    | Use of Automobile Gasoline in<br>Piper Aircraft                                | All Piston Powered<br>Models | 1/14/87  | N/A             |                      | 2800         | 10A7  |
| 879    | Rivet Inspection - Wing Skin<br>To Spar, Top Inboard                           | PA-38-112                    | 1/22/88  | **              |                      | 5730         | 10G3  |
| 890    | Forward Tunnel<br>Inspection and Flap<br>Handle Cover Rework                   | PA-38-112                    | 7/7/88   | 765-358         |                      | 2752         | 10H20 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

PA-38-112

| NUMBER | SUBJECT                                                                                                                                                  | MODELS<br>AFFECTED | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|-----------|-----------------|-------------|-------------|
| 891    | Wiring Modification<br>Wing To Main Wire<br>Harness Connectors                                                                                           | PA-38-112          | 7/15/88   | 764-530         |             | 2453        |
| 936    | Replacement of a 90 Degree<br>Fitting and Inspection of the Tee<br>Fitting and Nipple at the Oil<br>Pressure Transducer                                  | PA-38-112          | 3/16/90   | **              |             | 7257        |
| 991A   | Replacement or Modification of the<br>Alternator Out Light Fuse                                                                                          | PA-38-112          | 1/29/96   | **              |             | 2437        |
| 1026   | Distribution of Parker Hannifin<br>Airborne Service Letter 48,<br>"Inspection/Replacement of<br>dry air pump flexible couplings."                        | PA-38-112          | 10/5/98   | 753-910         |             | 3711        |
| 1041   | Distribution of Airborne<br>Service Letter Number 56,<br>"Inspection and Cleaning of<br>Airborne Air Filter Elements."                                   | PA-38-112          | 9/25/2000 | **              |             | 3714        |
| 1200   | Landing Gear Modification and<br>Hardware Replacement                                                                                                    | PA-38-112          | 5/29/2009 | 88455-002       | 90-19-03    | 3207        |
| 1284B  | Lycoming SB 622A, Slick/Champion<br>Aerospace SB1-15A, Potential<br>decreased service life of Slick<br>4-cylinder magneto distributor gear<br>assemblies | PA-38-112          | 4/12/2019 | N/A             |             | 7414        |
| 1297   | Altimeter Inspection and<br>Replacement (United Instruments<br>SB No. 13)                                                                                | All                | 5/10/2016 | N/A             |             | 3416        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

**SB93**

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------|--------------------|------|-----------------|-------------|-------------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.  
\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.



# SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                                      | MODELS<br>AFFECTED       | DATE     | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE      |
|--------|------------------------------------------------------------------------------|--------------------------|----------|----------------------|-------------|------------------|
| 677    | Publications for Aircraft Operation                                          | All Piper<br>Models      | 5/20/80  |                      |             | PARA<br>15.0 7H4 |
| 780A   | Part I - Flap Drive Mechanism<br>Modification                                | PA-46-310P               | 10/10/85 | 765-118V             |             | 2910 8K7         |
| 780A   | Part II - Flap Selector Valve<br>Replacement                                 | PA-46-310P               | 10/10/85 | 83729-04             |             | 2910 8K8         |
| 781    | Aft Rudder Cable Inspection                                                  | PA-46-310P               | 6/25/84  | **                   |             | 2720 8K10        |
| 782A   | Magneto Switch Guard Installation                                            | PA-46-310P               | 4/24/85  | N/A                  |             | 7410 8K12        |
| 783    | Interference of Elevator<br>to Stabilizer                                    | PA-46-310P               | 6/13/84  | 765-132V             |             | 5520 8K15        |
| 784    | Pressure Outflow & Safety<br>Valve Routing Inspection                        | PA-46-310P               | 8/7/84   | 557-114              |             | 2130 8K17        |
| 786    | Toe Brake Cylinder Clevis Rework                                             | PA-46-310P               | 8/20/84  | N/A                  |             | 3241 8L6         |
| 790A   | Part I - Turbo Oil Scavenge<br>Reservoir Inspection                          | PA-46-310P               | 2/14/85  | **                   |             | 7250 9A1         |
| 790A   | Part II - Turbo Oil Scavenge<br>Oil Line Support                             | PA-46-310P               | 2/14/85  | **                   |             | 7250 9A2         |
| 790A   | Part III - Lower Cowl Modification                                           | PA-46-310P               | 2/14/85  | N/A                  |             | 7250 9A3         |
| 791    | Oxygen System Electrical<br>Wiring Rerouting                                 | PA-46-310P               | 8/20/84  | N/A                  |             | 3529 9A7         |
| 792    | Fuel Supply Line Replacement &<br>Wing Rib Modification                      | PA-46-310P               | 8/7/84   | **                   |             | 2814 9A13        |
| 794    | Electric Fuel Pump Circuitry<br>Modification                                 | PA-46-310P               | 8/30/84  | **                   |             | 2820 9A20        |
| 796B   | Part I - Lower Wing Rivet<br>Replacement                                     | PA-46-310P<br>PA-46-350P | 1/25/95  | **                   |             | 5733 9B8         |
| 796B   | Part II - Wing to Fuselage Fairing<br>Replacement                            | PA-46-310P               | 1/25/95  | **                   |             | 5733 9B9         |
| 796B   | Part III - Upper Inboard Wing<br>Rivet Replacement                           | PA-46-310P               | 1/25/95  | **                   |             | 5733 9B9         |
| 799    | Landing Gear Control Lever<br>Safety Tab Modification                        | PA-46-310P               | 10/26/84 | **                   |             | 3260 9C1         |
| 803A   | Pneumatic Surface Deice<br>Pressure Control Valve                            | PA-46-310P               | 3/21/86  | 765-159<br>84523-805 |             | 3014 9C18        |
| 805A   | TRW Hartzell Propeller<br>Service Bulletin No. 142<br>(O-ring Deterioration) | PA-46-310P               | 3/14/86  | N/A                  |             | 6110 9D15        |
| 808    | Main And Nose Landing Gear<br>Actuator Seal Replacement                      | PA-46-310P               | 7/10/85  | **                   |             | 2930 9E10        |
| 809    | Nose Landing Gear<br>Steering Rotator Inspection<br>And Replacement          | PA-46-310P               | 7/1/85   | **                   |             | 3251 9E21        |
| 810    | Gear Safety Solenoid<br>Installation Modification                            | PA-46-310P               | 7/9/85   | 422-166<br>406-385   |             | 3200 9F1         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

**SB95**

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                              | MODELS<br>AFFECTED           | DATE      | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE        |
|--------|------------------------------------------------------------------------------------------------------|------------------------------|-----------|--------------------|-------------|--------------------|
| 820A   | Aft Wing Attach<br>Fitting Fastener<br>Inspection/Replacement                                        | PA-46-310P                   | 4/20/2011 | 680-660<br>557-501 |             | 5741               |
| 824    | Electric Flap Motor -<br>Actuator Installation<br>Rework                                             | PA 46-310P                   | 3/21/86   | **                 |             | 2753 9H11          |
| 837    | Main Landing Gear<br>Lower Torque Link<br>Bolt Inspection                                            | PA-46-310P                   | 5/21/86   | 424-052            |             | 3213 9J8           |
| 852    | Alternate Air Control<br>Linkage Adjustment                                                          | PA-46-310P                   | 11/14/86  | N/A                | 87-04-01    | 7164 9L19          |
| 853    | Fuel Drain Replacement                                                                               | PA-46-310P                   | 11/17/86  | 765-317            |             | 2823 10A1          |
| 854A   | Deice Timer Protection -<br>Electrical Circuit Change                                                | PA-46-310P                   | 10/28/87  | **                 |             | 3016 10A3          |
| 855    | Use of Automobile Gasoline in<br>Piper Aircraft                                                      | All Piston Powered<br>Models | 1/14/87   | N/A                |             | 2800 10A7          |
| 858    | Nose Landing Gear Steering Rotator<br>Horn Attach Bolt Replacement                                   | PA-46-310P                   | 4/1/87    | 401-302<br>407-565 |             | 3251 10A15         |
| 862A   | Electrically Operated Flap System,<br>Actuator Tube Replacement                                      | PA-46-310P                   | 8/11/87   | 85070-02           |             | 2753 10B3          |
| 863A   | Part I - Aileron Cable Routing - Wing                                                                | PA-46-310P                   | 1/31/89   | 765-331            |             | 2712 10B6          |
| 863A   | Part II - Phenolic Fairlead Installation                                                             | PA-46-310P                   | 1/31/89   | **                 |             | 2712 10B7          |
| 865A   | Part I - Freon Compressor Drive<br>Pulley Nut Inspection And<br>Belt Removal                         | PA-46-310P                   | 7/14/87   | **                 | 87-12-12    | 2513 10B13         |
| 865A   | Part II - TCM Mandatory<br>Service Bulletin M87-13<br>"Broken Starter Adapter<br>Shafts"             | PA-46-310P                   | 7/14/87   | **                 |             | 2513 10B14         |
| 871    | Airframe And Powerplant<br>Operational Limitations                                                   | PA-46-310P                   | 10/13/87  | **                 |             | 7100 10C15         |
| 876B   | Part I -Malibu Return<br>To Service                                                                  | PA-46-310P                   | 4/14/88   | **                 | 87-14-02    | 7200 10E8          |
| 876B   | Part II - Teledyne Continental<br>Motor Service Bulletin<br>M88-5 "Broken Starter<br>Adapter Shafts" | PA-46-310P                   | 4/8/88    | **                 | 88-17-03    | 7200 10E9          |
| 883    | Additional Post Lighting - Flight<br>and Engine Instrumentation                                      | PA-46-310P                   | 3/10/88   | 765-353            |             | 3311 10G18         |
| 884    | Lock Wiring of<br>V-Band Couplings                                                                   | PA-46-310P                   | 4/8/88    | **                 |             | 7800 10G20<br>2100 |
| 892A   | Powerplant Cooling<br>Improvement                                                                    | PA-46-310P                   | 5/17/89   | 765-365            | 88-25-08    | 7520 10I1          |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                                                  | MODELS<br>AFFECTED       | DATE     | PART/KIT<br>NO.               | A.D.<br>NO. | ATA<br>CODE         |
|--------|------------------------------------------------------------------------------------------|--------------------------|----------|-------------------------------|-------------|---------------------|
| 895    | Alternate Air Box<br>Bearing Block<br>Modification                                       | PA-46-310P               | 11/17/88 | 420-219                       |             | 7160 10I10          |
| 896    | Shoulder Harness<br>Installation & Usage                                                 | PA-46-310P               | 11/28/88 | **                            |             | 5340 10I13          |
| 900    | Missing Upper Fuselage<br>Rivets                                                         | PA-46-310P               | 2/13/89  | 522-601                       |             | 5333 10J11          |
| 913A   | Malibu Return to Service                                                                 | PA-46-310P               | 6/29/89  | N/A                           | 89-14-01    | 7226 10L15          |
| 915    | Lycoming Service Bulletin<br>No. 487 (Included with<br>Lycoming Kit)                     | PA-46-350P               | 7/8/89   | **                            | 89-15-10    | 7311 10aA5          |
| 917    | Angle Support Forward<br>Baggage Compartment                                             | PA-46-310P               | 7/19/89  | 765-367                       |             | 2551 10aA14         |
| 919    | Carpet Runner Retainer<br>Installation                                                   | PA-46-310P               | 8/3/89   | 765-369                       |             | 2520 10aB2          |
| 921    | Aileron Inspection                                                                       | PA-46-310P<br>PA-46-350P | 8/15/89  | **                            |             | 2715 10aB9          |
| 928A   | Textron Lycoming Service Bulletin<br>No. 491A, Inspection of Exhaust<br>Transition Bolts | PA-46-350P               | 3/22/90  | **                            |             | 7800 10aC12         |
| 930    | Inspection of Emergency Exit<br>Window Fit                                               | PA-46-350P               | 12/14/89 | N/A                           |             | 5621 10aC20         |
| 934    | Inspection and Rerouting of<br>the Manifold Pressure Line                                | PA-46-350P               | 2/8/90   | **                            |             | 7716 10aD12         |
| 939    | Weight and Balance Plotter                                                               | PA-46-350P               | 6/8/90   | N/A                           |             | 1110 10aE4          |
| 941    | Improved Engine Baffle Support                                                           | PA-46-350P               | 7/17/90  | **                            |             | 7236 10aE9          |
| 943A   | Landing Gear Locking Actuator<br>End Gland Replacement                                   | PA-46-310P               | 8/15/90  | 763-060                       |             | 3235 10aF1          |
| 944    | Empennage Rivet Replacement                                                              | PA-46-310P<br>PA-46-350P | 10/5/90  | **                            |             | 5510 10aF12<br>5530 |
| 947A   | Low Vacuum Annunciator Light<br>Operation                                                | PA-46-310P<br>PA-46-350P | 10/29/91 | **                            |             | 3720 10aF23         |
| 948    | Inboard Wing Rib Inspection,<br>Modification, Replacement                                | PA-46-310P<br>PA-46-350P | 1/25/91  | **                            |             | 5710 10aG3          |
| 949    | Wing Rib Reinforcement                                                                   | PA-46-310P<br>PA-46-350P | 2/18/91  | 766-247<br>766-248<br>766-249 |             | 5712 10aG10         |
| 951    | Mixture Control Cable<br>Inspection and Routing                                          | PA-46-350P               | 2/18/92  |                               |             | 7320 10aG14         |
| 953    | Elevator Trim Cable<br>Guide Tube Splice                                                 | PA-46-310P<br>PA-46-350P | 10/29/91 | 766-272                       |             | 2730 10aG23         |
| 958    | Horizontal Stabilizer<br>Drain Hole Installation                                         | PA-46-310P<br>PA-46-350P | 9/22/92  |                               |             | 5510 10aH17         |
| 959    | Fuselage Rivet Installation                                                              | PA-46-310P<br>PA-46-350P | 3/31/93  | **                            |             | 5310 10aH20         |
| 960    | Engine Mount Heat Shield                                                                 | PA-46-310P<br>PA-46-350P | 3/31/93  | 766-267<br>766-268            |             | 7120 10aI3          |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                | MODELS<br>AFFECTED                      | DATE       | PART/KIT<br>NO.     | A.D.<br>NO. | ATA<br>CODE   |
|--------|--------------------------------------------------------------------------------------------------------|-----------------------------------------|------------|---------------------|-------------|---------------|
| 961    | Alternate Air Door Replacement<br>and Control Linkage Inspection                                       | PA-46-310P<br>PA-46-350P                | 10/21/92   | **                  |             | 7160 10aI5    |
| 962    | Corrosion Inspection and Protection                                                                    | PA-46-310P<br>PA-46-350P                | 9/29/93    | **                  |             | 5510 10aJ4    |
| 963    | Electric Flap Cam Assembly<br>Modification                                                             | PA-46-310P<br>PA-46-350P                | 6/11/93    | 766-245             |             | 2750 10aI17   |
| 964B   | Hydraulic Power Pak Pressure<br>Switch Replacement                                                     | PA-46-310P<br>PA-46-350P                | 5/24/96    | 766-278<br>766-277  |             | 2911 10aJ14   |
| 976    | Inspection for and Replacement<br>of Components with Suspect<br>"O" Rings                              | PA-46-350P                              | 12/9/94    | **                  |             | 2911 10bA10   |
| 981    | Hydraulic Power Pak Lower<br>Manifold Inspection                                                       | PA-46-310P<br>PA-46-350P                | 1/17/95    | **                  |             | 2911 10bB15   |
| 982    | Installation of Limitations Placard                                                                    | PA-46-350P                              | 4/3/95     | **                  |             | 1100 10bC1    |
| 985    | Hydraulic System Power Pak<br>Pressure Switch Replacement                                              | PA-46-310P<br>PA-46-350P                | 6/16/95    | 765-457             |             | 2911 10bC17   |
| 990    | Pacific Scientific Seat Belt<br>Replacement                                                            | PA-46-350P                              | 1/3/96     | **                  |             | 5346 10bD12   |
| 993    | KLN-90B GPS Wiring Modification                                                                        | PA-46-350P                              | 3/18/96    | **                  |             | 3441 10bE4    |
| 994    | Intermittent Main Landing Gear<br>Indication (Parker Hannifin SB7049)<br>(Attached)                    | PA-46-310P<br>PA-46-350P                | 3/8/96     | **                  |             | 2911 10bE6    |
| 995C   | Turbine Inlet Temperature (T.I.T.)<br>System Calibration and Probe<br>Replacement                      | PA-46-310P<br>PA-46-350P<br>PA-46R-350T | 11/17/2009 | **                  | 2011-06-10  | 7726 (10bE11) |
| 997    | Inspection of Jack Pad attachment<br>Area at Wing Cutout for Radar                                     | PA-46-310P<br>PA-46-350P                | 2/7/97     | 766-628             |             | 5740 10bE20   |
| 999    | Modification of Inertia Reel Shoulder<br>Harness Mounting Brackets                                     | PA-46-310P<br>PA-46-350P                | 3/5/97     | 766-638             |             | 5346 10bF9    |
| 1000   | Inspection of Engine Electrical<br>Harness and Installation of<br>Chafing Protection                   | PA-46-350P                              | 4/25/97    | 49990-36<br>488-702 |             | 2436 10bF11   |
| 1001   | Inspection for Missing Washers<br>at Nose Gear Steering Arm Rod End                                    | PA-46-350P                              | 6/16/97    | **                  |             | 3251 10bF14   |
| 1012   | Distribution of Textron Lycoming<br>Service Bulletin 531, Inspection of<br>turbochargers and Tailpipes | PA-46-350P                              | 2/4/98     | **                  |             | 7800 10bH3    |
| 1014   | Replacement of Battery Power Fuse                                                                      | PA-46-350P                              | 3/2/98     | 461-681             |             | 2436 10bH11   |
| 1017   | Alternator Regulator Wiring Mod                                                                        | PA-46-350P                              | 4/10/98    | **                  |             | 2436 10bH21   |
| 1020   | Inspection of the ARTEX 110-4 ELT<br>and ELT Attachment Bracket                                        | PA-46-350P                              | 7/10/98    | **                  |             | 2563 10bI11   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                                                                                              | MODELS<br>AFFECTED                      | DATE       | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|------------|------------------------|-------------|-------------|
| 1021   | Modification of Control Wheel<br>Quadrant Stop and Inspection of<br>Forward Pressure Bulkhead                                        | PA-46-310P<br>PA-46-350P                | 8/4/98     | 766-654                |             | 5346 10b111 |
| 1027   | Modification of Forward and Aft<br>Wing Attach Fittings                                                                              | PA-46-350P                              | 11/19/98   | 766-656<br>766-657     | 99-16-06    | 5741 10bK4  |
| 1029   | Distribution of Textron Lycoming<br>Service Bulletin 534,<br>Turbocharger Oil Drain Tank<br>Inspection/Replacement                   | PA-46-350P                              | 4/30/99    |                        |             | 7164 10b17  |
| 1034   | Battery Master Contactor Wiring<br>Modification                                                                                      | PA-46-350P                              | 8/17/99    | 84350-11<br>84350-12   |             | 2454 10bL13 |
| 1035A  | Distribution of Textron Lycoming<br>Service Bulletin 529B, "Reprint of<br>Crane/Lear Romec Service<br>Bulletin No. 101SB020, Rev. 3" | PA-46-350P                              | 3/22/2007  | **                     | 2003-14-03  | 7311 10bL16 |
| 1041   | Distribution of Airborne<br>Service Letter Number 56,<br>"Inspection and Cleaning of<br>Airborne Air Filter Elements."               | PA-46-310P<br>PA-46-350P                | 9/25/2000  | **                     |             | 3714 10cB1  |
| 1046   | POH Supplement Installation                                                                                                          | PA-46-350P                              | 11/28/2000 | **                     |             | 2212 10cC4  |
| 1048   | Stainless Steel Control Cables                                                                                                       | PA-46-350P                              | 1/3/2001   | N/A                    |             | 2702 10cC9  |
| 1052   | Nose Gear Steering Bungee Assy<br>Modification                                                                                       | PA-46-500TP                             | 2/26/2001  | 766-690                |             | 3255 10cC23 |
| 1053   | Outside Air Temperature Probe<br>Relocation                                                                                          | PA-46-500TP                             | 4/3/2001   | 766-688                |             | 3416 10cD2  |
| 1054   | Pilot and Co-Pilot Seat Inspection<br>and Modification                                                                               | PA-46-310P<br>PA-46-350P<br>PA-46-500TP | 4/12/2001  | **                     |             | 2514 10cD6  |
| 1055   | Engine Control Quadrant Inspection<br>and Modification                                                                               | PA-46-500TP                             | 5/29/2001  | 82995-003              |             | 7601 10cD9  |
| 1056   | Fuel Drain Valve Inspection<br>and Replacement                                                                                       | PA-46-500TP                             | 4/4/2001   | 766-691                |             | 7319 10cD21 |
| 1058   | Overhead Switch Panel<br>Replacement                                                                                                 | PA-46-500TP                             | 5/31/2001  | 680-839<br>688-497     |             | 3110 10cE3  |
| 1059   | Low Pressure Engine Driven<br>Pump Leakage Inspection                                                                                | PA-46-500TP                             | 6/11/2001  | 461-752                |             | 7311 10cE6  |
| 1060   | Brake Pedal Binding                                                                                                                  | PA-46-310P<br>PA-46-350P<br>PA-46-500TP | 5/15/2001  | **                     |             | 3241 10cE9  |
| 1061   | Nose Landing Gear Strut Tube<br>Snap Ring Inspection                                                                                 | PA-46-500TP                             | 6/19/2001  | N/A                    |             | 3223 10cE13 |
| 1062   | Inboard Flap Drive Bellcrank<br>Inspection and Replacement                                                                           | PA-46-310P<br>PA-46-350P<br>PA-46-500TP | 5/11/2001  | 82905-002<br>82905-003 | 1-12-01     | 2755 10cE16 |
| 1063   | Circuit Breaker Panel Modifications                                                                                                  | PA-46-500TP                             | 6/11/2001  | 581-657                |             | 2451 10cE22 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                  | MODELS<br>AFFECTED                      | DATE       | PART/KIT<br>NO.                     | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------|-----------------------------------------|------------|-------------------------------------|-------------|-------------|
| 1064   | Mass Flow Control Valve Support<br>Clip Installation                                                     | PA-46-500TP                             | 6/14/2001  | 102501-002                          |             | 2125 10cF4  |
| 1065   | Primary Elevator Control Cable<br>Replacement                                                            | PA-46-500TP                             | 7/25/2001  | **                                  |             | 2735 10cF10 |
| 1066   | Cabin Door Latch Mechanism                                                                               | PA-46-350P<br>PA-46-500TP               | 7/10/2001  | 767-305                             |             | 5213 10cF14 |
| 1067A  | Entertainment Console (Small<br>Cabinet) Voltage Dropping<br>Resistor Shroud Installation                | PA-46-350P<br>PA-46-500TP               | 8/8/2001   | 767-301<br>767-302                  |             | 2507 10cF17 |
| 1068   | Fuel System Line Fitting Leakage                                                                         | PA-46-500TP                             | 7/19/2001  | **                                  |             | 2823 10cF20 |
| 1069   | Fuel System Trim Fitting and<br>Solenoid Valve Modification                                              | PA-46-500TP                             | 7/19/2001  | 766-682                             |             | 2825 10cG2  |
| 1070   | Lightning Protection Rivets<br>Installation                                                              | PA-46-500TP                             | 7/16/2001  | 767-303                             |             | 2816 10cG5  |
| 1071   | Main Landing Gear Squat Switch<br>Safetying                                                              | PA-46-500TP                             | 7/2/2001   | N/A                                 |             | 3237 10cG8  |
| 1072   | Mass Air Control Valve Recall                                                                            | PA-46-500TP                             | 8/13/2001  | 592-640                             |             | 2138 10cG12 |
| 1073   | Magnetic Flux Detector Connector                                                                         | PA-46-500TP                             | 8/13/2001  | 599-693                             |             | 3427 10cG15 |
| 1074   | Cabin Bleed Air Restriction                                                                              | PA-46-500TP                             | 7/23/2001  | N/A                                 |             | 2182 10cG20 |
| 1075A  | Steering Horn Modification                                                                               | PA-46-310P<br>PA-46-350P                | 5/5/2003   | 85154-002<br>85154-012              |             | 3251 10cH1  |
| 1076   | GI-106 NAV/GS Indicator<br>Wiring Harness Inspection /<br>Modification                                   | PA-46-500TP                             | 7/19/2001  | N/A                                 |             | 3316 10cH6  |
| 1077   | P&WC PT6A-42A Engine<br>Oil-to-Fuel Heater Inspection                                                    | PA-46-500TP                             | 7/13/2001  | 762-156                             |             | 7200 10cH11 |
| 1078   | Stall Warning Microswitch Bracket                                                                        | PA-46-500TP                             | 8/13/2001  | 767-306                             |             | 2226 10cI1  |
| 1080   | Lear Romec Fuel Pump                                                                                     | PA-46-500TP                             | 7/26/2001  | 461-757                             |             | 2820 10cI7  |
| 1082   | Aft Stowage Compartment Drain                                                                            | PA-46-500TP                             | 8/13/2001  | 766-693                             |             | 2550 10cI16 |
| 1084   | Flight Into Known Icing (FIKI)<br>Certification                                                          | PA-46-500TP                             | 9/20/2001  | **                                  |             | 3010 10cJ1  |
| 1085   | Nose Landing Gear Steering Arm<br>Chafing                                                                | PA-46-500TP                             | 10/26/2001 | 767-304                             |             | 3220 10cJ6  |
| 1086   | Generator Ammeter Relay Kit                                                                              | PA-46-500TP                             | 10/3/2001  | 767-308                             |             | 2434 10cJ10 |
| 1087B  | Nose Gear Emergency Downspring<br>Mechanism Replacement                                                  | PA-46-310P<br>PA-46-350P<br>PA-46-500TP | 5/27/2003  | 766-211<br>104723-002<br>104723-003 |             | 3235 10cJ13 |
| 1088   | Aft Spar Splice Cap Inspection                                                                           | PA-46-500TP                             | 12/10/2001 | 767-321                             |             | 2751 10cJ18 |
| 1089   | Nose Gear Squat Switch Adjustment                                                                        | PA-46-500TP                             | 11/12/2001 | N/A                                 |             | 3265 10cJ22 |
| 1090   | Fuel Restrictor Assy / Fuel Return<br>Solenoid Removal                                                   | PA-46-500TP                             | 8/23/2001  | 767-324                             |             | 2825 10cK1  |
| 1091   | Pratt & Whitney PT6A-42A Engines -<br>Turboprop Engine Oil-to-Fuel Heater<br>Thermal Element Replacement | PA-46-500TP                             | 9/20/2001  | N/A                                 |             | 7200 10cK4  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                                                        | MODELS<br>AFFECTED                      | DATE       | PART/KIT<br>NO.                                                    | A.D.<br>NO. | ATA<br>CODE |
|--------|------------------------------------------------------------------------------------------------|-----------------------------------------|------------|--------------------------------------------------------------------|-------------|-------------|
| 1093   | Alternator Isolation Diode Installation                                                        | PA-46-500TP                             | 12/5/2001  | 767-307                                                            |             | 2430        |
| 1094   | Fuel System Check Valve Replacement                                                            | PA-46-500TP                             | 10/19/2001 | 592-670                                                            |             | 2813        |
| 1095   | Gear Warning Horn Mute Switch                                                                  | PA-46-500TP                             | 1/18/2002  | 766-697                                                            |             | 3260        |
| 1098   | Pneumatic Deice System Line Inspection and Replacement                                         | PA-46-500TP                             | 2/1/2002   | 102437-086                                                         |             | 3015        |
| 1099   | Feather Solenoid Suppression Diode Kit                                                         | PA-46-500TP                             | 1/18/2002  | 767-328                                                            |             | 6123        |
| 1102   | Master Electrical Panel Mounting Plate Inspection and Fuse Block Protective Cover Installation | PA-46-500TP                             | 3/8/2002   | 767-327                                                            |             | 2400        |
| 1103F  | Engine Mount Inspection                                                                        | PA-46-310P<br>PA-46-350P<br>PA-46R-350T | 9/1/2015   | 84010-002<br>89137-041<br>89137-042<br>89137-043                   |             | 7120        |
| 1106   | Nose Gear Steering System Improvement                                                          | PA-46-500TP                             | 1/28/2002  | 767-336<br>767-338                                                 |             | 3220        |
| 1107   | Maneuvering Speed Placard Replacement                                                          | PA-46-500TP                             | 3/7/2002   | 692-721                                                            |             | 1100        |
| 1108   | Flux Detector Relocation                                                                       | PA-46-350P<br>PA-46-500TP               | 3/11/2002  | 767-335<br>767-334                                                 |             | 3429        |
| 1111   | Float Switch Wiring Inspection                                                                 | PA-46-500TP                             | 8/19/2002  | 602-501                                                            |             | 2424        |
| 1114   | No. 1 GNS 530 Lighting Rewiring                                                                | PA-46-500TP                             | 4/24/2002  | 766-696                                                            |             | 3457        |
| 1121   | Installation of Missing Rivets on Lower Surface of Horizontal Stabilizer Spar                  | PA-46-500TP                             | 10/3/2002  | MS20470AD5                                                         |             | 5510        |
| 1126A  | Emergency Gear Extension Cable Bracket Modification                                            | PA-46-350P<br>PA-46-500TP               | 2/21/2005  | 767-364                                                            |             | 3237        |
| 1132   | Electronic Control Module Failures                                                             | PA-46-500TP                             | 6/4/2003   | 102226-002<br>102227-002<br>102227-006<br>102228-002<br>102228-006 | 4-03-32     | 2400        |
| 1134   | Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)     | PA-46-350P                              | 6/10/2003  | **                                                                 |             | 2800        |
| 1135   | GMA-340 Audio Panel Wiring                                                                     | PA-46-350P<br>PA-46-500TP               | 7/16/2003  | N/A                                                                |             | 2370        |
| 1139A  | Control Wheel Attachment Inspection                                                            | PA-46-350P<br>PA-46-500TP               | 4/9/2004   | **                                                                 | 4-14-12     | 2701        |
| 1140   | Oxygen Generator Protective Cap Removal                                                        | PA-46-310P<br>PA-46-350P<br>PA-46-500TP | 9/16/2003  | 471-025                                                            |             | 3500        |
| 1144   | Nose Gear Door Hinge Modification                                                              | PA-46-500TP                             | 3/10/2004  | **                                                                 |             | 5280        |
| 1150   | Standby Airspeed and Altimeter Indicator Pitot/Static Lines Replacement                        | PA-46-500TP                             | 12/9/2004  | 767-377                                                            |             | 3411        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                             | MODELS<br>AFFECTED                                     | DATE       | PART/KIT<br>NO.                                          | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------|--------------------------------------------------------|------------|----------------------------------------------------------|-------------|-------------|
| 1151E  | 4130N Steel Hardness Discrepancy                    | PA-46-350P<br>PA-46-500TP                              | 6/9/2004   | **                                                       |             | 5741 10dJ4  |
| 1152   | Fuel Restrictor Replacement                         | PA-46-500TP                                            | 1/5/2005   | 767-386                                                  |             | 2821 10dJ8  |
| 1154C  | Engine Mount Inspection                             | PA-46-500TP                                            | 1/3/2008   | 102460-036<br>102460-002<br>767-515<br>401-509 (AN7-15A) |             | 7121 10dJ14 |
| 1158A  | Accessory Drive Pulley Improvement                  | PA-46-500TP                                            | 1/30/2006  | 102406-006                                               |             | 7260 10dK7  |
| 1159   | Fuel System Check Valve                             | PA-46-500TP                                            | 11/10/2005 | 592-670                                                  |             | 2813 10dK10 |
| 1166   | Electronic Control Module Replacement               | PA-46-500TP                                            | 1/5/2007   | 102227-007                                               | 4-03-32     | 3418 10dL12 |
| 1168   | Elevator Trim Tab Hinge Rivets                      | PA-46-350P                                             | 9/1/2006   | 767-544                                                  |             | 2711 10dL20 |
| 1170   | Louvered Cover Assembly                             | PA-46-500TP                                            | 10/6/2006  | 767-545                                                  |             | 2100 10eA1  |
| 1173B  | Engine Oil Hose Assemblies                          | PA-46-500TP                                            | 11/16/2011 | 88407-002                                                |             | 7920        |
| 1175B  | Pilot's Side Window Inspection                      | PA-46-310P<br>PA-46-350P<br>PA-46-500TP                | 9/30/2010  | **                                                       |             | 5610        |
| 1176   | Rudder Quadrant / Torque Tube Inspection - Tailcone | PA-46-350P<br>PA-46-500TP                              | 1/16/2007  | **                                                       |             | 2720 10eA22 |
| 1177   | Nose Wheel Assembly (Cleveland SB 7083A)            | PA-46-500TP                                            | 11/14/2006 | 40-77B<br>767-569                                        |             | 3246 10eB3  |
| 1178   | Nose Gear Forging Inspection / Replacement          | PA-46-350P<br>PA-46-500TP                              | 9/24/2007  | 67050-005<br>67050-006                                   |             | 3222 10eB10 |
| 1180A  | V-Band Exhaust Coupling Inspection                  | PA-46-350P                                             | 3/14/2007  | **                                                       |             | 7200 10eB18 |
| 1181B  | Flap Track/Splice Strap Inspection and Modification | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 9/10/2009  | 104469-002                                               |             | 2750        |
| 1182   | Wing Inspection Light                               | PA-46-350P                                             | 8/22/2007  | 84579-002                                                |             | 3340 10eC1  |
| 1183   | Emergency Exit Door Inspection                      | PA-46-500TP                                            | 5/15/2007  | 82650-004<br>102919-002                                  |             | 5220 10eC5  |
| 1185   | Placard Replacement                                 | PA-46-350P<br>PA-46-500TP                              | 8/30/2007  | 684-762<br>684-761                                       |             | 2440 10eC21 |
| 1187   | Voltage Suppressor Replacement                      | PA-46-350P<br>PA-46-500TP                              | 2/8/2008   | 88432-002<br>(Kit)                                       |             | 3400 10eD4  |
| 1190B  | Aileron Quadrant Inspection                         | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T | 1/22/2009  | 82858-002                                                |             | 2710        |
| 1192   | Stall Warning Heat Control Modification             | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 9/15/2008  | 88452-002<br>(Kit)                                       | 2008-26-11  | 3418        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.



# SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                                                          | MODELS<br>AFFECTED                                     | DATE       | PART/KIT<br>NO.                      | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------|--------------------------------------------------------|------------|--------------------------------------|-------------|-------------|
| 1193   | Nose Gear Down Spring Replacement                                                                | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T | 3/3/2009   | 687-931                              |             | 3230        |
| 1195B  | Comm 1 and Comm 2 Antenna and Skin Inspection                                                    | PA-46-350P<br>PA-46-500TP                              | 4/15/2010  | **                                   |             | 2312        |
| 1196   | Collector Tank Fuel Drain Inspection                                                             | PA-46-350P<br>PA-46R-350T                              | 10/23/2008 | 84029-018<br>84029-017               |             | 2830        |
| 1201   | Tie Bus Circuit Breaker Inspection                                                               | PA-46R-350T                                            | 2/16/2009  | N/A                                  |             | 2400        |
| 1202   | Beta / Reverse Lockout Lever Inspection                                                          | PA-46-500TP                                            | 3/18//2009 | **                                   |             | 7600        |
| 1204   | Re-Calculation of Wing Structure Life Limit Due To Unique Usage                                  | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T | 12/18/2009 | N/A                                  |             | 5711        |
| 1205   | Relocation of the PY Heater Ground Wire Termination                                              | PA-46-500TP                                            | 3/24/2010  | 106798-002                           |             | 3230        |
| 1208   | Lightning Diverter Inspection                                                                    | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 2/15/2010  | **                                   |             | 5180        |
| 1210   | TWX670 Antenna Inspection                                                                        | PA-46R-350T                                            | 12/21/2009 | **                                   |             | 3450        |
| 1211   | Aft Bulkhead Sealing Modification                                                                | PA-46R-350T                                            | 3/2/2010   | PR-1422-A2<br>PR-1422-B4             |             | 5110        |
| 1212   | Inspection of Flap Position Indicator Placard                                                    | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 1/5/2010   | **                                   |             | 1130        |
| 1214A  | Compressor Turbine Blade Inspection                                                              | PA-46-500TP                                            | 3/4/2010   | N/A                                  |             | 7231        |
| 1217A  | Starter Contactor Replacement                                                                    | PA-46-350P<br>PA-46R-350T                              | 1/14/2011  | 88465-002                            |             | 2400        |
| 1218   | Rudder Skin Inspection                                                                           | PA-46-500TP                                            | 10/13/10   | 83403-003<br>88471-002<br>106884-002 |             | 5540        |
| 1223   | Wire Screen Replacement                                                                          | PA-46-350P<br>PA-46R-350T                              | 11/10/10   | **                                   |             | 2126        |
| 1228   | Autopilot Circuitry Modification                                                                 | PA-46R-350T                                            | 1/21/2011  | 88485-002                            |             | 2210        |
| 1229   | Avox Systems Service Bulletin No. 36758-35-01 (O <sub>2</sub> Cylinder Bracket Latch Inspection) | PA-46-500TP                                            | 4/21/2011  | 453-528                              |             | 3510        |
| 1230   | Nose Wheel Grommet Inspection                                                                    | PA-46-500TP                                            | 6/6/2011   | 463-526                              |             | 3240        |
| 1232   | Cabin Door Handle Placard Inspection                                                             | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 5/16/2011  | 100700-014                           |             | 1120        |
| 1234   | Engine Oil Cooler Control Valve Replacement                                                      | PA-46-500TP                                            | 6/23/2011  | 592-712                              |             | 7920        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                                                                 | MODELS<br>AFFECTED                                     | DATE       | PART/KIT<br>NO.                        | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------------------------------------------------|--------------------------------------------------------|------------|----------------------------------------|-------------|-------------|
| 1236   | Landing Gear Servicing<br>and Placard Replacement                                                       | PA-46-500TP                                            | 10/6/2011  | 100700-084<br>100700-085<br>100700-086 |             | 1210        |
| 1237   | Static Discharger Replacement                                                                           | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 8/10/2011  | 456-904                                |             | 2360        |
| 1238   | Landing Gear Servicing<br>and Placard Replacement<br>- Meridian G1000 airplanes<br>registered in Brazil | PA-46-500TP                                            | 7/23/2013  | 106787-072<br>106787-073               |             | 1210        |
| 1243C  | Potential<br>Landing Gear Malfunction                                                                   | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 3/7/2012   | 102559-804RBL                          |             | 3200        |
| 1247B  | Garmin SafeTaxi® Limitation                                                                             | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 3/13/2019  | N/A                                    |             | 3420        |
| 1250A  | Pilot Operating Handbook<br>Permanent Revision                                                          | PA-46-350P<br>PA-46R-350T                              | 12/16/2013 | **                                     |             | 7320        |
| 1255   | Boost Pump Wiring Rerouting                                                                             | PA-46-500TP                                            | 3/4/2013   | 88541-001                              |             | 2820        |
| 1256   | Nose Landing Gear Torque Link<br>Hardware Replacement                                                   | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T | 1/23/2013  | 603-816<br>(MS14144-4)                 |             | 3220        |
| 1258   | Fuel Vent Valve Inspection                                                                              | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T | 6/5/2013   | 106927-001                             | 2013-13-01  | 2810        |
| 1262B  | Wing Inspection                                                                                         | PA-46-500TP                                            | 4/23/2015  | **                                     |             | 5713        |
| 1269A  | GWX 68 Ground Rewire                                                                                    | PA-46-350P<br>PA-46R-350T                              | 3/10/2014  | N/A                                    |             | 3440        |
| 1267A  | Empennage Rivets Inspection                                                                             | PA-46-500TP                                            | 12/18/2015 | 484-911                                |             | 5500        |
| 1271A  | Wing Spar Inspection                                                                                    | PA-46-310P<br>PA-46-350P<br>PA-46-500TP                | 12/12/2019 | **                                     |             | 5711        |
| 1275   | Nose Landing Gear Service Placard<br>Replacement                                                        | PA-46-500TP                                            | 6/26/2015  | 100700-125                             |             | 1130        |
| 1280A  | H3R Fire Extinguisher Replacement,<br>H3R Aviation SB 2015-1                                            | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 4/29/2016  | 459-887                                |             | 2620        |
| 1283A  | Cabin Altitude Encoder Installation<br>Modification                                                     | PA-46-350P<br>PA-46-500TP                              | 10/19/2016 | Sandia P/N<br>305216-02                |             | 2130        |
| 1284   | Aspen Avionics EFD1000 Update<br>to Software Version 2.10.2                                             | PA 46-350P<br>PA 46-500TP<br>PA-46-600TP               | ]2/7/2023  | N/A                                    |             | 3420        |
| 1288A  | Aft Vertical Fin Spar Inspection                                                                        | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 5/18/2017  | 404-532<br>MS21042-6                   |             | 5500        |
| 1290B  | Flap Bracket Inspection,<br>Inboard Bellcrank                                                           | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 12/14/2017 | N/A                                    |             | 2750        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                                                            | MODELS<br>AFFECTED                                                    | DATE       | PART/KIT<br>NO.                                   | A.D.<br>NO. | ATA<br>CODE  |
|--------|----------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|------------|---------------------------------------------------|-------------|--------------|
| 1291   | Executive Table Placards<br>Replacement                                                            | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                              | 8/11/2016  | 88581-701<br>or<br>88581-702                      |             | 2520         |
| 1293C  | Engine Mount Doubler Installation<br>and Towing Placards Replacement                               | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                | 3/9/2017   | 88582-701<br>88582-702<br>88584-701 (if required) |             | 1100<br>7120 |
| 1296   | Fuel Control Unit Manual Override<br>Inspection – Pratt & Whitney Canada<br>Service Bulletin A3487 | PA-46-500TP                                                           | 3/31/2016  | N/A                                               |             | 7600         |
| 1297   | Altimeter Inspection and<br>Replacement (United Instruments<br>SB No. 13)                          | All                                                                   | 5/10/2016  | N/A                                               |             | 3416         |
| 1303A  | Diode Module Installation                                                                          | PA-46-600TP                                                           | 10/15/2018 | 681-020                                           |             | 3410         |
| 1305   | Flight Into Known Icing (FIKI)<br>Modification                                                     | PA-46-600TP                                                           | 7/13/2017  | 88592                                             |             | 3000         |
| 1306   | Wing Rib Modification                                                                              | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                | 1/10/2018  | 88609-001<br>88609-002                            |             | 5712         |
| 1308   | Wet-Wing Fuel Access Cover<br>Inspection                                                           | PA-46-600TP                                                           | 5/10/2017  | Loctite 222MS<br>279-051                          |             | 2810         |
| 1310   | K303 Relay Relocation                                                                              | PA-46-600TP                                                           | 5/18/2017  | 584-423                                           |             | 2430         |
| 1314   | Cabin Door Frame Inspection                                                                        | PA-46-350P M350<br>PA-46-500TP M500<br>PA-46-600TP                    | 3/12/2018  | N/A                                               |             | 5311         |
| 1315   | Cabin Door Threshold Rivet<br>Replacement                                                          | PA-46-600TP                                                           | 12/21/2017 | N/A                                               |             | 5310         |
| 1317C  | Aft Wing Spar Inspection                                                                           | PA-46-600TP                                                           | 8/9/2017   | N/A                                               | 2017-16-03  | 5711         |
| 1318B  | Fuselage Station 144.25 Rivet<br>Replacement                                                       | PA-46-600TP                                                           | 6/7/2018   | 88623-701<br>88624-701                            | 2018-14-01  | 5330         |
| 1322   | Stall Warning Heat Ground Wire<br>Inspection                                                       | PA-46-500TP M500                                                      | 2/28/2018  | **                                                |             | 3418         |
| 1326A  | Propeller Heat Sensor Wiring<br>Modification                                                       | PA-46-600TP                                                           | 1/3/2019   | 465-258<br>461-654                                |             | 3060         |
| 1327   | Aileron Control Cable<br>Protection Tube Inspection                                                | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46-600TP<br>PA-46R-350T | 6/26/2018  | 88630-701                                         |             | 2710         |
| 1328   | Aileron Quadrant Cable Guard<br>Replacement                                                        | PA-46-350P M350<br>PA-46-500TP M500<br>PA-46-600TP                    | 6/26/2018  | 46F44A701-701                                     |             | 2710         |
| 1329   | Canted Frame Rivets Replacement                                                                    | PA-46-600TP                                                           | 2/3/2020   | 46F53A004<br>46F53A005                            |             | 5310         |
| 1332A  | Bulkhead Rivet Replacement                                                                         | PA-46-600TP                                                           | 1/29/2019  | N/A                                               |             | 5312         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE BULLETIN INDEX

| NUMBER | SUBJECT                                                              | MODELS<br>AFFECTED                                     | DATE       | PART/KIT<br>NO.                                  | A.D.<br>NO. | ATA<br>CODE  |
|--------|----------------------------------------------------------------------|--------------------------------------------------------|------------|--------------------------------------------------|-------------|--------------|
| 1333A  | Forward Wing Spar Attach Fitting Inspection                          | PA-46-600TP                                            | 4/18/2019  |                                                  |             | 5741         |
| 1334A  | EL Panel Inverter And Windshield Heat Relay Ground Wiring Relocation | PA-46-600TP                                            | 12/5/2018  | N/A                                              |             | 3040<br>3310 |
| 1336   | Aileron-Rudder Interconnect Inspection                               | PA-46-350P M350<br>PA-46-500TP M500<br>PA-46-600TP     | 1/18/2019  | 83287-006                                        |             | 2700         |
| 1338   | Main Gear Actuator Attach Fitting Inspection                         | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T | 3/25/2020  | 467-496                                          |             | 3211         |
| 1339A  | Generator Relay (K303) Replacement                                   | PA-46-600TP                                            | 9/9/2019   | 88646-002                                        |             | 2430         |
| 1341   | Lift Transducer Replacement                                          | PA-46-600TP                                            | 9/5/2019   | 585-719                                          |             | 3418         |
| 1343   | Canted Frame Doubler Inspection                                      | PA-46-350P M350<br>PA-46-500TP M500<br>PA-46-600TP     | 2/3/2020   | 82279-002                                        |             | 5300         |
| 1344   | Generator Relay (K303) Replacement                                   | PA-46-500TP                                            | 10/23/2019 | 88647-002                                        |             | 2430         |
| 1349   | Fuel Return Valve Wiring Modification                                | PA-46-500TP M500                                       | 2/14/2020  | N/A                                              |             | 3425         |
| 1350A  | Nose Landing Gear Steering Horn and Arm Assemblies Inspection        | PA-46-350P M350<br>PA-46-500TP M500<br>PA-46-600TP     | 2/10/2021  | 46N32A009-801<br>83626-004<br>(85154-012)        |             | 3200         |
| 1352   | Garmin G3000NG Software Version 2975.15                              | PA-46-600TP                                            | 4/10/2020  | 88678-001<br>190-02446-00<br>190-02447-00        |             | 3420         |
| 1358   | Fuel Probe Modification                                              | PA-46-350P M350                                        | 3/24/21    | 88667-701                                        |             | 2840         |
| 1360A  | Aileron Drive Sector Inspection                                      | PA-46-600TP                                            | 1/13/2021  | 46W440005                                        |             | 2710         |
| 1361   | Autothrottle Potentiometer Wiring Inspection                         | PA-46-600TP                                            | 3/12/2021  | 46F34A021-002                                    |             | 2230         |
| 1364A  | Fuel Quantity Capacitance Probe Inspection                           | PA-46-350P M350<br>PA-46-600TP                         | 4/14/2021  | **                                               |             | 2840         |
| 1367   | Aft Rib Assembly Rivets Replacement                                  | PA-46-600TP                                            | 9/17/21    | MS20426AD-4                                      |             | 5712         |
| 1369   | Elevator Spar Inspection                                             | PA-46-500TP<br>PA-46-600TP                             | 8/12/21    | 88694-701<br>88694-702                           |             | 5521         |
| 1370A  | Inertial Separator Duct Shredder Angle Modification or Replacement   | PA-46-500TP M500<br>PA-46-600TP                        | 3/28/2022  | 46P710003-003<br>46P710015-003<br>88700-701/-702 |             | 7160         |
| 1371   | M600 Wing Assembly Serialization Marking                             | PA-46-600TP                                            | 1/4/2022   | 46W57A100-001                                    |             | 1100         |
| 1385   | Rudder Skin Strap installation                                       | PA-46-500TP                                            | 10/25/2022 | 83403                                            |             | 5540         |
| 1395   | Garmin G1000 Software Update Version 720.18                          | PA-46-500TP                                            | 2/20/2023  | 88681-001                                        |             | 3420         |
| 2000A  | Current Limiter Inspection                                           | PA-46-350P / M350<br>PA-46R-350T                       | 3/10/2022  | 572-599<br>461-681                               | 2009-07-08  | 2400         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

# SERVICE LETTER INDEX

**CLASSIC AIRCRAFT:**  
**B-2/E-2/F-2/J-2/J-3/**  
**J-4/L-21/L-18/PA-11/NE-1/**  
**PA-15/PA-16/PA-17/PA-18/**  
**PA-19/PA-20/PA-22**

| NUMBER | SUBJECT                                                   | MODELS<br>AFFECTED      | DATE     | PART/KIT<br>NO.               | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------|-------------------------|----------|-------------------------------|-------------|-------------|
| 32     | Aileron Cable Pulley<br>Installation                      | J3                      | 6/15/42  |                               |             | 13A1        |
| 100    | Tie Rod Nipples-<br>J3, 8-36 Type A                       | J3                      | 11/23/43 |                               |             | 13A2        |
| 107    | Plexiglass One Piece<br>Windshield For J3 Series          | J3                      | 10/15/45 |                               |             | 13A3        |
| 109    | Winter Operation<br>Recommendations                       | J3, PA-11               | 10/15/47 |                               |             | 13A5        |
| 114    | Top Cowl Rivets                                           | PA-16                   | 6/13/49  |                               |             | 13A10       |
| 129    | Inspection of Landing<br>Gear Shock Strut<br>End Fittings | PA-15/17                | 10/28/49 |                               |             | 13A11       |
| 131    | Muffler Tail Pipe<br>Inspection                           | PA-11                   | 12/30/49 |                               |             | 13A12       |
| 136A   | Chafing of Fuel Line<br>and Fuel Valve Operation          | PA-20/22                | 9/2/52   |                               |             | 13A13       |
| 138    | Rudder Pedal Tube<br>Attachment                           | PA-20                   | 3/9/50   |                               |             | 13A15       |
| 140    | Rudder Cable<br>Rub Block                                 | PA-20                   | 3/24/50  |                               |             | 13A16       |
| 143    | Stabilizer Adjustment<br>Cable Pulley<br>Modification     | PA-20                   | 5/5/50   |                               |             | 13A18       |
| 144    | Fuselage Doors                                            | PA-15/17                | 5/5/50   |                               |             | 13A19       |
| 145    | Auxiliary Fuel Line                                       | PA-20                   | 6/1/50   |                               |             | 13A20       |
| 146    | Front Seat Frame<br>Revision                              | PA-20                   | 6/1/50   |                               |             | 13A21       |
| 150    | Bungee Cable<br>PA-18-105                                 | PA-18                   | 7/10/50  |                               |             | 13A22       |
| 153    | PA-20 Windshield Supports                                 | PA-20                   | 7/12/50  |                               |             | 13A24       |
| 154    | Addition of Felt Strips<br>on Wing Tank Covers            | PA-11/16<br>PA-18/20    | 7/12/50  |                               |             | 13B1        |
| 155    | Muffler Tail<br>Pipe Shroud                               | PA-18                   | 7/14/50  |                               |             | 13B2        |
| 157    | Loose Connections                                         | PA-16/20                | 8/1/50   |                               |             | 13B4        |
| 159    | PA-20 Baffle Seal                                         | PA-20                   | 10/24/50 |                               |             | 13B5        |
| 161    | Duraclad Finish                                           | PA-18/20/22             | 2/13/51  |                               |             | 13B6        |
| 162    | Control Sticks                                            | PA-18                   | 3/6/51   |                               |             | 13B8        |
| 165    | Oil Radiator Hoses                                        | PA-18<br>PA-20<br>PA-22 | 3/23/51  | 465-132<br>465-133<br>465-134 |             | 7920        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:  
B-2/E-2/F-2/J-2/J-3/  
J-4/L-21/L-18/PA-11/NE-1/  
PA-15/PA-16/PA-17/PA-18/  
PA-19/PA-20/PA-22**

## SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                             | MODELS<br>AFFECTED    | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------|-----------------------|----------|-----------------|-------------|-------------|
| 169    | Manifold Pressure<br>Gauge Installation                                                             | All 1951<br>Models    | 4/20/51  |                 |             | 13B9        |
| 175    | Nose Wheel Bumper<br>Block Spacer Plate                                                             | PA-22                 | 8/1/51   |                 |             | 13B10       |
| 176    | Stabilizer Adjustment<br>Mechanism                                                                  | PA-20/22              | 8/10/51  |                 |             | 13B11       |
| 177    | Firewalls                                                                                           | All Models            | 8/10/51  |                 |             | 13B13       |
| 178    | Optional Oil Radiator<br>Installation                                                               | PA-18                 | 8/24/51  |                 |             | 13B14       |
| 180    | Nose Wheel Mount<br>Stiffener Brace                                                                 | PA-22                 | 9/20/51  |                 |             | 13B15       |
| 183A   | Tail Wire Fittings                                                                                  | PA-18                 | 11/12/51 |                 |             | 13B16       |
| 186    | Clearance Between Engine<br>Mount and Tail<br>Pipe/Clearance In<br>Nose Wheel Steering<br>Mechanism | PA-22                 | 4/21/52  |                 |             | 13B17       |
| 187    | Brake Lever                                                                                         | PA-22                 | 3/13/52  |                 |             | 13B19       |
| 188    | Flap Cable Installation                                                                             | PA-18A                | 4/11/52  |                 |             | 13B20       |
| 189    | Tail Wheel Springs                                                                                  | PA-18A                | 4/17/52  |                 |             | 13B22       |
| 194    | Sealing of Firewalls                                                                                | PA-20/22              | 9/2/52   |                 |             | 13B23       |
| 195    | Battery Cable And<br>Rudder Cable Interference                                                      | PA-18A                | 10/6/52  |                 |             | 13B24       |
| 196    | Chafing of Oil<br>Pressure Line                                                                     | PA-18                 | 10/6/52  |                 |             | 13C2        |
| 203    | Weight & Balance Form                                                                               | PA-12                 | 5/7/53   |                 |             | 13C3        |
| 207    | Oil Quick Drain Valve<br>Assembly, Part No.<br>12956-04                                             | PA-18<br>PA-22        | 6/18/53  |                 |             | 13C4        |
| 209    | Navigation Light<br>Switch                                                                          | All Classic<br>Models | 8/18/53  |                 |             | 13C5        |
| 210    | PA-18A Agricultural<br>Airplane                                                                     | PA-18A                | 8/24/53  |                 |             | 13C6        |
| 212    | Nose Wheel Shimmy<br>Dampener, Part No. 13086-00                                                    | PA-22                 | 10/7/53  |                 |             | 13C8        |
| 213    | Primer Lines                                                                                        | PA-18, 20, 22         | 10/7/53  |                 |             | 13C10       |
| 214    | Navigation Light<br>Switch                                                                          | All Classic<br>Models | 11/17/53 |                 |             | 13C12       |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

**CLASSIC AIRCRAFT:**  
**B-2/E-2/F-2/J-2/J-3/**  
**J-4/L-21/L-18/PA-11/NE-1/**  
**PA-15/PA-16/PA-17/PA-18/**  
**PA-19/PA-20/PA-22**

| NUMBER | SUBJECT                                                          | MODELS<br>AFFECTED                                                                         | DATE       | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|------------------------------------------------------------------|--------------------------------------------------------------------------------------------|------------|-----------------|-------------|-------------|
| 216A   | Replacement of Aileron<br>Hinge Bearing Blocks<br>Part No. 10921 | All Classic<br>Models                                                                      | 12/14/1953 |                 |             |             |
| 220    | .040 Brass Safety<br>Wire                                        | All Classic<br>Models                                                                      | 3/29/1954  |                 |             |             |
| 221    | Carburetor Air<br>Filter                                         | All Classic<br>Models                                                                      | 5/13/1957  |                 |             |             |
| 223    | Engine Support<br>Bushing                                        | PA-12, 16<br>PA-18, 18A<br>PA-20, 22                                                       | 5/17/1954  |                 |             |             |
| 228    | Two Person Safety<br>Belts                                       | PA-12, 14, 15<br>PA-16, 17, 20, 22                                                         | 9/29/1954  |                 |             |             |
| 233    | Fuel Selector Valve                                              | PA-18, 20, 22                                                                              | 10/22/1954 |                 |             |             |
| 241    | Cigarette Lighters                                               | PA-22                                                                                      | 1/24/1955  |                 |             |             |
| 242A   | Special Air Filter<br>Kits                                       | PA-18A                                                                                     | 2/20/1959  | **              |             | 7160        |
| 243    | Engine Mount                                                     | PA-22                                                                                      | 2/8/1955   |                 |             |             |
| 247    | Tail Reinforcement<br>Agricultural Airplane                      | PA-18A                                                                                     | 4/15/1955  |                 |             |             |
| 248    | Auxiliary Fuel Tank                                              | PA-22                                                                                      | 5/13/1955  |                 |             |             |
| 258    | Fuel Tank Cap                                                    | PA-22                                                                                      | 11/30/1955 |                 |             |             |
| 259    | RPM Restriction<br>Placard                                       | PA-18, 18A                                                                                 | 11/30/1955 |                 |             |             |
| 260    | Brake System                                                     | PA-22 (1956<br>Models Only)                                                                | 11/30/1955 |                 |             |             |
| 283A   | Inspection Forms, 100,<br>500, 1000 Hour                         | PA-18, 18A<br>PA-22                                                                        | 2/26/1958  |                 |             | General     |
| 295A   | Aircraft Finishes                                                | All Classic<br>Models                                                                      | 1/3/1964   |                 |             |             |
| 298C   | Obsolete Airplanes                                               | B-2/E-2/F-2/J-2/J-3/J-4<br>L-4/L-18B/L-18C/ NE-1<br>PA-11/15/16/17/18/19/<br>PA-20/22/TG-8 | 6/7/2021   |                 |             | General     |
| 303A   | Aircraft Finish                                                  | PA-15/16/17<br>PA-18/20<br>PA-22 ***                                                       | 9/23/1959  |                 |             | 5300        |
| 312    | Tooling - Piper Auto Control                                     | PA-22                                                                                      | 11/24/1958 | **              |             | 2210        |
| 318    | Air Filter, Carburetor,<br>System Modification                   | PA-18/18A                                                                                  | 4/6/1959   | 754-223         |             | 7160        |
| 321    | Piper Autocontrol                                                | PA-18, 22<br>***                                                                           | 7/8/1959   |                 |             | 2210        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:  
B-2/E-2/F-2/J-2/J-3/  
J-4/L-21/L-18/PA-11/NE-1/  
PA-15/PA-16/PA-17/PA-18/  
PA-19/PA-20/PA-22**

## SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                      | MODELS<br>AFFECTED                         | DATE     | PART/KIT<br>NO.                          | A.D.<br>NO.          | ATA<br>CODE |       |
|--------|------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------|----------|------------------------------------------|----------------------|-------------|-------|
| 324C   | Maintenance And<br>Inspection of Exhaust<br>Systems And Heat<br>Exchanges                                                    | PA-18, 22                                  | 1/22/69  |                                          | 62-26-05<br>68-05-01 | 7810        | 13I1  |
| 327    | FAA Bureau of Flight Standards<br>Release No. 434                                                                            | All Models ***                             | 12/28/59 |                                          |                      | General     | 13I11 |
| 328    | Lycoming Service Letter #L126<br>Dated 1/24/60                                                                               | PA-22                                      | 2/17/60  |                                          |                      | 7200        | 13I19 |
| 329A   | Oil Cooler Lines, Inspection of                                                                                              | PA-22                                      | 5/17/60  | **                                       |                      | 7920        | 13J3  |
| 348    | Airspeed Indicators, Replacement of                                                                                          | PA-22-108                                  | 12/9/60  | 11339-16                                 |                      | 3410        | 13K11 |
| 349    | Bushings, Engine Support,<br>Adjustment of                                                                                   | PA-18/18A<br>PA-22                         | 12/14/60 | **                                       | 61-16-05             | 7100        | 13K12 |
| 353A   | Propeller Decal                                                                                                              | PA-22-108                                  | 2/20/61  |                                          |                      | 6100        | 13K16 |
| 355    | Stainless Steel Control Cables                                                                                               | PA-18/18A<br>PA-20<br>PA-22                | 2/23/61  | **                                       | 61-16-05             | 2700        | 13K19 |
| 358B   | Mount Assemblies, Engine And<br>Nose Wheel Inspection                                                                        | PA-22                                      | 6/7/66   |                                          |                      | 7120        | 13K23 |
| 362B   | Windshield Top Attachment,<br>Modification of                                                                                | PA-15<br>PA-16/17<br>PA-20<br>PA-22        | 12/11/74 | 754-404<br>760-799<br>754-404<br>754-404 | 74-17-04             | 5610        | 13L7  |
| 369    | Inspection of Brake Cable<br>And Pulleys                                                                                     | PA-22<br>PA-22-108                         | 3/7/62   |                                          |                      | 3240        | 14A5  |
| 373    | Dry Vacuum Pumps (Airborne<br>Mechanisms), Models 113A1 And<br>113A5 Installation of Oil Shields                             | PA-22-108                                  | 3/29/62  | 756-143                                  |                      | 3710        | 14A11 |
| 400    | Tail Brace Rods                                                                                                              | PA-20<br>PA-22                             | 3/20/63  | 10555-02<br>10556-02                     | 60-01-07             | 5510        | 14C11 |
| 405    | Bearing, Nose Gear Upper<br>Oleo, Inspection of                                                                              | PA-22                                      | 10/1/63  | 452-419                                  | 64-05-04             | 3220        | 14C20 |
| 406    | Revision To Owners Handbook                                                                                                  | PA-20<br>PA-22                             | 9/26/63  |                                          |                      | General     | 14C22 |
| 410    | Inspection And Lubrication<br>of Stabilizer                                                                                  | PA-22 Series                               | 10/16/63 |                                          |                      | 5500        | 14D6  |
| 423    | Muffler And Tailpipe<br>Support Kits                                                                                         | PA-22-108                                  | 5/5/64   | 756-803<br>756-804                       |                      | 7810        | 14E13 |
| 485    | Scott Aviation Corporation<br>Modification Instructions 1-298<br>For Constant Flow (Semi-Disposable)<br>Mask, Scott PN 28302 | All Aircraft With<br>Subject Mask<br>Assy. | 2/8/67   | 756-332                                  |                      | 3510        | 14J9  |
| 486A   | Cylinder Head Temperature<br>Probe Location                                                                                  | PA-18<br>PA-22                             | 4/16/68  |                                          |                      | 7720        | 14J13 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE LETTER INDEX

**CLASSIC AIRCRAFT:**  
**B-2/E-2/F-2/J-2/J-3/**  
**J-4/L-21/L-18/PA-11/NE-1/**  
**PA-15/PA-16/PA-17/PA-18/**  
**PA-19/PA-20/PA-22**

| NUMBER | SUBJECT                                                                                                                                                         | MODELS<br>AFFECTED                                    | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE  |
|--------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|----------|-----------------|-------------|--------------|
| 491    | Aeromarine Instrument Company<br>Service Bulletin No. 201                                                                                                       | Aeromarine<br>Airspeed Indicator<br>Equipped Aircraft | 8/8/67   |                 |             | 3400 14J18   |
| 513    | Service Memos And Service Aids                                                                                                                                  | All Models                                            | 8/30/68  |                 |             | General 14L2 |
| 529A   | Autopilot Gyro Instrument<br>Overhaul Centers                                                                                                                   | Piper Autopilot<br>Equipped Aircraft                  | 1/14/70  |                 |             | 3400 15A17   |
| 544    | Revised Gyro Service<br>Procedure                                                                                                                               | 3" D.G. 1 Attitude<br>Gyros                           | 1/5/70   |                 |             | 3420 15C7    |
| 573    | B.F. Goodrich Service Bulletin<br>No. E-68-36B (Sealer For<br>B.F. Goodrich Deicer And Strap)                                                                   | B. F. G. Deicer<br>Systems                            | 3/4/71   |                 |             | 3020 15F17   |
| 608    | Covering, Aircraft Ceconite                                                                                                                                     | PA-18-150                                             | 1/31/72  |                 |             | 5300 15J10   |
| 609    | Control Surfaces Inspection And<br>Maintenance Guidelines                                                                                                       | All Models                                            | 2/21/72  |                 |             | 5500 15J21   |
| 617B   | Piper Automatic Locator<br>Transmitter Replacement                                                                                                              | PA-18                                                 | 8/30/73  |                 | 72-22-03    | 2560 15K18   |
| 633    | Inspection And Repair of<br>Flood Exposed Airplanes                                                                                                             | PA-18 ***                                             | 10/9/72  |                 |             | 5300 16A18   |
| 636    | Prestolite Service Bulletin<br>No. ASM-8 (Alternator Fan<br>Replacement)                                                                                        | PA-18, 22                                             | 10/24/72 | **              |             | 2430 16B2    |
| 653    | Throttle Lever And Shaft,<br>Serrated ( Reference Avco Lycoming<br>Service Instruction No. 1265<br>Dated December 15, 1972)                                     | PA-15<br>PA-16, 18, 20, 22                            | 4/9/73   | **              |             | 7610 16C14   |
| 682B   | Required Inspection of Piston<br>Pin (Reference Lycoming Service<br>Bulletin No. 367D)                                                                          | PA-22                                                 | 4/19/74  |                 |             | 7230 16F9    |
| 695    | Roll Servo Inspection, Maintenance<br>And Shear Pin Installation<br>(Reference Attached Edo-Aire<br>Mitchell Service Letter No.<br>ML-38, Dated March 18, 1974) | PA-22                                                 | 5/3/74   | **              |             | 2210 16G13   |
| 718    | Bendix Magneto Bulletin No. 566<br>(Reference Avco Lycoming Service<br>Bulletin 373, Dated March 22, 1974)                                                      | PA-11                                                 | 5/31/74  | **              |             | 7410 16J18   |
| 740    | Fuel Requirements                                                                                                                                               | PA-16, 18, 20, 22                                     | 4/20/76  |                 |             | 2800 17A3    |
| 820    | Replacement of Lithium<br>Sulphur Dioxide (LiS02)<br>ELT Batteries and/or<br>Transmitters                                                                       | PA-18-150                                             | 7/28/80  | **              | 79-18-05    | 2560 17J2    |
| 828    | Electrical System Refinement                                                                                                                                    | PA-18-150                                             | 8/28/78  |                 |             | 2400 17J16   |
| 944    | Fuel Selector Valve Inspection<br>And Lubrication                                                                                                               | PA-18-150                                             | 4/20/82  | **              |             | 2820 18K11   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

**CLASSIC AIRCRAFT:**  
**B-2/E-2/F-2/J-2/J-3/**  
**J-4/L-21/L-18/PA-11/NE-1/**  
**PA-15/PA-16/PA-17/PA-18/**  
**PA-19/PA-20/PA-22**

## SERVICE LETTER INDEX

| NUMBER | SUBJECT                                               | MODELS<br>AFFECTED                                                                                                                  | DATE       | PART/KIT<br>NO.    | A.D.<br>NO.        | ATA<br>CODE |
|--------|-------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|------------|--------------------|--------------------|-------------|
| 1016   | Strut Cuff & Door Catch<br>Attachment Improvement     | PA-20,22                                                                                                                            | 11/11/95   | 766-269<br>766-270 |                    | 5701        |
| 1041A  | In-Service Safety Event Reporting                     | All                                                                                                                                 | 3/17/2020  | N/A                |                    | N/A         |
| 1052   | Life Limited Parts<br>Marking and Disposition         | All                                                                                                                                 | 5/21/2002  | N/A                |                    | 510         |
| 1069   | Flight Control Cable Terminal<br>Corrosion Inspection | All                                                                                                                                 | 3/31/2003  | N/A                | CE-02-05<br>(SAIB) | 2702        |
| 1093B  | Electrical Contactor Replacement<br>Kit               | PA-18 Series<br>PA-22 Series                                                                                                        | 11/28/2017 | 88371              |                    | 2400        |
| 1116A  | Contactor Maintenance                                 | PA-18 Series<br>PA-22 Series                                                                                                        | 3/15/2019  | N/A                |                    | 2435        |
| 1135   | Control Cable / Pulley Inspections                    | All                                                                                                                                 | 10/19/2010 | N/A                |                    | 5720        |
| 1141   | Gascolator Maintenance Procedures                     | J-2 Series<br>J-3 Series<br>J-4 Series<br>NE-1<br>L-4<br>PA-11<br>PA-15/17<br>PA-16<br>PA-18 Series<br>PA-20 Series<br>PA-22 Series | 4/27/2011  | MS20995-C32        |                    | 2800        |
| 1265   | Flight Control System Checks                          | All                                                                                                                                 | 8/6/2019   | N/A                |                    | 2700        |
| 1274   | Hartzell Propeller Preferred Grease                   | All                                                                                                                                 | 1/6/2020   | NYCO GN 3058       |                    | 6110        |
| 1280   | Rudder Pedal And Bar Assembly<br>Inspection           | All                                                                                                                                 | 2/14/2020  | N/A                |                    | 2720        |
| 1302   | Replacement Of Locking Gascolator<br>Drain Valve      | PA-11<br>PA-15<br>PA-16<br>PA-17<br>PA-18 Series<br>PA-20 Series<br>PA-22 Series                                                    | 12/1/2022  | 492-022<br>492-312 |                    | 2821        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-23/PA-23-160  
PA-23-235/PA-23-250  
PA-E23-250

| NUMBER | SUBJECT                                                         | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------|--------------------|----------|-----------------|-------------|-------------|
| 220    | .040 Brass Safety Wire                                          | PA-23              | 3/29/54  |                 |             | 13C14       |
| 221    | Carburetor Air Filter                                           | PA-23              | 5/13/57  |                 |             | 13C17       |
| 227    | Service Publication To The Field                                | PA-23              | 9/24/54  |                 |             | 13C19       |
| 229    | Balancer For The Hartzell HC-82XG-2 Propeller                   | PA-23              | 10/7/54  |                 |             | 13C21       |
| 231    | Electrical System                                               | PA-23              | 10/11/54 |                 |             | 13D1        |
| 235    | Flap Spar And Stabilizer Spar Reinforcement                     | PA-23              | 10/28/54 |                 |             | 13D4        |
| 236    | Cabin Heater Modification                                       | PA-23              | 10/28/54 |                 |             | 13D6        |
| 239    | Cabin Draft                                                     | PA-23              | 1/3/55   |                 |             | 13D7        |
| 240    | Landing Gear Actuating Lever                                    | PA-23              | 1/17/55  |                 |             | 13D8        |
| 246    | Engine Oil Thermostat Kit                                       | PA-23              | 4/15/55  |                 |             | 13D12       |
| 249    | Heater Fuel Line                                                | PA-23              | 5/24/55  |                 |             | 13D15       |
| 250    | Reference Service Bulletin #138 - Hydraulic Actuating Cylinders | PA-23              | 6/8/55   |                 |             | 13D17       |
| 251    | Carburetor Air Boxes                                            | PA-23              | 9/16/55  |                 |             | 13D19       |
| 252    | Primer Pump                                                     | PA-23              | 9/16/55  |                 |             | 13D20       |
| 255    | Cabin Door Handle Bracket                                       | PA-23              | 10/24/55 |                 |             | 13D22       |
| 256    | Heater Fuel Shutoff Valve                                       | PA-23              | 11/21/55 |                 |             | 13D24       |
| 266    | Throttle, Prop And Mixture Control Levers                       | PA-23              | 2/19/56  |                 |             | 13E6        |
| 270    | Electrically Heated Airspeed Pitot Head                         | PA-23              | 3/9/56   |                 |             | 13E7        |
| 271    | Landing Gear Door Hinges And Hinge Brackets                     | PA-23              | 3/19/56  |                 |             | 13E8        |
| 274    | Ground Wire For Audio Speaker - Phone Selector Switch           | PA-23              | 3/23/56  |                 |             | 13E9        |
| 277    | Brake Bleeding                                                  | PA-23              | 3/29/56  |                 |             | 13E11       |
| 278A   | Landing Gear Drag Link Assemblies                               | PA-23              | 2/28/57  |                 |             | 13E18       |
| 280    | Rerouting of Engine Breather And Oil Separator Discharge        | PA-23              | 9/11/56  |                 |             | 13E20       |
| 281    | Engine Nacelle Air Baffle                                       | PA-23              | 9/12/56  |                 |             | 13E22       |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                | MODELS<br>AFFECTED    | DATE     | PART/KIT<br>NO. | A.D.<br>NO.          | ATA<br>CODE  |
|--------|------------------------------------------------------------------------|-----------------------|----------|-----------------|----------------------|--------------|
| 283A   | Inspection Forms, 100,<br>500, 1000 Hour                               | PA-23                 | 2/26/58  |                 |                      | 500 13E24    |
| 286    | Auxiliary Fuel Valve<br>Control Modification                           | PA-23                 | 10/8/56  |                 |                      | 13F1         |
| 288B   | Accessories, Optional Equipment<br>And Modification Kits               | PA-23                 | 1/6/58   |                 |                      | General 13F2 |
| 289    | Engine Breather And Oil<br>Separator Discharge Line<br>Stoppage        | PA-23                 | 1/18/57  |                 |                      | 13F5         |
| 290    | Elevator Horn<br>Bushing Wear                                          | PA-23                 | 1/21/57  |                 |                      | 13F6         |
| 291    | Wheels And Brakes                                                      | PA-23                 | 6/5/57   |                 |                      | 13F7         |
| 292    | Drag Link Assemblies                                                   | PA-23                 | 9/5/57   |                 |                      | 13F8         |
| 293A   | Cabin Heaters                                                          | PA-23                 | 12/13/57 |                 |                      | 13F11        |
| 295A   | Aircraft Finishes                                                      | PA-23                 | 1/3/64   |                 |                      | 13F12        |
| 300B   | Propeller Feathering                                                   | PA-23                 | 3/30/59  |                 |                      | 6120 13F17   |
| 303A   | Aircraft Finishes                                                      | PA-23                 | 9/23/59  |                 |                      | 13F23        |
| 306    | Carburetor Heat Shroud<br>Support Modification                         | PA-23                 | 10/10/58 | 754-192         |                      | 7310 13G19   |
| 307    | Nacelle Fairing Installation                                           | PA-23                 | 10/10/58 | 754-175         |                      | 5450 13G20   |
| 312    | Tooling-Piper Autocontrol                                              | PA-23                 | 11/24/58 | **              |                      | 2210 13H4    |
| 313    | Elevator Control Tube Nylon<br>Sleeve Installation Kit                 | PA-23                 | 1/6/59   | 754-215         |                      | 2730 13H5    |
| 319    | Draining of Apache Fuel Strainers                                      | PA-23                 | 4/13/59  |                 |                      | 7310 13H20   |
| 320    | Nacelle Fairing Installation                                           | PA-23                 | 4/23/59  |                 |                      | 5450 13H21   |
| 321    | Piper Autocontrol                                                      | PA-23                 | 7/8/59   |                 |                      | 13H22        |
| 322A   | Fuel System Control Valves                                             | PA-23                 | 10/12/59 | **              | 60-03-08             | 7320 13H23   |
| 324C   | Maintenance And Inspection<br>of Exhaust Systems And<br>Heat Exchanges | PA-23/23-250          | 1/22/69  |                 | 62-26-05<br>68-05-01 | 7810 13I1    |
| 326    | PA-23 Elevator Tabs                                                    | PA-23                 | 12/28/59 |                 |                      | 5520 13I10   |
| 330    | South Wind Bulletin Dated<br>February 22, 1960                         | PA-23                 | 5/5/60   | 751-776         |                      | 2140 13J5    |
| 333C   | Radio Shelf Capacities                                                 | PA-23-235/250<br>UO-1 | 1/28/63  |                 |                      | 3400 13J13   |
| 334    | Fuel Cell Filler Neck<br>Reinforcement                                 | PA-23-250<br>UO-1     | 6/16/60  | 754-332         |                      | 2810 13J14   |
| 336    | Modification of Oil Pressure Lines                                     | PA-23                 | 6/17/60  | 19148-00        |                      | 7930 13J17   |
| 338    | Locking of Main Cabin Door                                             | PA-23-250             | 7/12/60  |                 |                      | 5210 13J20   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-23/PA-23-160  
PA-23-235/PA-23-250  
PA-E23-250

| NUMBER | SUBJECT                                                                                            | MODELS<br>AFFECTED        | DATE     | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------|---------------------------|----------|----------------------|-------------|-------------|
| 340    | Sealing of Fuel Cell Filler<br>Neck Riveted Seam                                                   | PA-23-250                 | 6/29/60  |                      |             | 2810 13J24  |
| 345    | Hartzell Service Bulletin #75-<br>Inspection of Hartzell Governor<br>For Presence of Vent Hole     | PA-23-250                 | 9/14/60  |                      |             | 6120 13K5   |
| 350    | Installation of Brush And Retainer<br>Plate Assembly, (Electric Propeller)<br>Deicer B.F. Goodrich | PA-23/23-250<br>UO-1      | 12/19/60 |                      |             | 6110 13K13  |
| 354    | Reinforcement of Aztec<br>Stabilator Leading Edge                                                  | PA-23-250                 | 5/25/61  | 30334-00             |             | 2730 13K17  |
| 359    | Modification of Fuel Cell Vent Tubes                                                               | PA-23                     | 8/16/61  |                      |             | 2810 13L1   |
| 363    | Inspection And Modification of Flaps                                                               | PA-23-250<br>UO-1         | 11/30/61 | **                   |             | 2750 13L10  |
| 367    | "Thermos Bottle" Type<br>Fuel Cell Caps                                                            | PA-23/23-250              | 2/1/62   |                      | 68-13-03    | 2810 13L21  |
| 368    | Lycoming Service Instruction<br>No. 1049 Dated December 29, 1961                                   | PA-23                     | 2/7/62   | **                   |             | 7200 14A1   |
| 388    | Removal of Carburetor Heat<br>Shroud Screen                                                        | PA-23-235<br>PA-23-250    | 11/2/62  |                      |             | 7160 14B12  |
| 398    | Replacement of Fuel Control<br>Valves "O" Rings                                                    | PA-23-235<br>PA-23-250    | 3/6/63   | 755-837              |             | 7320 14C7   |
| 404    | Inspection of Pitch Servo<br>Assembly Chain Adjustment<br>Screw, Altimatic And Altimatic II        | PA-23/23-235<br>PA-23-250 | 9/16/63  | **                   |             | 2210 14C17  |
| 407    | Rudder Trim Tab Control Rod,<br>Installation of Roll Pin In,<br>And Inspection of                  | PA-23                     | 10/4/63  | 480-728              | 63-24-03    | 2720 14C23  |
| 425    | Lycoming Service Bulletin<br>No. 298                                                               | PA-23-235<br>PA-23-250    | 5/13/64  | **                   |             | 7200 14E17  |
| 432    | Inspection of Auxiliary<br>Power Plug Solenoid                                                     | PA-23-250                 | 8/25/64  | 487-153              |             | 2400 14F10  |
| 438    | Priority Valve Actuating<br>Cable, Clamping                                                        | PA-23-250                 | 11/4/64  | 756-878              |             | 3250 14F21  |
| 441    | Fuel System, Modification of,<br>And Replacement of Electric<br>Fuel Booster Pumps                 | PA-23-250                 | 1/20/65  | 756-880              |             | 2820 14G6   |
| 449A   | Fuel Cells                                                                                         | PA-23-235<br>PA-23-250    | 2/18/69  |                      | 72-11-01    | 2810 14G16  |
| 454    | Pitch Breakaway Ball Bracket<br>(Altimatic II)                                                     | PA-23-250                 | 7/1/65   | 756-954              |             | 2210 14G21  |
| 462    | Inspection of Engine Mount Tubes                                                                   | PA-23-250                 | 12/9/65  | 31215-00<br>31215-01 | 68-07-04    | 7120 14H13  |
| 464A   | Fuel Injection, Bendix RS                                                                          | PA-23<br>PA-E23-250       | 11/12/65 |                      |             | 7310 14I1   |
| 466A   | Stewart-Warner Heater<br>Modification Kit                                                          | PA-23<br>PA-E23-250       | 8/8/67   | 756-995              |             | 2140 14I4   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                             | MODELS<br>AFFECTED          | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE  |
|--------|-------------------------------------------------------------------------------------|-----------------------------|----------|--------------------|-------------|--------------|
| 472    | Conduct Installation Modification,<br>B.F. Goodrich Service Bulletin<br>No. E-65-30 | PA-23<br>PA-E23-250         | 3/16/66  | 757-017            |             | 3020 14I12   |
| 474    | Increase In Flap Extension Speeds                                                   | PA-23-235/250<br>PA-E23-250 | 4/21/66  | 757-000            |             | 2750 14I16   |
| 480    | FAA Aircraft Specification<br>No. 1A10 Item 1(1)                                    | PA-23/E23-250               | 7/8/66   |                    |             | General 14J1 |
| 482    | Altitude Limitation, 25,000 Ft.<br>Removal of                                       | PA-23<br>PA-E23-250         | 9/20/66  | 757-063            |             | 3410 14J2    |
| 483    | Airesearch Service Information<br>Letter No. S. I. L. P-08                          | PA-23<br>PA-E23-250         | 8/17/66  |                    |             | 7200 14J5    |
| 486A   | Cylinder Head Temperature<br>Probe Location                                         | PA-23/23-235<br>PA-23-250   | 4/16/68  |                    |             | 7720 14J13   |
| 487    | Test Unit, Hydraulic<br>Part Number 753-080 And Stand                               | PA-23<br>PA-235/250         | 2/13/67  | 753-080            |             | 710 14J14    |
| 504    | B.F. Goodrich Service Bulletin<br>No. E-67-34                                       | PA-23<br>PA-E23-250         | 4/8/68   |                    |             | 3240 14K14   |
| 511    | Auxiliary Power Receptacle<br>Installation, Modification To The                     | PA-23-250                   | 8/30/68  | 760-180            |             | 2400 14K23   |
| 519    | Alternator Ground Wire,<br>Replacement And Relocation of                            | PA-23-250                   | 12/31/68 | 760-282            |             | 2430 14L17   |
| 520    | Inspection of Turbocharger<br>Plenum Exhaust Welds                                  | PA-23-250                   | 2/3/69   | **                 |             | 7230 14L19   |
| 522    | Fuel Pump Restrictor Fitting                                                        | PA-23-250                   | 1/14/69  | 760-275            |             | 2820 15A1    |
| 525    | Addition of Lock Washers To<br>Electrical Switch Installations                      | PA-23-250                   | 2/28/69  | 407-103<br>407-133 |             | 2450 15A8    |
| 532    | Voltage Regulation Component<br>Grounding                                           | PA-23-250                   | 7/7/69   | 760-331            |             | 2430 15B2    |
| 533    | Exhaust Stack Assembly                                                              | PA-23-250                   | 11/10/69 | 32907-07           |             | 7810 15B5    |
| 545    | Turbo (Lycoming) Aztec Owners<br>Handbook And Power Setting Chart                   | PA-23-250                   | 2/2/70   | **                 |             | 7220 15C10   |
| 547    | Lycoming Turbocharger Aztec,<br>Modification                                        | PA-23-250                   | 3/25/70  | **                 |             | 8120 15C15   |
| 550B   | Density Control Adjustment,<br>Turbocharger (Ref. Avco-Lycoming<br>Dated 4/5/74)    | PA-23-250                   | 7/10/74  |                    |             | 8120 15C21   |
| 559    | Alternate Air System, Inspection of                                                 | PA-23-250                   | 8/3/70   | 32343-00           |             | 7160 15E4    |
| 560    | Scott Fuel Selector Valves                                                          | PA-23-250                   | 8/7/70   | 757-520            |             | 2820 15E6    |
| 562    | Scott Aviation Service<br>Bulletin No. 35-32                                        | PA-23-235/250<br>PA-E23-250 | 8/25/70  | **                 |             | 2820 15E10   |
| 564    | Revised Hartzell Propellers                                                         | PA-23-250<br>PA-E23-250     | 9/28/70  | **                 |             | 6120 15E18   |
| 566    | Spacer Bushing Installation,<br>Autopilot Servo                                     | PA-23<br>PA-E23-250         | 11/25/70 | 760-472            |             | 2210 15F3    |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-23/PA-23-160  
PA-23-235/PA-23-250  
PA-E23-250

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED                   | DATE      | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE       |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|-----------|--------------------|-------------|-------------------|
| 578B   | Fuel Line (Stainless Steel Tube Assy.)<br>and Support Clamp Inspection<br>and Installation,<br>Lycoming Service Bulletin No. 342F | PA-23-250<br>PA-E23-250              | 7/27/2011 | N/A                | 2011-26-04  | 7310              |
| 579    | Heavy Duty Brake Disc<br>Replacement                                                                                              | PA-23-250<br>PA-E23-250              | 5/26/71   | 760-538            |             | 3240 15G16        |
| 580    | Fuel Selector Valve<br>Packing Lubrication                                                                                        | PA-23-235<br>PA-23-250<br>PA-E23-250 | 5/24/71   |                    |             | 2820 15G18        |
| 582A   | Exhaust System (Turbocharger)<br>Inspection And Modification<br>(Lycoming S.B. #339A)                                             | PA-23-250                            | 6/3/74    | **                 | 2008-14-07  | 8100 15G23        |
| 584    | Circuit Breaker Switch Inspection,<br>90 Amp Alternator                                                                           | PA-23-250                            | 7/8/71    |                    |             | 2430 15H4         |
| 585    | Inspection of Hydraulic Lines                                                                                                     | All Apache/Aztecs                    | 7/9/71    |                    |             | 2910 15H6         |
| 591    | Inspection And Reinforcement<br>Spar, Wing Front                                                                                  | PA-23-235<br>PA-23-250               | 8/31/71   | 760-521<br>760-524 |             | 5710 15H12        |
| 592    | Mounts, Engine Shock (Lord)                                                                                                       | PA-23-250                            | 10/6/71   | 475-116<br>475-117 |             | 7120 15H14        |
| 593    | Connector Plug, Harness, Strain<br>Relief Hood Installation                                                                       | PA-23-250<br>with Alt. V & VF/D      | 10/11/71  | 760-555            |             | 2400 15H15        |
| 606A   | Fuel System, Inspection<br>And Modification                                                                                       | PA-23-235<br>PA-23-250               | 8/23/72   | **                 | 72-11-01    | 2800 15J3         |
| 609    | Control Surfaces Inspection And<br>Maintenance Guidelines                                                                         | All Models                           | 2/21/72   |                    |             | 5500 15J21        |
| 613    | Brake Disc Inspection, Heavy<br>Duty (Cleveland Aircraft Products<br>S. B. #ESB-7002)                                             | PA-23-250                            | 5/11/72   | 760-538            |             | 3240 15K4         |
| 617B   | Piper Automatic Locator<br>Transmitter Replacement                                                                                | PA-23-250                            | 8/30/73   |                    | 72-22-03    | 2560 15K18        |
| 619    | Retainer Spring, Piper Part<br>Number 83302-13, Inspection of                                                                     | PA-23-235<br>PA-23-250               | 6/9/72    |                    |             | 7330 15L5<br>7160 |
| 627    | Propeller Installation                                                                                                            | PA-23-250                            | 9/1/72    |                    |             | 6100 16A1         |
| 628    | Control System Inspection,<br>Stabilator Trim                                                                                     | PA-23-250                            | 9/18/72   | 31970-03           |             | 2740 16A4         |
| 629    | Fuselage Frame Tube<br>Corrosion Inspection                                                                                       | All Apache/Aztecs                    | 9/5/72    | 760-703            |             | 5320 16A8         |
| 630    | Lubrication of Fuel Valve<br>Selector Mechanism                                                                                   | PA-23-250                            | 9/13/72   | **                 |             | 2820 16A11        |
| 633    | Inspection And Repair of<br>Flood Exposed Airplanes                                                                               | PA-23                                | 10/9/72   |                    |             | 5300 16A18        |
| 636    | Prestolite Service Bulletin<br>No. ASM-8 (Alternator<br>Fan Replacement)                                                          | PA-23                                | 10/24/72  | **                 |             | 2430 16B2         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                                             | MODELS<br>AFFECTED              | DATE    | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|---------|--------------------|-------------|-------------|
| 638A   | Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication - Rack And Pinion Type Servos)                                                        | PA-23                           | 2/8/73  |                    |             | 2210 16B7   |
| 641    | Replacement Exhaust Stack Support Assembly                                                                                                          | PA-23-250                       | 2/26/73 | 760-702            |             | 7810 16B13  |
| 642    | Alternator Inoperative Warning Light, Revised                                                                                                       | PA-23-250                       | 2/19/73 | 760-711<br>760-712 |             | 2730 16B15  |
| 645    | Starter Vibrator Wiring Inspection                                                                                                                  | PA-23-250                       | 4/12/73 | 492-431<br>492-644 |             | 8010 16B20  |
| 653    | Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)                                   | PA-23<br>PA-23-235<br>PA-23-250 | 4/9/73  | **                 |             | 7610 16C14  |
| 655    | Airesearch Service Bulletin No. 1172-1A; Reference Avco Lycoming Service Bulletin No. 361                                                           | PA-23-250<br>Turbocharged       | 4/10/73 | **                 |             | 7200 16C21  |
| 667A   | Stabilator Attachment Bolts                                                                                                                         | PA-23-235<br>PA-23-250          | 3/4/74  | **                 | 74-13-03    | 2740 16E1   |
| 672    | Wing Rear Spar Inspection                                                                                                                           | PA-23-150/160                   | 9/18/73 | **                 |             | 5710 16E12  |
| 674    | Overvoltage Relay Inspection                                                                                                                        | PA-23-250                       | 1/3/74  | 760-787            |             | 2430 16E16  |
| 676    | Weight And Balance/Equipment List Correction                                                                                                        | PA-23-250                       | 10/4/73 |                    |             | 3200 16E20  |
| 682B   | Reference Lycoming Service Bulletin 367D                                                                                                            | PA-23-250                       | 4/19/74 | **                 |             | 7230 16F9   |
| 683    | Stabilator Control Cable Attachment Fittings Inspection                                                                                             | PA-23-250                       | 10/3/73 |                    |             | 2740 16F16  |
| 695    | Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974) | PA-23<br>PA-23-235<br>PA-23-250 | 5/3/74  | **                 |             | 2210 16G13  |
| 696    | Control Surface Balancing Recommendation                                                                                                            | PA-23-250                       | 5/2/74  |                    |             | 2700 16G20  |
| 705    | Oil Tanks, Turbocharger Modification of, And Related Installation (Airesearch Service Bulletin No. 14.1.10 And 14.1.11 Dated February 6, 1974)      | PA-23-250                       | 4/16/74 | **                 |             | 8100 16H13  |
| 707    | Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)                               | PA-23<br>PA-23-235<br>PA-23-250 | 2/27/74 | **                 |             | 7710 16I11  |
| 710    | Inspection of Stabilator Control Cable And Rudder Control Cable Attachments                                                                         | PA-23-250                       | 5/2/74  |                    |             | 2740 16J1   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE LETTER INDEX

PA-23/PA-23-160  
PA-23-235/PA-23-250  
PA-E23-250

| NUMBER | SUBJECT                                                                                                 | MODELS<br>AFFECTED                                         | DATE       | PART/KIT<br>NO. | A.D.<br>NO.        | ATA<br>CODE |
|--------|---------------------------------------------------------------------------------------------------------|------------------------------------------------------------|------------|-----------------|--------------------|-------------|
| 717    | Brake Assembly Cylinder Retract,<br>Improved (Cleveland Aircraft<br>Products Service Letter No. 7000-5) | PA-23-250                                                  | 9/18/74    | 751-507         |                    | 3240 16J16  |
| 723    | Glideslope Indicator Placard                                                                            | PA-23-250                                                  | 8/14/74    | **              |                    | 3430 16K11  |
| 726    | Cigar Lighter Placard<br>24 Volt                                                                        | All PA-23-235/<br>23-250                                   | 8/8/74     | 80247-02        |                    | 3310 16K16  |
| 740    | Fuel Requirements                                                                                       | PA-23                                                      | 4/20/76    |                 |                    | 2800 17A3   |
| 786A   | Refined Engine Mount Assembly                                                                           | PA-23-250                                                  | 8/31/76    | **              |                    | 7120 17F15  |
| 807A   | Stabilator Outboard Nose<br>Rib Installation                                                            | PA-23-250                                                  | 9/8/77     | 761-141         | 2021-25-11         | 5570 17H13  |
| 815    | Radar Antenna Mounting Plate<br>Inspection And Modification                                             | PA-23-250                                                  | 3/8/78     | 48881-02        |                    | 3440 17I15  |
| 820    | Replacement of Lithium Sulphur<br>Dioxide (LiSO2) ELT Batteries<br>and/or Transmitters                  | PA-23-250                                                  | 7/28/80    | **              | 79-18-05           | 2560 17J2   |
| 830    | 24 Volt Cigar Lighter Element<br>Replacement                                                            | PA-23-250                                                  | 11/22/77   | **              |                    | 3310 17J19  |
| 846    | Stabilator Assembly Lower<br>Surface Rivet Inspection                                                   | PA-23-250                                                  | 5/3/78     | **              |                    | 2740 17K23  |
| 853    | Inspection For Cracked<br>Flap Spars At Hinge Area                                                      | PA-23<br>PA-23-235<br>PA-23-250                            | 6/8/79     | **              | 81-04-05           | 2750 17L20  |
| 1041A  | In-Service Safety Event Reporting                                                                       | All                                                        | 3/17/2020  | N/A             |                    | N/A         |
| 1052   | Life Limited Parts<br>Marking and Disposition                                                           | All                                                        | 5/21/2002  | N/A             |                    | 510 19L19   |
| 1069   | Flight Control Cable Terminal<br>Corrosion Inspection                                                   | All                                                        | 3/31/2003  | N/A             | CE-02-05<br>(SAIB) | 2702 20C2   |
| 1086   | Propeller Blade De-ice Boots<br>Maintenance                                                             | PA-23<br>PA-23-160<br>PA-23-235<br>PA-23-250<br>PA-E23-250 | 7/16/2004  | N/A             |                    | 3112 20F3   |
| 1093B  | Electrical Contactor Replacement<br>Kit                                                                 | PA-23<br>PA-23-160<br>PA-23-235<br>PA-23-250<br>PA-E23-250 | 11/28/2017 | 88371           |                    | 2400        |
| 1116A  | Contactor Maintenance                                                                                   | PA-23<br>PA-23-160<br>PA-23-235<br>PA-23-250<br>PA-E23-250 | 3/15/2019  | N/A             |                    | 2435        |
| 1135   | Control Cable / Pulley Inspections                                                                      | All                                                        | 10/19/2010 | N/A             |                    | 5720        |
| 1141   | Gascolator Maintenance Procedures                                                                       | PA-23<br>PA-23-160<br>PA-23-235<br>PA-23-250<br>PA-E23-250 | 4/27/2011  | MS20995-C32     |                    | 2800        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE LETTER INDEX

| NUMBER | SUBJECT                                             | MODELS<br>AFFECTED                      | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE | GRID |
|--------|-----------------------------------------------------|-----------------------------------------|-----------|-----------------|-------------|-------------|------|
| 1175   | POH Report 1948<br>Equipment List                   | PA-23-250 Aztec "F"                     | 12/2/2013 | N/A             |             | 2500        |      |
| 1188   | Landing Gear Hydraulic System<br>Filter Maintenance | PA-23-150/160<br>PA-23-235<br>PA-23-250 | 3/19/2015 | N/A             |             | 2912        |      |
| 1265   | Flight Control System Checks                        | All                                     | 8/6/2019  | N/A             |             | 2700        |      |
| 1274   | Hartzell Propeller Preferred Grease                 | All                                     | 1/6/2020  | NYCO GN 3058    |             | 6110        |      |
| 1280   | Rudder Pedal And Bar Assembly<br>Inspection         | All                                     | 2/14/2020 | N/A             |             | 2720        |      |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-24  
PA-30/39

| NUMBER | SUBJECT                                                                                                      | MODELS<br>AFFECTED     | DATE     | PART/KIT<br>NO.    | A.D.<br>NO.          | ATA<br>CODE          | GRID  |
|--------|--------------------------------------------------------------------------------------------------------------|------------------------|----------|--------------------|----------------------|----------------------|-------|
| 177    | Firewalls                                                                                                    | All PA-24 Models       | 8/10/51  |                    |                      |                      | 13B13 |
| 207    | Oil Quick Drain Valve Assembly,<br>Part No 12956-04                                                          | PA-24                  | 6/18/53  |                    |                      |                      | 13C4  |
| 283A   | Inspection Forms 100/500/1000<br>Hour                                                                        | PA-24                  | 2/26/58  |                    |                      | 500                  | 13E24 |
| 295A   | Aircraft Finishes                                                                                            | PA-24<br>PA-30         | 1/3/64   |                    |                      |                      | 13F12 |
| 299    | Cabin Door Lower Hinge<br>Reinforcement, Cabin Door<br>Holder And Landing Gear Oil<br>Level Instructions     | PA-24-180<br>PA-24-250 | 6/10/58  | **                 |                      | 5210                 | 13F15 |
| 301    | PA 24 Comanche Landing Gear                                                                                  | PA-24                  | 8/12/58  |                    |                      | 3200                 | 13F20 |
| 302    | Fuel Gauge Ground Wire                                                                                       | PA-24-180/250          | 8/19/58  |                    |                      | 2840                 | 13F21 |
| 303A   | Aircraft Finish                                                                                              | PA-24                  | 9/23/59  |                    |                      | 5300                 | 13F23 |
| 305    | Miscellaneous Modifications;<br>Door Latch, Oil Separator<br>Inlet Hose, Landing Gear<br>Retraction Tube Arm | PA-24-180/250          | 10/1/58  | **                 | 58-25-05             | 5200<br>7920<br>3230 | 13G14 |
| 310    | Locking of Landing Gear<br>Motor Release Arm                                                                 | PA-24-180/250          | 11/10/58 |                    |                      | 3230                 | 13H1  |
| 311    | PA-24 1959 Owners Handbook                                                                                   | PA-24                  | 11/22/58 |                    |                      | General              | 13H3  |
| 312    | Tooling - Piper Autocontrol                                                                                  | PA-24                  | 11/24/58 | **                 |                      | 2210                 | 13H4  |
| 314A   | Landing Gear Warning System                                                                                  | PA-24-180/250          | 6/8/59   | 754-221<br>754-217 |                      | 3260                 | 13H6  |
| 315    | PA-24 Comanche Landing Gear<br>Transmission Assembly                                                         | PA-24                  | 2/4/59   |                    |                      | 3200                 | 13H7  |
| 316    | Cabin Sealing                                                                                                | PA-24-180/250          | 4/7/59   | **                 |                      | 5300                 | 13H16 |
| 317    | 50 Ampere Generator Installation                                                                             | PA-24-180/250          | 4/6/59   | 754-230            |                      | 2400                 | 13H18 |
| 321    | Piper Autocontrol                                                                                            | PA-24                  | 7/8/59   |                    |                      | 2210                 | 13H22 |
| 323    | Defroster Operation                                                                                          | PA-24-180/250          | 11/23/59 |                    |                      | 2140                 | 13H24 |
| 324C   | Maintenance And Inspection<br>of Exhaust Systems And<br>Heat Exchanger                                       | PA-24                  | 1/22/69  |                    | 62-26-05<br>68-05-01 | 7810                 | 13I1  |
| 325    | Front Cabin Window<br>Defroster Kit                                                                          | PA-24-180/250          | 12/24/59 | 754-293            |                      | 2140                 | 13I9  |
| 333C   | Radio Shelf Capacities                                                                                       | All PA-24              | 1/28/63  |                    |                      | 3400                 | 13J13 |
| 339    | Insulation of Wiring At<br>Starter Solenoid Switch                                                           | PA-24-180/250          | 7/12/60  | 13586-94           |                      | 8010                 | 13J21 |
| 345    | Hartzell Service Bulletin #75 -<br>Inspection of Hartzell Governor<br>For Presence of Vent Hole              | PA-24-250              | 9/14/60  |                    |                      | 6110                 | 13K5  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                       | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------|--------------------|----------|-----------------|-------------|-------------|
| 346    | Relocation of Safety Belt Buckle - Right Front Seat Only                                      | PA-24-180/250      | 9/29/60  |                 |             | 5340 13K8   |
| 347    | Installation of Dry Vacuum Pump, Exhaust Tube                                                 | PA-24-180/250      | 12/2/60  | 754-358         |             | 3710 13K9   |
| 352    | Modification of Windshield Defroster System                                                   | PA-24-180/250      | 12/28/60 | 754-380         |             | 2140 13K14  |
| 356    | Installation of Landing Gear Retraction System, 30 Amp Circuit Protector                      | PA-24-180/250      | 3/31/61  | 454-661         | 63-27-03    | 3230 13K21  |
| 360    | Flap Retractor                                                                                | PA-24-180/250      | 9/5/61   | 754-413         |             | 2750 13L3   |
| 364A   | Rubatex Blocks In Detached Or Loose Wing Panels                                               | PA-24-180/250      | 3/14/62  |                 |             | 5700 13L15  |
| 365    | Special Bolt For Nose Gear Drag Link                                                          | PA-24-180/250      | 1/3/62   | 22066-00        |             | 3200 13L17  |
| 366    | Nose Gear Clevis                                                                              | PA-24-180/250      | 1/3/62   | 20859-03        | 65-25-03    | 3220 13L19  |
| 367    | Caps, Fuel Cell, "Thermos Bottle" Type                                                        | PA-24-180/250      | 2/1/62   |                 | 68-13-03    | 2810 13L21  |
| 368    | Lycoming Service Instruction #1049 Dated 12/29/61                                             | PA-24-250          | 2/7/62   | **              |             | 7200 14A1   |
| 370    | Modification To Engine Breather Line                                                          | PA-24/24-250       | 2/23/62  |                 |             | 7200 14A7   |
| 372    | Landing Gear Switch                                                                           | PA-24-250          | 3/8/62   |                 |             | 3230 14A10  |
| 373    | Dry Vacuum Pumps (Airborne Mechanisms) Models 113A1 And 113A5, Installation of Oil Shields On | PA-24-180/250      | 3/29/62  | 756-143         |             | 3710 14A11  |
| 379    | Landing Gear Safety Switch Harness                                                            | PA-24-180/250      | 8/10/62  | 754-475         | 64-22-03    | 3200 14A20  |
| 380    | Door Hinges, Main Landing Gear, And Nose Gear Door Hinge Bushings                             | PA-24-180/250      | 8/8/62   | **              |             | 3210 14A22  |
| 382    | Redesigned Landing Gear Selector Switch Knob                                                  | PA-24-250          | 9/27/62  | **              |             | 3200 14B1   |
| 393    | Replacement of Bendix Fuel Pump                                                               | PA-24-250          | 2/1/63   | 481-686         |             | 2820 14B22  |
| 395    | Flap Retraction Springs                                                                       | PA-24-250          | 2/11/63  | 83302-54        |             | 2750 14C1   |
| 397    | Inspection of Alternate Air Door Hinge Pin                                                    | PA-24-250          | 2/21/63  |                 |             | 7160 14C5   |
| 404    | Inspection of Pitch Servo Assembly Chain Adjustment Screw Altimatic And Altimatic II          | PA-24-180/250      | 9/16/63  | **              |             | 2210 14C17  |
| 408    | Installation of Fuel Valve Control Stop                                                       | PA-30              | 10/9/63  | 756-774         |             | 7320 14D1   |
| 409    | Replacement of Nose Gear Retraction Tube                                                      | PA-30              | 10/9/63  | 21109-05        | 64-16-06    | 3230 14D4   |
| 411    | Drain Holes In PA-30 Cowling                                                                  | PA-30              | 10/17/63 |                 |             | 7110 14D8   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-24  
PA-30/39

| NUMBER | SUBJECT                                                                                                                                                    | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |
|--------|------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|----------|--------------------|-------------|-------------|
| 412A   | Muffler And Tailpipe Support                                                                                                                               | PA-24-250          | 5/6/64   | 756-775            | 68-05-01    | 7810 14D11  |
| 414    | Modification of Right Side Exhaust Stack                                                                                                                   | PA-24-250          | 11/27/63 | 756-777<br>756-778 |             | 7810 14D15  |
| 415    | Sealing of The Nose Wheel Well                                                                                                                             | PA-30              | 12/3/63  |                    |             | 3240 14D18  |
| 416    | Heater Valve Friction Spring Installation                                                                                                                  | PA-30              | 12/3/63  | 756-779            |             | 2140 14D20  |
| 417    | Replacement of Fuel Injector Inlet Screens                                                                                                                 | PA-30              | 12/16/63 | 756-782            |             | 7310 14E1   |
| 418    | Replacement of Fuel Flow Gauge                                                                                                                             | PA-30              | 12/16/63 | 24536-00           |             | 7330 14E3   |
| 419    | Inspection of Heater Air Distribution Box Attachment Screws                                                                                                | PA-30              | 2/24/64  | **                 |             | 2140 14E4   |
| 420A   | Removal of Vanes From Throat of Carburetor Air Box                                                                                                         | PA-24-250          | 3/10/72  |                    | 64-10-04    | 7200 14E6   |
| 422    | Rework of Propeller Spinner Assembly                                                                                                                       | PA-30              | 3/10/64  | 756-796            |             | 6110 14E11  |
| 424    | Installation of "Generators On" Placard                                                                                                                    | PA-30              | 4/20/64  | **                 |             | 2430 14E15  |
| 425    | Lycoming Service Bulletin No. 298                                                                                                                          | PA-24-180/250      | 5/13/64  | **                 |             | 7200 14E17  |
| 426    | Propeller Flange Inspection, Crankshaft (Per Lycoming Service Bulletin No. 300) And Propeller Blades, Inspection of (Per Hartzell Service Bulletin No. 86) | PA-30              | 6/26/64  |                    |             | 6110 14E22  |
| 430    | Inspection of Nose Gear Drag Link Assembly                                                                                                                 | PA-30              | 8/17/64  |                    |             | 3220 14F6   |
| 431    | Insulation of Motor Mounts                                                                                                                                 | PA-24-250          | 9/2/64   | 756-831            |             | 7120 14F8   |
| 433    | Installation of Placard, (Cowl Flaps Open)                                                                                                                 | PA-24-400<br>PA-30 | 9/9/64   | 755-881            |             | 7110 14F12  |
| 434    | Lycoming Service Instruction #1110                                                                                                                         | PA-24-250          | 9/30/64  | 25006-00           |             | 7200 14F14  |
| 435    | Relocation of Nose Wheel Steering Tube Boot                                                                                                                | PA-24-250          | 9/30/64  | 21378-00           |             | 3250 14F15  |
| 437    | Replacement of Fuel Gauge Assembly                                                                                                                         | PA-24-400          | 11/4/64  | 450-771            |             | 2820 14F19  |
| 439    | Lycoming Service Bulletin No.300A                                                                                                                          | PA-30              | 11/13/64 |                    |             | 6110 14G1   |
| 440    | Engine Compartment Changes                                                                                                                                 | PA-24-400          | 12/3/64  | **                 |             | 7200 14G4   |
| 444    | Installation of Special Steel Fittings On Auxiliary Fuel Pumps                                                                                             | PA-24-250          | 2/24/65  | 751-268            |             | 2810 14G9   |
| 445    | Installation of Nose Gear Drag Link Clevis Reinforcement Bracket                                                                                           | PA-24-180/250      | 4/21/65  | 756-911            |             | 3270 14G11  |
| 446    | Fuel Leakage At the Fuel Cell Gauge                                                                                                                        | PA-24-400          | 3/1/65   | 756-902            |             | 2810 14G13  |
| 447    | Inspection of Landing Gear Transmission Retract Spring                                                                                                     | All PA-24<br>PA-30 | 3/26/65  | **                 |             | 3230 14G14  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                           | MODELS<br>AFFECTED         | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------------------------------------|----------------------------|----------|--------------------|-------------|-------------|
| 449A   | Fuel Cells                                                                                                        | PA-24-180/250/400<br>PA-30 | 2/18/69  |                    |             | 2810 14G16  |
| 451    | Fuel System Purging Valve                                                                                         | PA-24-400                  | 5/14/65  | 756-922            | 66-30-07    | 2810 14G18  |
| 453    | Engine Mount Refinishing                                                                                          | PA-24-400                  | 8/23/65  | 756-306            |             | 7110 14G19  |
| 459    | Mixture Control Cable Shield                                                                                      | PA-24-400                  | 10/6/65  | 25079-00           |             | 7320 14H8   |
| 460    | Revision To PA-30 Service Manual<br>And Owner's Handbook                                                          | PA-30                      | 9/17/65  |                    |             | 3260 14H10  |
| 461    | Inspection of Propeller Blades                                                                                    | PA-30                      | 9/28/65  |                    |             | 6110 14H11  |
| 464A   | Bendix RS Fuel Injection                                                                                          | PA-24-250/260<br>PA-30     | 11/12/65 | **                 |             | 7310 14I1   |
| 465    | Airworthiness Directive No. 65-25-03                                                                              | PA-24/24-250               | 12/20/65 |                    |             | 1617 14I3   |
| 469    | Replacement of Allowance Placard,<br>Baggage/Passenger                                                            | PA-24-260                  | 2/11/66  | 756-997            |             | 5430 14I7   |
| 470    | Starter Vibrating                                                                                                 | PA-24-400                  | 4/1/66   | 492-671            |             | 8010 14I8   |
| 477    | FAA Airworthiness Directive<br>No. 66-12-2 (Temporary Revision<br>To Airspeed Limits)                             | PA-30                      | 5/18/66  |                    |             | 3410 14I19  |
| 478    | Inspection of Baggage Door<br>Latch Enlargements                                                                  | PA-24-260                  | 6/13/66  |                    | 66-18-04    | 5210 14I22  |
| 481    | Muffler And Tailpipe Support                                                                                      | PA-24-250                  | 9/15/66  | 757-058            | 68-05-01    | 7810 14J2   |
| 486A   | Cylinder Head Temperature<br>Probe Location                                                                       | PA-24                      | 4/16/68  |                    |             | 7720 14J13  |
| 490    | Rajay Corporation Service Letter<br>No. 10 (Relocation of Turbocharger<br>Low Oil Pressure Warning<br>Light Wire) | PA-30                      | 6/28/67  | 757-312            |             | 7930 14J16  |
| 511    | Modification To The Auxiliary<br>Power Receptacle Installation                                                    | PA-24-260<br>PA-39         | 8/30/68  | 760-181<br>760-711 |             | 2400 14K23  |
| 516    | Modification Fuel Cell<br>Vent System                                                                             | PA-24-180/250              | 3/7/69   | 760-277<br>760-281 | 68-13-03    | 2810 14L11  |
| 518    | Modification of Exhaust Mufflers                                                                                  | PA-24-260                  | 1/22/69  | 760-289            | 68-05-01    | 7820 14L14  |
| 525    | Addition of Lock Washers To<br>Electrical Switch Installations                                                    | PA-30                      | 2/28/69  | **                 |             | 2400 15A8   |
| 532    | Voltage Regulator Component<br>Grounding                                                                          | PA-30                      | 7/7/69   | 760-332            |             | 2430 15B2   |
| 539    | Fuel Selector Valve Control<br>Handle Replacement                                                                 | PA-30                      | 2/18/70  | 760-356<br>760-357 |             | 2820 15B20  |
| 541    | Fuselage Nose Cone Drain Holes                                                                                    | PA-30                      | 12/4/69  |                    |             | 5350 15C1   |
| 542    | Control Surface Travel<br>And Cable Tension                                                                       | PA-30                      | 2/17/70  |                    |             | 2700 15C3   |
| 543    | Induction System Drain<br>Tube Relocation                                                                         | PA-24-260 "C"              | 11/17/69 | 760-351            |             | 7160 15C5   |
| 546A   | Nose Gear Push-Pull<br>Rod Assembly                                                                               | PA-24-180/250<br>PA-24-400 | 3/10/70  | 757-352            |             | 3250 15C12  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-24  
PA-30/39

| NUMBER | SUBJECT                                                                                                                                 | MODELS<br>AFFECTED                     | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE   |
|--------|-----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|-----------|-----------------|-------------|---------------|
| 549    | New Owner's Handbook                                                                                                                    | PA-30                                  | 3/20/70   | **              |             | General 15C19 |
| 552    | Counter Rotating Power<br>Plant Conversion-Kit                                                                                          | PA-30                                  | 5/1/70    | 760-368         |             | 7100 15D3     |
| 556A   | Turbocharger Waste Gate<br>Return Spring                                                                                                | PA-30/39                               | 9/21/70   | **              |             | 8120 15D17    |
| 557    | Rajay Oil Scavenge Pump                                                                                                                 | PA-30                                  | 6/16/70   | **              |             | 7250 15D19    |
| 558    | Air Flow Modification Kit                                                                                                               | PA-30                                  | 7/1/70    | 760-409         |             | 2700 15E1     |
| 564    | Revised Hartzell Propellers                                                                                                             | PA-30/39                               | 9/28/70   | **              |             | 6120 15E18    |
| 565    | Rear Cabin Dome Light<br>Mounting Screw                                                                                                 | PA-24-260<br>PA-30/39                  | 10/13/70  |                 |             | 3320 15F1     |
| 566    | Autopilot Servo Spacer<br>Bushing Installation                                                                                          | PA-24-260<br>PA-30/39                  | 11/25/70  | 760-472         |             | 2210 15F3     |
| 569    | Engine Compartment Modifications                                                                                                        | PA-24-260                              | 12/28/70  | 760-463         |             | 7200 15F14    |
| 574    | Revision To Emergency Gear<br>Checklist                                                                                                 | PA-24-260<br>PA-30/39                  | 3/22/71   |                 |             | 3200 15F20    |
| 575    | Landing Gear (Nose)<br>System Inspection                                                                                                | PA-30/39                               | 4/8/71    |                 |             | 3220 15F23    |
| 578B   | Fuel Line (Stainless Steel Tube Assy.)<br>and Support Clamp Inspection<br>and Installation,<br>Lycoming Service Bulletin No. 342F       | PA-24-250/260<br>PA-24-400<br>PA-30/39 | 7/27/2011 | N/A             | 2011-26-04  | 7310          |
| 584    | 90 Amp Alternator Circuit<br>Breaker Switch Inspection                                                                                  | PA-30/39                               | 7/8/71    |                 |             | 2430 15H4     |
| 589    | Stainless Steel Fuel Selector<br>Valve Housing                                                                                          | PA-30                                  | 8/18/71   | 757-187         | 83-10-01    | 2820 15H10    |
| 595    | Wing Flap System Maintenance                                                                                                            | PA-24-250/260<br>PA-24-400<br>PA-30/39 | 10/11/71  |                 |             | 2750 15I1     |
| 596A   | Nose Landing Gear System<br>Product Advancement Information                                                                             | All PA-24<br>PA-30/39                  | 9/5/75    | **              |             | 3220 15I3     |
| 598    | Adjustable Duct Micro Switch<br>Inspection                                                                                              | PA-39                                  | 11/16/71  | 487-940         |             | 2140 15I9     |
| 599    | Exhaust Wing Panel<br>Corrosion Protection                                                                                              | PA-30/39                               | 11/23/71  |                 |             | 5750 15I10    |
| 605    | Reissue of Owner's Handbook                                                                                                             | PA-24-260T                             | 2/7/72    | **              |             | 8100 15J1     |
| 609    | Control Surfaces Inspection<br>And Maintenance Guidelines                                                                               | All Models                             | 2/21/72   |                 |             | 5500 15J21    |
| 610    | Tail Control Surface Inspection,<br>Maintenance And Repair Information<br>PA-24 Comanche Service Manual<br>Temporary Revision TR 720127 | All PA-24                              | 2/28/72   | **              |             | 2700 15J23    |
| 617B   | Piper Automatic Locator<br>Transmitter Replacement                                                                                      | PA-24<br>PA-39                         | 8/30/73   |                 | 72-22-03    | 2560 15K18    |
| 623    | Inspection of Rajay Alternate<br>Air Valve Bracket                                                                                      | PA-30/39 T.C.                          | 8/9/72    | **              |             | 7160 15L14    |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                                                           | MODELS<br>AFFECTED                         | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE       |
|--------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------|----------|-----------------|-------------|-------------------|
| 627    | Propeller Installation                                                                                                                                            | PA-24-260<br>PA-30/39                      | 9/1/72   |                 |             | 6100 16A1         |
| 633    | Inspection And Repair of<br>Flood Exposed Airplanes                                                                                                               | PA-24<br>PA-39                             | 10/9/72  |                 |             | 5300 16A18        |
| 636    | Prestolite Service<br>Bulletin No. ASM-8<br>(Alternator Fan Replacement)                                                                                          | PA-24<br>PA-30                             | 10/24/72 | **              |             | 2430 16B2         |
| 637    | Rajay Service Letter No. 19,<br>Dated September 5, 1972                                                                                                           | PA-30/39 T.C.                              | 10/31/72 | **              |             | 7160 16B5         |
| 638A   | Edo-Aire Mitchell Service<br>Letter No. ML-35 (Servo<br>Lubrication—Rack And<br>Pinion Type Servos)                                                               | PA-24<br>PA-30                             | 2/8/73   |                 |             | 2210 16B7         |
| 642    | Revised Alternator Inoperative<br>Warning Light                                                                                                                   | PA-39                                      | 2/19/73  | 760-711         |             | 2430 16B15        |
| 648    | Battery Ground Inspection<br>And Modification                                                                                                                     | PA-24-260 "C"                              | 3/8/73   |                 |             | 2430 16C2         |
| 650    | Inspection of Transmission<br>Assemblies, Landing Gear<br>Retraction And Flap Control                                                                             | PA-24-180/250<br>PA-24-260/400<br>PA-30/39 | 9/27/73  | **              |             | 3230 16C5<br>2750 |
| 651    | Rudder Balance Weight Arm<br>Attachment Angle Installation Kit                                                                                                    | PA-24-180/250<br>PA-24-260                 | 2/27/73  | 760-732         |             | 2720 16C10        |
| 653    | Throttle Lever And Shaft,<br>Serrated (Reference Avco<br>Lycoming Service Instruction No. 1265<br>Dated December 15, 1972)                                        | PA-24<br>PA-30                             | 4/9/73   | **              |             | 7610 16C14        |
| 657    | Fuel Selector Valve Control<br>Handle Modification                                                                                                                | PA-30/39                                   | 9/13/73  | 760-788         |             | 2820 16D3         |
| 665A   | Intake Valves; Rotator Type<br>(Reference Avco Lycoming Service<br>Instruction No. 1280 A. 9/28/73)                                                               | PA-24-400                                  | 10/24/73 | **              |             | 7160 16D16        |
| 667A   | Stabilator Attachment Bolts                                                                                                                                       | PA-24-260/400<br>PA-30                     | 30/4/74  | **              | 74-13-03    | 2740 16E1         |
| 679    | Fuselage Aft Bulkhead Inspection                                                                                                                                  | PA-30/39                                   | 1/21/74  | 760-783         | 74-16-08    | 5310 16F2         |
| 682B   | Reference Lycoming Service<br>Bulletin 367D                                                                                                                       | PA-24-250<br>PA-24-400<br>PA-30            | 4/19/74  | **              |             | 7230 16F9         |
| 686    | Inspection of Fuel Pressure<br>Hose Assembly                                                                                                                      | PA-24-250/260                              | 1/3/74   | 17766-43        |             | 7330 16F20        |
| 687    | Stabilator Modification                                                                                                                                           | PA-24-250/260                              | 6/19/74  | 760-747         | 72-22-05    | 2740 16F23        |
| 695    | Roll Servo Inspection,<br>Maintenance And Sheer<br>Pin Installation (Reference<br>Attached Edo-Aire Mitchell<br>Service Letter No. ML-38<br>Dated March 18, 1974) | PA-24<br>PA-30                             | 5/3/74   | **              |             | 2210 16G13        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE LETTER INDEX

PA-24  
PA-30/39

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED                              | DATE       | PART/KIT<br>NO. | A.D.<br>NO.        | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|------------|-----------------|--------------------|-------------|
| 696    | Control Surface Balancing<br>Recommendation                                                                                       | PA-24<br>PA-30/39                               | 5/2/74     |                 |                    | 2700 16G20  |
| 707    | Flyball Assembly To Improve<br>RPM Control. Modified<br>(Reference Hartzell Service<br>Letter No. 75, Dated<br>November 16, 1973) | PA-24<br>PA-30/39                               | 2/27/74    | **              |                    | 7710 16I11  |
| 718    | Bendix Magneto Bulletin No. 566<br>(Reference Avco Lycoming Service<br>Bulletin 373, Dated<br>March 22, 1974)                     | PA-24                                           | 5/31/74    | **              |                    | 7410 16J18  |
| 751    | Fin Front Spar Modification                                                                                                       | PA-24-180-250<br>PA-24-260/400                  | 7/7/75     |                 |                    | 5520 17A23  |
| 758    | Bendix Ignition Switches, Inspection<br>of; Ref: Bendix Service Bulletin<br>No. 583                                               | PA-24-180/250<br>PA-24-260/400                  | 5/17/76    | 761-065V        |                    | 7410 17C2   |
| 772    | Stabilator Attachment Bolts                                                                                                       | PA-39                                           | 2/16/76    | **              | 74-13-03           | 2740 17E4   |
| 777    | Fin Front Spar Modification                                                                                                       | PA-30/39                                        | 6/16/76    |                 | 76-18-05           | 2740 17E12  |
| 782B   | Landing Gear Manual Extension<br>System And Nose Gear Down<br>Lock Spring Installation                                            | PA-24<br>PA-24-250/260<br>PA-24-400<br>PA-30/39 | 12/1/77    | **              | 77-13-21           | 3230 17E23  |
| 787    | Aileron Spar Inspection And<br>Reinforcement                                                                                      | PA-24/24-250/260<br>PA-24-400<br>PA-30/39       | 12/1/76    | 760-914         | 77-08-01           | 5750 17F17  |
| 850    | Aileron Nose Rib<br>Inspection/Reinforcement                                                                                      | PA-24<br>PA-24-250/260<br>PA-24-400<br>PA-30/39 | 4/18/79    |                 | 79-20-10           | 5750 17L8   |
| 851    | PART A - Fuel Valve Internal<br>Leak Check                                                                                        | PA-24-400<br>PA-30/39                           | 8/31/78    | **              | 79-12-08           | 2810 17L11  |
| 851    | PART B - Fuel System Draining<br>Procedure-Water Contamination                                                                    | PA-30/39                                        | 8/31/78    | **              | 79-12-08           | 2810 17L12  |
| 851    | PART C - Fuel System Draining<br>Procedures-Water Contamination                                                                   | PA-24-400                                       | 8/31/78    |                 | 79-12-08           | 2810 17L14  |
| 1041A  | In-Service Safety Event Reporting                                                                                                 | All                                             | 3/17/2020  | N/A             |                    | N/A         |
| 1052   | Life Limited Parts<br>Marking and Disposition                                                                                     | All                                             | 5/21/2002  | N/A             |                    | 510 19L19   |
| 1069   | Flight Control Cable Terminal<br>Corrosion Inspection                                                                             | All                                             | 3/31/2003  | N/A             | CE-02-05<br>(SAIB) | 2702 20C2   |
| 1093B  | Electrical Contactor Replacement<br>Kit                                                                                           | PA-24<br>PA-24-250/260<br>PA-24-400<br>PA-30    | 11/28/2017 | 88371           |                    | 2400        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE LETTER INDEX

| NUMBER | SUBJECT                                     | MODELS<br>AFFECTED                              | DATE       | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------|-------------------------------------------------|------------|-----------------|-------------|-------------|
| 1116A  | Contactator Maintenance                     | PA-24<br>PA-24-250/260<br>PA-24-400<br>PA-30/39 | 3/15/2019  | N/A             |             | 2435        |
| 1135   | Control Cable / Pulley Inspections          | All                                             | 10/19/2010 | N/A             |             | 5720        |
| 1141   | Gascolator Maintenance Procedures           | PA-24<br>PA-24-250/260<br>PA-24-400             | 4/27/2011  | MS20995-C32     |             | 2800        |
| 1265   | Flight Control System Checks                | All                                             | 8/6/2019   | N/A             |             | 2700        |
| 1274   | Hartzell Propeller Preferred Grease         | All                                             | 1/6/2020   | NYCO GN 3058    |             | 6110        |
| 1280   | Rudder Pedal And Bar Assembly<br>Inspection | All                                             | 2/14/2020  | N/A             |             | 2720        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                                                | MODELS<br>AFFECTED                 | DATE     | PART/KIT<br>NO.      | A.D.<br>NO.          | ATA<br>CODE               |
|--------|--------------------------------------------------------------------------------------------------------|------------------------------------|----------|----------------------|----------------------|---------------------------|
| 177    | Firewalls                                                                                              | All PA-28/28R Models               | 8/10/51  |                      |                      | 13B13                     |
| 295A   | Aircraft Finishes                                                                                      | All                                | 1/3/64   |                      |                      | 13F12                     |
| 324C   | Maintenance And Inspection<br>of Exhaust Systems And<br>Heat Exchanges                                 | PA-28-140/150/160/180/<br>235      | 1/22/69  |                      | 62-26-05<br>68-05-01 | 7810 13I1                 |
| 373    | Installation of Oil Shields On<br>Dry Vacuum Pumps (Airborne<br>Mechanisms, Models 113A1<br>And 113A5) | PA-28-150/160                      | 3/29/62  |                      |                      | 3710 14A11                |
| 374    | Modification of Bulkhead To Prevent<br>Control Cable Interference                                      | PA-28-150/160                      | 4/10/62  | 754-461V             |                      | 5310 14A13                |
| 375    | Control Shaft-Left Hand,<br>Installation of Micarta Sleeve On                                          | PA-28-150/160                      | 4/12/62  | 62852-00V            |                      | 2700 14A15                |
| 381    | Replacement of Wing Panels Service                                                                     | PA-28-150/160                      | 7/9/62   | **                   |                      | 5730 14A23                |
| 386    | Miscellaneous Airframe Modifications                                                                   | PA-28-150/160                      | 9/4/62   | **                   |                      | 5300 14B7<br>5320<br>5550 |
| 389    | Inspection of Exhaust Stacks                                                                           | PA-28-150/160                      | 12/11/62 | **                   | 62-26-05             | 7810 14B13                |
| 390    | Cherokee Gas Cap Placard                                                                               | PA-28-150/160/180                  | 1/3/63   | 62142-00V            |                      | 2810 14B16                |
| 391    | Cherokee Sun Visors                                                                                    | PA-28-150/160/180                  | 1/11/63  | 63230-00V            |                      | 2510 14B18                |
| 394    | Radio And Auto Control Cooling Kits                                                                    | PA-28-150/160/180                  | 2/4/63   | 754-477V<br>754-494V |                      | 2300 14B23                |
| 396    | Inspection of Shaft Assembly<br>(On Control T-Bar And Control<br>Wheels).Double Sprocket               | PA-28-150/160                      | 2/14/63  | 62818-00V            | 64-06-06             | 2710 14C2                 |
| 402    | Installation of Heat Shield Kit                                                                        | PA-28-150/160/180                  | 5/22/63  | 756-727              |                      | 2140 14C13                |
| 413    | Inspection of Nose Gear (Upper)<br>Oleo Bearing                                                        | PA-28-150/160/180                  | 11/25/63 | 452-419              |                      | 3230 14D13                |
| 421    | Inspection of Oil Coolers                                                                              | PA-28-235                          | 3/4/64   | 18622-00             |                      | 7920 14E9                 |
| 425    | Lycoming Service Bulletin No. 298<br>(Ac Fuel Pump Vent Restriction)                                   | PA-28-140/150/160<br>PA-28-180/235 | 5/13/64  | **                   |                      | 2800 14E17                |
| 427    | Fuel Cooling Modification                                                                              | PA-28-150/160/180                  | 6/29/64  | **                   |                      | 2820 14F2                 |
| 429    | Replacement of Oil Coolers                                                                             | PA-28-235                          | 8/10/64  | **                   |                      | 7920 14F3                 |
| 436    | Check of Alternator Through Bolts                                                                      | PA-28-140/150/160<br>PA-28-180/235 | 10/9/64  | 753-210V             |                      | 2430 14F17                |
| 442    | Lycoming Service Instruction<br>No. 1110 (Ac Fuel Pump<br>Replacement)                                 | PA-28-140/150/160<br>PA-28-180/235 | 12/14/64 | **                   |                      | 2820 14G7                 |
| 443    | Oil Line Relocation Kit                                                                                | PA-28-150/160/180                  | 1/27/65  | 756-905V             |                      | 7920 14G8                 |
| 450    | Stabilator Trim Installation                                                                           | PA-28-140/150/160<br>PA-28-180/235 | 9/24/65  | **                   |                      | 2740 14G17                |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                   | MODELS<br>AFFECTED                                        | DATE     | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |       |
|--------|-----------------------------------------------------------------------------------------------------------|-----------------------------------------------------------|----------|------------------------|-------------|-------------|-------|
| 456    | Cherokee 235 Constant Speed<br>Propeller Control                                                          | PA-28-235                                                 | 6/4/65   | 756-959V               |             | 6120        | 14H2  |
| 457    | Plastic On The Cherokee C Spinners                                                                        | PA-28-150/160/180                                         | 6/29/65  | 756-963V               | 66-20-05    | 6110        | 14H3  |
| 458    | Throttle Clamp                                                                                            | PA-28-140/150/160<br>PA-28-180/235                        | 10/8/65  | 554-860V               |             | 7610        | 14H5  |
| 471A   | Inspection of Propeller Spinner<br>And Spinner Attaching Bulkhead                                         | PA-28-150/160/180                                         | 5/23/66  | **                     | 66-20-05    | 6110        | 14I9  |
| 473    | Sensenich Service Bulletin No. R-11<br>(Inspection of Mid-Blade Area<br>of 76 EMM And 76 EMMS Propellers) | PA-28-180                                                 | 3/1/66   |                        |             | 6110        | 14I14 |
| 484    | Fuel System Operating Procedures                                                                          | PA-28-235                                                 | 12/20/66 |                        |             | 2800        | 14J7  |
| 486A   | Cylinder Head Temperature<br>Probe Location                                                               | PA-28-140/150/160/180/<br>235                             | 4/16/68  |                        |             | 7720        | 14J13 |
| 494    | Inspection of Cherokee Landing<br>Gears                                                                   | PA-28-140/150/160<br>PA-28-180/235                        | 11/7/67  | **                     |             | 3200        | 14J24 |
| 495    | Inspection of Constant Speed<br>Propeller Control Cable                                                   | PA-28-235                                                 | 1/29/68  | **                     |             | 6120        | 14K2  |
| 501    | Oil Sump Drain Valve                                                                                      | PA-28R-180                                                | 5/2/68   | 756-517                |             | 7160        | 14K10 |
| 503    | Inspection of Oil Cooler Hose                                                                             | PA-28-140                                                 | 4/18/68  |                        |             | 7920        | 14K13 |
| 526    | Sensenich Service Bulletin No. R-13                                                                       | PA-28-140/150/160/180/<br>235                             | 5/15/69  | 760-325V               |             | 6100        | 15A11 |
| 527D   | Inspection of Control Wheels                                                                              | PA-28-140/150/160<br>PA-28-180/235                        | 6/21/78  | **                     | 69-22-02    | 2700        | 15A14 |
| 534A   | Availability of Engine Oil<br>Quick Drain Valve                                                           | PA-28R-200                                                | 1/7/70   | 492-172V               |             | 7920        | 15B7  |
| 535A   | Rudder Trim Locking Pin                                                                                   | PA-28-140/180/235<br>PA-28R-180/200                       | 9/26/69  |                        |             | 2720        | 15B9  |
| 561    | Inspection of Cherokee<br>Muffler Assembly                                                                | PA-28-140/150/160/S160<br>PA-28-180/S180                  | 8/12/70  | 99482-00V<br>99482-02V |             | 7820        | 15E8  |
| 566    | Autopilot Servo Spacer<br>Bushing Installation                                                            | PA-28-140/180/235<br>PA-28R-180/200                       | 11/25/70 | **                     |             | 2210        | 15F3  |
| 567    | Flight Manual Supplement<br>(Expanded Center of Gravity Range)                                            | PA-28-180/235                                             | 1/25/71  | **                     |             | 3200        | 15F6  |
| 568    | Inspection of Engine Mount Tubes                                                                          | PA-28R-180/200                                            | 1/5/71   | **                     |             | 7120        | 15F8  |
| 571    | Flap Handle Assembly Modification                                                                         | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200           | 3/30/71  | 400-673                |             | 2750        | 15F15 |
| 576    | Stabilator Balance Weight<br>Tube Replacement                                                             | PA-28-140/150/160<br>PA-28-180/S180/235<br>PA-28R-180/200 | 4/20/71  |                        |             | 5510        | 15G2  |
| 577    | Replacement Bridle Cable<br>Servo Clamp                                                                   | PA-28-140/150/160<br>PA-28-180/235<br>PA-28R-180          | 6/1/71   | 757-863V               |             | 2210        | 15G8  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED                                           | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|-----------|-----------------|-------------|-------------|
| 578B   | Fuel Line (Stainless Steel Tube Assy.)<br>and Support Clamp Inspection<br>and Installation,<br>Lycoming Service Bulletin No. 342F | PA-28R-180/200<br>PA-28R-201<br>PA-28RT-201                  | 7/27/2011 | N/A             | 2011-26-04  | 7310        |
| 581    | Inspection of Aileron Hinge<br>Doubblers                                                                                          | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200              | 7/12/71   | 760-540V        |             | 5550 15G20  |
| 587    | Engine Baffle Modification                                                                                                        | PA-28R-200                                                   | 9/16/71   | 760-558V        |             | 7230 15H9   |
| 607    | Emergency Gear Lever Knob                                                                                                         | PA-28R-180/200                                               | 2/18/72   | 66980-02V       | 72-04-03    | 3200 15J9   |
| 609    | Control Surfaces Inspection<br>And Maintenance Guidelines                                                                         | All Models                                                   | 2/21/72   |                 |             | 5500 15J21  |
| 611    | Repositioning of Oil Cooler Hose                                                                                                  | PA-28-140                                                    | 4/28/72   | 760-599V        |             | 7920 15J24  |
| 612A   | Fuel Leakage - Fuel Sender Unit                                                                                                   | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200              | 6/8/72    | 68101-00V       |             | 7330 15K1   |
| 614    | Stabilator Attachment Fittings<br>Bolt Torque                                                                                     | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200              | 6/15/72   |                 | 72-14-07    | 2740 15K6   |
| 615    | Stabilator Drain Holes                                                                                                            | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200              | 7/6/72    |                 |             | 2740 15K8   |
| 616    | Main Landing Gear Trunnion Repair                                                                                                 | PA-28R-180/200                                               | 8/3/72    | **              |             | 3210 15K14  |
| 617B   | Piper Automatic Locator<br>Transmitter Replacement                                                                                | PA-28-140/180/235<br>PA-28R                                  | 8/30/73   |                 | 72-22-03    | 2560 15K18  |
| 620    | Forward Cabin Door<br>Reinforcement                                                                                               | PA-28-140/150/160<br>PA-28-180/235/28S-180<br>PA-28R-180/200 | 2/23/73   | 760-729V        |             | 5210 15L8   |
| 621    | Main Landing Gear Torque<br>Link Replacement                                                                                      | PA-28-140/150/160/180/<br>235                                | 11/9/72   | 78032-00V       |             | 3210 15L10  |
| 626    | Landing Gear Bolt Lubrication                                                                                                     | PA-28R-180/200                                               | 11/20/72  |                 |             | 3200 15L23  |
| 634    | Revision Pilot's Operating Manual                                                                                                 | PA-28R-200                                                   | 12/14/72  | **              |             | 1200 16A23  |
| 636    | Prestolite Service Bulletin<br>No. ASM-8 (Alternator<br>Fan Replacement                                                           | PA-28-180<br>PA-28R-200                                      | 10/24/72  | **              |             | 2430 16B2   |
| 638A   | Edo-Aire Mitchell Service<br>Letter No. ML-35 (Servo<br>Lubrication - Rack And<br>Pinion Type Servos)                             | PA-28-150/160/180/235                                        | 2/8/73    |                 |             | 2210 16B7   |
| 644    | Precautionary Throttle Operating<br>Placard                                                                                       | PA-28-140/150/160                                            | 2/8/73    | 76406-00V       | 72-24-02    | 7610 16B19  |
| 647    | Seat Back Stop Modification                                                                                                       | PA-28-140/180/235<br>PA-28R-200                              | 3/31/73   | 760-740V        |             | 2510 16C1   |
| 649    | Airplane Flight Manual/Weight<br>And Balance Revision                                                                             | PA-28-235                                                    | 5/3/73    | **              |             | 800 16C4    |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                                                           | MODELS<br>AFFECTED                              | DATE     | PART/KIT<br>NO.               | A.D.<br>NO. | ATA<br>CODE                                               |
|--------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------|----------|-------------------------------|-------------|-----------------------------------------------------------|
| 653    | Throttle Lever And Shaft,<br>Serrated (Reference Avco Lycoming<br>Service Instruction No. 1265<br>Dated December 15, 1972)                                        | PA-28-140/150/160/180/<br>235                   | 4/9/73   | **                            |             | 7610 16C14                                                |
| 662    | Engine Mount Bolt Torque                                                                                                                                          | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200 | 7/6/73   | AN960-616                     |             | 7120 16D10                                                |
| 665A   | Inspection of Intake Valves,<br>Rotator Type Knob,<br>Emergency Gear Lever                                                                                        | PA-28R-200                                      | 10/24/73 | **                            |             | 7160 16D16                                                |
| 670A   | Throttle Control Modification                                                                                                                                     | PA-28-140                                       | 6/24/74  | 760-780V<br>760-872V          | 74-13-04    | 7610 16E7                                                 |
| 671    | Rudder Bar Assembly<br>Inspection And Modification                                                                                                                | PA-28-140/150/160/180/<br>235<br>PA-28R-180/200 | 10/5/73  |                               |             | 2720 16E9                                                 |
| 682B   | Required Inspection of<br>Piston Pin (Reference<br>Lycoming Service Bulletin<br>No 367D)                                                                          | PA-28<br>PA-28R                                 | 4/19/74  |                               |             | 7230 16F9                                                 |
| 684    | Landing Gear Lubrication                                                                                                                                          | PA-28R-200                                      | 1/9/74   |                               |             | 3200 16F18                                                |
| 695    | Roll Servo Inspection,<br>Maintenance And Shear<br>Pin Installation (Reference<br>Attached Edo-Aire Mitchell<br>Service Letter No ML-38,<br>Dated March 18, 1974) | PA-28-150/160/235                               | 5/3/74   | **                            |             | 2210 16G13                                                |
| 700    | Toe Brake System Modification                                                                                                                                     | PA-28-140/151<br>PA-28-180/235<br>PA-28R-200    | 4/9/74   | 760-842V                      |             | 3240 16H5                                                 |
| 707    | Flyball Assembly To Improve<br>RPM Control, Modified<br>(Reference Hartzell Service<br>Letter No 75, Dated<br>November 16, 1973)                                  | PA-28-235<br>PA-28R-180/200                     | 2/27/74  | **                            |             | 7710 16I11                                                |
| 715    | Emergency Locator Transmitter<br>Switch Cover Modification                                                                                                        | PA-28-140/151<br>PA-28-180/235<br>PA-28R-200    | 9/27/74  | 760-876V                      |             | 2560 16J12                                                |
| 718    | Bendix Magneto Bulletin<br>No 566 (Reference Avco<br>Lycoming Service Bulletin 373,<br>Dated March 22, 1974)                                                      | PA-28R                                          | 5/31/74  | **                            |             | 7410 16J18                                                |
| 720    | Fuel Quantity Placard Inspection,<br>Section I, Landing Light WIRE<br>Rerouting, Section II                                                                       | PA-28-235                                       | 6/26/74  | **                            | 74-18-06    | 2840 16K2<br>3340                                         |
| 731    | Cherokee Warrior Product<br>Refinement Program                                                                                                                    | PA-28-151                                       | 10/15/74 | 760-854<br>760-855<br>760-856 |             | 2800 16L1<br>3340<br>6110<br>7110<br>7160<br>7230<br>7920 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                           | MODELS<br>AFFECTED                                                         | DATE     | PART/KIT<br>NO.                  | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------|----------------------------------------------------------------------------|----------|----------------------------------|-------------|-------------|
| 734    | Bendix ADF-T-12 C/D<br>Installation Inspection<br>And Modification                | PA-28-140/151/180/235<br>PA-28R-200                                        | 12/3/74  | 760-857V                         |             | 3450 16L8   |
| 735    | Muffler Shroud Modification                                                       | PA28-151/180                                                               | 12/11/74 |                                  |             | 7820 16L11  |
| 738A   | Modification of The Overhead<br>Fresh Air Vent System                             | PA-28-140/180/235<br>PA-28-151<br>PA-28R-200                               | 1/14/75  | 760-900V<br>760-901V<br>760-902V |             | 2120 16L20  |
| 740    | Fuel Requirements                                                                 | PA-28-140/150/151/160/<br>180/181/235                                      | 4/20/76  |                                  |             | 2800 17A3   |
| 744    | Steering System Modification                                                      | PA-28-140/151<br>PA-28-180/235                                             | 4/29/75  |                                  |             | 3250 17A13  |
| 745    | Inspection of Wing Main Spar<br>Attach Bolts                                      | PA-28-140/151/180/<br>235 (Crated)<br>PA-28R-200 (Crated)                  | 4/24/75  | 404-890                          |             | 5710 17A14  |
| 747    | Inspection of Throttle And<br>Mixture Control Attachments                         | PA-28-180/235<br>PA-28R-200                                                | 5/28/75  | **                               |             | 7610 17A18  |
| 749    | Torque Link Greaser Bolt<br>Replacement Kit                                       | PA-28-140/150/151<br>PA-28-160/180/181/235                                 | 10/14/75 | 760-910V                         |             | 3210 17A21  |
| 756    | Glideslope Indicator Placard,<br>Dual (King Radio Installations Only)             | PA-28-151/180/235<br>PA-28R-200                                            | 1/6/76   | 69669-112V                       |             | 3430 17B22  |
| 758    | Bendix Ignition Switches.<br>Inspection of; Re: Bendix<br>Service Bulletin No 583 | PA-28-140/151<br>PA-28-180/181/235<br>PA-28R-180/200                       | 5/17/76  | 761-065V                         |             | 7410 17C2   |
| 761    | Magnetic Compass<br>Relocation Kit                                                | PA-28-140/150/151<br>PA-28-180/235<br>PA-28R-180/200                       | 11/17/75 | 760-795V                         |             | 3440 17C14  |
| 762    | Modification of ELT<br>Remote Switches                                            | PA-28-140/151/180<br>PA-28-181/235<br>PA-28R-200                           | 1/26/76  | 760-009V                         |             | 2560 17C15  |
| 763A   | Seat Retention Mechanism<br>Inspection, Rear Leg Quick-<br>Disconnect             | PA-28-180/235<br>PA-28R-180/200                                            | 11/14/75 | **                               | 75-24-02    | 2510 17C16  |
| 785    | Carburetor Induction Air<br>Shroud Modification                                   | PA-28-151                                                                  | 9/15/76  | **                               |             | 7160 17F13  |
| 788    | Air Conditioning Installation                                                     | PA-28-140/180/181<br>PA-28R-200                                            | 9/3/76   | 79584-02V<br>79589-05V           |             | 2150 17F19  |
| 793    | Flap Warning Placard                                                              | PA-28-140/150/151/160/<br>180/181/235<br>PA-28R-180/200<br>PA-28R-201/201T | 1/6/77   | 35664-02                         |             | 2750 17G5   |
| 796    | Lower Cowl Drain Inspection                                                       | PA-28-150/160<br>PA-28-180/181/235                                         | 3/30/77  |                                  |             | 7100 17G10  |
| 800    | Refinement of Narco ADF-140<br>Installation Performance                           | PA-28-140/151<br>PA-28-180/181/235<br>PA-28R-200                           | 2/25/77  | **                               |             | 3450 17G19  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                | MODELS<br>AFFECTED                                                                                                                        | DATE    | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------------|-------------|-------------|
| 808    | Hydraulic Pump Terminal Inspection                                                                     | PA-28R-180<br>PA-28R-200<br>PA-28R-201<br>PA-28R-201T                                                                                     | 6/8/77  | **              |             | 2910 17H14  |
| 810    | Backup Diaphragm Replacement<br>Landing Gear Extender                                                  | PA-28R-180/200<br>PA-28R-201/201T                                                                                                         | 4/15/77 | 761-138V        |             | 3230 17H18  |
| 813    | Vertically Adjustable Seat<br>Refinement                                                               | PA-28-140/151/161<br>PA-28-180/181<br>PA-28R-200/201/201T<br>PA-28R-235                                                                   | 6/9/77  | **              |             | 2510 17I8   |
| 814    | Refinement Program Cherokee III<br>And Turbo Arrow III                                                 | PA-28R-201<br>PA-28R-201T                                                                                                                 | 9/26/77 |                 |             | 5300 17I10  |
| 814    | Part I - Engine Mount Painting                                                                         | PA-28R-201T                                                                                                                               | 9/26/77 | 763-415V        |             | 7100 17I10  |
| 814    | Part II - Aileron Bellcrank<br>Stop Assembly                                                           | PA-28R-201<br>PA-28R-201T                                                                                                                 | 9/26/77 | 761-142V        |             | 2710 17I11  |
| 814    | Part III - Winterization Plate                                                                         | PA-28R-201T                                                                                                                               | 9/26/77 | 37793-02V       |             | 7200 17I11  |
| 814    | Part IV - Landing Light Wire<br>Rework                                                                 | PA-28R-201T                                                                                                                               | 9/26/77 |                 |             | 3340 17I12  |
| 814    | Part V - Exhaust Heat Shield                                                                           | PA-28R-201T                                                                                                                               | 9/26/77 | 486-648V        |             | 7810 17I12  |
| 820    | Replacement of Lithium<br>Sulphur Dioxide (LiSO <sub>2</sub> )<br>ELT Batteries and/or<br>Transmitters | PA-28-140/151/161<br>PA-28-180/181<br>PA-28-235<br>PA-28-236<br>PA-28R-200/201<br>PA-28R-201T<br>PA-28RT-201<br>PA-28RT-201T<br>PA-44-180 | 7/28/80 | **              | 79-18-05    | 2560 17J2   |
| 826    | Spinner Bulkhead Doubler                                                                               | PA-28-151/161                                                                                                                             | 8/25/77 | 35667-02V       |             | 6110 17J14  |
| 832    | Wheel Well Reinforcement                                                                               | PA-28R-180/200/201<br>PA-28R-201T                                                                                                         | 1/25/78 |                 |             | 3240 17J21  |
| 836    | Inspection And Modification<br>Narco ADF-140/141 Antenna                                               | PA-28-140/180/235<br>PA-28-151/161 II/181 II<br>PA-28R-200<br>PA-28R-201/201T                                                             | 2/9/78  | **              |             | 3450 17K4   |
| 842    | Main Landing Gear Torque<br>Link Greaser Bolt<br>Inspection And Replacement                            | PA-28-140/150/151<br>PA-28-160/161<br>PA-28-180/181<br>PA-28-235                                                                          | 9/26/78 | 760-910V        |             | 3210 17K17  |
| 845    | Engine Breather Tube<br>Winterization Kit                                                              | PA-28-140/150/160/180<br>PA-28-151/161 II/181 II<br>PA-28R-180/200<br>PA-28R-201                                                          | 7/7/78  | 763-828V        |             | 7250 17K22  |
| 848    | Exhaust Heat Shield                                                                                    | PA-28R-201T                                                                                                                               | 6/21/78 | 763-843V        |             | 7810 17L4   |
| 856    | Fuel Drain Cover Replacement                                                                           | PA-28-235                                                                                                                                 | 9/15/78 | 763-883V        | 78-23-01    | 2810 18A21  |
| 859    | Landing Light Installation<br>Modification                                                             | PA-28-151/161                                                                                                                             | 11/8/78 | 760-854V        |             | 3340 18B2   |
| 860    | Engine Exhaust System Modification                                                                     | PA-44-180                                                                                                                                 | 12/4/79 | **              |             | 7810 18B4   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE LETTER INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                             | MODELS<br>AFFECTED                                                                       | DATE     | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|----------|----------------------|-------------|-------------|
| 861    | Part I - Forward Facing Seat<br>Back Modification                                   | PA-28-140/151/161<br>PA-28-180/181/235/236<br>PA-28R-200/201<br>PA-28R-201T<br>PA-44-180 | 11/13/78 | 763-890V             |             | 2520 18B7   |
| 862    | Main Landing Gear And<br>Strut Fairing Replacement                                  | PA-28-161/181<br>PA-28-236                                                               | 3/30/79  | 763-918V             |             | 3210 18B11  |
| 863    | Master Relay Diode Assembly -<br>Refinement                                         | PA-28-181<br>PA-28R-201<br>PA-28R-201T                                                   | 11/17/78 |                      |             | 2450 18B13  |
| 864    | Part I - Forward Cabin Door<br>Stop (Striker Plate) Installation                    | PA-28-140/151/161<br>PA-28-181/235/236<br>PA-28R-200/201<br>PA-28R-201T                  | 12/8/78  | **                   |             | 5210 18B16  |
| 864    | Part II - Cabin Heat Control<br>Refinement                                          | PA-28-140/151<br>PA-28-161/180/181<br>PA-28-235/236<br>PA-28R-180/200/201<br>PA-28R-201T | 12/8/78  | 763-870V<br>763-871V |             | 2140 18B19  |
| 864    | Part III - Turn And Slip<br>Indicator Conversion, Vacuum<br>To Electric Provision   | PA-28-140/150<br>PA-28-160/180<br>PA-28-235                                              | 12/8/78  | 763-874              |             | 3420 18B20  |
| 867    | Part I - Engine<br>Baffles Reinforcement                                            | PA-44-180                                                                                | 10/10/79 | **                   |             | 7230 18C4   |
| 867    | Part II - Replacement<br>of Nose Landing Gear<br>Micro Switch Bracket               | PA-44-180                                                                                | 10/10/79 | 763-925V             |             | 3230 18C5   |
| 867    | Part III - Cowl<br>Fastener Relocation                                              | PA-44-180                                                                                | 10/10/79 | 420-690              |             | 7110 18C5   |
| 867    | Part IV - Cabin Heater<br>Air Inlet Valve<br>Modification                           | PA-44-180                                                                                | 10/10/79 | **                   |             | 2140 18C6   |
| 867    | Part V - Battery Box<br>Drain Clamp Replacement                                     | PA-44-180                                                                                | 10/10/79 | 454-983              |             | 2430 18C7   |
| 867    | Part VI - Tachometer<br>And Manifold Pressure<br>Gauges Available Light<br>Increase | PA-44-180                                                                                | 10/10/79 |                      |             | 7710 18C7   |
| 867    | Part VII - Landing<br>Light Grounding Strap<br>Installation                         | PA-44-180                                                                                | 10/10/79 | **                   |             | 3340 18C8   |
| 891    | Air Induction Filter Retainer<br>Improvement                                        | PA-28-151/161                                                                            | 3/4/81   | 87349-02V            |             | 7160 18F24  |
| 895A   | Magneto Switch Modification                                                         | PA-28R-201<br>PA-28RT-201T                                                               | 3/19/81  | 153-010<br>488-396   |             | 7430 18G8   |
| 899    | Part I - Aft Spinner<br>Bulkhead Refinement                                         | PA-28-161                                                                                | 10/3/80  | 36757-003V           |             | 6110 18G16  |
| 899    | Part II - Forward Spinner<br>Bulkhead Refinement                                    | PA-28-161                                                                                | 10/3/80  | **                   |             | 6110 18G17  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                     | MODELS AFFECTED                                                                                                                              | DATE     | PART/KIT NO.          | A.D. NO. | ATA CODE   |
|--------|-----------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------------|----------|------------|
| 901    | Cabin Air Intake Duct Modification                                          | PA-28-161/181/236<br>PA-28RT-201/201T<br>PA-44-180                                                                                           | 9/2/80   | 764-013V              |          | 2120 18G22 |
| 903A   | Alternator Belt Installation (Air Conditioned Models)                       | Any Textron-Lycoming Powered PA-28                                                                                                           | 3/11/96  | 62833-82              |          | 2431 18H2  |
| 905    | Compass Deviation-Battery Ground Wire Replacement                           | PA-28RT-201                                                                                                                                  | 1/21/81  | 764-087V              |          | 2430 18H7  |
| 906    | Lower Cowl Exhaust Fairing Replacement                                      | PA-44-180                                                                                                                                    | 4/21/81  | **                    |          | 7110 18H8  |
| 907    | Weight And Balance Plotter Modification                                     | PA-44-180                                                                                                                                    | 1/22/81  | 764-040V              |          | 800 18H10  |
| 908    | Instrument Panel Lighting - Century 21 And 41 Autopilot Installation        | PA-28-161/181<br>PA-28-236<br>PA-28RT-201<br>PA-28RT-201T                                                                                    | 12/20/80 |                       |          | 3310 18H11 |
| 910    | Engine Oil Quick Drain Valve                                                | PA-28R-200/201<br>PA-28RT-201                                                                                                                | 12/29/80 | 87369-26V<br>492-172V | 81-11-02 | 7920 18H17 |
| 915    | Firewall Reinforcement                                                      | PA-44-180                                                                                                                                    | 4/14/81  | 764-103V              |          | 5410 18I7  |
| 920    | Required Placard Adhesion Check                                             | PA-28-161/181<br>PA-28-201T<br>PA-28-236<br>PA-28R-201/201T<br>PA-28RT-201<br>PA-28RT-201T<br>PA-44-180<br>PA-44-180T                        | 6/29/81  |                       |          | 2500 18I19 |
| 933    | Engine Baffle Seal Security                                                 | PA-44-180<br>PA-44-180T                                                                                                                      | 11/23/81 | 189-780               |          | 7230 18J20 |
| 951    | Aft Fuselage Moisture Drain                                                 | PA-28-236<br>PA-28RT-201                                                                                                                     | 10/6/82  | 764-386V              |          | 2120 18L2  |
| 988    | Nose Landing Gear Modification                                              | PA-28R-180<br>PA-28R-200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180<br>PA-44-180T                                                   | 7/29/86  | **                    | 94-14-14 | 3225 19D1  |
| 997    | Wing Removal And Reinstallation; Reference Airworthiness Directive 87-08 08 | PA-28-140<br>PA-28-150/160/180<br>PA-28-151/161<br>PA-28-181<br>PA-28-235<br>PA-28R-180<br>PA-28R-200<br>PA-28R-201/201T<br>PA-28RT-201/201T | 5/14/87  | **                    | 87-08-08 | 5711 19D24 |
| 1019A  | Alternator Support Bracket Improvement                                      | PA-28-181 III                                                                                                                                | 1/22/98  | 101103-02<br>418-421  |          | 2412 19H1  |
| 1024   | Induction Airbox Air Valve Bushing Improvement                              | PA-28-181                                                                                                                                    | 8/4/99   | **                    |          | 7164 19H20 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                                                       | MODELS AFFECTED                                                          | DATE      | PART/KIT NO.                      | A.D. NO.                       | ATA CODE   |
|--------|---------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------|-----------------------------------|--------------------------------|------------|
| 1027   | Manifold Pressure Line Filters Addition                                                                       | PA-44-180                                                                | 11/5/99   | 560-686<br>**                     |                                | 7164 19I7  |
| 1028A  | Induction Airbox Inspection/Repair and Inlet Air Duct Replacement                                             | PA-28-181 III                                                            | 1/14/2000 | 766-666<br>85479-003<br>85489-011 |                                | 7164 19I11 |
| 1029A  | Recognition Light Circuit Breaker Inspection/Replacement                                                      | PA-28R-201                                                               | 1/24/2005 | 454-708<br>87369-053              |                                | 2454 19I15 |
| 1033   | Air Conditioning Hose Replacement                                                                             | PA-28-181 III                                                            | 7/9/2001  | 566-419<br>454-868                |                                | 2155 19J4  |
| 1034A  | Compass Accuracy Improvement Modification                                                                     | PA-44-180                                                                | 11/7/2013 | 766-699                           |                                | 3447       |
| 1038A  | Combustion Heater Fuel Pump Replacement                                                                       | PA-44-180<br>PA-44-180T                                                  | 2/16/2011 | 88476-002                         |                                | 2148       |
| 1040A  | Alternator Drive Belt Conversion Kit (for Aircraft Equipped with Optional Factory Installed Air Conditioning) | PA-28-180<br>PA-28-181 II/III<br>PA-28R-200<br>PA-28R-201<br>PA-28RT-201 | 10/7/2021 | 767-310<br>(88306-000)            |                                | 2410       |
| 1041A  | In-Service Safety Event Reporting                                                                             | All                                                                      | 3/17/2020 | N/A                               |                                | N/A        |
| 1045   | Electric Fuel Pump Upgrade                                                                                    | PA-28R-201                                                               | 3/26/2002 | 461-758                           |                                | 2825 19K21 |
| 1047   | Pilot Sidepost Handgrip Kit                                                                                   | PA-28-161 Cadet<br>PA-28-161<br>PA-28R-201<br>PA-44-180<br>PA-44-180T    | 5/28/2002 | 767-343                           |                                | 2510 19L3  |
| 1052   | Life Limited Parts Marking and Disposition                                                                    | All                                                                      | 5/21/2002 | N/A                               |                                | 510 19L19  |
| 1060   | Engine Primer Hose Improvement                                                                                | PA-44-180                                                                | 2/11/2003 | 63901-200<br>63901-201            |                                | 7300 20A23 |
| 1063   | Stabilator Bellcrank Bracket Assembly Inspection                                                              | PA-28RT-201<br>PA-28RT-201T<br>PA-44-180<br>PA-44-180T                   | 4/21/2003 | N/A                               |                                | 2792 20B7  |
| 1066   | Ignition Harness Routing Inspection                                                                           | PA-28-181 III                                                            | 4/24/2003 | 189-549                           |                                | 7420 20B17 |
| 1069   | Flight Control Cable Terminal Corrosion Inspection                                                            | All                                                                      | 3/31/2003 | N/A                               | CE-11-01<br>CE-02-05<br>(SAIB) | 2702 20C2  |
| 1074   | S-TEC Autopilot Component Seating Procedure                                                                   | All                                                                      | 11/3/2003 | N/A                               |                                | 2210 20C14 |
| 1081   | Rib Inspection at W.S. 36.22 R.H.                                                                             | PA-28-161 III<br>PA-28-181 III                                           | 7/1/2005  | 767-363<br>62066-000              |                                | 5712 20E7  |
| 1087   | Wing Aft Spar-to-Fuselage Attachment Hardware                                                                 | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                | 3/30/2005 | **                                |                                | 5740 20F6  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                          | MODELS<br>AFFECTED                                                                                                                                                  | DATE       | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------------------|-------------|-------------|
| 1089   | Aircraft Painting Requirement                    | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                           | 10/21/2004 | N/A                    |             | 1100        |
| 1093B  | Electrical Contactor Replacement Kit             | PA-28-140/150/180<br>PA-28-151/161/181<br>PA-28-161 Cadet<br>PA-28-201T<br>PA-28-235/236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T | 11/28/2017 | 88371                  |             | 2400        |
| 1095B  | Classification and Disposition of<br>Hail Damage | PA-28-140/150/180<br>PA-28-151/161/181<br>PA-28-161 Cadet<br>PA-28-201T<br>PA-28-235/236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T | 11/20/2020 | N/A                    |             | 5100        |
| 1103   | Attitude Indicator<br>Standby Battery Failure    | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                           | 4/20/2007  | 88410-002<br>88414-002 |             | 3420        |
| 1106A  | Sky-Tec Starter<br>Cranking Instructions         | PA-28-161 II-III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                        | 10/28/2009 | N/A                    |             | 8011        |
| 1108   | Manifold Pressure Transducer<br>Failures         | PA-28R-201<br>PA-44-180                                                                                                                                             | 3/4/2008   | N/A                    |             | 7713        |
| 1116A  | Contactor Maintenance                            | PA-28-140/150/160/180<br>PA-28-151/161/181<br>PA-28-201T<br>PA-28-235/236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T                | 3/15/2019  | N/A                    |             | 2435        |
| 1123   | Avidyne EXP5000 Software<br>Upgrade (Mod 57)     | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                           | 9/27/2010  | N/A                    |             | 3420        |
| 1124   | Air Conditioning Servicing                       | PA-28-181 III                                                                                                                                                       | 12/6/2010  | 197-511                |             | 2150        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                        | MODELS<br>AFFECTED                                                                                                                                                            | DATE       | PART/KIT<br>NO.              | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------------------------|-------------|-------------|
| 1125   | Stall Horn Bracket Replacement                                 | PA-28-160/180<br>PA-28S-160/180<br>PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28-201T<br>PA-28-235/236<br>PA-28R-201/201T<br>PA-28RT-201/201T | 7/27/2010  | 88472-002                    |             | 2730        |
| 1126A  | Voltage Suppressor Advisory                                    | PA-28-161 III<br>PA-28-181 III<br>PA-28R-201<br>PA-44-180                                                                                                                     | 3/23/2017  | N/A                          |             | 3400        |
| 1134   | Wing Tip Inspection Requirements                               | PA-44-180/180T                                                                                                                                                                | 10/7/2010  | N/A                          |             | 5720        |
| 1135   | Control Cable / Pulley Inspections                             | All                                                                                                                                                                           | 10/19/2010 | N/A                          |             | 5720        |
| 1141   | Gascolator Maintenance Procedures                              | PA-28-140/150/160/180<br>PA-28-151/161/181<br>PA-28-161 Cadet<br>PA-28-201T<br>PA-28-235/236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-28S-160/180       | 4/27/2011  | MS20995-C32                  |             | 2800        |
| 1149   | Nose Cone Fastener Inspection                                  | PA-44-180/180T                                                                                                                                                                | 2/8/2012   | **                           |             | 5330        |
| 1153   | Auxiliary Vacuum Pump Elapsed Time Indicator (ETI) Replacement | PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28R-201                                                                                                         | 6/12/2012  | 88509-002                    |             | 3710        |
| 1156   | Propeller Feather Stop Product Improvement                     | PA-44-180/180T                                                                                                                                                                | 4/2/2012   | 78713-003                    |             | 6120        |
| 1161   | Fuel Quantity Gauge Installation and Calibration Requirements  | PA-28-161 III<br>PA-28-181 III                                                                                                                                                | 1/10/2013  | 88536-001                    |             | 2840        |
| 1165   | Hydraulic Pump Identification and Servicing Requirements       | PA-28R Series<br>PA-44 Series                                                                                                                                                 | 10/18/2012 |                              |             | 2910        |
| 1193   | Garmin G1000 Software Update, Versions 1648.04 and 1983.02     | PA-44-180                                                                                                                                                                     | 7/16/2015  |                              |             | 3420        |
| 1213   | Garmin G1000 NXi Software Update Version 2698.04               | PA-28-181 III                                                                                                                                                                 | 9/29/2017  | 190-02130-00<br>190-02131-00 |             | 3420        |
| 1214   | Garmin G1000 NXi Software Update Version 2694.04               | PA-44-180                                                                                                                                                                     | 6/25/2018  | 190-02198-01<br>190-02199-01 |             | 3420        |
| 1215   | Garmin G1000 Software Update Version 1618.05                   | PA-28-181 III                                                                                                                                                                 | 1/15/2019  | 190-01459-00<br>190-01460-00 |             | 3420        |
| 1216A  | Garmin Software Update With Oil Pressure Transducer            | PA-44-180                                                                                                                                                                     | 1/10/2020  | 88610-002                    |             | 3420        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                          | MODELS AFFECTED                                                                                                                                                     | DATE       | PART/KIT NO.                    | A.D. NO. | ATA CODE |
|--------|----------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------------------------|----------|----------|
| 1218A  | Crew Seat Control Cable Modification                                             | PA-28-161 II-III<br>PA-28-161 Cadet<br>PA-28-181 II-III<br>PA-28-236<br>PA-28R-201/201T<br>PA-44-180/180T                                                           | 8/8/2017   | 76356-003<br>554-422<br>487-490 |          | 2510     |
| 1226   | Auxiliary Power Harness Inspection                                               | PA-44-180                                                                                                                                                           | 8/3/2018   | 88629-002                       |          | 2440     |
| 1229   | Control Quadrant Inspection                                                      | PA-28 Series<br>PA-28R Series<br>PA-44 Series                                                                                                                       | 1/3/2019   | 408-815                         |          | 7603     |
| 1239   | One-Piece Propeller Spinner Kit (Optional)                                       | PA-44-180                                                                                                                                                           | 2/11/2019  | 44P61A701-001                   |          | 6113     |
| 1240   | Garmin G1000 NXi Software Update Ver. 3080.04                                    | PA-28-181 III                                                                                                                                                       | 7/18/2018  | N/A                             |          | 3420     |
| 1252   | Improved Front Exhaust Assemblies                                                | PA-44-180                                                                                                                                                           | 9/5/2019   | 44P78A000-001<br>44P78A000-002  |          | 7800     |
| 1254   | Oil Pressure Transducer Kit Installation And Garmin G1000 Sw Ver. 1618.05 Update | PA-28-181 III                                                                                                                                                       | 12/19/2019 | 88608-002                       |          | 3420     |
| 1255   | Propeller Unfeathering System Accumulator Maintenance                            | PA-44-180/180T                                                                                                                                                      | 3/20/2019  | N/A                             |          | 6123     |
| 1256   | Gascolator Bracket Assembly Inspection                                           | PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28-201T<br>PA-28-236<br>PA-28R-201/201T III<br>PA-28RT-201/201T IV                       | 7/9/2019   | N/A                             |          | 2821     |
| 1262   | Garmin G1000 NXi Software Update Version 3080.05                                 | PA-28-181 III                                                                                                                                                       | 5/30/2019  | 88650-001                       |          | 3420     |
| 1263   | Main Landing Gear Piston Tube Inspection                                         | PA-44-180/180T                                                                                                                                                      | 12/23/2020 | 67037-006                       |          | 3213     |
| 1265   | Flight Control System Checks                                                     | All                                                                                                                                                                 | 8/6/2019   | N/A                             |          | 2700     |
| 1267   | Garmin G1000 NXi Software Update Version 3080.09                                 | PA-28-181 III                                                                                                                                                       | 1/21/2020  | 88664-002                       |          | 3420     |
| 1268   | Hartzell 'K' Flange Propeller Hub Replacement                                    | PA-28-235<br>PA-28R-180<br>PA-28R-200, II<br>PA-28R-201 III<br>PA-28RT-201 IV                                                                                       | 10/9/2019  | N/A                             |          | 6114     |
| 1273A  | Fuel Selector Valve Maintenance Requirements                                     | PA-28-140/150/160/180<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28-201T<br>PA-28-235/236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201 | 10/6/2021  | 491-947<br>(6S122)              |          | 2823     |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-28  
PA-28R  
PA-44/PA-44T

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED                                                                                                                                                                                      | DATE      | PART/KIT<br>NO.                                                   | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------------------------------------------------------------|-------------|-------------|
| 1274   | Hartzell Propeller Preferred Grease                                                                                               | All                                                                                                                                                                                                     | 1/6/2020  | NYCO GN 3058                                                      |             | 6110        |
| 1277A  | Garmin G1000 NXi Software Update Version 3344.02                                                                                  | PA-44-180                                                                                                                                                                                               | 2/14/2020 | 88671-001                                                         |             | 3420        |
| 1278A  | Garmin G1000 Software Update Version 1618.07                                                                                      | PA-28-181 III                                                                                                                                                                                           | 4/11/2022 | 88675-001                                                         |             | 3420        |
| 1280   | Rudder Pedal And Bar Assembly Inspection                                                                                          | All                                                                                                                                                                                                     | 2/14/2020 | N/A                                                               |             | 2720        |
| 1284   | Aspen Avionics EFD1000 Update To Software Version 2.10.2                                                                          | PA-28-181 III<br>PA-44-180                                                                                                                                                                              | 2/3/2023  | N/A                                                               |             | 3420        |
| 1291   | ADAHRS Support Modification                                                                                                       | PA-28-181 III                                                                                                                                                                                           | 2/24/2021 | 88685-701                                                         |             | 5320        |
| 1293A  | Garmin G1000 NXi Software Update Version 3080.12                                                                                  | PA-28-181 III                                                                                                                                                                                           | 2/28/2022 | 88683-701                                                         |             | 3420        |
| 1302   | Replacement Of Locking Gascolator Drain Valve                                                                                     | PA-28-140/150/160/180<br>PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II<br>PA-28-181 II<br>PA-28-201T<br>PA-28-236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T                               | 12/1/2022 | 492-022<br>492-312                                                |             | 2821        |
| 1309   | Nose Landing Gear Steering Horn Inspection                                                                                        | PA-28-140/150/160/180<br>PA-28-181                                                                                                                                                                      | 2/13/2023 | 63300-004                                                         |             | 3250        |
| 1311   | Parker Lord SIL-J-9613-001 Rev. A, 'Potential Incorrect Combination of Components in Parker Lord J-9613 Series Engine Mount Kits' | PA-28-151/161<br>PA-28-161 Cadet<br>PA-28-180<br>PA-28-181 Archer II-III/Pilot<br>PA-28-236<br>PA-28R-180-200<br>PA-28R-201<br>PA-28RT-201<br>PA-44-180/180T                                            | 6/7/2022  | 470-516 / J-9613-19<br>475-115 / J-9613-12<br>475-124 / J-9613-40 |             | 7120        |
| 1313   | Interior Panel Attachment Mod                                                                                                     | PA-28-181 Pilot                                                                                                                                                                                         | 6/3/2022  | 289-765<br>28F250003-001                                          |             | 2510        |
| 1318A  | Brake Line Modification                                                                                                           | PA-28-161 Warrior II<br>PA-28-181 Archer III<br>PA-28-181 Pilot<br>PA-28R-201 Arrow III / Arrow                                                                                                         | 3/24/2023 | 454-934                                                           |             | 3240        |
| 1320   | Wing And Fuselage Skin Repair Limitations                                                                                         | PA-28-140/150/160/180<br>PA-28-151<br>PA-28-161 Cadet<br>PA-28-161 II-III<br>PA-28-181 II-III<br>PA-28-201T<br>PA-28-235/236<br>PA-28R-180/200<br>PA-28R-201/201T<br>PA-28RT-201/201T<br>PA-44-180/180T | 12/1/2022 | N/A                                                               |             | 5100        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                       | MODELS<br>AFFECTED                | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------------------------------------------------------------|-----------------------------------|-----------|-----------------|-------------|-------------|
| 1321   | Garmin G5 EFI Standby Display<br>Software Update Version 8.00 | PA-28-181 Archer III<br>PA-44-180 | 2/23/2023 | 88728-701       |             | 3420        |
| 1322   | Garmin G1000 Software Update<br>Version 1983.04               | PA-44-180                         | 1/18/2023 | 88716-701       |             | 3420        |
| 1324   | Garmin G1000 NXi Software Update<br>Version 2694.05           | PA-44-180                         | 1/20/2023 | 88717-707       |             | 3420        |
| 1325   | Garmin G1000 Software Update<br>Version 1648.06               | PA-44-180                         | 3/13/2023 | 88710-707       |             | 3420        |
| 1326   | Garmin G1000 NXi Software Update<br>Version 2698.06           | PA-28-181                         | 3/7/2023  | 88717-707       |             | 3420        |



# SERVICE LETTER INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                                                                                                                                                     | MODELS<br>AFFECTED       | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE        |
|--------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------|--------------------|-------------|--------------------|
| 487    | Test Unit, Hydraulic (And Fabricated Jack Stand)                                                                                                                                            | PA-31<br>PA-31-300       | 2/13/67  | 753-080            |             | 710 14J14          |
| 492    | Replacement of:<br>(I) Landing Gear Selector Handle<br>(And Associated Link Rod To Power Pak), General Instructions For Inspection And Operation of, And<br>(II) Nose Gear Idler Link Assy. | PA-31                    | 9/6/67   | **                 |             | 3200 14J20<br>3220 |
| 497    | Manifold Pressure Gauge Filter Assembly                                                                                                                                                     | PA-31                    | 1/30/68  | 760-171            |             | 7710 14K4          |
| 498    | Nose Gear Idler Link Assembly (Identification Tag)                                                                                                                                          | PA-31                    | 3/1/68   | 760-170            |             | 3230 14K5          |
| 500    | Altimatec III Series-<br>(I) Radio Coupler<br>(II) Amplifier Replacement                                                                                                                    | PA-31                    | 3/22/68  | 760-191<br>760-192 |             | 3400 14K7          |
| 502    | Navajo Cabin Heat Modification                                                                                                                                                              | PA-31                    | 3/18/68  | 760-187<br>760-188 |             | 2140 14K12         |
| 504    | B. F. Goodrich Service Bulletin No. E-67-34                                                                                                                                                 | PA-31                    | 4/8/68   |                    |             | 3240 14K14         |
| 505A   | Fuselage Drain Holes                                                                                                                                                                        | PA-31                    | 5/2/68   |                    |             | 5300 14K16         |
| 506    | Main Landing Gear (Outboard) Door Actuator Bracket                                                                                                                                          | PA-31                    | 5/2/68   | 757-178            |             | 3210 14K18         |
| 507    | ADF Installation Spacer                                                                                                                                                                     | PA-31                    | 5/22/68  | 760-211            |             | 3400 14K19         |
| 508    | Propeller Counterweight Attachment Bolt Clearance                                                                                                                                           | PA-31<br>PA-31-300       | 7/9/68   | 43556-00           |             | 6120 14K20         |
| 509    | Pneumatic Pump Air Inlet Relocation                                                                                                                                                         | PA-31                    | 6/24/68  | 760-200            |             | 3710 14K22         |
| 512    | Attachment of Rudder Tab Hinge Brackets                                                                                                                                                     | PA-31<br>PA-31-300       | 10/8/68  | 760-243            |             | 2720 14L1          |
| 514    | Flight Control Cable Systems                                                                                                                                                                | PA-31/31-300             | 9/19/68  |                    |             | 2210 14L3          |
| 517    | Beacon (Rotating) Attachment Screws-Shock Mounted Beacon                                                                                                                                    | PA-31<br>PA-31-300       | 10/23/68 |                    |             | 3340 14L13         |
| 523    | Modification To The Fuselage Bulkhead                                                                                                                                                       | PA-31<br>PA-31-300       | 4/9/69   | 760-295            |             | 5310 15A3          |
| 524    | Weldon Electric Fuel Pump Modification                                                                                                                                                      | PA-31<br>PA-31-300       | 5/20/69  | 760-316<br>760-317 |             | 2810 15A5          |
| 530    | Hydraulic Fluid Level Gauge "O" Ring Replacement                                                                                                                                            | PA-31<br>PA-31-300       | 5/23/69  | 484-815            |             | 2910 15A22         |
| 531    | Cowl Flap Support Assembly                                                                                                                                                                  | PA-31/31-300             | 8/22/69  | 760-330            |             | 7110 15A24         |
| 532    | Voltage Regulation Component Grounding                                                                                                                                                      | PA-31<br>PA-31-300       | 7/7/69   | 760-333            |             | 2430 15B2          |
| 537    | Landing Gear Door Hinge Bracket Reinforcement                                                                                                                                               | PA-31<br>PA-31-300       | 10/16/69 | 760-348            |             | 3230 15B15         |
| 538    | Inspection of Propeller Blade Shank (Hartzell Service Bulletin No. 94)                                                                                                                      | PA-31<br>(2 Blade Props) | 10/23/69 |                    |             | 6110 15B17         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED                                                    | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE        |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|-----------|-----------------|-------------|--------------------|
| 548    | Inspection of The Right Engine<br>Control System Installation                                                                     | PA-31<br>PA-31-300                                                    | 3/16/70   |                 |             | 7610 15C17         |
| 550B   | Turbocharger Density Control<br>Adjustment                                                                                        | PA-31<br>PA-31-350                                                    | 7/10/74   |                 |             | 8120 15C21         |
| 553    | Equipment (Required) Pressurized<br>Navajo Service Support                                                                        | PA-31P                                                                | 5/20/70   | **              |             | 2130 15D12         |
| 555    | Inspection of Nose Gear Idler<br>Link Assembly                                                                                    | PA-31<br>PA-31-300                                                    | 7/8/70    |                 |             | 3220 15D15         |
| 562    | Scott Aviation Service<br>Bulletin No. 35-32                                                                                      | PA-31-300                                                             | 8/25/70   | **              |             | 3500 15E10         |
| 566    | Autopilot Servo Spacer Bushing<br>Installation                                                                                    | PA-31-300                                                             | 11/25/70  | 760-473         |             | 2210 15F3          |
| 573    | B F Goodrich Service<br>Bulletin No. E-68-36B<br>(Sealer For B F. Goodrich<br>Deicer And Strap)                                   | PA-31<br>PA-31-350<br>PA-31-P                                         | 3/4/71    |                 |             | 3020 15F17         |
| 578B   | Fuel Line (Stainless Steel Tube Assy.)<br>and Support Clamp Inspection<br>and Installation,<br>Lycoming Service Bulletin No. 342F | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P-350 | 7/27/2011 | N/A             | 2011-26-04  | 7310               |
| 580    | Fuel Selector Valve Packing<br>Lubrication                                                                                        | PA-31/31-300<br>PA-31P                                                | 5/24/71   | 760-504         |             | 2820 15G18         |
| 593    | Connector Plug, Harness Strain<br>Relief Hood Installation                                                                        | PA-31, Alt. V<br>Or Alt. V/FD                                         | 10/11/71  | 760-556         |             | 2400 15H15         |
| 594    | Inspection of Flap Track And<br>Rudder Tip Rib Assemblies                                                                         | PA-31-300                                                             | 10/8/71   | **              |             | 5750 15H19<br>5510 |
| 603    | Hartzell Service Letter No. 70                                                                                                    | PA-31P                                                                | 2/8/72    | **              |             | 6110 15I17         |
| 609    | Control Surfaces<br>Inspection And<br>Maintenance Guidelines                                                                      | All Models                                                            | 2/21/72   |                 |             | 5500 15J21         |
| 617B   | Piper Automatic Locator<br>Transmitter Replacement                                                                                | PA-31<br>PA-31-350<br>PA-31P                                          | 8/30/73   |                 | 72-22-03    | 2560 15K18         |
| 619    | Inspection of Retainer Spring<br>Piper Part No. 83302-13                                                                          | PA-31<br>PA-31-300                                                    | 6/9/72    | 83302 13        |             | 7330 15L5<br>7160  |
| 630    | Lubrication of Fuel Selector<br>Valve Mechanism                                                                                   | PA-31/31-300<br>PA-31P                                                | 9/13/72   | **              |             | 2820 16A11         |
| 631A   | Wiring Inspection, Alternator<br>Switch And Circuit Breaker Panel                                                                 | PA-31<br>PA-31-300                                                    | 4/25/73   | **              |             | 2430 16A13         |
| 633    | Inspection And Repair of<br>Flood Exposed Airplanes                                                                               | PA-31<br>PA-31-350<br>PA-31P                                          | 10/9/72   |                 |             | 5300 16A18         |
| 635    | Lycoming Service Bulletin No. 356<br>(Addition of Alternator Bracket<br>Support)                                                  | PA-31                                                                 | 10/16/72  | **              |             | 2400 16A24         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                                                                                                                       | MODELS<br>AFFECTED                   | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE       |
|--------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|----------|--------------------|-------------|-------------------|
| 636    | Prestolite Service Bulletin<br>No. ASM-8 (Alternator Fan<br>Replacement)                                                                                      | PA-31<br>PA-31-350<br>PA-31P         | 10/24/72 | **                 |             | 2430 16B2         |
| 639    | Alternator Field Switch<br>Guard Modification                                                                                                                 | PA-31-P                              | 12/20/72 | 760-721            |             | 2430 16B11        |
| 642    | Revised Alternator Inoperative<br>Warning Light                                                                                                               | PA-31                                | 2/19/73  | 760-713            |             | 2430 16B15        |
| 643    | Control Shaft Collar<br>Restraining Strap                                                                                                                     | PA-31/31-300<br>PA-31P               | 2/5/73   | 760-723            | 76-04-11    | 2700 16B17        |
| 653    | Throttle Lever And Shaft,<br>Serrated (Reference Avco<br>Lycoming Service Instruction<br>No. 1265 Dated December 15, 1972)                                    | PA-31                                | 4/9/73   | **                 |             | 7610 16C14        |
| 654    | Heater Control System Modification                                                                                                                            | PA-31-350                            | 4/18/73  | **                 |             | 2140 16C17        |
| 655    | Turbocharger Modification;<br>Airesearch Service Bulletin<br>No. 1172-1A(Reference<br>Avco Lycoming Service<br>Bulletin No. 361, Dated<br>February 16, 1973)  | PA-31<br>PA-31-350<br>PA-31P         | 4/10/73  | **                 |             | 8120 16C21        |
| 656    | King Area Nav Operation<br>Limitation Placard                                                                                                                 | PA-31-310<br>PA-31-350<br>PA-31-P    | 5/15/73  | 696-1109-00        |             | 3450 16D2<br>3400 |
| 658    | Static System Line Modification                                                                                                                               | PA-31-350                            | 6/14/73  | 760-750            |             | 2350 16D5         |
| 660    | Revised Alternator Ground<br>Wire Installation                                                                                                                | PA-31-310<br>PA-31-350               | 7/6/73   | 760-778            |             | 2430 16D7         |
| 665A   | Intake Valves, Rotator Type                                                                                                                                   | PA-31/31-300<br>PA-31-350            | 10/24/73 | **                 |             | 7160 16D16        |
| 666    | Propeller Governor Speed<br>Adjusting Shaft, Lever And<br>Lever Clamp Screw Replacement<br>(Reference Woodward Service<br>Bulletin No. 33549, Dated May 1973) | PA-31P                               | 9/13/73  | **                 |             | 6120 16D18        |
| 674    | Over Voltage Relay Inspection                                                                                                                                 | PA-31-300/310<br>PA-31P              | 1/3/74   | 760-787            |             | 2430 16E16        |
| 675    | Magneto Switch Guard Installation                                                                                                                             | PA-31-300/310<br>PA-31-350<br>PA-31P | 9/17/73  | 760-789<br>760-790 | 74-26-10    | 2430 16E18        |
| 680    | Receiver Dehydrator Relocation                                                                                                                                | PA-31-310<br>PA-31-350               | 11/29/73 | 760-803            |             | 2710 16F5         |
| 681    | Inspection of Elevator Balance<br>Weight Bolts                                                                                                                | PA-31-350                            | 10/24/73 | **                 |             | 2730 16F7         |
| 682B   | Required Inspection of Piston<br>Pin (Reference Lycoming<br>Service Bulletin No. 367D)                                                                        | PA-31<br>PA-31-350<br>PA-31P         | 4/19/74  | **                 |             | 7230 16F9         |
| 685    | Installation Alternator Field<br>Wire Clamp                                                                                                                   | PA-31P                               | 10/24/73 | 760-807            |             | 2420 16F19        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                                        | MODELS<br>AFFECTED                  | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|----------|-----------------|-------------|-------------|
| 688    | Unfeathering Accumulator<br>Maintenance And Preventive<br>Maintenance (Reference<br>Woodward Service Bulletin<br>No 33551, Dated August, 1973) | PA-31P                              | 10/24/73 |                 |             | 6120 16G1   |
| 690A   | Cylinder (Engine) Baffle Removal<br>And Cylinder Head Temperature<br>Probe Relocation                                                          | PA-31-350                           | 3/4/74   |                 |             | 7720 16G4   |
| 691    | Cigar Lighter Circuit<br>Protector Replacement                                                                                                 | PA-31P                              | 11/12/73 | 760-809         |             | 3310 16G6   |
| 692    | Heater System Modification                                                                                                                     | PA-31-350                           | 2/12/74  | 760-804         |             | 2140 16G8   |
| 696    | Control Surface Balancing<br>Recommendation                                                                                                    | PA-31/31-300<br>PA-31-350<br>PA-31P | 5/2/74   |                 |             | 2700 16G20  |
| 697    | Fuselage Addition of Drain Holes                                                                                                               | PA-31-300/310<br>PA-31-350          | 3/14/74  |                 |             | 5300 16G22  |
| 698    | Ground Handling (Towing)<br>Recommendations                                                                                                    | PA-31-300/310<br>PA-31-350          | 2/6/74   |                 |             | 3200 16G24  |
| 699    | Fuel Vent Line Check Valve<br>Installation (Reference Avco<br>Lycoming Service Bulletin<br>No. 362A; Dated December 14, 1973)                  | PA-31P                              | 2/12/74  | LW-13324        |             | 2810 16H2   |
| 701    | Overvoltage Relays, Wiring of;<br>Alternator Paralleling System                                                                                | PA-31P                              | 3/14/74  | **              |             | 2430 16H6   |
| 707    | Flyball Assembly To Improve<br>RPM Control, Modified<br>(Reference Hartzell Service<br>Letter No. 75, Dated<br>November 16, 1973)              | PA-31<br>PA-31-350<br>PA-31P        | 2/27/74  | **              |             | 7710 16I11  |
| 709    | Inspection of Pneumatic Pump<br>Mounting Flanges                                                                                               | PA-31P                              | 5/1/74   |                 |             | 3710 16I17  |
| 711    | Inspection of Submerged<br>Fuel Pumps                                                                                                          | PA-31P                              | 5/30/74  | 48812-00        |             | 2820 16J4   |
| 712    | T-Bolt Clamping Bands, High<br>Tensile (Reference Avco Lycoming<br>Service Bulletin No. 372A,<br>Dated March 15, 1974)                         | PA-31-350                           | 5/15/74  | LW-13886        |             | 8120 16J7   |
| 713    | Static Air Sump Installation                                                                                                                   | PA-31-310<br>PA-31-350<br>PA-31-P   | 8/21/74  | 760-864         |             | 3410 16J9   |
| 716    | Moisture Seal, Cross Shaft<br>Support Tube (Reference Avco<br>Lycoming Service Bulletin<br>No. 375A, Dated May 10, 1974)                       | PA-31P                              | 6/3/74   | **              |             | 7200 16J13  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                                                                           | MODELS<br>AFFECTED                                         | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|----------|--------------------|-------------|-------------|
| 718    | Bendix Magneto Bulletin<br>No. 566 (Reference Avco<br>Lycoming Service Bulletin<br>373, Dated March 22. 1974)     | PA-31<br>PA-31-350<br>PA-31-P                              | 5/31/74  | **                 |             | 7410 16J18  |
| 719    | Deicer Boot Installation<br>Throttle Control Cable                                                                | PA-31P                                                     | 8/28/74  | 760-874            |             | 7610 16K1   |
| 722    | Fuel System Modification                                                                                          | PA-31-350                                                  | 8/27/74  | 760-873            |             | 2800 16K9   |
| 723    | Glideslope Indicator Placard                                                                                      | PA-31/31-300<br>PA-31-350<br>PA-31P                        | 8/14/74  | SK 2359            |             | 3430 16K11  |
| 725    | Fuel Pressure Gauge Modification                                                                                  | PA-31-350                                                  | 9/19/74  | 54209-02           |             | 7330 16K14  |
| 726    | Cigar Lighter Placard                                                                                             | PA-31P                                                     | 8/8/74   | 80247-02           |             | 3310 16K16  |
| 730    | Air Conditioning System Modification                                                                              | PA-31-350                                                  | 8/20/74  | 760-881            |             | 2150 16K23  |
| 733    | Pilot And Copilot Cabin<br>Heat Refinement                                                                        | PA-31-350                                                  | 4/21/75  | 760-924            |             | 2140 16L7   |
| 739    | Cabin Door Refinement                                                                                             | PA-31/31-300<br>PA-31-350                                  | 6/2/75   | **                 | 78-05-05    | 5210 17A1   |
| 741    | Radome Weather<br>Seal                                                                                            | PA-31P                                                     | 1/23/75  | 760-919<br>760-920 |             | 5340 17A7   |
| 752A   | Replacement of Alternator<br>Ground Wire                                                                          | PA-31P                                                     | 10/30/75 | 760-988            |             | 2420 17B2   |
| 753    | Propeller Feather Assist Spring<br>Assembly Installation Reference<br>Attached Hartzell Service<br>Letter No. 101 | PA-31-300/325<br>PA-31-350                                 | 7/16/76  | **                 |             | 6120 17B3   |
| 755C   | Part I - Landing Gear Lock<br>Actuator Rod And Rod End<br>Bearing Assemblies Inspection<br>And Lubrication        | PA-31/31-300<br>PA-31-325<br>PA-31-350<br>T-1020<br>PA-31P | 11/4/85  | **                 |             | 3235 17B13  |
| 755C   | Part II - Landing Gear Lock<br>Actuator Rod Replacement                                                           | PA-31/31-300<br>PA-31-325<br>PA-31-350<br>T-1020<br>PA-31P | 11/4/85  | 764-958            |             | 3235 17B15  |
| 755C   | Part III - Installation of<br>Anti-Rotation Stops                                                                 | PA-31<br>PA-31-325<br>PA-31 -350<br>T-1020<br>PA-31P-350   | 11/4/85  | **                 |             | 3235 17B16  |
| 764A   | Wing Flap System Maintenance<br>Procedure                                                                         | PA-31-300/325<br>PA-31-350<br>PA-31P                       | 7/17/79  |                    | 81-11-03    | 2750 17C19  |
| 766    | Inspection of Cleveland<br>Brake Discs                                                                            | PA-31-325<br>PA-31-350                                     | 1/6/77   | **                 |             | 3240 17D9   |
| 770    | Aileron Sprocket/Chain<br>Inspection                                                                              | PA-31-300/325<br>PA-31-350<br>PA-31 P                      | 1/27/77  | **                 |             | 2710 17D18  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                                            | MODELS<br>AFFECTED                        | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE        |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|----------|--------------------|-------------|--------------------|
| 773    | Nose Cone ("Radome")<br>Latch System Refinement                                                                                                    | PA-31P                                    | 6/28/76  | 761-012            |             | 5340 17E7          |
| 778    | Elevator Butt Rib Refinement                                                                                                                       | PA-31P                                    | 6/14/76  | 54755-02           |             | 5520 17E14         |
| 781    | Cockpit Forward Bulkhead/<br>Floorboard Sealing                                                                                                    | PA-31-350                                 | 10/22/76 | **                 |             | 5310 17E21<br>5320 |
| 783    | Inspection of Air Conditioning<br>System Capillary Sensor                                                                                          | PA-31P                                    | 9/20/76  | **                 |             | 2150 17F7          |
| 784    | Landing Gear Hydraulic<br>System Refinement                                                                                                        | PA-31-300                                 | 9/27/76  | 491-050<br>484-459 |             | 2920 1 7F10        |
| 789    | Inspection of Elevator<br>Bellcrank And Elevator<br>Control Rod                                                                                    | PA-31-300/325<br>PA-31-350<br>PA-31P      | 10/6/77  | **                 |             | 2730 17F21         |
| 798    | Cabin Headliner/Oxygen<br>Cover Panel Refinement                                                                                                   | PA-31P                                    | 2/4/77   |                    |             | 2520 17G13<br>3520 |
| 801    | Goodyear Tri-Metallic Brakes,<br>Maintenance And Operation;<br>Ref: Goodyear Service Letter<br>"PA-31-350/31 P/31T SL-1"<br>Dated January 15, 1977 | PA-31-350<br>PA-31P                       | 2/25/77  |                    |             | 3240 17G21         |
| 802    | Main Landing Gear Door Hinge<br>Attachment Screw Replacement                                                                                       | PA-31/31-325<br>PA-31-350<br>PA-31P       | 3/9/77   | 761-128            |             | 3210 17G24         |
| 803A   | Cabin Door Latch System<br>Refinement                                                                                                              | PA-31-300/325<br>PA-31-350                | 11/3/77  | 55633-03           | 78-05-05    | 5210 17H1          |
| 816    | Powerpak Reservoir Replacement<br>(Wiebel Hydraulic Powerpaks)                                                                                     | PA-31-350<br>PA-31P                       | 12/19/77 | 763-831            |             | 2910 17I18         |
| 820    | Replacement of Lithium<br>Sulphur Dioxide (LiS02)<br>ELT Batteries and/or<br>Transmitters                                                          | PA-31/31-300<br>PA-31-325<br>PA-31-350    | 7/28/80  | **                 | 79-18-05    | 2560 17J2          |
| 821    | Right Engine Cowl Louver<br>Installation Kit                                                                                                       | PA-31-350                                 | 3/7/78   | 763-802            |             | 7110 17J6          |
| 823    | Heater/Evaporator Return<br>Air Duct Hose Replacement                                                                                              | PA-31P                                    | 2/10/78  | 49478-02           |             | 2120 17J10         |
| 829    | Emergency Exit Window<br>Latch Modification                                                                                                        | PA-31P                                    | 11/14/77 | 763-809            |             | 5620 17J18         |
| 830    | 24 Volt Cigar Lighter Element<br>Replacement                                                                                                       | PA-31<br>PA-31-325<br>PA-31-350<br>PA-31P | 11/22/77 | **                 |             | 3310 17J19         |
| 833    | Cabin Pressurization<br>System Rupture Disc<br>Elimination                                                                                         | PA-31P                                    | 4/10/78  |                    |             | 2130 17J22         |
| 834    | Flap Electrical System Refinement                                                                                                                  | PA-31/300/325<br>PA-31-350<br>PA-31P      | 3/3/78   | **                 |             | 2750 17J24         |
| 844    | Heater System Rewiring                                                                                                                             | PA-31-350                                 | 4/24/78  |                    |             | 2140 17K20         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                                      | MODELS<br>AFFECTED                               | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE        |
|--------|--------------------------------------------------------------|--------------------------------------------------|----------|--------------------|-------------|--------------------|
| 847    | Avionics Emergency Bus Power<br>Switch Guard Installation    | PA-31P                                           | 8/13/79  | **                 |             | 2450 17L2          |
| 866    | Windshield Wiper Arm Retaining<br>Wire Installation          | PA-31/31-300<br>PA-31-325<br>PA-31-350<br>PA-31P | 12/7/79  | 151-295            |             | 5610 18C1          |
| 872    | Alternator Wiring Inspection                                 | PA-31/31-300<br>PA-31-325<br>PA-31-350           | 6/7/79   | 588-594            |             | 2430 18D6          |
| 873    | Stall Warning System Refinement                              | PA-31<br>PA-31-325<br>PA-31-350                  | 5/8/79   |                    |             | 2700 18D9          |
| 874    | Low Fuel Warning Sensor Sealing                              | PA-31<br>PA-31-325<br>PA-31-350                  | 10/19/79 | **                 |             | 2840 18D12         |
| 875    | Engine Front Baffle Replacement                              | PA-31<br>PA-31-325<br>PA-31-350                  | 5/11/81  | 764-093            | 93-23-13    | 7230 18D16         |
| 878A   | Oil Breather Tube Inspection/<br>Alignment                   | PA-31/31-300<br>PA-31-325<br>PA-31-350           | 3/6/81   |                    |             | 7220 18E13         |
| 879    | Razor Inverter Replacement                                   | PA-31<br>PA-31-325<br>PA-31-350                  | 5/20/80  | 467-488            |             | 3320 18E18         |
| 883    | Wing Flap Rivet Installation                                 | PA-31P                                           | 10/20/79 | **                 |             | 5750 18F8          |
| 885    | Aileron And Elevator Control<br>Systems Hardware Replacement | PA-31/31-300<br>PA-31-325<br>PA-31-350           | 3/10/81  | 763-996            |             | 5550 18F13         |
| 886    | Master Switch Replacement                                    | PA-31<br>PA-31-325<br>PA-31-350                  | 1/6/81   | 764-090            |             | 2450 18F15         |
| 887    | Starter And Battery Cable<br>Inspection                      | PA-31<br>PA-31-325<br>PA-31-350                  | 5/29/81  | **                 |             | 8010 18F16<br>2430 |
| 894    | Heater Modification                                          | PA-31-350                                        | 9/4/80   | 764-005            |             | 2140 18G7          |
| 904    | Sealing Procedures To Prevent<br>Water Leaks                 | PA-31/31-300<br>PA-31-325<br>PA-31-350           | 3/11/81  | **                 |             | 5210 18H5          |
| 912    | Main Landing Gear Downlock<br>Hook Rivet Replacement         | PA-31/300/325<br>PA-31-350                       | 3/5/81   | 420-890<br>422-241 |             | 3230 18H24         |
| 916    | Elevator Control Stop Screw<br>Replacement                   | PA-31/31-300<br>PA-31-350<br>PA-31P              | 7/17/81  | **                 |             | 2730 18I8          |
| 917    | Portable Fire Extinguisher<br>Inspection                     | PA-31<br>PA-31-325<br>PA-31-350                  | 7/20/81  | 459-839<br>459-848 |             | 2620 18I11         |
| 921    | Main Landing Gear Lock Rod<br>Attachment Fork Replacement    | PA-31P                                           | 4/21/82  | 764-127            |             | 3230 18I21         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                  | MODELS<br>AFFECTED                                                              | DATE       | PART/KIT<br>NO.        | A.D.<br>NO.        | ATA<br>CODE |
|--------|--------------------------------------------------------------------------|---------------------------------------------------------------------------------|------------|------------------------|--------------------|-------------|
| 935    | ELT Antenna Inspection                                                   | PA-31<br>PA-31-325<br>PA-31-350                                                 | 3/26/82    | **                     |                    | 2560 18J23  |
| 958    | Flap Travel Restriction<br>Supplementary Kit                             | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31P                                   | 10/25/82   | 764-920L               |                    | 5750 18L18  |
| 959    | Flap System Modification                                                 | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31P                                   | 6/10/83    |                        |                    | 5750 19A1   |
| 959    | Part I - Calco Flap<br>System Installation                               | PA-31<br>PA-31-300/325<br>PA-31-350                                             | 6/10/83    | 764-938L               |                    | 5750 19A1   |
| 959    | Part II - Flap Transmission<br>Replacement (Dukes 20:1 To<br>Calco 40:1) | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31P                                   | 6/10/83    | 764-957L               |                    | 5750 19A2   |
| 987    | Main Landing Gear<br>Mount Bolt Inspection                               | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 7/25/86    | 400-384                |                    | 3213 19C22  |
| 1041A  | In-Service Safety Event Reporting                                        | All                                                                             | 3/17/2020  | N/A                    |                    | N/A         |
| 1052   | Life Limited Parts<br>Marking and Disposition                            | All                                                                             | 5/21/2002  | N/A                    |                    | 510 19L19   |
| 1069   | Flight Control Cable Terminal<br>Corrosion Inspection                    | All                                                                             | 3/31/2003  | N/A                    | CE-02-05<br>(SAIB) | 2702 20C2   |
| 1086   | Propeller Blade De-ice Boots<br>Maintenance                              | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31-350 T-1020                         | 7/16/2004  | N/A                    |                    | 3112 20F3   |
| 1088   | 40336-000 Link Assembly Inspection                                       | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 12/15/2004 | 40336-000              |                    | 3220 20F11  |
| 1092C  | Main Gear Retraction Arms<br>Inspection, 42042-000/-002                  | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 7/25/2013  | 42042-000<br>42042-002 |                    | 3211        |
| 1093B  | Electrical Contactor Replacement Kit                                     | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P               | 11/28/2017 | 88371                  |                    | 2400        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE LETTER INDEX

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

| NUMBER | SUBJECT                                             | MODELS<br>AFFECTED                                                               | DATE       | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------|----------------------------------------------------------------------------------|------------|-----------------|-------------|-------------|
| 1116A  | Contactors Maintenance                              | PA-31<br>PA-31-300/325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350  | 3/15/2019  | N/A             |             | 2435        |
| 1135   | Control Cable / Pulley Inspections                  | All                                                                              | 10/19/2010 | N/A             |             | 5720        |
| 1188   | Landing Gear Hydraulic System<br>Filter Maintenance | PA-31<br>PA-31-300/-325<br>PA-31-350<br>PA-31-350 T-1020<br>PA-31P<br>PA-31P-350 | 3/19/2015  | N/A             |             | 2912        |
| 1265   | Flight Control System Checks                        | All                                                                              | 8/6/2019   | N/A             |             | 2700        |
| 1274   | Hartzell Propeller Preferred Grease                 | All                                                                              | 1/6/2020   | NYCO GN 3058    |             | 6110        |
| 1280   | Rudder Pedal And Bar Assembly<br>Inspection         | All                                                                              | 2/14/2020  | N/A             |             | 2720        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-31/PA-31-300/325  
PA-31-350, PA-31P  
PA-31P-350

# SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------|--------------------|------|-----------------|-------------|-------------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.  
\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.  
\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-31T/31T1  
PA-31T2/31T3  
PA-42

| NUMBER | SUBJECT                                                                                                    | MODELS<br>AFFECTED                      | DATE    | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE        |
|--------|------------------------------------------------------------------------------------------------------------|-----------------------------------------|---------|--------------------|-------------|--------------------|
| 609    | Control Surfaces Inspection<br>And Maintenance Guidelines                                                  | All Models                              | 2/21/72 |                    |             | 5500 15J21         |
| 736    | M-4D Automatic Flight Control<br>System Modification                                                       | PA-31T1                                 | 12/3/74 | **                 |             | 2210 16L14         |
| 741    | Radome Weather Seal                                                                                        | PA-31T                                  | 1/23/75 | 760-919<br>760-920 |             | 5340 17A7          |
| 743    | Cabin Altitude Controller Relocation                                                                       | PA-31T                                  | 2/19/75 | 760-921            |             | 2130 17A12         |
| 755C   | Part I - Landing Gear Lock<br>Actuator Rod And Rod<br>End Bearing Assemblies<br>Inspection And Lubrication | PA-31T/31T1<br>PA-31-31T2/31T3<br>PA-42 | 11/4/85 | **                 |             | 3235 17B13         |
| 755C   | Part II - Landing Gear Lock<br>Actuator Rod Replacement                                                    | PA-31T/31T1<br>PA-31-31T2/31T3<br>PA-42 | 11/4/85 | 764-958            |             | 3235 17B15         |
| 755C   | Part III - Installation of<br>Anti-Rotation Stops                                                          | PA-31T1                                 | 11/4/85 | **                 |             | 3235 17B16         |
| 764A   | Wing Flap System Maintenance<br>Procedure                                                                  | PA-31T<br>PA-31T1                       | 7/17/79 |                    |             | 2750 17C19         |
| 770    | Aileron Sprocket/Chain Inspection                                                                          | PA-31T                                  | 1/27/77 | **                 |             | 2710 17D18         |
| 773    | Nose Cone ("Radome") Latch<br>System Refinement                                                            | PA-31T                                  | 6/28/76 | 761-012            |             | 5340 17E7          |
| 779    | Heater Fuel Pressure Relief<br>Valve Inspection                                                            | PA-31T                                  | 8/16/76 | **                 |             | 2140 17E16         |
| 780    | New Engine Top Mounts                                                                                      | PA-31T                                  | 6/8/76  | 761-612<br>761-613 |             | 7120 17E19         |
| 783    | Inspection of Air Conditioning<br>System Capillary Sensor                                                  | PA-31T                                  | 9/20/76 | **                 |             | 2150 17F7          |
| 789    | Inspection of Elevator Bellcrank<br>And Elevator Control Rod                                               | PA-31T                                  | 10/6/77 | **                 |             | 2730 17F21         |
| 790    | Paralleling Relay Terminal<br>Strip Tab                                                                    | PA-31T                                  | 9/21/76 |                    |             | 2450 17G1          |
| 794    | Wing Tip Tank Drain Hose<br>Replacement                                                                    | PA-31T                                  | 1/4/77  | 80007-37           |             | 5720 17G7          |
| 798    | Cabin Headliner/Oxygen Cover<br>Panel Refinement                                                           | PA-31T                                  | 2/4/77  |                    |             | 2520 17G13<br>3520 |
| 801    | Goodyear Tri-Metallic Brakes,<br>Maintenance And Operation;<br>Goodyear SL-1 Dated<br>January 15, 1977     | PA-31T                                  | 2/25/77 |                    |             | 3240 17G21         |
| 802    | Main Landing Gear Door Hinge<br>Attachment Screw Replacement                                               | PA-31T                                  | 3/9/77  | 761-128            |             | 3210 17G24         |
| 804    | Heater System Maintenance<br>And Operation                                                                 | PA-31T                                  | 2/8/77  | **                 |             | 2140 17H4          |
| 805    | Engine Ignition Exciter<br>Box Relocation                                                                  | PA-31T                                  | 3/18/77 | 761-126            |             | 7420 17H9          |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                       | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO.    | A.D.<br>NO. | ATA<br>CODE        |
|--------|---------------------------------------------------------------------------------------------------------------|--------------------|----------|--------------------|-------------|--------------------|
| 806    | Air Scoop Lip Deicer Rewiring/<br>Hour Meter Harness Revision                                                 | PA-31T             | 2/22/77  | 456-763            |             | 3020<br>3120 17H10 |
| 809    | Engine Oil Breather Tube Extension                                                                            | PA-31T             | 4/6/77   | 55997-03           |             | 7920 17H16         |
| 816    | Powerpak Reservoir Replacement<br>(Wiebel Hydraulic Powerpaks)                                                | PA-31T             | 12/19/77 | 763-831            |             | 2910 17I18         |
| 817    | Propeller Synchronizer System<br>Refinement                                                                   | PA-31T             | 2/13/78  | 560-807            |             | 6120 17I20         |
| 819A   | Air Conditioning Compressor Drive<br>Belt Alignment Procedure                                                 | PA-31T             | 8/31/77  | 49186-02           |             | 2150 17I23         |
| 820    | Replacement of Lithium<br>Sulphur Dioxide (LiSO2)<br>ELT Batteries and/or<br>Transmitters                     | PA-31T<br>PA-31T1  | 7/28/80  | **                 | 79-18-05    | 2560 17J2          |
| 822    | Engine Compartment Fire<br>Extinguisher Switch Protection                                                     | PA-31T             | 7/12/77  | **                 |             | 2620 17J8          |
| 823    | Heater/Evaporator Return Air<br>Duct Hose Replacement                                                         | PA-31T             | 2/10/78  | 49478-02           |             | 2120 17J10         |
| 829    | Emergency Exit Window Latch<br>Modification                                                                   | PA-31T             | 11/14/77 | 763-809            |             | 5620 17J18         |
| 830    | 24 Volt Cigar Lighter Element<br>Replacement                                                                  | PA-31T             | 11/22/77 |                    |             | 3310 17J19         |
| 831    | Heater Fuel Pressure Regulator<br>Valve Installation                                                          | PA-31T             | 1/10/78  | 761-139            |             | 2140 17J20         |
| 833    | Cabin Pressurization System<br>Rupture Disc Elimination                                                       | PA-31T             | 4/10/78  |                    |             | 2130 17J22         |
| 834    | Flap Electrical System Refinement                                                                             | PA-31T             | 3/3/78   |                    |             | 2750 17J24         |
| 835B   | Stability Augmentation<br>System Refinement                                                                   | PA-31T             | 6/20/80  | 763-896<br>764-031 |             | 2220 17K2          |
| 840    | Air Conditioning System<br>Refinements                                                                        | PA-31T<br>PA-31T1  | 8/29/80  |                    |             | 2150 17K12         |
| 840    | Part I - Condenser Fan Motor<br>Support Bracket Replacement                                                   | PA-31T             | 8/29/80  | 764-034            |             | 17K12              |
| 840    | Part II - Unpressurized Air<br>Source Annunciator Light And<br>Freon Pressure Limiting<br>Device Installation | PA-31T<br>PA-31T1  | 8/29/80  | 764-035            |             | 17K13              |
| 841    | Heater Spark Plug Replacement<br>Or Modification                                                              | PA-31T<br>PA-31T1  | 1/7/80   | 763-495            |             | 2140 17K14         |
| 847    | Avionics Emergency Bus<br>Power Switch Guard<br>Installation                                                  | PA-31T             | 8/13/79  | **                 |             | 2450 17L2          |
| 854    | Generator Airscoop Door<br>Replacement                                                                        | PA-31T<br>PA-31T1  | 1/3/79   | 763-875            |             | 8000 17L22         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-31T/31T1  
PA-31T2/31T3  
PA-42

| NUMBER | SUBJECT                                                                             | MODELS<br>AFFECTED           | DATE     | PART/KIT<br>NO.     | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------|------------------------------|----------|---------------------|-------------|-------------|
| 857    | Propeller Beta Switch<br>Replacement                                                | PA-31T<br>PA-31T1            | 2/7/79   | 763-839             |             | 6120 18A22  |
| 866    | Windshield Wiper Arm Retaining<br>Wire Installation                                 | PA-31T<br>PA-31T1            | 12/7/79  | 151-295             |             | 5610 18C1   |
| 868    | Wing Flap Selector Switch<br>Positive Detent Kit Installation                       | PA-31T<br>PA-31T1            | 3/26/79  | 763-894             |             | 2750 18C16  |
| 871    | Pedestal Control Assembly<br>Inspection                                             | PA-31T<br>PA-31T1            | 3/7/79   |                     |             | 7600 18D3   |
| 883    | Wing Flap Rivet Installation                                                        | PA-31T<br>PA-31T1            | 10/20/79 | **                  |             | 5750 18F8   |
| 888    | Lift Transducer Case Rewire                                                         | PA-42                        | 7/21/81  | 764-098             |             | 3050 18F21  |
| 890    | Janitrol Heater Conversion                                                          | PA-31T<br>PA-31T1            | 10/15/79 | 763-963             |             | 2140 18F23  |
| 893A   | Gyro Indicator Relay Replacement                                                    | PA-31T1                      | 5/21/80  | **                  |             | 3420 18G5   |
| 896    | Landing Gear - Left Main, Torque<br>Link And Safety Switch Deflector<br>Replacement | PA-31T<br>PA-31T1            | 5/23/80  | 764-014             |             | 3210 18G11  |
| 902A   | Gyro Slaving Panel Switch<br>Modification                                           | PA-31T<br>PA-31T1            | 4/15/81  | 29299-R2            |             | 3420 18G24  |
| 913A   | Part I - Torque Transmitter<br>Electrical Connector<br>Restraint                    | PA-31T<br>PA-31T1            | 3/16/83  | 764-105             |             | 7710 18I3   |
| 913A   | Part II - Torque Transmitter<br>Relocation/Isolation                                | PA-31T<br>PA-31T1<br>PA-42   | 3/16/83  | 764-126<br>764-947L |             | 7710 18I3   |
| 916    | Elevator Control Stop Screw<br>Replacement                                          | PA-31T<br>PA-31T1            | 7/17/81  | **                  |             | 2730 18I8   |
| 917    | Portable Fire Extinguisher<br>Inspection                                            | PA-42                        | 7/20/81  | 459-839<br>459-848  |             | 2620 18I11  |
| 921    | Main Landing Gear Lock<br>Rod Attachment Fork<br>Replacement                        | PA-31T<br>PA-31T1<br>PA-31T2 | 4/21/82  | 764-127             |             | 3230 18I21  |
| 922    | Autopilot Rudder Servo Motor Access                                                 | PA-42                        | 8/2/82   | 420-217             |             | 5320 18I22  |
| 924    | Maximum Operating Airspeed (VMO)                                                    | PA-31T1                      | 1/20/82  | 764-150<br>764-151  |             | 3410 18J2   |
| 925    | Bleed Air Line Inspection/<br>Generator Cooling Scoop Cam<br>Loc Receptacle Removal | PA-42                        | 7/21/81  | **                  |             | 7110 18J3   |
| 926    | Deice Relay Shelf Modification<br>And Diode Addition                                | PA-42                        | 7/21/81  | **                  |             | 2450 18J6   |
| 928    | Pedestal Support Channel<br>Assembly Removal                                        | PA-42                        | 9/29/81  | 404-829             |             | 7600 18J11  |
| 929    | Pitch Servo Bridle Clamp Instruction                                                | PA-42                        | 2/11/82  |                     |             | 2210 18J13  |
| 930    | Powerplant Cowl Drain Inspection/<br>Modification                                   | PA-42                        | 7/21/81  |                     |             | 7100 18J15  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                           | MODELS<br>AFFECTED          | DATE     | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------|-----------------------------|----------|----------------------|-------------|-------------|
| 932    | Pressurization Control Wiring Rework                              | PA-42                       | 11/19/82 | 764-403              |             | 2130 18J19  |
| 935    | ELT Antenna Inspection                                            | PA-42                       | 3/26/82  | **                   |             | 2560 18J23  |
| 937    | Nose Gear Actuator Hose Replacement                               | PA-42                       | 5/24/82  | **                   |             | 3210 18K1   |
| 941    | Nose Wheel Shimmy Dampener Replacement                            | PA-31T<br>PA-31T2           | 9/21/82  | 456-010              |             | 3250 18K5   |
| 942    | Flap Handle Travel Inspection                                     | PA-42                       | 4/4/82   | 77196-03             |             | 2750 18K7   |
| 943    | Pilot's Right Rudder Pedal Torque Tube Retention                  | PA-42                       | 11/4/81  | 424-059              |             | 2720 18K9   |
| 945    | Cowl Inlet Lip Screw Replacement                                  | PA-42                       | 2/16/82  | 414-468<br>406-561   |             | 5440 18K14  |
| 949    | Elevator Trim Mechanism Modification And Enclosure Installation   | PA-42                       | 9/24/82  | 764-411L             |             | 2730 18K23  |
| 950    | Battery Ventilation Tube Inspection                               | PA-42                       | 6/8/82   | 420-202              |             | 2430 18K24  |
| 952    | Engine Dual Drive Oil Supply Line Oil Pressure Snubber Relocation | PA-42                       | 12/10/82 | 764-414              |             | 7920 18L3   |
| 954    | Nose Landing Gear Strut Placard Inspection Replacement            | PA-42                       | 2/2/83   | 72236-02             |             | 3220 18L9   |
| 956    | Cabin Door Cable Assembly Inspection And Modification             | PA31T<br>PA-31T1<br>PA-31T2 | 5/17/82  | 47716-04<br>57462-03 |             | 5210 18L11  |
| 960    | Aft Fuselage Drain Holes Inspection                               | PA-42                       | 12/3/82  |                      |             | 5560 19A4   |
| 961    | Environmental Control System Wiring Modification                  | PA-42                       | 1/5/83   | **                   |             | 2100 19A7   |
| 962    | Pitch Trim Drum Shaft Roll Pin Security                           | PA-42                       | 3/18/83  | MS20995-C32          |             | 2731 19A10  |
| 964    | Avionics Bay Blanket Modification                                 | PA-31T2                     | 4/29/83  | 764-946              |             | 3400 19A14  |
| 969    | Wing Tip Ground Strap Installation                                | PA-31T1<br>PA-31T3          | 7/11/84  | **                   |             | 2360 19A24  |
| 977    | Dynamic Stability Improvement Kit                                 | PA-31T                      | 3/1/85   | 765-158              |             | 2730 19B21  |
| 979    | Emergency Pressurization Bleed Air Valve Modification             | PA-42                       | 1/8/85   | **                   |             | 7530 19C1   |
| 983    | Engine Air Inlet Duct Assembly Reinforcement                      | PA-42<br>PA-42-720          | 3/14/86  | **                   |             | 7161 19C12  |
| 986    | Series Start Circuit Change Modification                          | PA-42-1000                  | 7/22/86  | 765-194              |             | 2453 19C20  |
| 993    | Engine Air Inlet Drain Holes                                      | PA-42-1000                  | 1/5/87   | N/A                  |             | 7162 19D13  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-31T/31T1  
PA-31T2/31T3  
PA-42

| NUMBER | SUBJECT                                                                                                | MODELS<br>AFFECTED                                                                        | DATE       | PART/KIT<br>NO.        | A.D.<br>NO.        | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|------------|------------------------|--------------------|-------------|
| 994    | Propeller Ground Clearance                                                                             | PA-42-1000                                                                                | 1/12/87    | **                     |                    | 3223 19D15  |
| 998    | Remote Control Circuit Breaker (RCCB) Ground Wire Installation                                         | PA-42-1000                                                                                | 7/8/87     | 765-322                |                    | 2451 19E4   |
| 1002   | Overhead Panel Map Light Switch Installation                                                           | PA-42-1000                                                                                | 4/4/88     | 84112-03               |                    | 3314 19E14  |
| 1003   | Oxygen Shutoff Valve Assembly                                                                          | PA-42-720<br>PA-42-720R<br>PA-421000                                                      | 8/19/88    | **                     |                    | 3510 19E17  |
| 1013   | Improved Elevator Trim Cover Replacement                                                               | PA-42<br>PA-42-720<br>PA-42-720R                                                          | 10/11/94   | **                     |                    | 5510 19G1   |
| 1014   | Addition of Grease Fitting to Nose Gear Steering Arm Bracket                                           | PA-42<br>PA-42-720<br>PA-42-720R                                                          | 10/17/94   | **                     |                    | 3250 19G1   |
| 1015   | Replacement of EATON Brand Electrical Contactor Box                                                    | PA-42-1000                                                                                | 7/14/95    | 766-296<br>557-125     |                    | 2436 19G6   |
| 1017   | Engine Fire Extinguisher System Rewire and Distribution of Walter Kidde Service Bulletin 899857-26-365 | PA-42<br>PA-42-720                                                                        | 3/7/97     | 766-617                |                    | 2623 19G11  |
| 1041A  | In-Service Safety Event Reporting                                                                      | All                                                                                       | 3/17/2020  | N/A                    |                    | N/A         |
| 1052   | Life Limited Parts Marking and Disposition                                                             | All                                                                                       | 5/21/2002  | N/A                    |                    | 510 19L19   |
| 1054   | Propeller Control Arm Attachment Inspection                                                            | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3                                                   | 10/10/2002 | 51623-000              |                    | 6120 20A3   |
| 1069   | Flight Control Cable Terminal Corrosion Inspection                                                     | All                                                                                       | 3/31/2003  | N/A                    | CE-02-05<br>(SAIB) | 2702 20C2   |
| 1088   | 40336-000 Link Assembly Inspection                                                                     | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000 | 12/15/2004 | 40336-000              |                    | 3220 20F11  |
| 1092C  | Main Gear Retraction Arms Inspection, 42042-000/-002                                                   | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720                             | 7/25/2013  | 42042-000<br>42042-002 |                    | 3211        |
| 1116A  | Contactor Maintenance                                                                                  | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720<br>PA-42-1000               | 3/15/2019  | N/A                    |                    | 2435        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                             | MODELS<br>AFFECTED                                                                        | DATE       | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------|-------------------------------------------------------------------------------------------|------------|-----------------|-------------|-------------|
| 1135   | Control Cable / Pulley Inspections                  | All                                                                                       | 10/19/2010 | N/A             |             | 5720        |
| 1188   | Landing Gear Hydraulic System<br>Filter Maintenance | PA-31T<br>PA-31T1<br>PA-31T2<br>PA-31T3<br>PA-42<br>PA-42-720<br>PA-42-720R<br>PA-42-1000 | 3/19/2015  | N/A             |             | 2912        |
| 1265   | Flight Control System Checks                        | All                                                                                       | 8/6/2019   | N/A             |             | 2700        |
| 1274   | Hartzell Propeller Preferred Grease                 | All                                                                                       | 1/6/2020   | NYCO GN 3058    |             | 6110        |
| 1280   | Rudder Pedal And Bar Assembly<br>Inspection         | All                                                                                       | 2/14/2020  | N/A             |             | 2720        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE LETTER INDEX

PA-32 SERIES

| NUMBER | SUBJECT                                                                                                                  | MODELS<br>AFFECTED                                                                                                                                                                                            | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE  |
|--------|--------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|-------------|--------------|
| 177    | Firewalls                                                                                                                | All Models                                                                                                                                                                                                    | 8/10/51   |                 |             | 13B13        |
| 467    | Alternator - Regulator System Modification                                                                               | PA-32-260                                                                                                                                                                                                     | 1/10/66   | 756-992V        |             | 2430 14I5    |
| 475    | Inspection of Landing Gear Strut Exposure                                                                                | PA-32-260                                                                                                                                                                                                     | 7/6/66    |                 |             | 3210 14I17   |
| 476    | Replacement of Fuel Selector Valve                                                                                       | PA-32-260                                                                                                                                                                                                     | 4/26/66   | 492-104V        | 67-03-07    | 2820 14I18   |
| 484    | Fuel System Operating Procedures                                                                                         | PA-32                                                                                                                                                                                                         | 12/20/66  |                 |             | 2800 14J7    |
| 486A   | Cylinder Head Temperature Probe Location                                                                                 | PA-32                                                                                                                                                                                                         | 4/16/68   |                 |             | 7720 14J13   |
| 494    | Inspection of Cherokee Landing Gears                                                                                     | PA-32-260/300                                                                                                                                                                                                 | 11/7/67   |                 |             | 3200 14J24   |
| 495    | Inspection of Control Cable-Constant Speed Propellers                                                                    | PA-32-260/300                                                                                                                                                                                                 | 1/29/68   | **              |             | 6120 14K2    |
| 499    | Owners Handbook Revision                                                                                                 | PA-32-260                                                                                                                                                                                                     | 3/14/68   |                 |             | General 14K6 |
| 527D   | Inspection of Control Wheels                                                                                             | PA-32-260/300                                                                                                                                                                                                 | 6/21/78   | **              | 69-22-02    | 2700 15A14   |
| 535A   | Rudder Trim Locking Pin                                                                                                  | PA-32-260/300                                                                                                                                                                                                 | 9/26/69   |                 |             | 2720 15B9    |
| 566    | Autopilot Servo Spacer Bushing Installation                                                                              | PA-32-260/300                                                                                                                                                                                                 | 9/25/70   | 760-508V        |             | 2210 15F3    |
| 571    | Flap Handle Assembly Modification                                                                                        | PA-32-260/300                                                                                                                                                                                                 | 3/30/71   | 760-531V        |             | 2750 15F15   |
| 576    | Stabilator Balance Weight Tube Replacement                                                                               | PA-32-260/300                                                                                                                                                                                                 | 4/20/71   | **              |             | 5570 15G2    |
| 577    | Servo Bridle Cable Clamp Replacement                                                                                     | PA-32-260/300                                                                                                                                                                                                 | 6/1/71    | 757-863V        |             | 2210 15G8    |
| 578B   | Fuel Line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation, Lycoming Service Bulletin No. 342F | PA-32-300<br>PA-32-301<br>PA-32-301FT<br>PA-32-301T<br>PA-32-301XTC<br>PA-32R-300<br>PA-32R-301<br>PA-32R-301 SP<br>PA-32R-301T SP<br>PA-32R-301 II HP<br>PA-32R-301T II TC<br>PA-32RT-300/300T<br>PA-32S-300 | 7/27/2011 | N/A             | 2011-26-04  | 7310         |
| 581    | Inspection of Aileron Hinge Doublers                                                                                     | PA-32-260/300                                                                                                                                                                                                 | 7/12/71   | 760-540V        |             | 5550 15G20   |
| 609    | Control Surfaces Inspection And Maintenance Guidelines                                                                   | All Models                                                                                                                                                                                                    | 2/21/72   |                 |             | 5500 15J21   |
| 612A   | Fuel Leakage - Fuel Sender Unit                                                                                          | PA-32-260/300                                                                                                                                                                                                 | 6/8/72    | 68101-00V       |             | 7330 15K1    |
| 614    | Stabilator Attachment Fittings Bolt Torque                                                                               | PA-32-260/300                                                                                                                                                                                                 | 6/15/72   |                 | 72-14-07    | 2740 15K6    |
| 615    | Stabilator Drain Holes                                                                                                   | PA-32-260/300                                                                                                                                                                                                 | 7/6/72    |                 |             | 2740 15K8    |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                                             | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|----------|-----------------|-------------|-------------|
| 617B   | Piper Automatic Locator Transmitter Replacement                                                                                                     | PA-32              | 8/30/73  |                 | 72-22-03    | 2560 15K18  |
| 620    | Forward Cabin Door Reinforcement                                                                                                                    | PA-32-260/300      | 2/23/73  | 760-729V        |             | 5210 15L8   |
| 621    | Main Landing Gear Torque Link Replacement                                                                                                           | PA-32-260/300      | 11/9/72  | **              |             | 3210 15L10  |
| 624    | Altimatic III-1 Gyro Horizon Fitting Installations                                                                                                  | PA-32-300          | 9/1/72   | 458 840         |             | 3420 15L17  |
| 636    | Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)                                                                                  | PA-32              | 10/24/72 | **              |             | 2430 16B2   |
| 647    | Seat Back Stop Modification                                                                                                                         | PA-32-260/300      | 3/31/73  | 760-740V        |             | 2510 16C1   |
| 653    | Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265, Dated December 15, 1972)                                  | PA-32              | 4/9/73   | **              |             | 7610 16C14  |
| 662    | Engine Mount Bolt Torque                                                                                                                            | PA-32-260/300      | 7/6/73   | AN960-616       |             | 7120 16D10  |
| 665A   | Rotator Type Intake Valves                                                                                                                          | PA-32-300          | 10/24/73 | **              |             | 7160 16D16  |
| 671    | Inspection And Modification Rudder Bar Assembly                                                                                                     | PA-32-260/300      | 10/5/73  |                 |             | 2720 16E9   |
| 682B   | Required Inspection of Piston Pin (Reference Lycoming Service Bulletin No. 367D)                                                                    | PA-32              | 4/19/74  | **              |             | 7230 16F9   |
| 695    | Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974) | PA-32              | 5/3/74   | **              |             | 2210 16G13  |
| 700    | Toe Brake System Modification                                                                                                                       | PA-32-260/300      | 4/9/74   | 760-842V        |             | 3240 16H5   |
| 707    | Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)                               | PA-32              | 2/27/74  | **              |             | 7710 16I11  |
| 708    | Nose Wheel Steering System Inspection                                                                                                               | PA-32-260/300      | 6/7/74   | **              |             | 3250 16I14  |
| 715    | Emergency Locator Transmitter Switch Cover Modification                                                                                             | PA-32-260/300      | 9/27/74  | 760-876V        |             | 2560 16J12  |
| 718    | Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)                                                | PA-32              | 5/31/74  | **              |             | 7410 16J18  |
| 732    | Steering Stop Replacement                                                                                                                           | PA-32-260/300      | 9/30/74  | 95061-129       |             | 3250 16L6   |
| 734    | Bendix ADF-T-12 C/D Installation Inspection And Modification                                                                                        | PA-32-260/300      | 12/3/74  | 760-857V        |             | 3450 16L8   |
| 738A   | Modification of The Overhead Fresh Air Vent System                                                                                                  | PA-32-260/300      | 1/14/75  | **              |             | 2120 16L20  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-32 Series

| NUMBER | SUBJECT                                                                                   | MODELS<br>AFFECTED                              | DATE     | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------------------|-------------------------------------------------|----------|------------------------|-------------|-------------|
| 745    | Inspection of Wing Mainspar<br>Attach Bolts                                               | PA-32-260/300                                   | 4/24/75  | 404-890                |             | 5710 17A14  |
| 747    | Inspection of Throttle Mixture<br>Control Attachments                                     | PA-32-260/300                                   | 5/28/75  | **                     |             | 7610 17A18  |
| 749    | Torque Link Greaser Bolt<br>Replacement Kit                                               | PA-32-260/300                                   | 10/14/75 | 760-910V               |             | 3210 17A21  |
| 750    | Rain Gutter Installation                                                                  | PA-32-260/300                                   | 8/15/75  | 760-975V               |             | 5210 17A22  |
| 756    | Dual Glideslope Indicator Placard<br>(King Radio Installations Only)                      | PA-32-260/300                                   | 1/6/76   | 69669-112V             |             | 3430 17B22  |
| 758    | Inspection of Bendix Ignition<br>Switches; Re: Bendix Service<br>Bulletin No. 583         | PA-32-260/300<br>PA-32R-300                     | 5/17/76  | 761-065V               |             | 7410 17C2   |
| 761    | Magnetic Compass Relocation Kit                                                           | PA-32-260/300                                   | 11/17/75 | 760-695V               |             | 3440 17C14  |
| 762    | Modification of ELT Remote<br>Switches                                                    | PA-32-260/300<br>PA-32R-300                     | 1/26/76  | 761-009V               |             | 2560 17C15  |
| 763A   | Rear Leg Quick-Disconnect Seat<br>Retention Mechanism Inspection                          | PA-32-260/300                                   | 11/14/75 | **                     | 75-24-02    | 2570 17C16  |
| 768    | Aileron Balance Cable Pulley<br>Support Bracket Modification                              | PA-32R-300                                      | 5/25/76  | 761-042V               |             | 2710 17D14  |
| 788    | Air Conditioning Installations                                                            | PA-32-300<br>PA-32R-300                         | 9/3/76   | 79584-02V<br>79589-05V |             | 2150 17F19  |
| 791    | Electrical System Refinement                                                              | PA-32R-300                                      | 2/24/77  | 761-087V               |             | 2400 17G3   |
| 793    | Flap Warning Placard                                                                      | PA-32-260/300<br>PA-32S-300<br>PA-32R-300       | 1/6/77   | 35664-02               |             | 2750 17G5   |
| 796    | Lower Cowl Drain Inspection                                                               | PA-32-260                                       | 3/30/77  |                        |             | 7100 17G10  |
| 797    | Front Seat Modification (Aircraft<br>With Club Seating Only)                              | PA-32-260/300<br>PA-32R-300                     | 2/25/77  | 761-110V               |             | 2510 17G12  |
| 800    | Performance Refinement of<br>Narco ADF - 140 Installation                                 | PA-32-260/300<br>PA-32R-300                     | 2/25/77  | **                     |             | 3450 17G19  |
| 808    | Hydraulic Pump Terminal Inspection                                                        | PA-32R-300                                      | 6/8/77   | **                     |             | 2910 17H14  |
| 810    | Landing Gear Extender, Backup,<br>Diaphragm Replacement                                   | PA-32R-300                                      | 4/15/77  | 761-138V               |             | 3230 17H18  |
| 813    | Vertically Adjustable Seat<br>Refinement                                                  | PA-32-260/300<br>PA-32R-300                     | 6/9/77   | **                     |             | 2510 17I8   |
| 820    | Replacement of Lithium<br>Sulphur Dioxide (LiS02)<br>ELT Batteries and/or<br>Transmitters | PA-32-260/300<br>PA-32R-300<br>PA-32RT-300/300T | 7/28/80  | **                     | 79-18-05    | 2560 17J2   |
| 836    | Inspection And Modification<br>Narco ADF-140/141<br>Antenna                               | PA-32-260<br>PA-32-300<br>PA-32R-300            | 2/9/78   | **                     |             | 3450 17K4   |
| 837    | Inspection of Elbow Assembly<br>Engine Air Filter                                         | PA-32-300<br>PA-32R-300                         | 5/22/78  |                        |             | 7160 17K7   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                           | MODELS<br>AFFECTED                                     | DATE     | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------|--------------------------------------------------------|----------|----------------------|-------------|-------------|
| 842    | Main Landing Gear Torque<br>Link Greaser Bolt<br>Inspection And Replacement       | PA-32-260/300                                          | 9/26/78  | 760-910V             |             | 3210 17K17  |
| 861    | Part I - Forward Facing Seat<br>Back Modification                                 | PA-32-260/300<br>PA-32R-300<br>PA-32RT-300/300T        | 11/13/78 | 763-890V             |             | 2520 18B7   |
| 861    | Part II - Rear Facing (Club)<br>Seat Back Retention                               | PA-32-260/300<br>PA-32RT-300/300T                      | 11/13/78 | 408 834V             |             | 2520 18B8   |
| 862    | Main Landing Gear And<br>Strut Fairing Replacement                                | PA-32-260<br>PA-32-300                                 | 3/30/79  | 760-910V             |             | 3210 18B11  |
| 864    | Part I - Forward Cabin Door<br>Stop (Striker Plate) Installation                  | PA-32-260/300<br>PA-32RT-300/300T                      | 12/8/78  | **                   |             | 5210 18B16  |
| 864    | Part II - Cabin Heat Control<br>Refinement                                        | PA-32-260/300<br>PA-32RT-300/300T                      | 12/8/78  | 763-870V<br>763-871V |             | 2140 18B19  |
| 864    | Part III - Turn And Slip<br>Indicator Conversion, Vacuum<br>To Electric Provision | PA-32-260                                              | 120/8/78 | 763-874              |             | 3420 18B20  |
| 864    | Part IV - Induction Sump<br>Drain Valve                                           | PA-32R-300<br>PA-32RT-300                              | 12/8/78  | 763-887V             |             | 7160 18B21  |
| 869    | Part I - Installation<br>of Top Cowl Exhaust<br>System Heat Shields               | PA-32RT-300T                                           | 9/10/79  | 753-910V             |             | 7810 18C18  |
| 869    | Part II - Modification<br>of Fuel Boost Pump<br>Outlet Fitting                    | PA-32RT-300T                                           | 9/10/79  | **                   |             | 2820 18C19  |
| 869    | Part III - Tachometer<br>Cable Rerouting                                          | PA-32-300<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T | 9/10/79  | 763-916V             |             | 7710 18C20  |
| 882A   | Part I - Rudder Skin<br>Inspection And<br>Modification                            | PA-32RT-300<br>PA-32RT-300T                            | 11/12/81 | 763-936V             | 79-26-04    | 5540 18F4   |
| 882A   | Part II - Rudder Skin<br>Replacement                                              | PA-32RT-300<br>PA-32RT-300T                            | 11/12/81 | 763-940V             | 79-26-04    | 5540 18F6   |
| 884    | Fuel Quantity Sender Check                                                        | PA-32-260/300                                          | 9/15/80  | 68101-002V           |             | 2840 18F11  |
| 895A   | Magneto Switch Modification                                                       | PA-32-301                                              | 3/19/81  | 153-010<br>488-396   |             | 7430 18G8   |
| 900    | Air Induction Valve Assembly<br>Support Reinforcement                             | PA-32R-301T                                            | 7/30/80  | **                   |             | 7160 18G19  |
| 901    | Cabin Air Intake Duct<br>Modification                                             | PA-32-301/301T<br>PA-32R-301/301T                      | 9/2/80   | 764-013V             |             | 2120 18G22  |
| 903A   | Alternator Belt Installation<br>(Air Conditioned Models)                          | Any Textron-Lycoming<br>Powered PA-32                  | 3/11/96  | 62833-82             |             | 2431 18H2   |
| 908    | Instrument Panel Lighting -<br>Century 21 And 41 Autopilot<br>Installation        | PA-32-301/301T<br>PA-32R-301/301T                      | 12/20/80 |                      |             | 3310 18H11  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-32 Series

| NUMBER | SUBJECT                                                                                                             | MODELS<br>AFFECTED                                                                                                          | DATE      | PART/KIT<br>NO.        | A.D.<br>NO.                    | ATA<br>CODE |
|--------|---------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|-----------|------------------------|--------------------------------|-------------|
| 920    | Required Placard Adhesion<br>Check                                                                                  | PA-32-260<br>PA-32-300<br>PA-32-301<br>PA-32-301T<br>PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301<br>PA-32R-301T | 6/29/81   |                        |                                | 2500 18119  |
| 923A   | Cabin Heat Cable Heatshield<br>Installation                                                                         | PA-32-301T<br>PA-32R-301T<br>PA-32RT-300T                                                                                   | 2/12/82   | 764-138V<br>764-137V   |                                | 2140 18124  |
| 927    | Nose Landing Gear Refinement                                                                                        | PA-32R-300<br>PA-32RT-300<br>PA-32RT-300T<br>PA-32R-301<br>PA-32R-301T                                                      | 10/2/81   | 764-135V               | 81-24-07                       | 3220 18J10  |
| 934    | Bottom Cowl Modification                                                                                            | PA-32-300<br>PA-32-301                                                                                                      | 11/23/81  | 764-136V               |                                | 7110 18J22  |
| 947    | Pressure Switch Relocation<br>Manifold Pressure Gauge                                                               | PA-32RT-300T<br>PA-32R-301T<br>PA-32-301T                                                                                   | 2/5/82    | 764-216V               |                                | 7710 18K19  |
| 948    | Heated Windshield Panel Sealing<br>And Gyro Filter Protection                                                       | PA-32R-301T                                                                                                                 | 2/5/82    | **                     |                                | 5610 18K20  |
| 997    | Wing Removal And Reinstallation;<br>Reference Airworthiness Directive<br>87-08-08                                   | PA-32-260<br>PA-32-300                                                                                                      | 5/14/87   | **                     | 87-08-08                       | 5711 19D24  |
| 1032   | Improved Fuel Quantity Senders<br>Available                                                                         | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                       | 3/13/2001 | 686-202<br>686-203     |                                | 2842 19J1   |
| 1033   | Air Conditioning Hose Replacement                                                                                   | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                       | 7/9/2001  | 566-419<br>454-868     |                                | 2155 19J4   |
| 1040   | Alternator Drive Belt Conversion Kit<br>(for Aircraft Equipped with Optional<br>Factory Installed Air Conditioning) | PA-32-300<br>PA-32-301<br>PA-32-301T<br>PA-32R-300<br>PA-32R-301<br>PA-32R-301T<br>PA-32RT-300<br>PA-32RT-300T              | 10/7/2021 | 767-310<br>(88306-000) |                                | 2410        |
| 1041A  | In-Service Safety Event Reporting                                                                                   | All                                                                                                                         | 3/17/2020 | N/A                    |                                | N/A         |
| 1043   | Oil Cooler Kit                                                                                                      | PA-32R-301T II TC                                                                                                           | 4/25/2002 | 767-332                |                                | 7921 19K15  |
| 1049   | Voltage Regulator Replacement                                                                                       | PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                       | 4/30/2002 | 68804-007<br>68804-006 |                                | 2424 19L9   |
| 1052   | Life Limited Parts<br>Marking and Disposition                                                                       | All                                                                                                                         | 5/21/2002 | N/A                    |                                | 510 19L19   |
| 1069   | Flight Control Cable Terminal<br>Corrosion Inspection                                                               | All                                                                                                                         | 3/31/2003 | N/A                    | CE-11-01<br>CE-02-05<br>(SAIB) | 2702 20C2   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                       | MODELS<br>AFFECTED                                                                                                                                                           | DATE       | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------------|-------------|-------------|
| 1074   | S-TEC Autopilot Component Seating Procedure   | All                                                                                                                                                                          | 11/3/2003  | N/A             |             | 2210        |
| 1084   | Cabin Heater Improvement Kit                  | PA-32-301XTC<br>PA-32R-301T II TC                                                                                                                                            | 1/14/2005  | 767-333         |             | 2140        |
| 1089   | Aircraft Painting Requirement                 | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                         | 10/21/2004 | N/A             |             | 1100        |
| 1093B  | Electrical Contactor Replacement Kit          | PA-32-260/300<br>PA-32-301/301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-300<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC<br>PA-32RT-300/300T | 11/28/2017 | 88371           |             | 2400        |
| 1095B  | Classification and Disposition of Hail Damage | PA-32-260/300<br>PA-32-301/301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-300<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T SP<br>PA-32R-301T II TC<br>PA-32RT-300/300T | 11/20/2020 | N/A             |             | 5100        |
| 1103   | Attitude Indicator Standby Battery Failure    | PA-32-301FT<br>PA-32-301XTC                                                                                                                                                  | 4/20/2007  | 88411-002       |             | 3420        |
| 1105   | Automatic Baggage Door Light Switch Upgrade   | PA-32-301<br>PA-32-301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 SP<br>PA-32R-301T SP<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                           | 4/24/2007  | 88422-002       |             | 3300        |
| 1106A  | Sky-Tec Starter Cranking Instructions         | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                         | 10/28/2009 | N/A             |             | 8011        |
| 1108   | Manifold Pressure Transducer Failures         | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                         | 3/4/2008   | N/A             |             | 7713        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-32 Series

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED                                                                                                                                                                                                | DATE       | PART/KIT<br>NO.                                                   | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------------------------------------------------------------|-------------|-------------|
| 1116A  | Contactator Maintenance                                                                                                           | PA-32-260/300<br>PA-32S-300<br>PA-32R-300<br>PA-32RT-300/300T<br>PA-32-301<br>PA-32-301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301<br>PA-32R-301 SP<br>PA-32R-301T SP<br>PA-32R-301 II HP<br>PA-32R-301T II TC | 3/15/2019  | N/A                                                               |             | 2435        |
| 1123   | Avidyne EXP5000 Software Upgrade (Mod 57)                                                                                         | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                              | 9/27/2010  | N/A                                                               |             | 3420        |
| 1126A  | Voltage Suppressor Advisory                                                                                                       | PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP<br>PA-32R-301T II TC                                                                                                                                              | 3/23/2017  | N/A                                                               |             | 3400        |
| 1135   | Control Cable / Pulley Inspections                                                                                                | All                                                                                                                                                                                                               | 10/19/2010 | N/A                                                               |             | 5720        |
| 1165   | Hydraulic Pump Identification and Servicing Requirements                                                                          | PA-32R Series                                                                                                                                                                                                     | 10/18/2012 |                                                                   |             | 2910        |
| 1218A  | Crew Seat Control Cable Modification                                                                                              | PA-32-301<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 SP<br>PA-32R-301 II HP<br>PA-32R-301T Turbo SP<br>PA-32R-301T II TC                                                                                        | 8/8/2017   | 76356-003<br>554-422<br>487-490                                   |             | 2510        |
| 1265   | Flight Control System Checks                                                                                                      | All                                                                                                                                                                                                               | 8/6/2019   | N/A                                                               |             | 2700        |
| 1268   | Hartzell 'K' Flange Propeller Hub Replacement                                                                                     | PA-32-300<br>PA-32S-300<br>PA-32R-300<br>PA-32RT-300                                                                                                                                                              | 10/9/2019  | N/A                                                               |             | 6114        |
| 1274   | Hartzell Propeller Preferred Grease                                                                                               | All                                                                                                                                                                                                               | 1/6/2020   | NYCO GN 3058                                                      |             | 6110        |
| 1280   | Rudder Pedal And Bar Assembly Inspection                                                                                          | All                                                                                                                                                                                                               | 2/14/2020  | N/A                                                               |             | 2720        |
| 1311   | Parker Lord SIL-J-9613-001 Rev. A, 'Potential Incorrect Combination of Components in Parker Lord J-9613 Series Engine Mount Kits' | PA-32-301<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301 II HP                                                                                                                                                      | 6/7/2022   | 470-516 / J-9613-19<br>475-115 / J-9613-12<br>475-124 / J-9613-40 |             | 7120        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                      | MODELS<br>AFFECTED                                                                                                                                                                                  | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-----------------|-------------|-------------|
| 1320   | Wing And Fuselage<br>Skin Repair Limitations | PA-32-260/300<br>PA-32R-300<br>PA-32RT-300/300T<br>PA-32-301<br>PA-32-301T<br>PA-32-301FT<br>PA-32-301XTC<br>PA-32R-301<br>PA-32R-301 SP<br>PA-32R-301T SP<br>PA-32R-301 II HP<br>PA-32R-301T II TC | 12/1/2022 | N/A             |             | 5100        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE LETTER INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED | DATE      | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|--------------------|-----------|----------------------|-------------|-------------|
| 578B   | Fuel Line (Stainless Steel Tube Assy.)<br>and Support Clamp Inspection<br>and Installation,<br>Lycoming Service Bulletin No. 342F | PA-34-200          | 7/27/2011 | N/A                  | 2011-26-04  | 7310        |
| 609    | Control Surfaces Inspection<br>And Maintenance Guidelines                                                                         | All Models         | 2/21/72   |                      |             | 5500 15J21  |
| 614    | Stabilator Attachment Fittings<br>Bolt Torque                                                                                     | PA-34-200          | 6/15/72   |                      | 72-14-07    | 2740 15K6   |
| 615    | Stabilator Drain Holes                                                                                                            | PA-34-200          | 7/6/72    |                      |             | 2740 15K8   |
| 617B   | Piper Automatic Locator<br>Transmitter                                                                                            | PA-34-200          | 8/30/73   |                      | 73-07-02    | 2560 15K18  |
| 618    | Alternator Fan Replacement                                                                                                        | PA-34-200          | 10/8/73   | 754-827V             | 72-15-02    | 2430 15L1   |
| 620    | Forward Cabin Door Reinforcement                                                                                                  | PA-34-200          | 2/23/73   | 760-729V             |             | 5210 15L8   |
| 622    | Cabin Heater/Defroster Modification                                                                                               | PA-34-200          | 8/24/72   | 760-692V<br>760-693V |             | 2140 15L12  |
| 624    | Altimatec III-1 Gyro Horizon<br>Fitting Installation                                                                              | PA-34-200          | 9/1/72    | 458-840              |             | 3400 15L17  |
| 625    | Heat Exchangers And Heat<br>Silencers Modification                                                                                | PA-34-200          | 11/13/72  | 69471-21V            |             | 2140 15L20  |
| 626    | Landing Gear Bolt Lubrication                                                                                                     | PA-34-200          | 11/20/72  |                      |             | 3200 15L23  |
| 647    | Seat Back Stop Modification                                                                                                       | PA-34-200          | 3/31/73   | 760-740V             |             | 2510 16C1   |
| 661    | Engine Firewall Modification                                                                                                      | PA-34-200          | 6/26/73   | 760-758V             |             | 5410 16D8   |
| 663    | Stabilator Drain Hole Inspection<br>(Deicer Equipped Aircraft Only)                                                               | PA-34-200          | 5/25/73   |                      |             | 5300 16D11  |
| 664    | Wing Skin/Rib Inspection And<br>Modification                                                                                      | PA-34-200          | 4/17/74   | 760-771V             |             | 5710 16D13  |
| 665A   | Intake Valves, Rotator Type                                                                                                       | PA-34-200          | 10/24/73  | **                   |             | 7160 16D16  |
| 668A   | Engine Cowl Modifications                                                                                                         | PA-34-200          | 8/7/74    | **                   |             | 7110 16E4   |
| 669    | Aileron/Rudder Interconnect Cable<br>System Modification                                                                          | PA-34-200          | 4/16/74   | 760-776V             |             | 2710 16E6   |
| 671    | Rudder Bar Assembly Inspection<br>And Modification                                                                                | PA-34-200          | 10/5/73   |                      |             | 2720 16E9   |
| 673    | Exhaust System Replacement                                                                                                        | PA-34-200          | 9/28/73   | 760-764V             |             | 7810 16E14  |
| 677A   | Propeller Spinner And<br>Propeller Damper Installation<br>Kits                                                                    | PA-34-200          | 11/14/73  | 760-766V<br>760-781V |             | 6110 16E22  |
| 682B   | Required Inspection of Piston<br>Pin (Reference Lycoming Service<br>Bulletin No. 367D)                                            | PA-34-200          | 4/19/74   | **                   |             | 7230 16F9   |
| 684    | Landing Gear Lubrication                                                                                                          | PA-34-200          | 1/9/74    |                      |             | 3200 16F18  |
| 700    | Toe Brake System Modification                                                                                                     | PA-34-200          | 4/9/74    | 760-842V             |             | 3240 16H5   |
| 704A   | Inspection of Fuel Crossfeed<br>Drain Valves                                                                                      | PA-34-200          | 11/25/74  | 492-202V             |             | 2820 16H10  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                               | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE                                                 |
|--------|-----------------------------------------------------------------------------------------------------------------------|--------------------|----------|-----------------|-------------|-------------------------------------------------------------|
| 706    | Propeller Damper Compression Spring (Reference Hartzell Service Bulletin No. 103 Dated 2/20/74)                       | PA-34-200          | 5/6/74   | 760-853V        |             | 6120 16I3                                                   |
| 707    | Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973) | PA-34-200          | 2/27/74  | **              |             | 7710 16I11                                                  |
| 714    | Rudder Trim Modification                                                                                              | PA-34-200          | 6/4/74   | 760-800V        | 73-13-01    | 2720 16J11                                                  |
| 715    | Emergency Locator Transmitter Switch Cover Modification                                                               | PA-34-200          | 9/27/74  | 760-876B        |             | 2560 16J12                                                  |
| 718    | Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)                  | PA-34-200          | 5/31/74  | **              |             | 7410 16J18                                                  |
| 734    | Bendix ADF-T-12 C/D Installation Inspection And Modification                                                          | PA-34-200          | 12/3/74  | 760-857V        |             | 3450 16L8                                                   |
| 737    | Manifold Pressure Gauge Line Modification                                                                             | PA-34-200          | 12/2/74  | 760-765V        |             | 7710 16L19                                                  |
| 738A   | Modification of The Overhead Fresh Air Vent System                                                                    | PA-34-200          | 1/14/75  | **              |             | 2120 16L20                                                  |
| 742    | Seneca II Refinement Modifications                                                                                    | PA-34-200T         | 5/9/75   | **              |             | 1. 7110<br>2. 5200<br>3. 2740<br>4. 3400<br>5. 7410<br>17A8 |
| 747    | Inspection of Throttle And Mixture Control Attachments                                                                | PA-34-200          | 5/28/75  | **              |             | 7610 17A18                                                  |
| 750    | Rain Gutter Installation                                                                                              | PA-34-200          | 8/15/75  | 760-975V        |             | 5210 17A22                                                  |
| 754    | Auxiliary Fuel System Modification                                                                                    | PA-34-200T         | 7/31/75  | 760-926V        |             | 2810 17B12                                                  |
| 756    | Glideslope, Dual, Indicator Placard (King Radio Installation Only)                                                    | PA-34-200/200T     | 1/6/76   | 69669-112V      |             | 3430 17B22                                                  |
| 757    | Aft Wing Modification (Optional)                                                                                      | PA-34-200          | 10/22/75 | **              |             | 5710 17C1                                                   |
| 761    | Magnetic Compass Relocation Kit                                                                                       | PA-34-200/200T     | 11/17/75 | 760-795V        |             | 3440 17C14                                                  |
| 762    | Modification of ELT Remote Switches                                                                                   | PA-34-200/200T     | 1/26/76  | 761-009V        |             | 2560 17C15                                                  |
| 763A   | Rear Leg Quick-Disconnect Seat Retention Mechanism Inspection                                                         | PA-34-200/200T     | 11/14/75 | **              | 75-24-02    | 2510 17C16                                                  |
| 769    | Cold Weather Starting Procedures                                                                                      | PA-34-200T         | 3/10/76  | **              |             | 7200 17D15                                                  |
| 792    | Optional Cold Weather Priming System Installation                                                                     | PA-34-200T         | 12/10/76 | 761-094V        |             | 7310 17G4                                                   |
| 793    | Flap Warning Placard                                                                                                  | PA-34-200/200T     | 1/6/77   | 35664-02        |             | 2750 17G5                                                   |
| 795    | Oil Cooler Baffle Winterization Modification                                                                          | PA-34-200T         | 2/8/77   | **              |             | 7230 17G9                                                   |
| 797    | Front Seat Modification (Aircraft With Club Seating Only)                                                             | PA-34-200T         | 2/25/77  | 761-110V        |             | 2510 17G12                                                  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT                                                                                             | MODELS<br>AFFECTED       | DATE     | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------|--------------------------|----------|-----------------|-------------|-------------|
| 800    | Refinement of Narco ADF-140<br>Installation Performance                                             | PA-34-200T               | 2/25/77  | **              |             | 3450 17G19  |
| 808    | Hydraulic Pump Terminal Inspection                                                                  | PA-34-200/200T           | 6/8/77   | **              |             | 2910 17H14  |
| 813    | Vertically Adjustable Seat<br>Refinement                                                            | PA-34-200/200T           | 6/9/77   | **              |             | 2510 17I8   |
| 818    | Outside Air Temperature<br>Gauge Replacement                                                        | PA-34-200T               | 10/19/77 | 99479-03V       |             | 3410 17I22  |
| 820    | Replacement of Lithium Sulphur<br>Dioxide (LiSO <sub>2</sub> ) ELT Batteries<br>and/or Transmitters | PA-34-200<br>PA-34-200T  | 7/28/80  | **              | 79-18-05    | 2560 17J2   |
| 836    | Inspection And Modification<br>Narco ADF-140/141<br>Antenna                                         | PA-34-200T               | 2/9/78   | **              |             | 3450 17K4   |
| 839    | Main Landing Gear<br>Trunnion Bushings                                                              | PA-34-200T               | 9/27/78  | 67026-10        |             | 3210 17K10  |
| 852    | Nose Gear Placard (P/N 582 943V)                                                                    | PA-34-200/200T           | 9/14/78  | 582-943V        |             | 3220 17L17  |
| 858    | Inspection of The Landing<br>Gear Relay Wiring                                                      | PA-34-200T               | 10/10/78 |                 |             | 3230 18A24  |
| 861    | Part I - Forward Facing Seat<br>Back Modification                                                   | PA-34-200<br>PA-34-200T  | 11/13/78 | 763-890V        |             | 2520 18B7   |
| 861    | Part II - Rear Facing (Club)<br>Seat Back Retention                                                 | PA-34-200T               | 11/13/78 | 408-834V        |             | 2520 18B8   |
| 881    | Wiring Harness Protective<br>Sleeve Installation                                                    | PA-34-200T               | 11/13/79 | **              |             | 2400 18F1   |
| 889    | Pneumatic Pump Inlet Filter<br>Relocation                                                           | PA-34-200T               | 11/6/79  | 763-919V        |             | 3710 18F22  |
| 898    | King KNS - 80 Area Navigation<br>System Cooling                                                     | PA-34-200T<br>PA-34-220T | 5/28/82  | 764-385V        |             | 2300 18G15  |
| 920    | Required Placard Adhesion Check                                                                     | PA-34-200T<br>PA-34-220T | 6/29/81  |                 |             | 2500 18I19  |
| 946B   | KNS - 81 Wiring Change                                                                              | PA-34-220T               | 9/1/82   |                 |             | 3450 18K15  |
| 948    | Heated Windshield Panel Sealing<br>And Gyro Filter Protection                                       | PA-34-220T               | 2/5/82   | **              |             | 5610 18K20  |
| 963    | Radio Master Relay Retrofit                                                                         | PA-34-200T               | 11/9/83  | **              |             | 2450 19A12  |
| 966    | Tachometer Generator<br>Mounting Modification                                                       | PA-34-220T               | 12/19/83 | 764-942V        |             | 7710 19A18  |
| 1020   | Relocation of Signal Ground for<br>Cylinder Head and Oil Temperature<br>Sensors                     | PA-34-220T V             | 8/27/98  | **              |             | 7701 19H4   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

## SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                                                                                                        | MODELS<br>AFFECTED                             | DATE       | PART/KIT<br>NO. | A.D.<br>NO.                    | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|------------|-----------------|--------------------------------|-------------|
| 1021   | Distribution of Teledyne Continental Motors Service Bulletin SB 98-8 "Number One and Three Cylinder Intake Tube Modification" and subsequent modification of the engine installation to facilitate compliance. | PA-34-220T V                                   | 1/27/99    | **              |                                | 7313        |
| 1025   | Replacement of Existing Cylinder Head Temperature Wires with Shielded Wiring.                                                                                                                                  | PA-34-220T V                                   | 10/1/99    | **              |                                | 7701        |
| 1031   | Fuel Pump Cooling Inlet Installation                                                                                                                                                                           | PA-34-220T V                                   | 12/11/2000 | 766-678         |                                | 7311        |
| 1036   | Teledyne Continental Motors Service Information Letter SIL 01-2, "Precision Airmotive Corporation SIL RS-59"                                                                                                   | PA-34-220T V                                   | 11/5/2001  | 554-321         |                                | 7318        |
| 1041A  | In-Service Safety Event Reporting                                                                                                                                                                              | All                                            | 3/17/2020  | N/A             |                                | N/A         |
| 1048A  | DDMP May Provide Erroneous Information in the Percent Power Query Mode at High Altitudes                                                                                                                       | PA-34-220T V                                   | 5/30/2003  | 680-475         |                                | 7700        |
| 1052   | Life Limited Parts Marking and Disposition                                                                                                                                                                     | All                                            | 5/21/2002  | N/A             |                                | 510         |
| 1069   | Flight Control Cable Terminal Corrosion Inspection                                                                                                                                                             | All                                            | 3/31/2003  | N/A             | CE-11-01<br>CE-02-05<br>(SAIB) | 2702        |
| 1074   | S-TEC Autopilot Component Seating Procedure                                                                                                                                                                    | All                                            | 11/3/2003  | N/A             |                                | 2210        |
| 1078   | Improved Flap Potentiometer                                                                                                                                                                                    | PA-34-220T V                                   | 1/19/2004  | 100661-003      |                                | 2751        |
| 1086   | Propeller Blade De-ice Boots Maintenance                                                                                                                                                                       | PA-34-200<br>PA-34-200T<br>PA-34-220T III-IV-V | 7/16/2004  | N/A             |                                | 3112        |
| 1087   | Wing Aft Spar-to-Fuselage Attachment Hardware                                                                                                                                                                  | PA-34-220T V                                   | 3/30/2005  | **              |                                | 5740        |
| 1089   | Aircraft Painting Requirement                                                                                                                                                                                  | PA-34-220T V                                   | 10/21/2004 | N/A             |                                | 1100        |
| 1093B  | Electrical Contactor Replacement Kit                                                                                                                                                                           | PA-34-200<br>PA-34-200T<br>PA-34-220T III-IV-V | 11/28/2017 | 88371           |                                | 2400        |
| 1095B  | Classification and Disposition of Hail Damage                                                                                                                                                                  | PA-34-200<br>PA-34-200T<br>PA-34-220T III-IV-V | 11/20/2020 | N/A             |                                | 5100        |
| 1108   | Manifold Pressure Transducer Failures                                                                                                                                                                          | PA-34-220T V                                   | 3/4/2008   | N/A             |                                | 7713        |
| 1116A  | Contactor Maintenance                                                                                                                                                                                          | PA-34-200<br>PA-34-200T<br>PA-34-220T III-IV-V | 3/15/2019  | N/A             |                                | 2435        |
| 1123   | Avidyne EXP5000 Software Upgrade (Mod 57)                                                                                                                                                                      | PA-34-220T V                                   | 9/27/2010  | N/A             |                                | 3420        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

PA-34-200/200T/220T

| NUMBER | SUBJECT                                                                                                                                    | MODELS<br>AFFECTED                             | DATE       | PART/KIT<br>NO.                                                   | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------|------------|-------------------------------------------------------------------|-------------|-------------|
| 1126A  | Voltage Suppressor Advisory                                                                                                                | PA-34-220T V                                   | 3/23/2017  | N/A                                                               |             | 3400        |
| 1135   | Control Cable / Pulley Inspections                                                                                                         | All                                            | 10/19/2010 | N/A                                                               |             | 5720        |
| 1141   | Gascolator Maintenance Procedures                                                                                                          | PA-34-200<br>PA-34-200T                        | 4/27/2011  | MS20995-C32                                                       |             | 2800        |
| 1154   | Engine Starter Motor Replacement                                                                                                           | PA-34-220T V                                   | 3/28/2012  | **                                                                |             | 8010        |
| 1156   | Propeller Feather Stop<br>Product Improvement                                                                                              | PA-34-200<br>PA-34-200T<br>PA-34-220T III-IV-V | 4/2/2012   | 78713-003                                                         |             | 6120        |
| 1162   | Cowl Flap Replacement                                                                                                                      | PA-34-220T V                                   | 3/5/2013   | **                                                                |             | 7110        |
| 1164   | Engine Front Baffle Replacement Kit                                                                                                        | PA-34-220T V                                   | 11/6/2012  | 88537-001                                                         |             | 7160        |
| 1165   | Hydraulic Pump Identification and<br>Servicing Requirements                                                                                | PA-34 Series                                   | 10/18/2012 |                                                                   |             | 2910        |
| 1197   | Propeller Spinner Bulkhead<br>Improvement                                                                                                  | PA-34-220T V                                   | 6/21/2016  | 688-023<br>(E-7258-5)                                             |             | 6113        |
| 1210   | Magneto Timing Procedure                                                                                                                   | PA-34-220T IV                                  | 12/21/2016 | 761-888                                                           |             | 7414        |
| 1218A  | Crew Seat Control Cable<br>Modification                                                                                                    | PA-34-220T III-IV-V                            | 8/8/2017   | 76356-003<br>554-422<br>487-490                                   |             | 2510        |
| 1265   | Flight Control System Checks                                                                                                               | All                                            | 8/6/2019   | N/A                                                               |             | 2700        |
| 1268   | Hartzell 'K' Flange Propeller<br>Hub Replacement                                                                                           | PA-34-200                                      | 10/9/2019  | N/A                                                               |             | 6114        |
| 1274   | Hartzell Propeller Preferred Grease                                                                                                        | All                                            | 1/6/2020   | NYCO GN 3058                                                      |             | 6110        |
| 1280   | Rudder Pedal And Bar Assembly<br>Inspection                                                                                                | All                                            | 2/14/2020  | N/A                                                               |             | 2720        |
| 1284   | Aspen Avionics EFD1000 Update<br>to Software Version 2.10.2                                                                                | PA-34-220T                                     | 2/7/2023   | N/A                                                               |             | 3420        |
| 1311   | Parker Lord SIL-J-9613-001 Rev. A,<br>'Potential Incorrect Combination of<br>Components in Parker Lord J-9613<br>Series Engine Mount Kits' | PA-34-200                                      | 6/7/2022   | 470-516 / J-9613-19<br>475-115 / J-9613-12<br>475-124 / J-9613-40 |             | 7120        |
| 1320   | Wing And Fuselage<br>Skin Repair Limitations                                                                                               | PA-34-200<br>PA-34-200T<br>PA-34-220T III-IV-V | 12/1/2022  | N/A                                                               |             | 5100        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT | MODELS<br>AFFECTED | DATE | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|---------|--------------------|------|-----------------|-------------|-------------|
|--------|---------|--------------------|------|-----------------|-------------|-------------|

THIS SPACE INTENTIONALLY BLANK

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED     | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|------------------------|-----------|-----------------|-------------|-------------|
| 177    | Firewalls                                                                                                                         | All Models             | 8/10/51   |                 |             | 13B13       |
| 578B   | Fuel Line (Stainless Steel Tube Assy.)<br>and Support Clamp Inspection<br>and Installation,<br>Lycoming Service Bulletin No. 342F | PA-36-300<br>PA-36-375 | 7/27/2011 | N/A             | 2011-26-04  | 7310        |
| 609    | Control Surfaces Inspection<br>And Maintenance Guidelines                                                                         | All Models             | 2/21/72   |                 |             | 5500 15J21  |
| 633    | Inspection And Repair of<br>Flood Exposed Airplanes                                                                               | PA-36                  | 10/9/72   |                 |             | 5300 16A18  |
| 652A   | Pilot And Maintenance<br>Training Program                                                                                         | PA-36                  | 6/14/73   |                 |             | 500 16C11   |
| 659    | Seat Back Modification                                                                                                            | PA-36                  | 5/9/74    | 760-797V        |             | 2510 16D6   |
| 678    | Relocation of Throttle Control<br>Rod End                                                                                         | PA-36                  | 12/12/73  |                 |             | 7610 16E24  |
| 682B   | Required Inspection of<br>Piston Pin (Reference<br>Lycoming Service<br>Bulletin No. 367D)                                         | PA-36                  | 4/19/74   | **              |             | 7230 16F9   |
| 693    | Upper Cowl Support Modification                                                                                                   | PA-36                  | 3/29/74   | 760-811V        |             | 7110 16G9   |
| 707    | Flyball Assembly To Improve<br>RPM Control, Modified<br>(Reference Hartzell Service<br>Letter No. 75, Dated<br>November 16, 1973) | PA-36                  | 2/27/74   | **              |             | 7710 16I11  |
| 718    | Bendix Magneto Bulletin<br>No. 566 (Reference Avco<br>Lycoming Service Bulletin<br>373, Dated March 22, 1974)                     | PA-36                  | 5/31/74   | **              |             | 7410 16J18  |
| 727    | Spray Pump Windmill Assembly<br>Modification (Reference<br>Agrinautics Service Bulletin<br>No. SP-74-1 Dated April 30, 1974)      | PA-36                  | 8/8/74    | **              |             | 910 16K17   |
| 729    | Elevator Control System Modification                                                                                              | PA-36-285              | 11/6/74   | 760-879V        |             | 2730 16K22  |
| 746    | Air Filtration                                                                                                                    | PA-36                  | 7/10/75   | **              |             | 7160 17A16  |
| 759    | Fuselage Forward Bottom<br>Panel Reinforcement                                                                                    | PA-36                  | 3/26/76   | 760-999         |             | 5310 17C11  |
| 765    | Oil Change And Pre-Start<br>Procedures                                                                                            | PA-36                  | 11/26/75  |                 |             | 7920 17D5   |
| 767    | Replacement of Parking<br>Brake Valve                                                                                             | PA-36                  | 1/28/76   | 98384-00        |             | 3240 17D12  |
| 771    | Engine Care And Operational<br>Tips, Tiara 6-285                                                                                  | PA-36                  | 5/18/76   |                 |             | 7200 17E1   |
| 774    | Engine Cowl Modification                                                                                                          | PA-36                  | 5/18/76   | 761-062         |             | 7110 17E9   |
| 776    | Fitting Installation Flap<br>Control Bellcrank Grease                                                                             | PA-36                  | 10/11/76  | 761-068         |             | 2750 17E11  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                       | MODELS<br>AFFECTED                      | DATE       | PART/KIT<br>NO.     | A.D.<br>NO.        | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------|-----------------------------------------|------------|---------------------|--------------------|-------------|
| 820    | Replacement of Lithium Sulphur Dioxide (LiSO <sub>2</sub> ) ELT Batteries and/or Transmitters | PA-36-285/300<br>PA-36-375              | 7/28/80    | **                  | 79-18-05           | 2560        |
| 825    | Cockpit Door Emergency Release Refinement                                                     | PA-36-285<br>PA-36-300                  | 11/30/78   | 763-811             |                    | 5210        |
| 838    | Manifold Pressure Gauge Line Filter Installation                                              | PA-36-300                               | 3/14/78    | 763-835             |                    | 7710        |
| 849    | Stabilizer Refinement                                                                         | PA-36-300                               | 10/31/78   |                     |                    | 5530        |
| 892    | Engine Air Induction System Modification                                                      | PA-36-285<br>PA-36-300<br>PA-36-375     | 3/21/80    | 99849-14<br>555-846 |                    | 7160        |
| 897    | Rudder Attachment Hardware Replacement                                                        | PA-36-285/300<br>PA-36-375              | 6/2/80     | **                  |                    | 5540        |
| 1041A  | In-Service Safety Event Reporting                                                             | All                                     | 3/17/2020  | N/A                 |                    | N/A         |
| 1052   | Life Limited Parts Marking and Disposition                                                    | All                                     | 5/21/2002  | N/A                 |                    | 510         |
| 1069   | Flight Control Cable Terminal Corrosion Inspection                                            | All                                     | 3/31/2003  | N/A                 | CE-02-05<br>(SAIB) | 2702        |
| 1093B  | Electrical Contactor Replacement Kit                                                          | PA-36-285<br>PA-36-300<br>PA-36-375     | 11/28/2017 | 88371               |                    | 2400        |
| 1116A  | Contactor Maintenance                                                                         | PA-36-285<br>PA-36-300<br>PA-36-375     | 3/15/2019  | N/A                 |                    | 2435        |
| 1135   | Control Cable / Pulley Inspections                                                            | All                                     | 10/19/2010 | N/A                 |                    | 5720        |
| 1265   | Flight Control System Checks                                                                  | All                                     | 8/6/2019   | N/A                 |                    | 2700        |
| 1268   | Hartzell 'K' Flange Propeller Hub Replacement                                                 | PA-36-300<br>(Restricted Category Only) | 10/9/2019  | N/A                 |                    | 6114        |
| 1274   | Hartzell Propeller Preferred Grease                                                           | All                                     | 1/6/2020   | NYCO GN 3058        |                    | 6110        |
| 1280   | Rudder Pedal And Bar Assembly Inspection                                                      | All                                     | 2/14/2020  | N/A                 |                    | 2720        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

\*\*\* All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.



# SERVICE LETTER INDEX

PA-38-112

| NUMBER | SUBJECT                                                                                                | MODELS<br>AFFECTED | DATE     | PART/KIT<br>NO.     | A.D.<br>NO. | ATA<br>CODE                                                                                                                                                                                      |
|--------|--------------------------------------------------------------------------------------------------------|--------------------|----------|---------------------|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 177    | Firewalls                                                                                              | All Models         | 8/10/51  |                     |             | 13B13                                                                                                                                                                                            |
| 609    | Control Surfaces Inspection<br>And Maintenance Guidelines                                              | All Models         | 2/21/72  |                     |             | 5500 15J21                                                                                                                                                                                       |
| 820    | Replacement of Lithium<br>Sulphur Dioxide (LiSO <sub>2</sub> )<br>ELT Batteries and/or<br>Transmitters | PA-38-112          | 7/28/80  | **                  | 79-18-05    | 2560 17J2                                                                                                                                                                                        |
| 855    | Tomahawk Product Refinement<br>Program                                                                 | PA-38-112          | 10/20/78 | **                  |             | 1. 2520 18A1<br>2. 2510<br>3. 5300<br>4. 6110<br>5. 7810<br>6. 2520<br>7. 5340<br>8. 3210<br>9. 2740<br>2560<br>10. 5210<br>11. 2820<br>12. 5530<br>13. 2750<br>14. 3220<br>15. 5300<br>16. 2140 |
| 865    | Elevator Trim System<br>Inspection/Modification                                                        | PA-38-112          | 1/22/79  | 77878-02            |             | 2730 18B22                                                                                                                                                                                       |
| 870    | Upper Rudder Fairing<br>Clearance Inspection                                                           | PA-38-112          | 7/5/79   |                     |             | 5350 18C23                                                                                                                                                                                       |
| 876    | Additional Flow Strip Installation                                                                     | PA-38-112          | 4/12/79  | **                  | 83-14-08    | 5720 18D17                                                                                                                                                                                       |
| 877    | Part I - Seat Cover<br>Attachment Replacement                                                          | PA-38-112          | 4/30/79  | 455-001             |             | 2510 18D19                                                                                                                                                                                       |
| 877    | Part II - Aft Bulkhead<br>Stiffener Channel<br>Installation                                            | PA-38-112          | 4/30/79  | 77554-06            |             | 5310 18D20                                                                                                                                                                                       |
| 877    | Part III - Placards<br>Replacement                                                                     | PA-38-112          | 4/30/79  | 763-932             |             | 2500 18D21                                                                                                                                                                                       |
| 877    | Part IV - Fuel<br>Selector Handle<br>Inspection                                                        | PA-38-112          | 4/30/79  |                     |             | 2820 18D22                                                                                                                                                                                       |
| 877    | Part V - Stabilizer<br>Drain Holes Addition                                                            | PA-38-112          | 4/30/79  | **                  |             | 5300 18D22                                                                                                                                                                                       |
| 877    | Part VI - Compass<br>Compensation                                                                      | PA-38-112          | 4/30/79  | **                  |             | 3440 18D23                                                                                                                                                                                       |
| 877    | Part VII - Main<br>Gear Alignment                                                                      | PA-38-112          | 4/30/79  | **                  |             | 3210 18D24                                                                                                                                                                                       |
| 877    | Part VIII - Elevator<br>Stop Attachment                                                                | PA-38-112          | 4/30/79  | **                  |             | 5520 18E5                                                                                                                                                                                        |
| 877    | Part IX - Elevator<br>Leading Edge Straps                                                              | PA-38-112          | 4/30/79  | 77618-D2<br>420-200 |             | 5720 18E5                                                                                                                                                                                        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

**SL69**

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                               | MODELS<br>AFFECTED | DATE       | PART/KIT<br>NO.      | A.D.<br>NO.        | ATA<br>CODE |
|--------|-------------------------------------------------------|--------------------|------------|----------------------|--------------------|-------------|
| 895A   | Magneto Switch Modification                           | PA-38-112          | 3/19/81    | 153-010<br>488-396   |                    | 7430        |
| 909    | Magneto Switch Replacement                            | PA-38-112          | 6/9/81     | 688 178              | 93-05-06           | 7430        |
| 911    | Aft Spinner Bulkhead<br>Replacement                   | PA-38-112          | 4/22/81    | 77710-04<br>77710-06 |                    | 6110        |
| 931    | Nose Gear Fork Assembly<br>Improvement                | PA-38-112          | 8/25/81    | 764-213              |                    | 3220        |
| 944    | Fuel Selector Valve Inspection<br>And Lubrication     | PA-38-112          | 4/20/82    | **                   |                    | 2820        |
| 1041A  | In-Service Safety Event Reporting                     | All                | 3/17/2020  | N/A                  |                    | N/A         |
| 1052   | Life Limited Parts<br>Marking and Disposition         | All                | 5/21/2002  | N/A                  |                    | 510         |
| 1069   | Flight Control Cable Terminal<br>Corrosion Inspection | All                | 3/31/2003  | N/A                  | CE-02-05<br>(SAIB) | 2702        |
| 1093B  | Electrical Contactor Replacement Kit                  | PA-38-112          | 11/28/2017 | 88371                |                    | 2400        |
| 1116A  | Contactor Maintenance                                 | PA-38-112          | 3/15/2019  | N/A                  |                    | 2435        |
| 1135   | Control Cable / Pulley Inspections                    | All                | 10/19/2010 | N/A                  |                    | 5720        |
| 1141   | Gascolator Maintenance Procedures                     | PA-38-112          | 4/27/2011  | MS20995-C32          |                    | 2800        |
| 1265   | Flight Control System Checks                          | All                | 8/6/2019   | N/A                  |                    | 2700        |
| 1280   | Rudder Pedal And Bar Assembly<br>Inspection           | All                | 2/14/2020  | N/A                  |                    | 2720        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

# SERVICE LETTER INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                                                                                           | MODELS<br>AFFECTED        | DATE      | PART/KIT<br>NO. | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------------------------------------------------------------------|---------------------------|-----------|-----------------|-------------|-------------|
| 177    | Firewalls                                                                                                                         | All Models                | 8/10/51   |                 |             | 13B13       |
| 578B   | Fuel Line (Stainless Steel Tube Assy.)<br>and Support Clamp Inspection<br>and Installation,<br>Lycoming Service Bulletin No. 342F | PA-46-350P<br>PA-46R-350T | 7/27/2011 | N/A             | 2011-26-04  | 7310        |
| 609    | Control Surfaces Inspection<br>And Maintenance Guidelines                                                                         | All Models                | 2/21/72   |                 |             | 5500 15J21  |
| 938    | Forward Baggage Door Modification                                                                                                 | PA-46-310P                | 7/10/84   | 765-109V        |             | 5230 18K4   |
| 965    | Hydraulic Pump Installation<br>Modification                                                                                       | PA-46-310P                | 9/25/85   | 765-161         |             | 2910 19A16  |
| 967    | Lower Cabin Door Modification                                                                                                     | PA-46-310P                | 6/28/84   | 765-104V        |             | 5210 19A20  |
| 968A   | Oil Filler Door/Top Cowl Modification                                                                                             | PA-46-310P                | 7/28/86   | **              |             | 7250 19A22  |
| 970    | Main Landing Gear Door Link                                                                                                       | PA-46-310P                | 8/7/84    | **              |             | 3216 19B3   |
| 971B   | Engine Baffle Modification And<br>Aftercooler Clip Installation                                                                   | PA-46-310P                | 2/23/87   | **              |             | 7230 19B6   |
| 972    | PART I - Hydraulic Pressure Gauge<br>Line Fitting Replacement                                                                     | PA-46-310P                | 8/20/84   | 762-643V        |             | 2930 19B9   |
| 972    | PART II - Hydraulic Pressure Gauge<br>Line Poppet Spring<br>Replacement                                                           | PA-46-310P                | 8/20/84   | 764-874V        |             | 2930 19B9   |
| 973    | Lower Cabin Door Step Up -<br>Stop Installation                                                                                   | PA-46-310P                | 8/20/84   | 765-107V        |             | 5260 19B13  |
| 974    | Fiberglass Nose Cowl<br>Replacement                                                                                               | PA-46-310P                | 8/20/84   | **              |             | 5430 19B15  |
| 975    | Lower Cabin Door Duct Seal<br>& Chain Stand-off                                                                                   | PA-46-310P                | 2/13/85   | 765-135V        |             | 2120 19B17  |
| 976    | Seat Pan Reinforcement                                                                                                            | PA-46-310P                | 8/20/84   | 765-103V        |             | 2506 19B19  |
| 978    | Cabin Heat Valve<br>Modification                                                                                                  | PA-46-310P                | 1/15/86   | 765-176         |             | 2140 19B23  |
| 981    | Engine Tachometer<br>Replacement                                                                                                  | PA-46-310P                | 10/22/85  | 765-183         |             | 7710 19C7   |
| 982    | Turbo Inlet Temperature<br>Probe Wiring Modification                                                                              | PA-46-310P                | 2/4/86    | 588-859         |             | 7728 19C9   |
| 984    | Hydraulic Pump Annunciator<br>And Controller Installation                                                                         | PA-46-310P                | 7/15/86   | **              |             | 2917 19C15  |
| 985    | PART I - Teledyne Continental<br>Motors Special Service<br>Notice No. 3-86.<br>"TSIO-520BE Engine"                                | PA-46-310P                | 4/18/86   |                 |             | 7230 19C17  |
| 985    | PART II - Alternate Air<br>Intake Assembly<br>Modification                                                                        | PA-46-310P                | 4/18/86   | 765-198         | 87-04-01    | 7160 19C17  |
| 989    | Stiffener Installation -<br>Induction Air Panel                                                                                   | PA-46-310P                | 8/20/86   | 765-304         |             | 7102 19D3   |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

**SL71**

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                | MODELS<br>AFFECTED       | DATE      | PART/KIT<br>NO.      | A.D.<br>NO. | ATA<br>CODE |
|--------|--------------------------------------------------------------------------------------------------------|--------------------------|-----------|----------------------|-------------|-------------|
| 990    | Engine And Airframe<br>Operational Characteristics<br>And Operating Limitations                        | PA-46-310P               | 11/17/86  | N/A                  |             | 1100 19D5   |
| 991    | Pilot/Copilot Oxygen<br>System Modification                                                            | PA-46-310P               | 11/18/86  | **                   |             | 3512 19D9   |
| 992    | Stereo System Power<br>Supply Modification                                                             | PA-46-310P               | 11/19/86  | 584-387              |             | 2334 19D11  |
| 995A   | Landing Gear Actuator Switch<br>Modification - Gar Kenyon                                              | PA-46-310P               | 5/28/87   | 407-560              |             | 3266 19D18  |
| 996    | Engine Mount Heat Shield<br>Installation                                                               | PA-46-310P               | 3/5/87    | 765-323              |             | 7120 19D22  |
| 999    | Air Conditioner Compressor<br>Mount - Shim Installation                                                | PA-46-310P               | 7/17/87   | 84044-10<br>84044-11 |             | 2152 19E6   |
| 1000   | Nose Gear Door Hinge<br>Support Modification                                                           | PA-46-310P               | 10/16/87  | 765-347              |             | 3226 19E9   |
| 1001   | Engine Mount<br>Inspection/Modification                                                                | PA-46-310P               | 12/9/87   | 84010-48             |             | 7121 19E11  |
| 1004   | Addition of Main Gear<br>Door Protection Pad                                                           | PA-46-310P<br>PA-46-350P | 5/23/89   | **                   |             | 3216 19E20  |
| 1005   | Nose Bowl Modification                                                                                 | PA-46-350P               | 6/8/89    | 766-215              |             | 5422 19E23  |
| 1006   | Fuel Vent Line Protection                                                                              | PA-46-310P               | 8/25/89   | 63913-199<br>488-702 |             | 3216 19F1   |
| 1007   | Engine Air/Oil Separator<br>Improvement                                                                | PA-46-350P               | 9/25/89   | 42414-00<br>2565-02  |             | 7251 19F3   |
| 1008   | Operational Caution: Inoperative<br>Turbine Inlet Temperature System                                   | PA-46-350P               | 6/22/90   | N/A                  |             | 7200 19F5   |
| 1009   | Bendix/King Installation Bulletin No.<br>312, Water Damage to the Pitch<br>and Yaw Capstans and Servos | PA-46-310P<br>PA-46-350P | 9/19/90   | **                   |             | 2212 19F7   |
| 1010   | Modification of Engine Baffle                                                                          | PA-46-350P               | 1/19/94   | **                   |             | 7230 19F14  |
| 1011   | Nose Gear Trunnion Replacement                                                                         | PA-46-310P               | 4/27/94   | 766-211              |             | 7230 19F16  |
| 1012   | Aileron Control Cable Replacement                                                                      | PA-46-310P<br>PA-46-350P | 11/30/94  | **                   |             | 2710 19F23  |
| 1018A  | Improved Intercooler Attachment Clips                                                                  | PA-46-350P               | 9/13/99   | 89082-05             |             | 7236 18G23  |
| 1022   | Lower Cowling Assembly<br>Modification                                                                 | PA-46-350P               | 2/12/99   | 766-658              |             | 5432 19H15  |
| 1023   | Improved Security of the<br>Pressure Controls Cable                                                    | PA-46-350P               | 4/12/99   | **                   |             | 2125 19H17  |
| 1026   | Storm Window Seal<br>Improvement Kit                                                                   | PA-46-350P               | 11/3/99   | 766-659              |             | 5614 19I5   |
| 1035   | Concorde Lead Acid Battery<br>Conditioning                                                             | PA-46-500TP              | 7/20/2001 | N/A                  |             | 2432 19J12  |
| 1037   | Power Lever / Manual Override<br>(MOR) Knob                                                            | PA-46-500TP              | 7/26/2001 | N/A                  |             | 7611 19J21  |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

# SERVICE LETTER INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                               | MODELS<br>AFFECTED                      | DATE       | PART/KIT<br>NO.    | A.D.<br>NO.        | ATA<br>CODE |       |
|--------|-----------------------------------------------------------------------|-----------------------------------------|------------|--------------------|--------------------|-------------|-------|
| 1039A  | Replacement TIT Probe Availability                                    | PA-46-350P                              | 12/8/2006  | 686-216            | 2011-06-10         | 7726        | 19K4  |
| 1041A  | In-Service Safety Event Reporting                                     | All                                     | 3/17/2020  | N/A                |                    | N/A         |       |
| 1046A  | Generator Control Unit (GCU)<br>Rewire Kit                            | PA-46-500TP                             | 9/27/2002  | 767-329            |                    | 2430        | 19L1  |
| 1051   | Gullwing Door Rub Strip Installation                                  | PA-46-500TP                             | 1/21/2003  | 104644-004         |                    | 7110        | 19L15 |
| 1052   | Life Limited Parts<br>Marking and Disposition                         | All                                     | 5/21/2002  | N/A                |                    | 510         | 19L19 |
| 1053   | Engine Starter Motor Replacement                                      | PA-46-350P                              | 10/16/2002 | 767-337            |                    | 8011        | 20A1  |
| 1055   | Executive Table Stow Adjustments                                      | PA-46-500TP                             | 6/20/2003  | N/A                |                    | 2520        | 20A6  |
| 1056   | Accessory Cooling Air Inlet Drain<br>Hose Routing Inspection          | PA-46-500TP                             | 2/19/2003  | **                 |                    | 7500        | 20A9  |
| 1057   | Upper Wing Skin Inspection<br>and Reinforcement                       | PA-46-310P<br>PA-46-350P<br>PA-46-500TP | 1/29/2003  | 767-352<br>767-353 |                    | 5730        | 20A12 |
| 1058A  | Horizontal Stabilizer Maintenance<br>Manual Correction - Torque Value | PA-46-500TP                             | 10/16/2012 | 767-005            |                    | 5510        |       |
| 1059A  | Tailcone Gusset Installation Kit                                      | PA-46-500TP                             | 10/16/2015 | 767-356            |                    | 5300        |       |
| 1062   | Lower Torque Link Bolt Inspection                                     | PA-46-500TP                             | 2/13/2003  | **                 |                    | 3213        | 20B4  |
| 1065   | Aileron Rivet Inspection                                              | PA-46-500TP                             | 7/29/2005  | 522-655            |                    | 2710        | 20B13 |
| 1067   | Steering Bellows Improvement                                          | PA-46-500TP                             | 3/31/2003  | 691-527            |                    | 3250        | 20B20 |
| 1069   | Flight Control Cable Terminal<br>Corrosion Inspection                 | All                                     | 3/31/2003  | N/A                | CE-02-05<br>(SAIB) | 2702        | 20C2  |
| 1072   | Possible Magnetization of<br>ELT Antenna                              | PA-46-500TP                             | 6/4/2003   | 762-362            |                    | 2300        | 20C9  |
| 1074   | S-TEC Autopilot Component<br>Seating Procedure                        | All                                     | 11/3/2003  | N/A                |                    | 2210        | 20C14 |
| 1075   | Higher Capacity Battery Availability                                  | PA-46-500TP                             | 10/27/2003 | 601-910<br>767-375 |                    | 2432        | 20C19 |
| 1076   | Stall Warning Computer Verification                                   | PA-46-500TP                             | 1/9/2004   | 600-517<br>599-161 |                    | 3418        | 20C22 |
| 1077   | Magic 1500 Autopilot Go-Around<br>Switch Wire Security                | PA-46-500TP                             | 12/3/2003  | 767-376            |                    | 2200        | 20D1  |
| 1079   | ADAHRS Fault Finding Guide<br>(Meggitt SIL No. 26, Issue 1)           | PA-46-500TP                             | 5/5/2004   | N/A                |                    | 3400        | 20D7  |
| 1082   | Fuel Filter Replacement<br>(Pall SB ADB474-72-01)                     | PA-46-500TP                             | 6/25/2004  | 601-808<br>601-809 |                    | 2821        | 20E12 |
| 1085   | ADAHRS Calibration Harness                                            | PA-46-350P<br>PA-46-500TP               | 7/1/2004   | 101453-002         |                    | 3420        | 20E23 |
| 1086   | Propeller Blade De-ice Boots<br>Maintenance                           | PA-46-310P<br>PA-46-350P<br>PA-46-500TP | 7/16/2004  | N/A                |                    | 3112        | 20F3  |
| 1089   | Aircraft Painting Requirement                                         | PA-46-350P<br>PA-46-500TP               | 10/21/2004 | N/A                |                    | 1100        | 20F15 |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                                                              | MODELS<br>AFFECTED                                                    | DATE       | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|------------|------------------------|-------------|-------------|
| 1090   | Performance Upgrade,<br>Lower Operating Temperature<br>Limitation                                                                                    | PA-46-500TP                                                           | 9/26/2005  | 767-380<br>767-381     |             | 2843 20F18  |
| 1091   | Door Seal Protection<br>(Latch Stop Kit)                                                                                                             | PA-46-350P                                                            | 12/15/2005 | 767-387                |             | 5210 20F21  |
| 1093B  | Electrical Contactor Replacement Kit                                                                                                                 | PA-46-310P<br>PA-46-350P<br>PA-46R-350T                               | 11/28/2017 | 88371                  |             | 2400        |
| 1097   | Flap Bellcrank Inspection<br>and Flap Rigging Check                                                                                                  | PA-46-310P<br>PA-46-350P<br>PA-46-500TP                               | 10/17/2005 | 82905-10/-11           |             | 2700 20H4   |
| 1100   | Crew Seat Modification                                                                                                                               | PA-46-350P<br>PA-46-500TP                                             | 6/18/2006  | 767-522                |             | 2510 20H10  |
| 1102   | Oil Pressure Indication<br>Subject to RFI/EMI                                                                                                        | PA-46-500TP                                                           | 10/9/2006  | 88408-002              |             | 7261 20H14  |
| 1104   | Flow Sensor Assy., Mass Flow<br>Controller and ECS Crossover<br>Tube Assy. Replacement                                                               | PA-46-500TP                                                           | 3/14/2008  | 88417-002<br>88417-003 |             | 2140 20H20  |
| 1106A  | Sky-Tec Starter<br>Cranking Instructions                                                                                                             | PA-46-350P<br>PA-46R-350T                                             | 10/28/2009 | N/A                    |             | 8011 20I2   |
| 1107A  | Modification to Eliminate False<br>"GEN INOP" Annunciation                                                                                           | PA-46-500TP                                                           | 10/3/2007  | N/A                    |             | 2420 20I6   |
| 1108   | Manifold Pressure Transducer<br>Failures                                                                                                             | PA-46-350P<br>PA-46R-350T                                             | 3/4/2008   | N/A                    |             | 7713 20I10  |
| 1110A  | Pratt & Whitney Canada<br>SIL No. PT6A-206 latest revision,<br>Compressor and Turbine Washes<br>as an Effective Means of<br>Preventative Maintenance | PA-46-500TP                                                           | 9/3/2013   | N/A                    |             | 7100        |
| 1111   | Autopilot Pitch Servo and<br>Programmer / Computer Upgrade                                                                                           | PA-46-350P<br>PA-46R-350T                                             | 5/29/2008  | 88438-002<br>88439-002 |             | 2212 20I23  |
| 1113   | Crew Seat Back Modification                                                                                                                          | PA-46-500TP<br>PA-46-350P<br>PA-46R-350T                              | 2/25/2009  | 88444-002<br>(Kit)     |             | 2510        |
| 1114   | NACA Inlet Guide Vane<br>Installation Kit                                                                                                            | PA-46R-350T                                                           | 2/16/2009  | 88446-002<br>(Kit)     |             | 2140        |
| 1115A  | WAAS Compatible Autopilot                                                                                                                            | PA-46-500TP                                                           | 2/19/2009  | N/A                    |             | 2210        |
| 1116A  | Contactor Maintenance                                                                                                                                | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46-600TP<br>PA-46R-350T | 3/15/2019  | N/A                    |             | 2435        |
| 1117   | MLB 700 Remote Control Antenna<br>Modification                                                                                                       | PA-46R-350T                                                           | 3/16/2009  | 561-572                |             | 2330        |
| 1118   | Sky-Tec Starter Replacement                                                                                                                          | PA-46-350P<br>PA-46R-350T                                             | 10/28/2009 | **                     |             | 8011        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

# SERVICE LETTER INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                          | MODELS<br>AFFECTED                                                    | DATE       | PART/KIT<br>NO.                    | A.D.<br>NO. | ATA<br>CODE |
|--------|------------------------------------------------------------------|-----------------------------------------------------------------------|------------|------------------------------------|-------------|-------------|
| 1120   | Air Conditioning Servicing                                       | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                              | 6/18/2010  | **                                 |             | 2150        |
| 1121   | RG-41 Battery Service Life Improvement                           | PA-46-500TP                                                           | 4/1/2010   | 601-910                            |             | 2430        |
| 1122   | G1000 Split Communications Enable                                | PA-46-350P<br>PA-46R-350T                                             | 5/20/2010  | N/A                                |             | 2300        |
| 1123   | Avidyne EXP5000 Software Upgrade (Mod 57)                        | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                              | 9/27/2010  | N/A                                |             | 3420        |
| 1126A  | Voltage Suppressor Advisory                                      | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                              | 3/23/2017  | N/A                                |             | 3400        |
| 1127   | Emergency Exit Interior Panel Hook and Loop Fastener Replacement | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                              | 7/2/2010   | **                                 |             | 5220        |
| 1128   | Improved Capacity Battery                                        | PA-46-350P<br>PA-46R-350T                                             | 3/7/2012   | 88495-002<br>601-919               |             | 2430        |
| 1129   | Improved Landing Gear Service Replacement Actuators Available    | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                | 6/27/2011  | **                                 |             | 3230        |
| 1130   | Lower Entry Door Upgrade                                         | PA-46-350P<br>PA-46-500TP                                             | 8/4/2010   | 88423-002<br>452-215<br>106611-003 |             | 5210        |
| 1131A  | Aileron Sector Bearing Lubrication Requirements                  | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46-600TP<br>PA-46R-350T | 2/11/2019  | MIL-PRF-7870C                      |             | 5755        |
| 1132   | Fuel Tank Leaks                                                  | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                | 12/7/2010  | N/A                                |             | 5712        |
| 1135   | Control Cable / Pulley Inspections                               | All                                                                   | 10/19/2010 | N/A                                |             | 5720        |
| 1136A  | Fuel Pressure Switch Adjustment                                  | PA-46-350P<br>PA-46R-350T                                             | 4/28/2011  | 74093-002<br>688-192               |             | 2820        |
| 1137   | Circuit Breaker Panel Modification                               | PA-46-500TP                                                           | 11/3/2010  | 88482-002<br>88482-003             |             | 3910        |
| 1138   | Safe Flight Service Letter No. 65, Lift Transducer Modification  | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                              | 1/17/2011  | 599-160<br>652-689                 |             | 3410        |
| 1140   | Garmin G1000 Software Version 720.12                             | PA-46-350P<br>PA-46R-350T                                             | 6/22/2011  | **                                 |             | 3420        |
| 1142A  | Line Contactor and Generator Control Unit Replacement            | PA-46-500TP                                                           | 3/10/2014  | 602-943<br>PS60047-1<br>601-922    |             | 2430        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                               | MODELS<br>AFFECTED                                     | DATE       | PART/KIT<br>NO.                                                                    | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------------------------|--------------------------------------------------------|------------|------------------------------------------------------------------------------------|-------------|-------------|
| 1147   | Garmin G1000 Software<br>Version 720.14                               | PA-46-500TP                                            | 12/1/2011  | **                                                                                 |             | 3420        |
| 1148   | Garmin G1000 Software<br>Version 720.14                               | PA-46-350P<br>PA-46R-350T                              | 5/2/2012   | **                                                                                 |             | 3420        |
| 1155   | Ground Idle Adjustment                                                | PA-46-500TP                                            | 1/30/2012  | N/A                                                                                |             | 7610        |
| 1157   | Exterior Lighting - Led Upgrade                                       | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46R-350T | 4/26/2012  | **                                                                                 |             | 3340        |
| 1158   | Hubcap Upgrade                                                        | PA-46-500TP                                            | 4/26/2012  | 551-621                                                                            |             | 3240        |
| 1159B  | Fuel Sender Upgrade                                                   | PA-46-310P<br>PA-46-350P<br>PA-46R-350T                | 10/12/2018 | 88535<br>88462                                                                     |             | 2840        |
| 1160   | Interior Lighting – LED Upgrade                                       | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 10/31/2017 | 479-000<br>479-001<br>479-002<br>488-770<br>103203-005<br>103203-006<br>103203-007 |             | 3300        |
| 1168   | False Alternator Fail Annunciations                                   | PA-46-350P<br>PA-46R-350T                              | 2/28/2013  | N/A                                                                                |             | 2300        |
| 1170   | Evaporator Module Assembly<br>Replacement Requirements                | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 6/27/2013  | 88542                                                                              |             | 2150        |
| 1178A  | Garmin G1000 Software<br>Version 720.15                               | PA-46-500TP                                            | 4/23/2014  | **                                                                                 |             | 3420        |
| 1179   | Garmin G1000 Software<br>Version 720.15                               | PA-46-350P<br>PA-46R-350T                              | 4/24/2014  | **                                                                                 |             | 3420        |
| 1183   | Elevator Plate Assembly Rivet<br>Inspection                           | PA-46-310P<br>PA-46-350P<br>PA-46R-350T                | 10/21/2014 | 83515-002,<br>83508-002                                                            |             | 2730        |
| 1184   | Stall Warning System Test Update                                      | PA-46-350P<br>PA-46R-350T                              | 2/11/2015  | **                                                                                 |             | 2730        |
| 1185A  | Stall Warning System Test Update                                      | PA-46-500TP                                            | 3/26/2015  | **                                                                                 |             | 2730        |
| 1189B  | Inspection of GCU Reverse Current<br>Protection Circuit and Connector | PA-46-500TP                                            | 8/14/2015  | 461-659                                                                            |             | 2424        |
| 1194A  | Garmin G1000 Software Update<br>Version 720.17                        | PA-46-350P<br>PA-46R-350T                              | 9/1/2015   | N/A                                                                                |             | 3420        |
| 1195   | Garmin G1000 Software Update<br>Version 720.17                        | PA-46-500TP                                            | 9/2/2015   | N/A                                                                                |             | 3420        |
| 1196A  | Availability of GTX 33ES Transponder                                  | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T               | 12/21/2017 | N/A                                                                                |             | 3452        |
| 1198   | Garmin G1000 Software<br>Version 2164.03                              | PA-46-350P M350                                        | 2/24/2016  | N/A                                                                                |             | 3420        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.



# SERVICE LETTER INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                                                                              | MODELS<br>AFFECTED                                      | DATE       | PART/KIT<br>NO.                                                      | A.D.<br>NO. | ATA<br>CODE |
|--------|----------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|------------|----------------------------------------------------------------------|-------------|-------------|
| 1199A  | Garmin G1000 Software<br>Version 2163.05                                                                             | PA-46-500TP M500                                        | 7/26/2016  | N/A                                                                  |             | 3420        |
| 1200A  | Pratt & Whitney Canada Service<br>Bulletin No. 3482 – Replacement/<br>Modification of Turboprop<br>Fuel Control Unit | PA-46-500TP                                             | 4/27/2016  | N/A                                                                  |             | 7320        |
| 1201B  | Garmin G1000 Software Update<br>Version 2164.06 with<br>Stall Heat Control                                           | PA-46-350P M350                                         | 8/19/2016  | 88589-002<br>190-01889-00<br>190-01888-00                            |             | 3420        |
| 1202   | Main Landing Gear Actuator<br>Hydraulic Hose Replacement                                                             | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                | 2/7/2017   | 187-273<br>102551-004                                                |             | 3230        |
| 1203A  | Garmin G1000 Software Update<br>Version 720.17 with<br>Stall Heat Control                                            | PA-46-350P<br>PA-46R-350T                               | 3/21/2019  | 88589-002<br>88589-003<br>190-01108-01<br>190-01107-01               |             | 3420        |
| 1204   | Heated Windshield Test Procedure                                                                                     | PA-46-350P<br>PA-46-500TP<br>PA-46-600TP<br>PA-46R-350T | 8/17/2016  | N/A                                                                  |             | 3040        |
| 1205   | Garmin G1000 Software Update<br>Version 720.17<br>with Stall Heat Control                                            | PA-46-500TP                                             | 6/27/2017  | 88590-002<br>VB-1993 R17                                             |             | 3420        |
| 1206   | Garmin G1000 Software Update<br>Version 2163.08<br>with Stall Heat Control                                           | PA-46-500TP M500                                        | 4/14/2017  | 88590-003                                                            |             | 3420        |
| 1208A  | Garmin G3000 Software Update<br>Ver. 2039.06 with<br>Sidetone Improvement                                            | PA-46-600TP                                             | 12/12/2016 | 10-01615-06                                                          |             | 3420        |
| 1211   | Audio Bus Wiring Inspection<br>and Fuse Replacement                                                                  | PA-46-350P<br>PA-46-500TP                               | 5/3/2017   | 461-685                                                              |             | 2350        |
| 1212   | Garmin G3000 Software Update<br>Version 2039.08 with<br>Aural Alert Improvement                                      | PA-46-600TP                                             | 3/10/2017  | 10-01615-08                                                          |             | 3420        |
| 1217   | Garmin G3000 Software Update<br>Version 2039.11 with<br>FIKI Modification                                            | PA-46-600TP                                             | 7/13/2017  | 10-01615-11<br>VB-2366 R03                                           |             | 3420        |
| 1219   | Cabin Pressure Control System<br>(CPCS) Troubleshooting Procedure<br>Revision                                        | PA-46-350P M350<br>PA-46-500TP M500<br>PA-46-600TP      | 1/5/2018   | N/A                                                                  |             | 2130        |
| 1220   | Garmin G1000 Software Version<br>2164.08                                                                             | PA-46-350P M350                                         | 11/6/2017  | 190-01889-00<br>190-01888-00                                         |             | 3420        |
| 1221   | Wing Access Cover Clinch Nut<br>Repair                                                                               | PA-46-500TP<br>PA-46-600TP                              | 9/25/2017  | 477-899<br>414-779                                                   |             | 2810        |
| 1222B  | Hydraulic Pump Pressure Switch<br>Replacement                                                                        | PA-46-350P<br>PA-46-500TP<br>PA-46-600TP<br>PA-46R-350T | 3/29/2018  | 102559-002 (461-751)<br>102559-003 (461-768)<br>102559-004 (461-770) |             | 2913        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                                                                                 | MODELS<br>AFFECTED                                                    | DATE       | PART/KIT<br>NO.                           | A.D.<br>NO. | ATA<br>CODE  |
|--------|---------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|------------|-------------------------------------------|-------------|--------------|
| 1224   | Decorative Window Sealant Improvement                                                                   | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46-600TP                | 10/9/2017  | 179-759                                   |             | 5610<br>5620 |
| 1227   | Forward Ballast Plates Installation                                                                     | PA-46-600TP                                                           | 11/2/2017  | 46N08A000-800                             |             | 5300         |
| 1228A  | Engine Wiring Harness Improvement                                                                       | PA-46-500TP M500<br>PA-46-600TP                                       | 1/23/2019  | **                                        |             | 2497         |
| 1230   | G3000 And G3000 NG Electronic Checklist                                                                 | PA-46-600TP                                                           | 1/7/2020   | N/A                                       |             | 3140         |
| 1231A  | Garmin G3000 Software Version 2039.12                                                                   | PA-46-600TP                                                           | 8/3/2018   | 190-01927-01<br>190-01928-01              |             | 3420         |
| 1232C  | Garmin G1000 Software Version 2163.09                                                                   | PA-46-500TP M500                                                      | 8/21/2018  | 190-01843-01<br>190-01842-01              |             | 3420         |
| 1233   | Wing And Flap Protective Tape Improvement                                                               | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46-600TP<br>PA-46R-350T | 7/13/2020  | 380-066                                   |             | 5753         |
| 1234   | Garmin GIA Software Update 2963.01 for Transponder Compatibility with ADS-B Out in G1000 Sw Ver. 720.17 | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                              | 1/16/2018  | **                                        |             | 3452         |
| 1236   | Channel Modification For Nose Landing Gear Trunnion Clearance                                           | PA-46-500TP<br>PA-46-600TP                                            | 10/2/2019  | N/A                                       |             | 5311         |
| 1238B  | Aileron Seal Removal And Aileron Replacement                                                            | PA-46-600TP                                                           | 1/6/2022   | 46W43A001<br>415-533<br>(MS35206-243)     |             | 5751         |
| 1244   | Wiring Ground Modification                                                                              | PA-46-600TP                                                           | 6/21/2018  | N/A                                       |             | 2397         |
| 1245   | G1000 NXi Electronic Checklist                                                                          | PA-46-500TP M500                                                      | 12/14/2022 | N/A                                       |             | 3140         |
| 1246   | G1000 NXi Electronic Checklist                                                                          | PA-46-350P M350                                                       | 1/7/2020   | N/A                                       |             | 3140         |
| 1247A  | Hydraulic System Flexible Hose Inspection And Replacement                                               | PA-46-600TP                                                           | 11/5/2019  | 566-670<br>(171001-4CR-0110)              |             | 2910<br>3233 |
| 1249   | Control Column Plug Modification                                                                        | PA-46-350P<br>PA-46-500TP<br>PA-46-600TP<br>PA-46R-350T               | 5/20/2019  | 85228-002                                 |             | 2701         |
| 1250A  | Garmin G1000 Software Update Version 2164.09                                                            | PA-46-350P M350                                                       | 4/12/2019  | 88642-001<br>190-01889-01<br>190-01888-01 |             | 3420         |
| 1251   | Garmin G1000 Software Version 2163.10                                                                   | PA-46-500TP                                                           | 5/29/2019  | 88651-001                                 |             | 3420         |
| 1253   | G1000 Electronic Checklist                                                                              | PA-46-350P M350                                                       | 12/11/2019 | N/A                                       |             | 3140         |
| 1257   | Servicing The Alternative Wheel Nut Configuration                                                       | PA-46-600TP                                                           | 5/6/2019   | N/A                                       |             | 3420         |
| 1259A  | Garmin G3000 Software Version 2039.15                                                                   | PA-46-600TP                                                           | 11/17/2020 | 88644-001                                 |             | 3420         |
| 1260   | Optional Nav/Com Analog Conversion Kit                                                                  | PA-46-600TP                                                           | 5/24/2019  | 88648-001                                 |             | 2397         |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

# SERVICE LETTER INDEX

PA-46-310P, PA-46-350P  
PA-46-500TP, PA-46-600TP  
PA-46R-350T

| NUMBER | SUBJECT                                                                       | MODELS<br>AFFECTED                                                    | DATE       | PART/KIT<br>NO.                                  | A.D.<br>NO. | ATA<br>CODE |
|--------|-------------------------------------------------------------------------------|-----------------------------------------------------------------------|------------|--------------------------------------------------|-------------|-------------|
| 1261   | Stall Warning Heat Control Inspection                                         | PA-46-350P<br>PA-46-350T<br>PA-46-500TP                               | 7/19/2019  | N/A                                              |             | 3418        |
| 1264   | Garmin G3000NG Software Version 2975.05                                       | PA-46-600TP                                                           | 8/16/2019  | 88637-001                                        |             | 3420        |
| 1265   | Flight Control System Checks                                                  | All                                                                   | 8/6/2019   | N/A                                              |             | 2700        |
| 1266   | Piper HALO Autoland System Activation and Garmin Software Update Ver. 2975.16 | PA-46-600TP                                                           | 6/26/2020  | 88660-701<br>88660-702<br>88645-702<br>88680-001 |             |             |
| 1269A  | Radar Altimeter Installation                                                  | PA-46-600TP                                                           | 3/6/2023   | 88643-701<br>88654-001                           |             | 3444        |
| 1270   | Radar Altimeter Installation                                                  | PA-46-600TP                                                           | 1/28/2021  | 88645-702<br>88654-001                           |             | 3444        |
| 1272   | Elevator Spar Inspection                                                      | PA-46-500TP<br>PA-46-600TP                                            | 10/25/2019 | N/A                                              |             | 5521        |
| 1274   | Hartzell Propeller Preferred Grease                                           | All                                                                   | 1/6/2020   | NYCO GN 3058                                     |             | 6110        |
| 1275   | Optional Radar Altimeter Installation (Garmin GRA 55 Radar Altimeter)         | PA-46-600TP                                                           | 1/12/2021  | 88645-701<br>88654-001                           |             | 3444        |
| 1279   | High-Side Current Monitor Calibration                                         | PA-46-600TP                                                           | 7/8/2020   | N/A                                              |             | 3420        |
| 1280   | Rudder Pedal And Bar Assembly Inspection                                      | All                                                                   | 2/14/2020  | N/A                                              |             | 2720        |
| 1281B  | Piper Halo Autoland System Activation                                         | PA-46-600TP                                                           | 1/7/2022   | 88670-701                                        |             | 2230        |
| 1282   | Avionics Cooling Fan Advisory                                                 | PA-46-350P<br>PA-46-500TP<br>PA-46R-350T                              | 6/22/2020  | 460-124                                          |             | 2120        |
| 1283A  | Piper HALO Autoland System Activation                                         | PA-46-600TP                                                           | 1/7/2022   | 88662                                            |             | 2230        |
| 1284   | Aspen Avionics EFD1000 Update to Software Version 2.10.2                      | PA-46-350P<br>PA-46-500TP<br>PA-46-600TP                              | 2/7/2023   | N/A                                              |             | 3420        |
| 1285C  | Proper Tire Pressure Maintenance                                              | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46-600TP<br>PA-46R-350T | 3/29/2022  | **                                               |             | 3244        |
| 1286D  | Nose Landing Gear Steering Components Inspection And Adjustment               | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46-600TP<br>PA-46R-350T | 10/15/2021 | N/A                                              |             | 3200        |
| 1292B  | Garmin G3000NG Software Version 2975.22                                       | PA-46-600TP                                                           | 1/13/2022  | 88680-001<br>88704-701                           |             | 3420        |
| 1296   | Flap Fail Module Assembly Replacement                                         | PA-46-600TP                                                           | 3/10/2022  | 602-575                                          |             | 2756        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.

# SERVICE LETTER INDEX

| NUMBER | SUBJECT                                             | MODELS<br>AFFECTED                                                    | DATE       | PART/KIT<br>NO.        | A.D.<br>NO. | ATA<br>CODE |
|--------|-----------------------------------------------------|-----------------------------------------------------------------------|------------|------------------------|-------------|-------------|
| 1297   | Rudder Tube Assembly Inspection                     | PA-46-310P<br>PA-46-350P<br>PA-46R-350T<br>PA-46-500TP<br>PA-46-600TP | 10/22/2021 | 82810-015<br>82810-016 |             | 2720        |
| 1301A  | Standalone Autothrottle Enablement                  | PA-46-600TP                                                           | 2/14/2023  | 88661                  |             | 2230        |
| 1304   | Garmin G1000 NXi Software Update<br>Version 2783.08 | PA-46-350P M350                                                       | 1/18/2022  | 88711                  |             | 3420        |
| 1310A  | M600 Unpaved Field Operations                       | PA-46-600TP                                                           | 11/7/2022  | 88596-001<br>88705-701 |             | 3200        |
| 1314   | Oxygen Generator Inspection                         | PA-46-310P<br>PA-46-350P<br>PA-46-500TP<br>PA-46-600TP                | 8/22/2022  | N/A                    |             | 3500        |
| 1317   | GI 275 Standby Instrument<br>Magnetic Model Update  | PA-46-350P M350<br>PA-46-500TP M500<br>PA-46-600TP                    | 11/11/2022 | 006-B3182-10           |             | 3420        |
| 1323   | Garmin G1000 NXi Software Update<br>Version 2785.11 | PA-46-500TP M500                                                      | 3/20/2023  | 88719-701              |             | 3420        |

\* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

\*\* Reference appropriate service letter for material identification and/or appropriate aircraft model.